

INS. CASE OWNER: Bernard CC6 / AIG180 01028 / UKES / V LKK: 03 IDAC:

Surveyor: MARCUS DOI: 17/01/18 Date / Time: 17/01/18
Registered in Meriton: 17/01/18

Pre-assign / CCU / FTE



Insured Vehicle No.: SLD 7437F Claim No.: 109SD23862 SQ
Name of Insured: MING DO TRADING AND SERVICES Policy No.: 2100472365
Insured Tel No.: _____ HP: _____ Make / Model: TOYOTA COROLLA ALTIS 1.6 CVT
Excess Sec II : \$5 D.O.A: 15/01/18 Place of Accident: ALONG CIE AFTER AMK AVE 15-ET
Is driver the owner? (YES / NO) Nature of Accident: _____
If NO, Driver Name / Age: TAN BOON WAH OI GIA REPORT YES / NO : TP GIA REPORT YES / NO
Driver Tel No.: 9750 6087 (VA NO / NO) Insured Liability: % Final ? Yes / No



INSRS: _____
WSP: Kim Chwee
Tel: _____
Liability: _____
RMKS: _____



INSRS: _____
WSP: _____
Tel: _____
Liability: _____
RMKS: _____



INSRS: _____
WSP: _____
Tel: _____
Liability: _____
RMKS: _____



INSRS: _____
WSP: _____
Tel: _____
Liability: _____
RMKS: _____

Date/ Time	STAGE	DATE / PIC
22/01/18 (ZAN)	Non-Reporting 1st (1st)	
	Non-Reporting 1st (2nd)	
	Non-Reporting 1st (Final)	
	Notification 1st (if non-pickup)	
	Call OI	
	After call 1st to OI	
22/01/18 @ 4-44pm	Documentation Check List: Handler Typist	
	Notification 1st (if non-pickup)	
	After call 1st to OI	
	Authorisation To Act	
	Release Voucher	
	Final Repair Bill	
	Car Rental Invoice	
	Towing Invoice	
	LTA / GIA	
	Medical Bill	
	PIR	
	Mandate/Reject Instruction	
	LOD	
	Payment Breakdown Form	
	Post-Repair Photos	
	Others	

PRELIMINARY ADVICE Date/Time: 22/01/18 Sent By: Kim Chwee

FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: _____
Repair Cost: \$5 _____ (days) Reduction: % _____ Email ☐ Call ☐

FINAL SETTLEMENT Date/Time: 12/04/2018 Confirm with: 3020N Email ☒ Call ☐
Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 27
Repair Cost: (w/15ST) \$5 9,095.00
Loss of Rental (LOR): \$5 _____ (days)
Loss of Use (LOU): \$5 700.00 (550.0 x 14 days)
Loss of Income (LOI): \$5 _____ (\$ _____ x _____ days)
LOR only ☐ LOU only ☒ LOR + LOU ☐ LOR + LO ☐ (Tick only one)
GIA/LTA Search \$5 2.00
Medical: \$5 _____
Disbursement: \$5 _____ (e.g. Tow/ Independent)
Legal Cost: \$5 _____
Total: \$5 9,797.00 Global Sum \$5: _____

FINAL PAYMENT Date/Time: 12/04/2018 Confirm with: 3020N Email ☒ Call ☐
Payee 1: \$5 9,797.00 Name 1: Kim Chwee Auto Pte Ltd.
Payee 2: (Strike if N.A.) \$5 _____ Name 2: _____
Payee 3: (Strike if N.A.) \$5 _____ Name 3: _____

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *SKM0352*at Workshop m/s *Kim Chuee*

of _____

Insured _____

Policy No. _____

Claims No. _____

Sum insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: *26k.*

IDAC Incident Report: _____ Consistent? Yes or No

GIA / BP / Seed: _____ Consistent? Yes or No

Est. Repairs: *12* days Res: Yes or NoLum Sum: *10* % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

17/12/19

Vehicle IN / OUT

Date: _____ Person Contacted: _____

Date / Time Action / Instruction

24/1/18 *Rep. - Sum & HCU confirmed with Alan.*
workshop want repair at 24 hrs.
Note new parts replacement
surveys recommended days
(12 days 7 + weekends (2 days)) = 14 days.
(red: \$9,091.70 / 52 %)

Date/Time File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee:

☐

Site Insp (\$

) \$ + RS \$

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Copies

☐

Weekend (\$

) TOTAL

Report Format :

Lump Sum / I.B.I. (\$

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/AIG18001028/Uks3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 17-01-2018		
		Code : AIG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLD 7437P	Veh. Inspected	SKM 8035Z	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	17/01/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	15/01/2018	Inspection Date	17/01/2018	
Survey held at	KIM CHWEE AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

KIM CHWEE AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-46 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

NOT Approved
Man
Repair Sum \$8500
12 day.

Amount S\$

Qty Particular

List Item:

1PCS BOOTLID
1PCS BOOTLID REAR LOGO
1PCS BOOTLID 'COROLLA' EMBLEM
1PCS BOOTLID 'ALTIS' EMBLEM
1PCS BOOTLID INNER LOCK
1PCS BOOTLID LOCK STRIKER
1PCS BOOTLID WEATHERSTRIP
2PCS BOOTLID REFLECTORS @\$339.50 182.40
1PCS BOOTLID OUTER CHROME MOULDING
1PCS BOOTLID INNER TRIM COVER
1SET BOOTLID INNER TRIM COVER CLIPS
2PCS BOOTLID HINGES @\$67.40
1PCS REAR END PANEL
1PCS REAR END PANEL TOP GARNISH
1PCS REAR END PANEL LOCK SENSOR
1PCS REAR BUMPER
2PCS REAR BUMPER SIDE RETAINERS @\$104.40
2PCS REAR BUMPER SIDE HOLDERS @\$57.60
2PCS REAR BUMPER SPLASH SHIELDS @\$52.80
2PCS REAR BUMPER REFLECTORS @\$57.30
2PCS REAR BUMPER PARKING SENSORS @\$282.00
1PCS REAR BUMPER PARKING SENSOR WIRE HARNESS
1PCS REAR BUMPER REINFORCEMENT w/sponge

20/3uc \$963.10 ✓
nr \$58.90 ✓
nr \$39.30 ✓
nr \$43.60 ✓
Tm \$382.70 ✓
nr \$34.60 X
Tm \$168.20 ✓
o/s cre \$679.00 1pc
nr \$233.70 X
Tm \$349.30 ✓
nr \$45.00 ✓
o/s set \$134.80 1pc
Bo by 20 \$587.20 ✓
Tm \$232.00 ✓
nr \$159.30 X
Dis \$486.50 ✓
o/s set \$208.80 1pc
o/s cre \$115.20 1pc
o/s Tm \$105.60 1pc
o/s cre \$114.60 1pc
shk \$564.00 2005.00
nr \$247.80 X
Tm \$362.70 ✓

257

KIM CHWEE AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-46 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Qty	Particular	Amount S\$
<u>List Item:</u>		
2PCS	TAILLAMPS @\$364.50	o/s 3/20 \$729.00 1pc
2PCS	TAILLAMP HOUSING PANELS @\$106.20	o/s 20 \$212.40 1pc
2PCS	REAR FENDERS @\$986.80	o/s 3uc \$1973.60 1pc
2PCS	REAR FENDER INNER TRIMS @\$355.90	o/s 70.11 \$711.80 1pc
1PCS	REAR FLOOR PANEL	n \$786.90 x
1PCS	REAR FLOOR PANEL TOP BOARD	71.11 \$256.40 /
1PCS	REAR EXHAUST	dent/tu \$931.90 /
2PCS	REAR EXHAUST MOUNTINGS @\$40.70	nu \$81.40 /
1PCS	REAR WINDSCREEN MOULDING	nu \$86.10 /
1PCS	REAR EXHAUST HEAT SHIELD	n \$66.30 x
List Item Total:		\$12,151.70

6257

7409.6
5557.20

Special Nett Item:

1PCS	REAR END PANEL SEALANT	nu \$80.00 50s.~
1SET	REAR FLOOR PANEL INSULATOR	nu \$300.00 120.5.~
1PCS	REAR WINDSCREEN SEALANT	nu \$80.00 40s.~
<u>Special Nett Total:</u>		\$460.00

Labour Charge:

TO CHECK WIRING.	\$80.00 30
TO DISMANTLE & REPLACING PARKING SENSOR.	\$80.00 50
TO DISMANTLE & REFIX BOOTLID MECHANISM.	\$100.00 60
TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTERY.	\$150.00 80

KIM CHWEE AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-46 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Qty Particular

Amount S\$

Labour Charge:

TO SPRAY RUST PROOFING.

\$120.00 ✓

TO DISMANTLE & REPLACING REAR EXHAUST.

\$100.00 60

TO DISMANTLE & REFIX REAR WINDSCREEN.

\$150.00 120

LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN

& REPLACING PARTS.

\$2200.00 1600

TO PUTTY & SPRAY PAINTING.

\$2000.00 1380

Labour Charge Total:

\$4980.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$17,591.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8042B
Vehicle Details	
Vehicle No.:	SKM8035Z
Vehicle to be Exported:	No
Intended De-registration Date:	17 Jan 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	3ZZ4963906
Chassis No.:	MR053ZEE106164959
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$17,853.00
Original Registration Date:	18 Dec 2009
First Registration Date:	18 Dec 2009
Transfer Count:	1
Actual ARF Paid:	\$17,853.00 <i>8926</i>
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Dec 2019
PARF Rebate Amount:	\$9,819.00
Intended COE Rebate Details	
COE Expiry Date:	17 Dec 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$17,189.00
COE Rebate Amount:	\$3,294.00
Total Rebate Amount:	\$13,113.00

The information contained herein is correct as at 17 Jan 2018

OK

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8042B
Vehicle Details	
Vehicle No.:	SKM8035Z
Vehicle to be Exported:	No
Intended De-registration Date:	16 Jan 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	3ZZ4963906
Chassis No.:	MR053ZEE106164959
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$17,853.00
Original Registration Date:	18 Dec 2009
First Registration Date:	18 Dec 2009
Transfer Count:	1
Actual ARF Paid:	\$17,853.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Dec 2019
PARF Rebate Amount:	\$9,819.00
Intended COE Rebate Details	
COE Expiry Date:	17 Dec 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$17,189.00
COE Rebate Amount:	\$3,299.00
Total Rebate Amount:	\$13,118.00

The information contained herein is correct as at 16 Jan 2018

OK

sgCARMART.COM

Login Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Articles

Forum

Tools & Tips

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

First Registration Date 20 Feb 2012.



Direct Owner Sell, Please Feel
Free To Call For Further
Information And Viewing.
Direct Owner - Started



Browse by Category

Back (1 2 3) Next >

Sort by Date Posted

20 results/page

58 vehicles

toyota altis

Advanced Search

Submit

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	toyota altis	Any	Any	2009	Any	Any	Any	Available



Toyota Corolla Altis 1.6A

\$17,800

\$8,550 /yr

19-Feb-2009

1,598 cc

155,000 km

Sedan

Available

Very Well Maintain Previous Female Owner. Excellent Interior And Exterior Condition. Regularly Serviced. Ease Of Maintenance With Good Fuel Efficiency. Bank Loan And In House Loan Available. \$0 Downpa...

Posted: 16-Jan-2018 Page: 2009 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Corolla Altis 1.6A

\$23,800

\$9,420 /yr

17-Aug-2009

1,598 cc

135,689 km

Sedan

Available

Down Payment Start As Low As \$2500 Onwards. Welcome Old Car 1-1 Exchange Without Cash Top Up.

Posted: 16-Jan-2018 Page: 2009 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Corolla Altis 1.6A

\$26,800

\$8,570 /yr

01-Dec-2009

1,598 cc

121,000 km

Sedan

Available

Set To Sell! 1 Owner, Original Paintwork With Genuine Low Mileage! 100% Accident Free, Absolute No Repairs Needed! Come View To Appreciate Anytime, Before It's Gone!

Posted: 15-Jan-2018 Page: 2009 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Corolla Altis 1.6A

\$19,800

\$9,530 /yr

27-Mar-2009

1,598 cc

116,203 km

Sedan

Available

Car In Tip Top Condition With Low Mileage Done. Buy From Thong Lee With A Peace Of Mind. High Trade In And In House Loan Available.

Posted: 15-Jan-2018 Page: 2009 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota

Car Buying

Car Selling

Car Aftermarket

Car Ownership

On The Move

Lifestyle



Toyota Corolla Altis 1.6A

\$27,800

\$11,560 /yr

01-Sep-2009

1,598 cc

Sedan

Available

Only 1 Owner, Healthy Mileage Clocked! No Repair Needed For Its Well-known Durability. Good Fuel Consumption. Highly Sought After. Buy With No Worries. We Take Pride In Our Work, Regardless Of Comm...

Car (S) Pte Ltd

Posted: 14-Jan-2018 Page: 2009 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Corolla Altis 1.6A

\$19,500

\$9,430 /yr

20-Mar-2009

1,598 cc

Sedan

Available

Lowest Depreciation! Just Serviced. Grab And Get High Loans And Trade In Available! Perfect Car To Renew Car! Call Now To View This Beauty. Viewing Strictly By Appointment Based.

Posted: 14-Jan-2018 Page: 2009 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Corolla Altis 1.6A

\$24,800

\$10,650 /yr

22-Jul-2009

1,598 cc

Sedan

Available

Ka-Hup Vehicles Trading

Posted: 14-Jan-2018 Page: 2009 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



Toyota Corolla Altis 1.6A

\$20,800

\$10,740 /yr

12-Mar-2009

1,598 cc

129,000 km

Sedan

Available

Beautiful Inside Out, Low Fuel Consumption, Low Maintenance, Low Insurance Premium. Great Car, Low Mileage Only 129000km. Agent Regular Servicing. Call Us Now.

Ka-Hup Vehicles Trading

Posted: 14-Jan-2018 Page: 2009 Toyota Corolla, Toyota Corolla, Toyota, Corolla, Used Toyota



KIM CHWEE AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-50 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 199802379R

Date : 31.01.2018

AIG Asia Pacific Insurance Pte Ltd

Chartis Building

78 Shenton Way #07-16

Singapore 079120

Attn: Motor Claim Department

ACCIDENT INVOLVING VEHICLE: SKM8035Z AND SLD7437P ON 15.01.2018

We are the authorized repair workshop for the owner of motor vehicle no: **SKM8035Z**, which was involved in the captioned accident with your insured vehicle no: **SLD7437P**. The vehicle owner has requested and authorized us to assist him in presenting his/her claim against the party responsible for the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving, we are submitting these claims for your consideration on behalf of the owner/claimant.

1) Cost of Repair (inclusive of GST)	\$ 9,095.00
2) Loss Of Use (12days + 2sun x \$100)	\$ 1,400.00
3) GIA Search Fee	\$ 2.00
	<u>\$ 10,497.00</u>

We enclosed herewith the following documents to support the claims:

- | | |
|------------------------------------|----------------------------------|
| a) Final Repair Invoice | b) Vehicle Registration Log Card |
| c) GIA Report | d) I/C & Driving Licence |
| e) Insurance Certificate | f) GIA Search Result |
| g) Letter of Authorisation, etc... | |

Kindly look into the matter and let us hear from you on the settlement of our customer's claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

Thank you.

Yours faithfully,

Jason Tang (jason@fastechauto.com.sg)

For Kim Chwee Auto Pte Ltd

Zaini (LKK Auto)

From: Ler, Bernard-JQ <Bernard-JQ.Ler@aig.com>
Sent: Monday, 9 April 2018 2:33 PM
To: Zaini (LKK Auto)
Cc: Hsiao Tong (LKKAuto)
Subject: RE: <Seek Mandate> Your Ref: 1095023862SG_ACCIDENT INVOLVING SLD 7437P(OI) & SKM 8035Z(TP) ON 15/01/2018

Follow Up Flag: Follow up
Flag Status: Completed

Dear Zaini,

Kindly proceed as per recommended.

Thank you.

Best Regards,

Bernard Ler
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

18 Shenton Way #08-18 Singapore(079120)

Tel: +65 6419 1945 | Fax: +65 6335 7416

Bernard-JQ.Ler@aig.com | www.aig.com.sg

From: Zaini (LKK Auto) [mailto:Zaini@lkkauto.com]
Sent: Thursday, April 05, 2018 9:18 AM
To: Ler, Bernard-JQ
Cc: Hsiao Tong (LKKAuto)
Subject: RE: <Seek Mandate> Your Ref: 1095023862SG_ACCIDENT INVOLVING SLD 7437P(OI) & SKM 8035Z(TP) ON 15/01/2018

WITHOUT PREJUDICE

Dear Bernard,

We refer to your email below.

According to our surveyor, TP repairer strongly requested for part by part basis as TP claimant requested for replacements of new parts and there were no old / 2nd hand parts available at the time of inspection. Enclosed copy of merimen photos (No. 112 – 117) on the replacement of new parts for your reference.

However, TP repairer is willing to undertake Lump Sum Repair (89% etc) to reduce repair cost. Our surveyor has checked the price of the parts and revised accordingly to a reduction of more than 50% from the initial estimate of \$17,591.70.

For your approval / instruction in merimen.

Thank you.

Best Regards,

Zaiji Kusaini | Case Handler

LKK Auto Consultants Pte Ltd

MO: 6841-2132 | email: zaiji@lkkauto.com | fax: 6741-4106

11K-31, Piyaji Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ler, Bernard-JQ (<mailto:Bernard-JQ.Ler@aig.com>)

Sent: Thursday, 29 March 2018 2:15 PM

To: Zaini (LKK Auto) <Zaini@lkkauto.com>

Cc: Hsiao Tong (LKKAuto) <chewhtr@lkkauto.com>

Subject: RE: <Seek Mandate> Your Ref: 1095023862SG_ACCIDENT INVOLVING SLD 7437P(OI) & SKM 8035Z(TP) ON 15/01/2018

Dear Zaini,

Any update please?

Thanks.

Best Regards,

Bernard Ler

AIG

Complex Claims Examiner

Claims | AIG Asia Pacific Insurance Pte. Ltd

18 Shenton Way #08-16 Singapore(079120)

Tel: +(65) 6419 1946 | Fax: +(65) 6335 7416

Bernard-JQ.Ler@aig.com | www.aig.com.sg

From: Ler, Bernard-JQ

Sent: Wednesday, February 28, 2018 3:55 PM

To: 'Zaini (LKK Auto)'

Cc: Hsiao Tong (LKKAuto)

Subject: RE: <Seek Mandate> Your Ref: 1095023862SG_ACCIDENT INVOLVING SLD 7437P(OI) & SKM 8035Z(TP) ON 15/01/2018

Dear Zaini,

May I check why the overridden cost is 89% of the gross total? As the discount for lump sum repair should be around 20%.

Kindly advise.

Thanks.

Best Regards,

Bernard Ler

AIG

Complex Claims Examiner

Claims | AIG Asia Pacific Insurance Pte. Ltd

18 Shenton Way #08-16 Singapore(079120)

Tel: +65 6419 1948 | Fax: +65 6335 7416

Bernard-JQ.Ler@aig.com | www.aig.com.sg

From: Zaini (LKK Auto) [<mailto:Zaini@lkkauto.com>]

Sent: Thursday, February 22, 2018 8:48 AM

To: Ler, Bernard-JQ

Cc: Hsiao Tong (LKKAuto)

Subject: <Seek Mandate> Your Ref: 1095023862SG_ACCIDENT INVOLVING SLD 7437P(OI) & SKM 8035Z(TP) ON 15/01/2018

WITHOUT PREJUDICE

Your Ref: 10950238625G

Our Ref: CC6/AIG18001028/Uks3

Dear Bernard,

ACCIDENT INVOLVING SLD 7437P(OI) & SKM 8035Z(TP) ON 15/01/2018

We refer to the above matter.

This is a head-to-rear collision. Liability is not in our insured's favour.

We did clarify with insured the nature of the accident and he's aware that NCD (if any) would be affected.

We seek your approval to offer to Third Party repairer, KIM CHWEE AUTO PTE LTD is as follows: -

	Amount <u>Claimed</u>	Amount <u>Revised</u>
1. Cost of Repair(w/GST)	\$ 17,591.70	\$ 9,095.00
2. Loss of Use(14days x \$100.00)	\$ 1,400.00	\$ 840.00 (14days x \$60.00)
3. LTA / GIA Search fee	\$ 2.00	\$ 2.00
TOTAL	\$ 18,993.70	\$ 9,937.00

Total amount of claim (Liability 100%) **\$ 9,937.00**

For your approval in Merimen please.

Best Regards,

Zaini Kusaini | Case Handler

LKK Auto Consultants Pte Ltd

Cell: 6841-2132 | email: Zaini@lkkauto.com | fax: 6741-4108

Blk 51, Poyu@Industrial Park, Ute Avenue 1, #02-25 | S(408933)

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Print Received Message

This mail is associated with :

*SKM8035Z (1095023862SG)
[SLD7437P]

TP

TAN HEOK KHIN

Jan 15 2018 12:00AM

[Mingdo Trading And Services]

Kim Chwee Auto Pte Ltd

From: AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 09/04/2018 14:32 PM.
To: LKK_HQ
Subject: Alert - Adj Mandate Approved (S\$9937.00) - SKM8035Z - Claim Handler: Ler, Bernard-JQ

Approved:9937,00:Hi, kindly proceed as per recommended.

Zaini (LKK Auto)

From: Jason Fastech Auto <jason@fastechauto.com.sg>
Sent: Wednesday, 11 April 2018 2:57 PM
To: Zaini (LKK Auto)
Cc: Hsiao Tong (LKKAuto)
Subject: RE: Your Ref: SKM 8035Z_ACCIDENT INVOLVING SLD 7437P AND SKM 8035Z ON 15/01/2018

Follow Up Flag: Follow up
Flag Status: Flagged

Without Prejudice

Dear Zaini,

We are pleased to accept your offer of \$ 9,797.00 all in.

Thank you.

Best Regards

Jason Tang
Kim Chwee Auto Pte Ltd
1 Kaki Bukit Ave 6
#01-46/48/50 AutoBay
Singapore 417883
Tel: 67465405
Hp: 98218445
jason@fastechauto.com.sg

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

From: Zaini (LKK Auto) [mailto:Zaini@lkkauto.com]
Sent: Wednesday, April 11, 2018 11:30 AM
To: jason@fastechauto.com.sg
Cc: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Subject: Your Ref: SKM 8035Z_ACCIDENT INVOLVING SLD 7437P AND SKM 8035Z ON 15/01/2018

WITHOUT PREJUDICE

Your Ref: SKM 8035Z
Our Ref: CC6/AIG18001028/Uka3

Dear Jason,

ACCIDENT INVOLVING SLD 7437P AND SKM 8035Z ON 15/01/2018

We refer to the above matter.

We propose settlement as follows: -

1. Cost of Repair (w/GST)	\$ 9,095.00
2. Loss of Use(14days x \$50.00)	\$ 700.00
3. LTA/GIA Search Fee	\$ 2.00
TOTAL	<u>\$ 9,797.00</u>

Please confirm acceptance.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Best Regards,

Zaini Kusaini | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841-2132 | email: Zaini@lkkauto.com | fax: 6741-4108

Blk 51, Poyu Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC6/AIG18001028/Uks3

29 JANUARY 2018

MINGDO TRADING AND SERVICES
32 TANAH MERAH KECHIL ROAD
#04-23 EAST MEADOWS
SINGAPORE 465559

Dear Sir/Madam,

ACCIDENT INVOLVING SLD 7437P AND SKM 8035Z ON 15.01.2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,


Zaini
Case Handler
DID: 6841 2132
FAX: 6741 4108
Email: Zaini@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, Tan Heok Khin ("the third party claimant")
of Blk 253A Ang Mo Kio St 21 #05-175 5561253 (address),
owner of SKM 8035Z (vehicle no.) hereby authorize
Kim Chwee Auto Pte Ltd
("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. SKM 8035Z that was
damaged pursuant to the accident which occurred on 15/01/2018 (date) along
CTE towards town (location)
involving vehicle no/s SLD 7437P ("the accident").

I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment forthwith settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 17 day of January (month) 2018 (year)



Signed by "the third party claimant"



Signed by "the workshop"

RELEASE VOUCHER
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

We/I, Kim Chwee Auto Pte Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte. Ltd., LKK Auto Consultants Pte Ltd. ("name of surveyor") with respect to the amount claimed for S\$ 9,095.00 (repair costs), S\$ 700.00 (loss of use/rental) S\$ 2.00 (search fees) for vehicle no. SKM8035Z that was damaged pursuant to the accident which occurred on 15/1/18 (date) along CTE towards town (location) involving vehicle no/s SLD 7437P.

This is pursuant to the inspection conducted on 17.01.2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Tan Heok Khin ("third party claimant") of vehicle no. SKM8035Z to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte. Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SKM8035Z (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 12 day of April (month) 2018 (year)



CKS

Signed by AIG appointed surveyor



Chopped & Signed by "the workshop"

TAX INVOICE

KIM CHWEE AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-50 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 199802379R

AIG Asia Pacific Insurance Pte Ltd

Chartis Building

78 Shenton Way #07-16

Singapore 079120

Attn: Motor Claim Department

Tax Invoice : 20100

Date: 31.01.2018

Vehicle No: SKM8035Z

Make/Model: TOYOTA ALTIS

Chassis/Eng# :

Accident Date: 15.01.2018

Claim No : 0118-20100

:

	Amount
To proceed on repair sum	S\$ 8,500.00

E. & O. E.

Total : S\$ 8,500.00

GST @ 7% : S\$ 595.00

Amount Due : **S\$ 9,095.00**


for KIM CHWEE AUTO PTE LTD

All Invoices are subjected to GST



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-008507

Date of Request: 16/01/2018

Your Ref No: Online Purchase

Kim Chwee Auto Pte Ltd
1 Kaki Bukit Avenue 6 #01-48
AutoBay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Enquiry Date 16/01/2018
Enquiry By Tang Kok Wee, Allan
TP Vehicle No. SLD7437P
Accident Date 15/01/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SLD7437P	AIG Asia Pacific Insurance Pte. Ltd.	28/06/2017-27/06/2018	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-008507

Date of Request: 16/01/2018

Your Ref No: Online Purchase

Kim Chwee Auto Pte Ltd
1 Kaki Bukit Avenue 6 #01-48
AutoBay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Enquiry Date 16/01/2018
Enquiry By Tang Kok Wee, Allan
TP Vehicle No. SLD7437P
Accident Date 15/01/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane



















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Jan 2018 Edit Reg		17 Jan 2018 00:00 Edit Adj Rpt	\$58,500.00 Edit Estimates	\$58,500.00 View Rpt		Pending for Survey Report Cancel Case

















































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: Mingdo Trading And Services , Co. Reg. No.: 53317894X									
Main Claimant: TAN HEOK KHIN , ID: 508380428									
Vehicle Reg. No.: SKM8035Z		Date of Loss: 15/01/2018 00:00 - :59 [96 Months and 28 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 1095023862SG		Policy/Cover Note No.: 2100472865 (Comprehensive)							
Vehicle Reg. No. (Insured): SLD7437P		Policy No. (Claimant): 17-MX004129-R03							
		Excess:							
Repairer: Kim Chwee Auto Pte Ltd (HQ) 1 Kaki Bukit Avenue 6 #01-48, AutoBay@Kaki Bukit, 417883 Eunos - Tel: 67465405/67417244									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJiQian.Ler@aig.com									
Claimant's Insurer: Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 26/01/2018]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG_EXPRESS (09/04/2018): Alert - Adj Mandate Approved (\$59937.00) - SKM8035Z - Claim Handler: Ler, Bernar... AIG_SG (18/01/2018): Request for TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									




Claim Documents

*SKM8035Z (1095023862SG)
[SLD7437P]
TP
TAN HEOK KHIN
Jan 15 2018 12:00AM
[Mingdo Trading And Services]
Kim Chwee Auto Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser		▼	
Letters/Correspondences											1 per page		▼		<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)									Thumbnail		Print			
1	(Draft)	Third Party Express Settlement – Payment Breakdown											Edit			
Assessment Reports											1 per page		▼		<input checked="" type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)									Thumbnail		Print			
1	18/01/18 16:47	Accident Statement From:OD - Reg. No: SLD7437P, Claimant: MINGDO TRADING AND SERVICES											Load HTM			
Photos/Images											3 per page		▼		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)									Thumbnail		Print			
1	17/01/18 14:14	Chassis Number											Load JPG		<input checked="" type="checkbox"/>	
2	17/01/18 14:14	General View											Load JPG		<input checked="" type="checkbox"/>	
3	17/01/18 14:14	Odometer Reading											Load JPG		<input checked="" type="checkbox"/>	
4	17/01/18 14:14	General View											Load JPG		<input checked="" type="checkbox"/>	
5	17/01/18 14:14	General View											Load JPG		<input checked="" type="checkbox"/>	
6	17/01/18 14:14	General View											Load JPG		<input checked="" type="checkbox"/>	
7	17/01/18 14:14	General View											Load JPG		<input checked="" type="checkbox"/>	
8	17/01/18 14:14	General View											Load JPG		<input checked="" type="checkbox"/>	
9	17/01/18 14:14	General View											Load JPG		<input checked="" type="checkbox"/>	
10	17/01/18 14:14	General View											Load JPG		<input checked="" type="checkbox"/>	
11	17/01/18 14:14	General View											Load JPG		<input checked="" type="checkbox"/>	
12	17/01/18 14:14	General View											Load JPG		<input checked="" type="checkbox"/>	
13	17/01/18 14:14	General View											Load JPG		<input checked="" type="checkbox"/>	
14	17/01/18 14:14	General View											Load JPG		<input checked="" type="checkbox"/>	
15	17/01/18 14:14	General View											Load JPG		<input checked="" type="checkbox"/>	
16	17/01/18 14:14	General View											Load JPG		<input checked="" type="checkbox"/>	
17	17/01/18 14:14	General View											Load JPG		<input checked="" type="checkbox"/>	
18	17/01/18 14:14	General View											Load JPG		<input checked="" type="checkbox"/>	
19	17/01/18 14:14	General View											Load JPG		<input checked="" type="checkbox"/>	
20	17/01/18 14:14	General View											Load JPG		<input checked="" type="checkbox"/>	
21	17/01/18 14:14	General View											Load JPG		<input checked="" type="checkbox"/>	
22	17/01/18 14:14	General View											Load JPG		<input checked="" type="checkbox"/>	
23	17/01/18 14:14	General View											Load JPG		<input checked="" type="checkbox"/>	
24	17/01/18 14:14	General View											Load JPG		<input checked="" type="checkbox"/>	
25	17/01/18 14:14	General View											Load JPG		<input checked="" type="checkbox"/>	
26	17/01/18 14:14	General View											Load JPG		<input checked="" type="checkbox"/>	
27	17/01/18 14:14	General View											Load JPG		<input checked="" type="checkbox"/>	
28	17/01/18 14:14	General View											Load JPG		<input checked="" type="checkbox"/>	
29	17/01/18 14:14	General View											Load JPG		<input checked="" type="checkbox"/>	
30	17/01/18 14:14	General View											Load JPG		<input checked="" type="checkbox"/>	

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
31	17/01/18 14:14	General View	 Load JPG	<input checked="" type="checkbox"/>
32	17/01/18 14:14	General View	 Load JPG	<input checked="" type="checkbox"/>
33	17/01/18 14:14	General View	 Load JPG	<input checked="" type="checkbox"/>
34	17/01/18 14:14	General View	 Load JPG	<input checked="" type="checkbox"/>
35	17/01/18 14:14	General View	 Load JPG	<input checked="" type="checkbox"/>
36	17/01/18 14:14	General View	 Load JPG	<input checked="" type="checkbox"/>
37	17/01/18 14:14	General View	 Load JPG	<input checked="" type="checkbox"/>
38	17/01/18 14:14	General View	 Load JPG	<input checked="" type="checkbox"/>
39	17/01/18 14:14	General View	 Load JPG	<input checked="" type="checkbox"/>
40	17/01/18 14:14	General View	 Load JPG	<input checked="" type="checkbox"/>
41	17/01/18 14:14	General View	 Load JPG	<input checked="" type="checkbox"/>
42	17/01/18 14:14	General View	 Load JPG	<input checked="" type="checkbox"/>
43	17/01/18 14:14	General View	 Load JPG	<input checked="" type="checkbox"/>
44	17/01/18 14:14	General View	 Load JPG	<input checked="" type="checkbox"/>
45	17/01/18 14:14	General View	 Load JPG	<input checked="" type="checkbox"/>
46	17/01/18 14:14	General View	 Load JPG	<input checked="" type="checkbox"/>
47	17/01/18 14:14	General View	 Load JPG	<input checked="" type="checkbox"/>
48	17/01/18 14:14	General View	 Load JPG	<input checked="" type="checkbox"/>
49	17/01/18 14:14	General View	 Load JPG	<input checked="" type="checkbox"/>
50	17/01/18 14:14	General View	 Load JPG	<input checked="" type="checkbox"/>
51	17/01/18 14:14	General View	 Load JPG	<input checked="" type="checkbox"/>
52	17/01/18 14:14	General View	 Load JPG	<input checked="" type="checkbox"/>
53	17/01/18 14:14	General View	 Load JPG	<input checked="" type="checkbox"/>
54	17/01/18 14:14	General View	 Load JPG	<input checked="" type="checkbox"/>
55	17/01/18 14:14	General View	 Load JPG	<input checked="" type="checkbox"/>
56	17/01/18 14:14	General View	 Load JPG	<input checked="" type="checkbox"/>
57	17/01/18 14:14	General View	 Load JPG	<input checked="" type="checkbox"/>
58	17/01/18 14:14	General View	 Load JPG	<input checked="" type="checkbox"/>
59	17/01/18 14:14	General View	 Load JPG	<input checked="" type="checkbox"/>
60	17/01/18 14:14	General View	 Load JPG	<input checked="" type="checkbox"/>
61	17/01/18 14:14	General View	 Load JPG	<input checked="" type="checkbox"/>
62	17/01/18 14:14	General View	 Load JPG	<input checked="" type="checkbox"/>
63	17/01/18 14:14	General View	 Load JPG	<input checked="" type="checkbox"/>
64	17/01/18 14:14	General View	 Load JPG	<input checked="" type="checkbox"/>
65	17/01/18 14:14	General View	 Load JPG	<input checked="" type="checkbox"/>
66	17/01/18 14:14	General View	 Load JPG	<input checked="" type="checkbox"/>
67	17/01/18 14:14	General View	 Load JPG	<input checked="" type="checkbox"/>
68	17/01/18 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	17/01/18 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	17/01/18 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	17/01/18 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	17/01/18 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	17/01/18 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	17/01/18 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	17/01/18 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	17/01/18 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	17/01/18 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	17/01/18 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	17/01/18 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	17/01/18 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
81	17/01/18 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	17/01/18 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	17/01/18 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	17/01/18 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	17/01/18 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	17/01/18 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	17/01/18 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	17/01/18 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	17/01/18 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	17/01/18 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	17/01/18 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	17/01/18 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	17/01/18 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	17/01/18 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	17/01/18 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	17/01/18 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	17/01/18 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	17/01/18 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	17/01/18 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	17/01/18 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	17/01/18 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	17/01/18 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	17/01/18 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	17/01/18 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	17/01/18 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	17/01/18 14:14	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	22/02/18 08:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	22/02/18 08:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	22/02/18 08:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	22/02/18 08:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	22/02/18 08:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	22/02/18 08:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	22/02/18 08:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
114	22/02/18 08:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
115	22/02/18 08:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
116	22/02/18 08:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
117	22/02/18 08:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
118	22/02/18 08:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
119	22/02/18 08:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
120	22/02/18 08:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
121	22/02/18 08:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
122	22/02/18 08:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
123	22/02/18 08:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	22/01/18 09:54	TP GIA REPORT 1	 Load PDF	
2	22/01/18 09:54	TP GIA REPORT 2	 Load PDF	
3	20/02/18 15:25	LETTER TO OI	 Load PDF	
4	20/02/18 15:25	GIA SEARCH	 Load PDF	
5	22/02/18 08:45	TP ESTIMATE - MARKED.	 Load PDF	

Letters/Correspondences			1 per page	<input type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
6	13/04/18 11:48	WORKSHOP INVOICE	 Load PDF	<input type="checkbox"/>
7	13/04/18 11:48	AUTHORISATION TO ACT FORM	 Load PDF	<input type="checkbox"/>
8	13/04/18 11:48	Release Voucher	 Load PDF	<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLD7437P (Insd veh)	Model:	TOYOTA COROLLA ALTIS
	SKM8035Z (TP veh)		1.6 (A)
Date of Accident:	15/01/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	18,823.12
Final Repair Cost	:	\$	9,095.00
Loss of Use	:	\$	700.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	9,797.00

14.00 days at \$50.00 per day
days

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For **Non GIA Registered Workshop**: Agreed Liability _____ 100 _____ (%)

B) For **GIA Registered Workshop**: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Kim Chwee Auto Pte Ltd	:	\$ 9,797.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

13 Apr
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18001028/UWA3Q2

Date: 13/04/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100472865
Claimant Vehicle No : SKM8035Z **Insured Vehicle No :** SLD7437P
 Date of Loss: 15/01/2018 Nature of Claim: TP Claim No: 1095023862SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKM8035Z**
 Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A) Engine No: 3ZZ4963906
 Reg. Date: 18/12/2009 (Man. Year: 2009) Chassis No: MR053ZEE106164959
 Colour: Grey Odometer: 155526 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65 R15 Rear Tyre Size: 185/65 R15
 Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
 Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,611.70	5,967.20	6,644.50	52.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,980.00	3,500.00	1,480.00	29.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,591.70	9,467.20	8,124.50	46.18
Approved Total (Overridden) (S\$)		8,500.00		
(S\$)	17,591.70	8,500.00	9,091.70	51.68
+ GST 7.00/7.00% (S\$)	1,231.42	595.00	636.42	51.68
Nett Amount (S\$)	18,823.12	9,095.00	9,728.12	51.68
+ Loss of Use (14.0 x S\$50.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		9,797.00		

INSPECTION

Date of Assignment: 17/01/2018
 Date Inspected: 17/01/2018 Inspected At: Kim Chwee Auto Pte Ltd (HQ)
 1 Kaki Bukit Avenue 6 #01-48,

AutoBay@Kaki Bukit
Singapore 417883

Estimated Period of Repair: 12.0 days

Adjuster: MARCUS CHUA

Manager: VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented / Buckled	963.10 F	*963.10 FL
2	1		*BOOTLID REAR LOGO	Necessary	58.90 F	*58.90 FL
3	1		*BOOTLID COROLLA EMBLEM	Necessary	39.30 F	*39.30 FL
4	1		*BOOT LID ALTIS EMBLEM	Necessary	43.60 F	*43.60 FL
5	1		*BOOTLID INNER LOCK	Twisted	382.70 F	*382.70 FL
6	1		*BOOTLID LOCK STRIKER	Not Necessary	34.60 F	*- FL
7	1		*BOOTLID WEATHERSTRIP	Twisted	168.20 F	*168.20 FL
8	1		*BOOTLID REFLECTORS	O/S Cracked	679.00 F	*182.40 FL
9	1		*BOOTLID OUTER CHROME MOULDING	Not Necessary	233.70 F	*- FL
10	1		*BOOTLID INNER TRIM COVER	Torn	349.30 F	*349.30 FL
11	1		*SET BOOTLID INNER TRIM COVER CLIPS	Necessary	45.00 F	*45.00 FL
12	1		*BOOTLID HINGES	O/S Bent	134.80 F	*67.40 FL
13	1		*REAR END PANEL	Badly Dented	587.20 F	*587.20 FL
14	1		*REAR END PANEL TOP GARNISH	Twisted	232.00 F	*232.00 FL
15	1		*REAR END PANEL LOCK SENSOR	Not fitted	159.30 F	*- FL
16	1		*REAR BUMPER	Distorted	486.50 F	*486.50 FL
17	1		*REAR BUMPER SIDE RETAINERS	O/S Bent	208.80 F	*104.40 FL
18	1		*REAR BUMPER SIDE HOLDERS	O/S Cracked	115.20 F	*57.60 FL
19	1		*REAR BUMPER SPLASH SHIELDS	O/S Torn	105.60 F	*52.80 FL
20	1		*REAR BUMPER REFLECTORS	O/S Cracked	114.60 F	*57.30 FL
21	2		*REAR BUMPER PARKING SENSORS	Shorted	564.00 FS	*200.00 FS
22	1		*REAR BUMPER PARKING SENSOR WIRE HARNESS	Not fitted	247.80 F	*- FL
23	1		*REAR BUMPER REINFORCEMENT W/SPONGE	Torn	362.70 F	*362.70 FL
24	1		*TAILLAMPS	O/S Broken	729.00 F	*364.50 FL
25	1		*TAILLAMP HOUSING PANELS	O/S Dented	212.40 F	*106.20 FL
26	1		*REAR FENDERS	O/S Buckled	1,973.60 F	*986.80 FL
27	1		*REAR FENDER INNER TRIMS	O/S Torn	711.80 F	*355.90 FL
28	1		*REAR FLOOR PANEL	Repair	786.90 F	*- FL
29	1		*REAR FLOOR PANEL TOP BOARD	Torn	256.40 F	*256.40 FL
30	1		*REAR EXHAUST	Bent / Twisted	931.90 F	*931.90 FL
31	2		*REAR EXHAUST MOUNTINGS	Necessary	81.40 F	*81.40 FL
32	1		*REAR WINDSCREEN MOULDING	Necessary	86.10 F	*86.10 FL
33	1		*REAR EXHAUST HEAT SHIELD	Repair	66.30 F	*- FL
34	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*50.00 FS
35	1		*SET REAR FLOOR PANEL INSULATOR	Necessary	300.00 FS	*120.00 FS
36	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **12,611.70** **7,819.60**
 - List Item Discount on L Items 0.00/25.00% (\$\$) 0.00 1,852.40

Total Parts (\$\$) 12,611.70 5,967.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMANTLE & REPLACING PARKING SENSOR	New	80.00	50.00
3	TO DISMANTLE & REIX BOOTLID MECHANISM	New	100.00	60.00
4	TO DISMANTLE & REFIX SEAT ,CUSHION UPHOLSTERY	New	150.00	80.00
5	TO SPRAY RUST PROOFING	New	120.00	120.00
6	TO DISMANTLE & REPLACING REAR EXHAUST	New	100.00	60.00
7	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	120.00
8	LABOUR FOR PANEL BEATING ,CUT,WELD ,STRAIGHTEN & REPLACING PARTS	New	2,200.00	1,600.00
9	TO PUTTY & SPRAY PAINTING	New	2,000.00	1,380.00
Gross Labour Cost (\$\$)			4,980.00	3,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >