POLICE REPORT





Police Station Of Origin: Bedok North N.P.C 30 Bedok North Road SINGAPORE 469676 Tel No: 1800-2449999 3 of 3 Report No. T/20180115/2007

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Repo G / Sgt 2 MOHAMED NASZRUL BIN MOHD	11	Signature Of Informant:
Signature Of Interpreter: Not applicable	l	Date/Time: 15/01/2018 05:38
Officer In Charge Of Case: TP / GIT / Sr Staff Sgt ONG YONG HOCK		Classification Of Case:
Contact No.: 65476436	RE /	
Authentication Stamp NP168	1	
-	SIGNATURE	

POLICE REPORT





1 of 3

· Report No. T/20180115/2007

Police Station Of Origin: Bedok North N.P.C 30 Bedok North Road SINGAPORE 469676 Tel No: 1800-2449999

REPORT	F A TRAFFIC	ACCIDENT			
	ne Report M 018 05:38	lade:	Vide Report No.: G/20180115/0052	Station Diary No.:	
Informa	nt's Partici	ulars		TOTAL STATE OF THE PARTY OF THE	
	Informant: IMAD RAMI	DAN BIN SAIM	Address: APT BLK 100 BEDOK N SINGAPORE 460100	ORTH AVENUE 4 #03-1920	
	/ ID No.: O / S84159	81F	Contact No.: , Home/Office: Mobile: 87148281		
National SINGAP	lity: PORE CITIZ	'EN	Email:		
Sex: Male	Age:	Date of Birth: 01/06/1984	Type of Informant: Driver		
Race: Boyanese		Language:	Institution / School Name:		
Occupation:		Driving Licence Informat	tion:		

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 15/01/2018 03:40	Type of Location X-Junction	
Location: Along Road 1 TAMPINES A TAMPINES C TRAFFIC LIG	VENUE 4				
Weather: Raining		Road Surface: Wet		Road Speed Limit:	
Traffic Flow: Traffic Control:				Traffic Volume:	
Type of Collis Between Mo	sion: ving Vehicles - Head To F	Rear		Anyone conveyed by ambulance:	

Details of V	ehicle Invo	lved				THE PERSONAL PROPERTY.
Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenger
PC1404G	Van				Slightly Damaged	2

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

POLICE REPORT





Police Station Of Origin: Bedok North N.P.C 30 Bedok North Road SINGAP

Report No. T/20180115/2007

2 of 3

30 Bedok North Road SINGAPORE 469676

Tel No: 1800-2449999 CONTINUATION OF REPORT

Driver					TALL DE	
Name	MUHAMMAD RAMI	DAN BIN S	AIM	ID No.		S8415981F
Related Vehicle	PC1404G (Van)	1		Conta	ct No.	87148281
Hospital/Clinic	NIL			Class Drivin Licend Expiry	g	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Dis	charge	NIL	
No. of Days gran	ted Medical Leave	NIL	Degree o	of Injury	NIL	

Brief Details.

On the 15th January 2018 at about 2.45am, I was working and had to pick up 2 passengers, 1 male and 1 female, from Raffles Hotel. I was driving my company's van, PC1404G.

On the same day at about 3.40am, I was at the traffic light junction of Tampines Avenue 4 and Tampines Central 1. I was going straight as it was green light. As I was driving, suddenly a taxi hit my van on the left rear portion. As a result, my van swerved around and hit onto the middle kerb.

My male passenger knocked his head while my female passenger's nose was bleeding. Traffic police and ambulance were called. Both my passengers were conveyed to Changi General Hospital. The taxi driver has 1 passenger. I did not take the taxi driver's particulars and vehicle registration. I do not have any camera in my van. I wish to state that I do not have any injury as of now.

I am lodging this report as informed by the traffic police vide incident number G/20180115/0052

Accident Photo





Accident Photo





