

DATE

ASS. REP. BTH

REP

CS/FCI18001053/Urbnz

ASS. REP. BTH

SA

Marcus

ASSIGNMENT (Office)

CWS

Lurene Jaw

FCI

DATE/TIME

3:49pm @ 18/01/18

Estimated Cost

REMARK

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CG

To Inspect Vehicle(s) by:

SLV 6674H

Insured

SHC 71594

at Workshop by:

Fastech Auto

Ref

6746 5405

of 1 kaki Bkt Ave 6 # 01-46 Autobay

Policy No

Claim No

D18000494 MFSTH

Sum Insured

Excess

Make of Veh

(Client's Record)

D.O.A

17/01/2018

CA / REV / REP. / REV 24 HRS

'up

MOD. Equipment

Date/Time

4:00pm @ 18/1/18

Person Contacted

Nancy

Vehicle

OUT

Date/Time

Action/Instruction

(✓) EST note

SLV 6674H-X

SHC 71594- CS/MSG17009913/Hlvbe2

N.O.A : 22/05/2017

1:11/18

sent pending est email to Lurene

sent preli thru email.

08/11/13

web

REF:

ASS. REC. BY: Marcus

Fci/

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLV 6674H

at Workshop m/s

of

Insured: SWC 7159U

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

|     |     |
|-----|-----|
| N/S | O/S |
|     |     |

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

30936

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SLV 6674H Yr Regn: 1/18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda City C.C. 1497

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 185 T/Radio: Insured / Std / NI / NA

Eng No: \_\_\_\_\_

C/No: MRHGM 6660JT 000280

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/55-R16

R: \_\_\_\_\_

BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 9 mm R/Bal: 9 mm

L/Bal: 9 mm L/Bal: 9 mm

D.O.A. 17/1/18 D.O.I. 18/1/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction 24/1/18 2/5 5300

24/1/18 2/5 5300 confirmed with Alan.

Red: \$8764.00, 61%.

RECEIVED 29 JAN 2018

Date/Time File Pass to?

1) 2/5 +

Date/Time File Return to?

2)

☐ : Preli. Report☒ : Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Photos

Others

TOTAL

Add Fee:

☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Report Format: TP

Lump Sum / t.B.I.: (\$ 5500)

4x15: 60

130 + 60

50

50

121

451



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                                           |                          |                                                                                     |
|----------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------|--------------------------|-------------------------------------------------------------------------------------|
| FIRST CAPITAL INSURANCE LTD                                                                                                            |                                                                                           | Ref : CS/FCI18001053/Urb |                                                                                     |
| 36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877                                                                                  |                                                                                           | Date : 17-01-2018        |  |
|                                                                                                                                        |                                                                                           | Code : FCI2              |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                                           |                          |                                                                                     |
| Insured Veh.                                                                                                                           | SHC 7159U                                                                                 | Veh. Inspected           | SLV 6674H                                                                           |
| Policy No.                                                                                                                             |                                                                                           | Coverage (\$)            | 0.00                                                                                |
| Claim No.                                                                                                                              |                                                                                           | Excess (\$)              | 0.00                                                                                |
| Assign From                                                                                                                            |                                                                                           | Assign Date              | 17/01/2018                                                                          |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                                           |                          |                                                                                     |
| Make & Model                                                                                                                           |                                                                                           | c.c                      | 0                                                                                   |
| Engine No.                                                                                                                             | HIDDEN                                                                                    | Year of Reg.             |                                                                                     |
| Chassis No.                                                                                                                            |                                                                                           | Colour                   |                                                                                     |
| Odometer                                                                                                                               | -                                                                                         | Steering                 |                                                                                     |
| Brakes                                                                                                                                 |                                                                                           | Modification             |                                                                                     |
| General                                                                                                                                |                                                                                           |                          |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                                           |                          |                                                                                     |
|                                                                                                                                        | Size                                                                                      | Make                     | Balance                                                                             |
| R/H Front Tyre                                                                                                                         |                                                                                           |                          | mm                                                                                  |
| L/H Front Tyre                                                                                                                         |                                                                                           |                          | mm                                                                                  |
| R/H Rear Tyre                                                                                                                          |                                                                                           |                          | mm                                                                                  |
| L/H Rear Tyre                                                                                                                          |                                                                                           |                          | mm                                                                                  |
| <b>4. Description of Damages</b>                                                                                                       |                                                                                           |                          |                                                                                     |
|                                                                                                                                        |                                                                                           |                          |                                                                                     |
| <b>5. General Information</b>                                                                                                          |                                                                                           |                          |                                                                                     |
| Accident Date                                                                                                                          | 17/01/2018                                                                                | Inspection Date          | 17/01/2018                                                                          |
| Survey held at                                                                                                                         | FASTECH AUTO PTE LTD<br>1 KAKI BUKIT AVENUE 6<br>#01-46/48/50 AUTOBAY<br>SINGAPORE 417883 |                          |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                     |                                                                                           |                          |                                                                                     |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                           |                          |                                                                                     |



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18000494MFSH

Our Ref: CS/FCI18001053/Urb

The Motor Claims Department  
First Capital Insurance Ltd

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. SLV 6674H .**

Please be informed that we had conducted the inspection of the above mentioned vehicle on 17/01/2018 at the premises of M/s FASTECH AUTO PTE LTD and have the following to report:-

|                          |                   |
|--------------------------|-------------------|
| Workshop Estimate Amount | : S\$ 14,264.80 . |
| Revised Estimate Amount  | : S\$ 6,883.12 .  |
| "Check" Items Amount     | : S\$ .           |
| Market Value             | : S\$ - .         |
| LTA Reimbursement Value  | : S\$ - .         |
| Nett Value               | : S\$ - .         |

**Description of Damage:**

The vehicle sustained damages  
at rear portion.



Yours faithfully  
MARCUS CHUA  
Automotive Assessor

**MOTOR SURVEY ASSIGNMENT**

|                    |                                                             |                               |
|--------------------|-------------------------------------------------------------|-------------------------------|
| Date               | 17-01-2018                                                  | Our Ref No. D18000494MFSH     |
| Accident Date      | 17-01-2018                                                  | Claim Type. Third Party       |
| Insured Vehicle    | SHC7159U                                                    | Third Party Vehicle. SLV6674H |
| Survey Location    | 1 KAKI BUKIT AVENUE 6 #01-46/48/50AUTOBAY                   |                               |
| Contact Person.    | NANCY LAM                                                   |                               |
| Contact No.        | 67465405/ 0                                                 | Fax No. 67458520              |
| Survey Type        | WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED: |                               |
| Appointed Surveyor | LKK AUTO CONSULTANTS PTE LTD                                |                               |
| Contact Person     | NA                                                          | Fax No. 68416315              |
| Contact Number.    | NA                                                          |                               |

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

|                   |                      |                         |
|-------------------|----------------------|-------------------------|
| Cc : Workshop     | FASTECH AUTO PTE LTD | Attention. NIL          |
| Cc : TP Solicitor | NA                   | TP Solicitor Fax No. NA |
| Officer Incharge  | LURENE               |                         |

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/233923)



PRI Documents



Close



## PRI Header Details

|                          |                                                      |                                              |                                                                                                                                                               |                                 |              |
|--------------------------|------------------------------------------------------|----------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------|--------------|
| <b>Claim No</b>          | D18000494MFSH                                        | <b>Policy No</b>                             | D-18088937MFSH                                                                                                                                                | <b>Claimant S.No &amp; Name</b> | 1 & FASTECH  |
| <b>Workshop Name</b>     | FASTECH AUTO PTE LTD<br>(Contact Person : NANCY LAM) | <b>Survey Location &amp; Contact Details</b> | 1 KAKI BUKIT AVENUE 6 #01-46/48/50AUTOBAY<br><b>Mobile:</b> 0 , <b>Phone:</b> 67465405 , <b>Fax:</b> 67458520<br><b>EmailId:</b> NANCY.LAM@FASTECHAUTO.COM.SG |                                 |              |
| <b>Our Surveyor</b>      | LKK AUTO CONSULTANTS PTE LTD                         | <b>Instructions To Surveyor</b>              | WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM                                                                                                                 |                                 |              |
| <b>Insured Name</b>      | CITYCAB PTE LTD                                      | <b>Insured Vehicle No</b>                    | SHC7159U                                                                                                                                                      | <b>TP Vehicle No</b>            | SLV6674H     |
| <b>PRI Recieved Date</b> | 17-01-2018 08:52:47 PM                               | <b>Surveyor Appointed Date</b>               | 18-01-2018 03:47:56 PM                                                                                                                                        | <b>Surveyor Accent Date</b>     | 18-01-2018 0 |

## Survey Report Upload

|                                    |                      |                             |            |                                |                                            |
|------------------------------------|----------------------|-----------------------------|------------|--------------------------------|--------------------------------------------|
| <b>Surveyor Inspection Date *:</b> | <input type="text"/> | <b>Surveyor Report Date</b> | 18-01-2018 | <b>Upload Survey Report *:</b> | <input type="button" value="Choose File"/> |
|------------------------------------|----------------------|-----------------------------|------------|--------------------------------|--------------------------------------------|

## Vehicle Particulars

|                  |                      |                       |                       |               |                      |
|------------------|----------------------|-----------------------|-----------------------|---------------|----------------------|
| <b>Make</b>      | Please Select Make ▼ | <b>Model</b>          | Please Select Model ▼ | <b>Year</b>   | Select Year ▼        |
| <b>Chasis No</b> | <input type="text"/> | <b>Engine No</b>      | <input type="text"/>  | <b>Milage</b> | <input type="text"/> |
| <b>Color</b>     | <input type="text"/> | <b>Cubic Capacity</b> | <input type="text"/>  |               |                      |

## Multiple Documents Upload

Upload Multiple Documents

File Name

Action

## Surveyor Job Remarks

|                |                      |                                     |
|----------------|----------------------|-------------------------------------|
| <b>Remarks</b> | <input type="text"/> | <input type="button" value="Save"/> |
|----------------|----------------------|-------------------------------------|

## Janice Lee (LKKAUTO)

---

**From:** Janice Lee (LKKAUTO)  
**Sent:** Friday, January 19, 2018 12:49 PM  
**To:** 'Claim Workflow System'  
**Cc:** CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG;  
LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR; assignments  
**Subject:** RE: SURVEY ASSESSMENT - D18000494MFSH/1

Dear Sir,

Please be informed that we have inspected the vehicle **SLV 6674H** on 17/01/2018.

We are pending for estimate from repairer.

Thank you.

Best Regards,

**Janice Lee (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [janicelee@lkkauto.com](mailto:janicelee@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Thursday, January 18, 2018 4:11 PM  
**To:** 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>  
**Cc:** CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>  
**Subject:** RE: SURVEY ASSESSMENT - D18000494MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]  
**Sent:** Thursday, 18 January 2018 3:47 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** [CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG](mailto:CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG); [LURENEJAW@MSFIRSTCAPITAL.COM.SG](mailto:LURENEJAW@MSFIRSTCAPITAL.COM.SG)  
**Subject:** PRI: SURVEY ASSESSMENT - D18000494MFSH/1

Dear Sir/Mdm,

**Janice Lee (LKKAUTO)**

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Thursday, January 18, 2018 4:11 PM  
**To:** 'Claim Workflow System'; assignments  
**Cc:** CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG;  
LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D18000494MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Claim Workflow System [mailto:[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)]  
**Sent:** Thursday, 18 January 2018 3:47 PM  
**To:** ASSIGNMENTS@LKKAUTO.COM  
**Cc:** CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG  
**Subject:** PRI: SURVEY ASSESSMENT - D18000494MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,  
Admin Team  
Claim Workflow System  
Motor Claims Department  
First Capital Insurance Limited  
Tel : 6507 3848  
Fax : 6507 3849

**PS: This is a system generated mail. Please do not reply to this mail.**

## Enquire PARF/COE Rebate for Registered Vehicle

|                                |                                         |
|--------------------------------|-----------------------------------------|
| Vehicle Owner Particulars      |                                         |
| Owner ID Type:                 | Singapore NRIC                          |
| Owner ID:                      | 3093E                                   |
| Vehicle Details                |                                         |
| Vehicle No.:                   | SLV6674H                                |
| Vehicle to be Exported:        | No                                      |
| Intended De-registration Date: | 17 Jan 2018                             |
| Vehicle Make:                  | HONDA                                   |
| Vehicle Model:                 | CITY 1.5 SV CVT                         |
| Primary Colour:                | Grey                                    |
| Manufacturing Year:            | 2017                                    |
| Engine No.:                    | L15Z15204879                            |
| Chassis No.:                   | MRHGM6660JT000280                       |
| Maximum Power Output:          | 88.0 kW (118 bhp)                       |
| Open Market Value:             | \$17,683.00                             |
| Original Registration Date:    | 09 Jan 2018                             |
| First Registration Date:       | 09 Jan 2018                             |
| Transfer Count:                | 0                                       |
| Actual ARF Paid:               | \$17,683.00                             |
| Intended PARF Rebate Details   |                                         |
| PARF Eligibility:              | Yes                                     |
| PARF Eligibility Expiry Date:  | 08 Jan 2028                             |
| PARF Rebate Amount:            | \$13,262.00                             |
| Intended COE Rebate Details    |                                         |
| COE Expiry Date:               | 08 Jan 2028                             |
| COE Category:                  | A - Car up to 1600cc & 97kW<br>(130bhp) |
| COE Period(Years):             | 10                                      |
| QP Paid:                       | \$42,902.00                             |
| COE Rebate Amount:             | \$42,798.00                             |
| <b>Total Rebate Amount:</b>    | <b>\$56,060.00</b>                      |

The information contained herein is correct as at 17 Jan 2018

OK

Date of Accident : 17/01/2018 Accident Time: 14.34pm (24-HR-Format)  
 Accident Place : Along AYE toward PIE  
 Vehicle. No. (Car Plate No.) : SLV6674H Make/Model: \_\_\_\_\_  
 Insurance Company : TOKIO Marine Policy No: \_\_\_\_\_  
 Owner or Company Name /IC No. : Zulkiflee Bin Ahmad /S1643093E  
 Owner or Company Contact No. : \_\_\_\_\_ Owner's Hp \_\_\_\_\_ Company Tel \_\_\_\_\_  
 DRIVER'S Name / IC No. : \_\_\_\_\_  
 DRIVER'S Date Of Birth : \_\_\_\_\_ DRIVER'S License Pass Date \_\_\_\_\_  
 Relationship of Owner & Driver : Spouse \ Parents \ Children \ Sibling \ Employee \ Others: owner  
 DRIVER'S Address : \_\_\_\_\_  
 DRIVER'S Contact No./ Alt No. : 1) \_\_\_\_\_ 2) \_\_\_\_\_  
 DRIVER'S Occupation : INDOOR \ OUTDOOR (e.g. working inside or outside office)  
 Email Address : \_\_\_\_\_  
 Weather & Road Surface : CLEAR & DRY \ RAINING & WET \ AFTER RAIN & WET  
 Reporting Type : Reporting Only \ Claim Other Party \ Claim Own Insurance  
 Number of Passengers (Including Driver): 1 passenger  
 Was there any video Captured by car camera YES \ NO  
 Exact purpose for which vehicle was being used at the time of accident: Private use \ Work purpose  
 Any Injury (If YES, Pls state): yes

**Other Party Driver's Particular (if any)**

|                                         |                                |
|-----------------------------------------|--------------------------------|
| Vehicle. No: <u>SH 67159A (1st car)</u> | Vehicle. No: <u>SS F 7406S</u> |
| Vehicle Make/Model: _____               | Vehicle Make/Model: _____      |
| Name Driver: _____                      | Name Driver: _____             |
| IC No. Driver/Contact: _____            | IC No. Driver/Contact: _____   |

**\* NEW - Passenger's name & gender:**

Rohana Binti. Mohamed salleh (F)

# SKETCH PLAN

A - SLV6674H  
B - SHC71594  
C - SSF74063

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

on 17/01/18 at 14.34hr, I was driving my vehicle (A) along AYE towards PIE. In front of the vehicle stop a fellow suit, suddenly a taxi hit on my rear portion. There were 3 cars involved in an accident

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# **FASTECH AUTO PTE LTD**

VEHICLE NO: SLV6674H

Qty Particular

Amount S\$

## List Item:

|       |                                     |                         |    |        |     |
|-------|-------------------------------------|-------------------------|----|--------|-----|
| 1 PCS | BOOTLID                             | Bent/3uc 655.20         | \$ | 841.20 | ✓   |
| 1 PCS | BOOTLID INNER LOCK                  | 7w1                     | \$ | 195.30 | ✓   |
| 1 PCS | BOOTLID LOCK STRIKER                | 11                      | \$ | 66.50  | X   |
| 1 PCS | BOOTLID 'H' LOGO                    | nu                      | \$ | 42.00  | ✓   |
| 1 PCS | BOOTLID 'I-VTEC' EMBLEM             | nu                      | \$ | 62.00  | ✓   |
| 1 PCS | BOOTLID 'CITY' EMBLEM               | nu                      | \$ | 48.00  | ✓   |
| 1 PCS | BOOTLID OUTER CHROME MOULDING       | nu 184.20               | \$ | 325.00 | ✓   |
| 2 PCS | BOOTLID REFLECTORS @\$333           | 11                      | \$ | 666.00 | X   |
| 1 PCS | BOOTLID WEATHERSTRIP                | 7w1 144.20              | \$ | 197.20 | ✓   |
| 1 PCS | BOOTLID INNER TRIM                  | 11                      | \$ | 288.30 | X   |
| 1 SET | BOOTLID INNER TRIM CLIPS            | 11                      | \$ | 50.00  | X   |
| 1 PCS | REAR BUMPER                         | DO/9c 463.70            | \$ | 642.30 | ✓   |
| 1 PCS | REAR BUMPER LOWER CENTRE GARNISH    | 7w1                     | \$ | 185.40 | ✓   |
| 2 PCS | REAR BUMPER SIDE RETAINERS @\$35.20 | Bent                    | \$ | 70.40  | ✓   |
| 1 SET | REAR BUMPER CLIPS                   | nu                      | \$ | 39.00  | ✓   |
| 4 PCS | REAR BUMPER PARKING SENSORS @\$188  | shh/ 376                | \$ | 752.00 | 29c |
| 2 PCS | REAR BUMPER SIDE GARNISH @\$65      | ols 1w1                 | \$ | 130.00 | 1pc |
| 2 PCS | REAR BUMPER REFLECTORS @\$60        | ols 1w1                 | \$ | 120.00 | 1pc |
| 2 PCS | TAILLAMPS @\$388                    | one 285.30 x 2 = 570.60 | \$ | 776.00 | ✓   |
| 1 PCS | REAR END PANEL                      | 3.015.00                | \$ | 605.00 | ✓   |
| 1 PCS | REAR END PANEL TOP GARNISH          | 7w1 182.50              | \$ | 320.00 | ✓   |
| 1 PCS | REAR END PANEL OUTER LOCK SENSOR    | one                     | \$ | 190.00 | ✓   |
| 1 PCS | REAR FLOOR PANEL                    | nu                      | \$ | 985.00 | X   |
| 1 PCS | REAR FLOOR PANEL TOP BOARD          | 7w1 295.20              | \$ | 480.00 | ✓   |
| 2 PCS | REAR FENDER INNER TRIMS @\$305      | 11                      | \$ | 610.00 | X   |
| 1 PCS | REAR EXHAUST                        | Bent/nu 433.20          | \$ | 588.20 | ✓   |
| 2 PCS | REAR EXHAUST MOUNTINGS @\$35        | nu                      | \$ | 70.00  | ✓   |

List Item Total:

\$ 9,344.80

4928.9  
3943.2

## Special Nett Item:

|       |                            |    |    |        |     |
|-------|----------------------------|----|----|--------|-----|
| 1 PCS | BOOTLID TOP SPOILER        | 11 | \$ | 680.00 | X   |
| 1 PCS | REAR END PANEL SEALANT     | nu | \$ | 50.00  | ✓   |
| 1 PCS | REAR REVERSE CAMERA        | 11 | \$ | 380.00 | X   |
| 1 SET | REAR FLOOR PANEL INSULATOR | nu | \$ | 150.00 | 130 |

Special Nett Total:

\$ 1,260.00

## Labour Charge:

|                                               |    |        |    |
|-----------------------------------------------|----|--------|----|
| TO CHECK WIRING                               | \$ | 80.00  | 30 |
| TO TRANSFER BOOTLID MECHANISM                 | \$ | 80.00  | 60 |
| TO DISMANTLE & REPLACE REVERSE SENSOR         | \$ | 80.00  | 50 |
| TO DISMANTLE & REPLACE REAR EXHAUST           | \$ | 80.00  | 60 |
| TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTERY | \$ | 120.00 | 80 |
| TO SPRAY RUST PROOFING                        | \$ | 120.00 | 80 |
| TO DISMANTLE & REFIX PETROL TANK              | \$ | 100.00 | X  |

11

30  
60  
50  
60  
80  
80  
X

Not Authorized  
Mark  
1/5 #5500/  
5 day.

LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS  
TO PUTTY & SPRAY PAINTING  
Labour Charge Total:

\$ 1,500.00 /200  
\$ 1,500.00 /200  
\$ 3,660.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL

\$ 14,264.80

LKR Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

**Acknowledged by Repairer**

Signature:

Date:



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                                                                      |                                                                                           |                       |                            |                                                                                     |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------|-----------------------|----------------------------|-------------------------------------------------------------------------------------|
| FIRST CAPITAL INSURANCE LTD                                                                                                                                                            |                                                                                           |                       | Ref : CS/FCI18001053/Urbn2 |                                                                                     |
| 36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877                                                                                                                                  |                                                                                           |                       | Date : 31-01-2018          |  |
|                                                                                                                                                                                        |                                                                                           |                       | Code : FCI2                |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                                                                      |                                                                                           |                       |                            |                                                                                     |
| Insured Veh.                                                                                                                                                                           | SHC 7159U                                                                                 | Veh. Inspected        | SLV 6674H                  |                                                                                     |
| Policy No.                                                                                                                                                                             | D-18088937MFSH                                                                            | Coverage (\$)         | 0.00                       |                                                                                     |
| Claim No.                                                                                                                                                                              | D18000494MFSH                                                                             | Excess (\$)           | 0.00                       |                                                                                     |
| Assign From                                                                                                                                                                            | LURENE                                                                                    | Assign Date           | 18/01/2018                 |                                                                                     |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                                                                          |                                                                                           |                       |                            |                                                                                     |
| Make & Model                                                                                                                                                                           | HONDA CITY (A)                                                                            | c.c                   | 1497                       |                                                                                     |
| Engine No.                                                                                                                                                                             | HIDDEN                                                                                    | Year of Reg.          | 2018                       |                                                                                     |
| Chassis No.                                                                                                                                                                            | MRHGM6660JT000280                                                                         | Colour                | GREY                       |                                                                                     |
| Odometer                                                                                                                                                                               | 185                                                                                       | Steering              | IN ORDER                   |                                                                                     |
| Brakes                                                                                                                                                                                 | IN ORDER                                                                                  | Modification          | SPORTS RIM                 |                                                                                     |
| General                                                                                                                                                                                | GOOD                                                                                      |                       |                            |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                                                                          |                                                                                           |                       |                            |                                                                                     |
|                                                                                                                                                                                        | Size                                                                                      | Make                  | Balance                    |                                                                                     |
| R/H Front Tyre                                                                                                                                                                         | 185/55 R16                                                                                | BRIDGESTONE           | 9 mm                       |                                                                                     |
| L/H Front Tyre                                                                                                                                                                         | 185/55 R16                                                                                | BRIDGESTONE           | 9 mm                       |                                                                                     |
| R/H Rear Tyre                                                                                                                                                                          | 185/55 R16                                                                                | BRIDGESTONE           | 9 mm                       |                                                                                     |
| L/H Rear Tyre                                                                                                                                                                          | 185/55 R16                                                                                | BRIDGESTONE           | 9 mm                       |                                                                                     |
| <b>4. Description of Damages</b>                                                                                                                                                       |                                                                                           |                       |                            |                                                                                     |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br>DAMAGES SEE DETAILS.                                                                                                             |                                                                                           |                       |                            |                                                                                     |
| <b>5. General Information</b>                                                                                                                                                          |                                                                                           |                       |                            |                                                                                     |
| Accident Date                                                                                                                                                                          | 17/01/2018                                                                                | Inspection Date       | 18/01/2018                 |                                                                                     |
| Survey held at                                                                                                                                                                         | FASTECH AUTO PTE LTD<br>1 KAKI BUKIT AVENUE 6<br>#01-46/48/50 AUTOBAY<br>SINGAPORE 417883 |                       |                            |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                                                                     |                                                                                           |                       |                            |                                                                                     |
| A) DAMAGES CONSISTENT TO ACCIDENT REPORT.<br>B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                           |                       |                            |                                                                                     |
| <b>5b. Estimate Days of Repair</b>                                                                                                                                                     |                                                                                           |                       |                            |                                                                                     |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                                                                    |                                                                                           | <b>5 Working Days</b> |                            |                                                                                     |



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 6674H

| Qty                         | Description of Parts                  | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------|---------------------------------------|----------------------|---------------------------|-------------------|
| <b>REPLACEMENT OF PARTS</b> |                                       |                      |                           |                   |
| 1                           | BOOTLID                               | BENT / BUCKLED       | 841.20                    | 655.20            |
| 1                           | BOOTLID INNER LOCK                    | TWISTED              | 195.30                    | 195.30            |
| 1                           | BOOTLID LOCK STRIKER                  | NOT NECESSARY        | 66.50                     | -                 |
| 1                           | BOOTLID "H" LOGO                      | NECESSARY            | 42.00                     | 42.00             |
| 1                           | BOOTLID "I-VTEC" EMBLEM               | NECESSARY            | 62.00                     | 62.00             |
| 1                           | BOOTLID "CITY" EMBLEM                 | NECESSARY            | 48.00                     | 48.00             |
| 1                           | BOOTLID OUTER CHROME MOULDING         | NECESSARY            | 325.00                    | 184.20            |
| 2                           | BOOTLID REFLECTORS @\$333.00          | NOT NECESSARY        | 666.00                    | -                 |
| 1                           | BOOTLID WEATHERSTRIP                  | TWISTED              | 197.20                    | 144.20            |
| 1                           | BOOTLID INNER TRIM                    | NOT NECESSARY        | 288.30                    | -                 |
| 1                           | SET BOOTLID INNER TRIM CLIPS          | NOT NECESSARY        | 50.00                     | -                 |
| 1                           | REAR BUMPER                           | DENTED / DEFORMED    | 642.30                    | 463.70            |
| 1                           | REAR BUMPER LOWER CENTRE GARNISH      | TORN                 | 185.40                    | 185.40            |
| 2                           | REAR BUMPER SIDE RETAINERS @\$35.20   | BENT                 | 70.40                     | 70.40             |
| 1                           | SET REAR BUMPER CLIPS                 | NECESSARY            | 39.00                     | 39.00             |
| 4                           | REAR BUMPER PARKING SENSORS @\$188.00 | SHORTED (2 PCS ONLY) | 752.00                    | 376.00            |
| 2                           | REAR BUMPER SIDE GARNISH @\$65.00     | O/S TWISTED          | 130.00                    | 65.00             |
| 2                           | REAR BUMPER REFLECTORS @\$60.00       | O/S CRACKED          | 120.00                    | 52.00             |
| 2                           | TAILLAMPS @\$388.00                   | CRACKED              | 776.00                    | 570.60            |
| 1                           | REAR END PANEL                        | BADLY DENTED         | 605.00                    | 605.00            |
| 1                           | REAR END PANEL TOP GARNISH            | TWISTED              | 320.00                    | 182.50            |
| 1                           | REAR END PANEL OUTER LOCK SENSOR      | CRACKED              | 190.00                    | 190.00            |
| 1                           | REAR FLOOR PANEL                      | TO REPAIR SEE LABOUR | 985.00                    | -                 |
| 1                           | REAR FLOOR PANEL TOP BOARD            | TORN                 | 480.00                    | 295.20            |
| 2                           | REAR FENDER INNER TRIMS @\$305.00     | NOT NECESSARY        | 610.00                    | -                 |
| 1                           | REAR EXHAUST                          | BENT / TWISTED       | 588.20                    | 433.20            |
| 2                           | REAR EXHAUST MOUNTINGS @\$35.00       | NECESSARY            | 70.00                     | 70.00             |

Report Ref No. CS/FC118001053/Urbn2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty                                                                         | Description of Parts                                                                                        | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------|---------------|---------------------------|-------------------|
|                                                                             | LESS 20% DISCOUNT                                                                                           |               | -                         | -985.78           |
|                                                                             |                                                                                                             |               | 9,344.80                  | 3,943.12          |
|                                                                             | <b>SPECIAL NETT ITEMS</b>                                                                                   |               |                           |                   |
| 1                                                                           | BOOTLID TOP SPOILER (SN)                                                                                    | NOT NECESSARY | 680.00                    | -                 |
| 1                                                                           | REAR END PANEL SEALANT (SN)                                                                                 | NECESSARY     | 50.00                     | 50.00             |
| 1                                                                           | REAR REVERSE CAMERA (SN)                                                                                    | NOT NECESSARY | 380.00                    | -                 |
| 1                                                                           | SET REAR FLOOR PANEL INSULATOR (SN)                                                                         | NECESSARY     | 150.00                    | 130.00            |
|                                                                             |                                                                                                             |               | 1,260.00                  | 180.00            |
|                                                                             | <b>LABOUR</b>                                                                                               |               |                           |                   |
|                                                                             | TO CHECK WIRING.                                                                                            |               | 80.00                     | 30.00             |
|                                                                             | TO TRANSFER BOOTLID MECHANISM.                                                                              |               | 80.00                     | 60.00             |
|                                                                             | TO DISMANTLE & REPLACE REVERSE SENSOR.                                                                      |               | 80.00                     | 50.00             |
|                                                                             | TO DISMANTLE & REPLACE REAR EXHAUST.                                                                        |               | 80.00                     | 60.00             |
|                                                                             | TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTERY.                                                               |               | 120.00                    | 80.00             |
|                                                                             | TO SPRAY RUST PROOFING.                                                                                     |               | 120.00                    | 80.00             |
|                                                                             | TO DISMANTLE & REFIX PETROL TANK.                                                                           | NOT NECESSARY | 100.00                    | -                 |
|                                                                             | LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF REAR FLOOR PANEL. |               | 1,500.00                  | 1,200.00          |
|                                                                             | TO PUTTY & SPRAY PAINTING.                                                                                  |               | 1,500.00                  | 1,200.00          |
|                                                                             |                                                                                                             |               | 3,660.00                  | 2,760.00          |
| <b>GRAND TOTAL</b>                                                          |                                                                                                             |               | <b>14,264.80</b>          | <b>6,883.12</b>   |
| <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b> |                                                                                                             |               |                           | <b>5,500.00</b>   |

Report Ref No. CS/FCI18001053/Urbn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.