

REF CS3/AIG18001063/Tld3²

DAR & days

Mstr/min.

ASSIGNMENT (Office)

From Person

Chin Lee Ying

AIG

Task Date 17/01/2018 @ 3.49pm

Estimated Cost

Bill

OD (TP) WS / TP RES / OD RES / EVA / ENV / MV / CS

To Inspect Vehicle No.

FBA 6184J

Insured

SDR 8823Y

at Workshop no.

Chek Kong Motor

Tel

6769 8793

of Block 1, 387B Woodlands Rd, Yew Tee Ind.

Policy No.

210040604#

Claim No.

1568311898SG

Sum Insured

Excess

Make of Vehi

(Client's Record)

DOL 11/01/2018

18/01/2018

CA / REV / REP. / REV 24 HRS 'wp'

R.O.P. Estimated

Date Time 4.08pm @ 17/1/18

Person Contacted

Mr. Lionel

Vehicle OUT

Date Time Action/Instructions (X) Estimate

FBA 6184J-X

SDR 8823Y-X

Tanjah

ALG

ASSIGNMENT

06

Date 18/01/2018

FBA6184J

Estimated Cost:

OD TP WS TP RES / CO RES / EVA / INV / MV

To inspect vehicle No: FBA6184J
at Workshop No: Chek Kong Motor
Blk 1, 387B Woodlands Rd, Yew Teo Ind. Est.

Insured:

Policy No:

Claims No:


Sum Insured: Excess:

Client's Record: Mr. Lionel @ 67698793

Make of Veh:

Policy Condition:

Remark: The veh had commenced its repair at the time of inspection.



Ball or Market value:

DAC Accident Report: Consistent? Yes or No

GIA: PP: Seen: Consistent? Yes or No

Est. Repairs: 5 days Res: Yes or No

Lim Sum: 100k B Val: Yes or No

QA / REV / REP / 24 HRS

Date: Person Contacted:

Vehicle IN / OUT

Type: M/Gar/M/Bus/Truck/Tram/Tractor/Trailer/Truck/Tractor

Make:

Color:

St. Parking:

Eng No:

Chassis:

Gen/Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: M / S Rim / STD A Rim or

Tyre Size:

BS / DUN / EXNOVA / GY / RS / LIZA / MID / OHTSU / PIR / SUMI

TOYO / YOKO or

Front:

Rear:

LBal:

D.O.A:

Survey held at:

Des of Damages:

The U/C / Chassis frame / Body Structure affected due to collision

Date: Time: Action: Instruction:

30/4 w/s No GIA
Submit DAR report.

RECEIVED 30 APR 2018

Cost/Time For Fault:

☐ Prel. Report
☐ Final Report

Days Of Repair: 5

Resurvey No. of Trip:

Cost/Time For Return of:

Add Fee:

☐ Site Visit
☐ Estimate
☐ Repair
☐ Rep. & Ins.

Site Visit

Estimate

Repair

Rep. & Ins.

Survey Fee:

Transport:

Lab. Fee:

Other:

Other:

Other:

Request for Report:

DAR

Cost/Time For Report:



- FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SDR8823Y AND FBA6184J ON 11/01/2018

From: Chin, Lee-Ying
To: 'assignments', Admin A
Cc: Fong, Andy-SY
Sent: 17/1/2018 3:49:28 PM
Attachments:  FaxB098.tif

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947 | Fax +(65) 6835 7416
Lee-Ying.Chin@aig.com | www.aig.com.sg

From: Mail office [mailto:mail@gohjpwong.com]

Sent: Wednesday, January 17, 2018 2:47 PM

To: Abu Kassim, Noor Mariesa

Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Fan, Winnie-LW; Chin, Lee-Ying; Lim, Sheng Yang; Md Ishak, Mohd Imran; Chan, Yoke Shi; Supramaniam, Darshene

Subject: Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SDR8823Y AND FBA6184J ON 11/01/2018

Dear Sir/Mdm

Kindly proceed to conduct the pre-repair inspection forthwith and let us know once the pre-repair inspections has been conducted, failing which we shall assume that the pre-repair inspection is conducted within the next 2 working days. Our client's motorcycle is now at the following location:

Chek Kong Motor Pte Ltd
Block 1, 387B Woodlands Road, Yew Tee Industrial Estate Singapore 677948
Tel: 6769 8793 (Mr Lionel)

Lee Wee Ka
for and on behalf of Goh Teck Wee
GOH JP & WONG LLC
Advocates & Solicitors
Commissioner for Oaths

133 New Bridge Road #16-09
Chinatown Point
Singapore 059413
Tel : 6538 5869
Fax: 6538 4898

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 5 pm and we are closed on Saturday, Sundays and Public Holidays. UEN/GST Regn No: 201406078M

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender.

You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

**GOH JP & WONG LLC**advocates & solicitors
commissioner for oaths

GOH TECK WEE

WONG TZE BOY

WONG FUNG KWAI

SOON WEI MUN

133 New Bridge Road #16-09 Chinatown Point Singapore 059413
Tel: 6538 5868 Fax: 6538 4898 (Not for service of Court documents) Email: mail@gohjpwong.com
Goh JP & Wong LLC is a law corporation with limited liability. GST/UTN: 201406078M

YOUR REF: GTW.ACC.1007.10.wk
OUR REF: GTW.ACC.1007.10.wk
WHEN REPLYING, PLEASE QUOTE OUR REFERENCE NO
DATE: 17 JAN 2018

Yu Yung Tek
20 Begonia Walk
Singapore 805808

Dear Sirs

NOTIFICATION OF ACCIDENT
SUBJECT MATTER: TRAFFIC ACCIDENT INVOLVING FBA 6184J & SDR 8823Y ON 11.1.2018 ALONG CTE

We act for Wang Keng Chee in the above matter.

We are instructed to notify you of the above accident on 11th January 2018 at about 06:10 hrs along CTE involving our client's motorcycle FBA 6184J and motorcar SDR 8823Y driven by you at the material time. A copy of the traffic police report filed is enclosed.

As a result of the accident, our client's motorcycle FBA 6184J has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days (excluding Saturdays, Sundays and Public Holidays) of your receipt of this notice whether you or your insurer would like to conduct a pre-repair inspection of the vehicle or whether you or your insurer waive the pre-repair inspection. If we do not receive any reply from you within the stipulated timeline our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully

Goh Teck Wee

Enc.

Cc **AIG Asia Pacific Insurance Pte Ltd**
Fax No. 6935 7416
Attention: Motor Claims Department

Cc **Chek Kong Motor Pte Ltd**
Fax No. 6769 7367
Please do not proceed with repairs until further notice.

Enquire Transfer Fee

Vehicle Details

Vehicle No. :	FBA6184J
Vehicle Type :	P00 - Passenger Motorcycle/Autocycle/Moped
Vehicle Attachment 1 :	No Attachment
Vehicle Scheme :	Normal
Vehicle Make :	HONDA
Vehicle Model :	WAVE 125R A
Chassis No. :	NF125MP0072486
Propellant :	Petrol
Engine No. :	NF125MPE0072486
Engine Capacity :	125 cc
Maximum Power Output :	-
Maximum Laden Weight :	-
Unladen Weight :	96 kg
Year Of Manufacture :	2006
Original Registration Date :	26 Jun 2006
Lifespan Expiry Date :	-
COE Category :	D - Motorcycle
PQP Paid :	\$3,226.00
COE Expiry Date :	25 Jun 2021
Road Tax Expiry Date :	25 Jun 2018
Inspection Due Date :	25 Jun 2018
Intended Transfer Date :	30 Apr 2018
CO2 Emission :	-
CO Emission :	-
HC Emission :	-
NOx Emission :	-
PM Emission :	-

The current road tax expiry is 25 Jun 2018. You may renew the road tax from 26 Mar 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 25 Jun 2018, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable (From 26 Jun 2018 to 25 Dec 2018)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	42.00	-	42.00
Total Amount Payable :			67.00

Amount Payable (From 26 Jun 2018 to 25 Jun 2019)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7756C
Vehicle Details	
Vehicle No.:	FBA6184J
Vehicle to be Exported:	No
Intended De-registration Date:	30 Apr 2018
Vehicle Make:	HONDA
Vehicle Model:	WAVE 125R A
Primary Colour:	Red
Manufacturing Year:	2006
Engine No.:	NF125MPE0072486
Chassis No.:	NF125MP0072486
Maximum Power Output:	-
Open Market Value:	\$1,537.00
Original Registration Date:	26 Jun 2006
First Registration Date:	26 Jun 2006
Transfer Count:	1
Actual ARF Paid:	\$231.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	25 Jun 2021
COE Category:	D - Motorcycle
COE Period(Years):	5
PQP Paid:	\$3,226.00
COE Rebate Amount:	\$2,034.00
Total Rebate Amount:	\$2,034.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 30 Apr 2018

OK

(01) Bent (02) Dented (03) Distorted (04) Cracked (05) Cut (06) Scratched
(07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary
(12) Missing (13) Torn (14) Unconfirmed (15) Not Working

1. Replace (✓) 2. Repair (X) 3. Check (?)
4. Not Consistent (NC)

May 2009

Vehicle No: FBA 6184.T

[illegible]

Assessor: _____

ORIGINAL COPY

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Jan 2018 Edit Reg		17 Jan 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	-	Co. Reg. No.:	-
Main Claimant:	-		
Vehicle Reg. No.:	FBA6184J	Date of Loss:	11/01/2018 00:00 - :59 [138 Months and 16 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 1568311898SG	Policy/Cover Note No.:	2100406047 (Comprehensive) Coverage: 19/03/2017 - 18/03/2018
Vehicle Reg. No. (Insured):	SDR8823Y	Policy No. (Claimant):	
		Excess:	
Repairer:	Chek Kong Motor Company (HQ) 387B WOODLANDS ROAD, 677948 Woodlands - Tel: 67698793		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 15/03/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (13/03/2018): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Claim Documents

***FBA6184J (1568311898SG)**
[SDR8823Y]

TP

-

Jan 11 2018 12:00AM

[~]

Chek Kong Motor Company

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View [View in Browser](#) ▼

Assessment Reports				1 per page ▼	✓
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	13/03/18 15:42	Accident Statement From:OD - Reg. No: SDR8823Y, Claimant: YU YUNG TEK		Load HTM	

Photos/Images				3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	30/04/18 12:09	General View		Load JPG	✓
2	30/04/18 12:09	General View		Load JPG	✓
3	30/04/18 12:09	General View		Load JPG	✓
4	30/04/18 12:09	General View		Load JPG	✓
5	30/04/18 12:09	General View		Load JPG	✓
6	30/04/18 12:09	General View		Load JPG	✓
7	30/04/18 12:09	General View		Load JPG	✓
8	30/04/18 12:09	General View		Load JPG	✓
9	30/04/18 12:09	General View		Load JPG	✓
10	30/04/18 12:09	General View		Load JPG	✓
11	30/04/18 12:09	General View		Load JPG	✓
12	30/04/18 12:09	General View		Load JPG	✓
13	30/04/18 12:09	General View		Load JPG	✓
14	30/04/18 12:09	General View		Load JPG	✓
15	30/04/18 12:09	General View		Load JPG	✓
16	30/04/18 12:09	General View		Load JPG	✓
17	30/04/18 12:09	General View		Load JPG	✓
18	30/04/18 12:09	General View		Load JPG	✓
19	30/04/18 12:09	General View		Load JPG	✓
20	30/04/18 12:09	General View		Load JPG	✓
21	30/04/18 12:09	General View		Load JPG	✓
22	30/04/18 12:09	General View		Load JPG	✓
23	30/04/18 12:09	General View		Load JPG	✓
24	30/04/18 12:09	General View		Load JPG	✓
25	30/04/18 12:09	General View		Load JPG	✓
26	30/04/18 12:09	General View		Load JPG	✓
27	30/04/18 12:09	General View		Load JPG	✓
28	30/04/18 12:09	General View		Load JPG	✓
29	30/04/18 12:09	General View		Load JPG	✓
30	30/04/18 12:09	General View		Load JPG	✓
31	30/04/18 12:09	General View		Load JPG	✓

Assessment Reports			1 per page ▼	✓
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
32	30/04/18 12:09	General View	 Load JPG	✓
33	30/04/18 12:09	General View	 Load JPG	✓
34	30/04/18 12:09	General View	 Load JPG	✓
35	30/04/18 12:09	General View	 Load JPG	✓
36	30/04/18 12:09	General View	 Load JPG	✓
37	30/04/18 12:09	General View	 Load JPG	✓
38	30/04/18 12:09	General View	 Load JPG	✓
39	30/04/18 12:09	General View	 Load JPG	✓
40	30/04/18 12:09	General View	 Load JPG	✓
41	30/04/18 12:09	General View	 Load JPG	✓
42	30/04/18 12:09	General View	 Load JPG	✓
43	30/04/18 12:09	General View	 Load JPG	✓
44	30/04/18 12:09	General View	 Load JPG	✓
45	30/04/18 12:09	General View	 Load JPG	✓
46	30/04/18 12:09	General View	 Load JPG	✓
47	30/04/18 12:09	General View	 Load JPG	✓
48	30/04/18 12:09	General View	 Load JPG	✓
49	30/04/18 12:09	General View	 Load JPG	✓
50	30/04/18 12:09	General View	 Load JPG	✓
51	30/04/18 12:09	General View	 Load JPG	✓
52	30/04/18 12:09	General View	 Load JPG	✓

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18001063/T1D3S2

Date: 04/05/2018

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100406047
Claimant Vehicle No :	FBA6184J	Insured Vehicle No :	SDR8823Y
Date of Loss:	11/01/2018	Nature of Claim:	TP
		Claim No:	1568311898SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBA6184J	Engine No:	NF125MPE0072486
Make & Model:	HONDA WAVE 125, 125cc	Chassis No:	NF125MP0072486
Reg. Date:	26/06/2006 (Man. Year: 2006)	Odometer:	17877 km
Colour:	Red		
Engine Capacity:	125 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	70/90R17	Rear Tyre Size:	80/90R17
Front Left Side:	Maxxis 5 mm	Rear Left Side:	Maxxis 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	17/01/2018		
Date Inspected:	18/01/2018	Inspected At:	Chek Kong Motor Company (HQ) 387B WOODLANDS ROAD Singapore 677948
Estimated Period of Repair:	5.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE	Deformed	0.00 F	*- F
2	1		*FRONT FENDER WHEEL GUARD	Damaged	0.00 F	*- F
3	1		*FRONT HEADLAMP	Scratched	0.00 F	*- F
4	1		*FRONT HEADLAMP FAIRING	Cut	0.00 F	*- F
5	1		*FRONT WING MIRROR	Cut	0.00 F	*- F
6	1		*FRONT LH SIGNAL LAMP	Scratched	0.00 F	*- F
7	1		*ERP UNIT	Cut	0.00 F	*- F
8	1		*HANDLE BAR BALANCER LH	Damaged	0.00 F	*- F
9	1		*SIDE FAIRING	Scratched	0.00 F	*- F
10	1		*FAIRING SHIELD	Scratched	0.00 F	*- F
11	1		*FRONT FOOT REST	Damaged	0.00 F	*- F
12	1		*SIDE STAND	Scratched	0.00 F	*- F
13	1		*MAIN STAND	Cut	0.00 F	*- F
14	1		*KICK STAND RUBBER	Missing	0.00 F	*- F
15	1		*REAR FOOT REST	Cut	0.00 F	*- F
16	1		*REAR FENDER WHEEL GUARD	Cut	0.00 F	*- F
17	1		*REAR NUMBER PLATE	Damaged	0.00 F	*- F
18	1		*REAR BOX	Cut	0.00 F	*- F
19	1		*REAR BOX BRACKET	Cut	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)

0.00

0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >