

MOTORIMAGE ENTERPRISES PTE. LTD.

19 LORONG 8, TOA PAYOH

SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0573/2018
DATE : 02-JAN-2018

MSIG INSURANCE (SINGAPORE) PTE LTD

16 RAFFLES QUAY

#24-01 HONG LEONG BUILDING

S(048581)

TEL : 66431335/6827 7880

FAX : 66431349/6827 7809

7313 DAVID

OWNER'S NAME : CHIANG SHEU CHING JOSIE (ZHANG XIJING)
ADDRESS : BLK 510C TAMPINES CENTRAL 7 #11-60

S(523518)
TELEPHONE NO : 96174658 - SHAUN

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : A28883673QMY(COMP)
VEHICLE NO : SFL9959R
MODEL CODE : SJ5DK7C
MODEL/YEAR : FORESTER 2.0I-L AND CVT
ENGINE NO : FB20Y221740
CHASSIS NO : JF1SJ5K25G0068834
MILEAGE : 1 KM
DATE IN : 02/01/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SAYEDINAH ALI**
ACCIDENT DATE : 31/12/2017

Print Date : 16/01/2018

Print Time : 10:19:16

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 119255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO 6ML9959R

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM)		
2	ZZ/001	CONDUCT TP CLAIM LOCATION, PIE TO WARDS TUAS DATE: 31/12/2017 TIME: 1215H		
3	ZZ/002	REPLACE/REFIX BUMPER, END PANEL, TAILGATE	1680.00	✓
4	ZZ/003	RESEAL BUMPER, END PANEL, TAILGATE	1260.00	✓
5	ZZ/004	TO CONDUCT WATER SEEPAGE TEST	100.00	50
6	ZZ/005	TRANSFER (DOOR LID/TAILGATE) MECHANISM	150.00	✓
7	ZZ/006	WHEEL ALIGNMENT	200.00	?
8	ZZ/007	TO CONDUCT (FRONT/REAR) LIGHTING TEST	50.00	30
9	ZZ/008	TO SUPPLY AND INSTALL REVERSE SENSOR-2 EYE	300.00	?
10	ZZ/009	TO SUPPLY AND INSTALL (PER SIDE) TINTED FILM	145.00	✓
11	ZZ/10	SUNDRIES	100.00	50
TOTAL LABOUR CHARGES			3985.00	

MOTORIMAGE ENTERPRISES PTE. LTD.

19 LORONG 8, TOA PAYOH

SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SFL9959R

S/NO PARTS DESCRIPTION		PARTS NUMBER	DAMAGED PARTS & PRICES				REMARKS
			NETT	LIST	S/NETT	S/LIST	
1	R EXH CUTTER RH/LH	OE3/SH	44370FG002	72.00	X		
2	FLOOR PAN R R CP		52129SG0019P	432.00			
3	SKIRT COMPL R	USE SG0009P (SUPP)	52401SG0109P	288.00			
4	BUMPER FACE R	(1PC-DTM USE)	57704SG012	540.00			
5	BRKT SD R	RH	57707SG080	14.40	7		
6	BRKT SD R LH		57707SG090	14.40	7		
7	BEAM COMPL R EU		57711SG0219P	288.00	7		
8	COVER HOOK R		57711SG010NN	12.60	X		
9	PANEL CPL R/G NA		60809SG0109P	1072.80			
10	GLASS R/G	(SUPP)	63019SG000	799.20			
11	RUBBER DAM CLS * 2		63232SG000	7.20			
12	RUBBER R/G		63232SG010	12.60			
13	WATR DR R G		63516SG001	111.60	X		
14	GARNISH AY RG, D		91111SG000	144.00	7		
15	PROTR R GARNISH		91713SG000	21.60	7		
16	PROTECTOR LWR SD		91713SG010	5.40	7		
17	ORNAMENT R		93033SG001	79.20			
18	LETTER MARK FORESTOR R		93079SG000	39.60			
19	LETTER MK R SUB		93079SG030	64.80			
20	CARGO STEP PANEL (RESIN)		E775E8G000	420.00			
SUB TOTAL			4439.40	0.00	0.00	0.00	
LESS DISCOUNT (NETT-20 %)			887.88	0.00	0.00	0.00	
GRAND TOTAL			3551.52	0.00	0.00	0.00	
OVERALL TOTAL			3551.52				

MOTONIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 119255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SFL9959R

		DAMAGED PARTS & PRICES			
S/NO	PARTS DESCRIPTION	PARTS NUMBER			
			NETT	LIST	S/NETT
					S/LIST REMARKS

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 9, TOA PAYOH
SINGAPORE 319255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SF19959R

TOTAL LABOUR CHARGES	3985.00
TOTAL SPARE PARTS CHARGES	3551.52
GRAND TOTAL	7536.52 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Authorized

1.B.1

Resurvey B4 painting

Ex & Fuel

8 days

Pre

Ex: 62564315

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.