

Exceeded 48 hrs LKK / AVEV

COMFORTDELGRO ENGINEERING PTE LTD

Date: 12.01.2018

REPAIR ESTIMATE

Time: 09:23:29

Page: 1

Cheney

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305106036
REGN NO : SHC2954Z
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : SONATA
DATE OF REGN : 31.01.2011
DATE/TIME IN : 11.01.2018 12:25
ACCIDENT DATE : 10.01.2018

JOB / PARTS DESCRIPTION

Cheney

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0101-0001-G	SNTVC COVER ASSY-RR BUMPE	1 L	578.40	20.00	462.72	X repair
0002 04-01-0101-0034-G	SNTVC MOULDING ASSY-RR BP	1	38.00	2.00-	38.00	X repair
0003 04-01-0101-0048-G	SNTVC TAIL LAMP ASSY RH(9	1	344.00	0.20	344.00	—
0004 09-01-9999-0068-A	HYUNDAI REVERSE SENSOR AS	1	135.70	0.02-	135.70	X

SUB-TOTAL : 980.42

JOB NATURE

0000 L	PANEL BEATING
0001 23-502	SPRAYPAINT ON AFFECTED AREA
0002 17-01	CHECK ALL LIGHTING
0003 20-22	REMOVE/REFIX REVERSE SENSOR

~~360.00~~ 100
~~300.00~~ 180
~~60.00~~ 20
~~60.00~~ X

SUB-TOTAL : 780.00


COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305106036
REGN NO : SHC2954Z
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : SONATA
DATE OF REGN : 31.01.2011
DATE/TIME IN : 11.01.2018 12:25
ACCIDENT DATE : 10.01.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 1,760.42


MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

Kalan 16/1/18

A 16/1/18
10.00 hrs.

2 Days

4/5

After Repair photo

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: