

22/03/2002

ASS. REC. BY:

REF: CS/FCI 18601153/RH8<sup>\$2</sup> Special Instruction:

SUNVAYOR:

ASSIGNMENT (Office)

From (Person):

Sithara

of

FCI

Date/Time:

26/01/2018

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

JSB 5231

Insured:

SHC7031D

at Workshop m/s

SG 98 Motor

Tel:

of

4001, Amk Industrial Park 1 #01-21 S (569622)

Policy No:

Claim No:

D18000368 MFSH/1

Sum Insured:

Excess:

Make of Veh:

D.O.A.

10/1/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN / OUT

Date/Time

Action/Instruction ( ) Estimate

lump sum \$700/- (Red: 2001; 74%)

Signature *[Signature]*

REF:


# ASSIGNMENT

4 2017

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: JSB 5231 Yr Regn: 4  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: Yamaha / PZ150 (LS) C.C. 150  
 Colour: RED A/C: Insured / Std / NI / NA  
 Sp. Reading: 27184 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: \_\_\_\_\_  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Order / Jammed / Leaked / Burnt or  
 Brake: Order / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 90-80/17  
 R: 17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or MAXXIS

Front Rear  
 R/Bal. 3 mm R/Bal. 3 mm  
 L/Bal. mm L/Bal. mm  
 D.O.A. 10/01/18 D.O.I. 24/01/18  
 Survey held at SC MOTM  
 Des. of Damages: 0 / Rear / 0 / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 25 OCT 2018

Date/Time, File Pass to?

☐ : Preli. Report  
☒ : Final Report

1) 25/10 Typist  
 Date/Time, File Return to?

2)

Days Of Repair: 2

Resurvey No. of Trip: 1

Survey Fee:

Transportation

\$ = RS. SI

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

TP  
700/-

|     |
|-----|
| 110 |
| 50  |
| 47  |
| 207 |

## Denise Tay (LKKAuto)

---

**From:** Denise Tay (LKKAuto)  
**Sent:** Friday, 26 January 2018 2:05 PM  
**To:** Admin-D (LKKAuto); 'Claim Workflow System'; assignments  
**Cc:** CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG;  
SITHARA@MSFIRSTCAPITAL.COM.SG; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D18000368MFSH/1

Dear Sir/Madam,

Please be informed that we have inspected the vehicle JSB 5231 on 24/01/2018  
We are pending estimate from repairer.

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Wednesday, 17 January 2018 5:50 PM  
**To:** 'Claim Workflow System' <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; SITHARA@MSFIRSTCAPITAL.COM.SG; SUR  
<[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: SURVEY ASSESSMENT - D18000368MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]  
**Sent:** Wednesday, 17 January 2018 3:55 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** [CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG](mailto:CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG); [SITHARA@MSFIRSTCAPITAL.COM.SG](mailto:SITHARA@MSFIRSTCAPITAL.COM.SG)  
**Subject:** PRI: SURVEY ASSESSMENT - D18000368MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

## Denise Tay (LKKAUTO)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Wednesday, 17 January 2018 5:50 PM  
**To:** 'Claim Workflow System'; assignments  
**Cc:** CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG;  
SITHARA@MSFIRSTCAPITAL.COM.SG; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D18000368MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Claim Workflow System [mailto:[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)]  
**Sent:** Wednesday, 17 January 2018 3:55 PM  
**To:** ASSIGNMENTS@LKKAUTO.COM  
**Cc:** CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; SITHARA@MSFIRSTCAPITAL.COM.SG  
**Subject:** PRI: SURVEY ASSESSMENT - D18000368MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,  
Admin Team  
Claim Workflow System  
Motor Claims Department  
First Capital Insurance Limited  
Tel : 6507 3848  
Fax : 6507 3849

**PS: This is a system generated mail. Please do not reply to this mail.**



# SIJIL PEMILIKAN KENDERAAN

JABATAN PENGANGKUTAN JALAN

66RVJDE1

No. Pendaftaran : JSB5231  
No. ID : 841104016987  
Nama Pemunya Sardaftar : CHIAN WEE SIAN  
Alamat : # 02-04 BLOK N JLN SERI SETANGGA TMN SERI SETANGGA  
80250 JOHOR BAHRU JOHOR  
No. Chassis / Enjin : PHYRG3410H0010822 / G3G6E-00-00  
Buatan / Nama Model : YAMAHA / FZ150I(S)  
Saizwayan Enjin : 150  
Bahan Bakar : PETROL  
Status Asal : PEMASANGAN TEMPATAN  
Kelas Kegunaan : MOTOSIKAL  
Jenis Badan / Tahun Dibuat : MOTOSIKAL / 2017  
Tarikh Pendaftaran : 02/04/2017  
B. D. M/B. G. K. / BTM : -  
Syarat Pendaftaran 1 : -  
Syarat Pendaftaran 2 : -  
Syarat Pendaftaran 3 : -

## LESEN KENDERAAN MOTOR

ROAD TRANSPORT ACT 1967 (MOTOR VEHICLES (REGISTRATION AND LICENSING) RULES 1918)

MOTOSIKAL No. SIRE AF 525166  
01 APR 2018  
JSB5231

006976 02042017 JSB5231 RM2.00  
0101011 YASME 01042018 150 SP AA  
JG2grWd  
INS1 : 017017JCF001161  
INS2 :

VEL01001

LESEN IN TIKAH DAN KEKUATAN ADA CAP HESSE PEMERINTAH JABATAN PENGANGKUTAN JALAN

sto REX 00/519



# SINGAPORE POLICE FORCE



T/20180115/2121

1 of 3

Police Station Of Origin:  
Ang Mo Kio South N.P.C  
81 Ang Mo Kio Avenue 3 SINGAPORE  
569929  
Tel No: 1800-4519999

Report No. T/20180115/2121

**REPORT OF A TRAFFIC ACCIDENT**

|                                            |                  |                          |
|--------------------------------------------|------------------|--------------------------|
| Date/Time Report Made:<br>15/01/2018 15:53 | Vide Report No.: | Station Diary No.:<br>96 |
|--------------------------------------------|------------------|--------------------------|

**Informant's Particulars**

|                                                                   |            |                                                        |                             |
|-------------------------------------------------------------------|------------|--------------------------------------------------------|-----------------------------|
| Name of Informant:<br>CHIAH WEE SIAN                              |            | Address:                                               |                             |
| ID Type / ID No.:<br>NRIC NO / G8413354Q                          |            | Contact No.:<br>Home/Office: Mobile: 94896903          |                             |
| Nationality:<br>MALAYSIAN                                         |            | Email:                                                 |                             |
| Sex:<br>Male                                                      | Age:<br>33 | Date of Birth:<br>04/11/1984                           | Type of Informant:<br>Rider |
| Race:<br>Chinese                                                  |            | Language:                                              | Institution / School Name:  |
| Occupation:<br>ELECTRICAL & ELECTRONICS<br>ENGINEERING TECHNICIAN |            | Driving Licence Information:<br>Class: Date of Expiry: |                             |

**General Information of the Accident**

|                                                              |                           |                                    |                                            |                                     |
|--------------------------------------------------------------|---------------------------|------------------------------------|--------------------------------------------|-------------------------------------|
| Type of Accident:                                            | Injury<br>Foreign Vehicle | Drink Drive:<br>No                 | Date/Time of Accident:<br>10/01/2018 23:45 | Type of Location:<br>Y-Junction     |
| Location:<br><br>SOON LEE ROAD                               |                           |                                    |                                            |                                     |
| Weather:<br>Drizzling                                        |                           | Road Surface:<br>Wet               |                                            | Road Speed Limit:                   |
| Traffic Flow:<br>Two Way                                     |                           | Traffic Control:<br>Not Controlled |                                            | Traffic Volume:<br>No Traffic       |
| Type of Collision:<br>Between Moving Vehicles - Head To Side |                           |                                    |                                            | Anyone conveyed by ambulance:<br>No |

**Details of Vehicle Involved**

| Vehicle No. | Type         | Make | Model | Color | Condition        | No of Passenger |
|-------------|--------------|------|-------|-------|------------------|-----------------|
| JSB5231     | Motorcycle   |      |       |       | Slightly Damaged | 0               |
| SHC7031D    | Comfort Taxi |      |       |       | Slightly Damaged | 0               |

**Details of Person Involved**

|                                 |                                |
|---------------------------------|--------------------------------|
| Any Pedestrian Involved: No     |                                |
| No. of Pedestrians Injured: NIL | Use of Pedestrian Crossing: NA |



**SINGAPORE  
POLICE FORCE**



T/20180115/2121

Police Station Of Origin:  
Ang Mo Kio South N.P.C  
81 Ang Mo Kio Avenue 3 SINGAPORE  
569929  
Tel No: 1800-4519999

2 of 3

Report No. T/20180115/2121

**CONTINUATION OF REPORT**

|                                   |                            |                                        |                                         |
|-----------------------------------|----------------------------|----------------------------------------|-----------------------------------------|
| <b>Rider</b>                      |                            |                                        |                                         |
| Name                              | CHIAH WEE SIAN             | ID No.                                 | G8413354Q                               |
| Related Vehicle                   | JSB5231 (Motorcycle)       | Contact No.                            |                                         |
| Hospital/Clinic                   | CENTRAL 24-HR CLINIC GROUP | Class of Driving Licence & Expiry Date | Class: 2B<br>Date of Expiry: 04/11/2020 |
| Date Treatment                    | 11/01/2018                 | Date Discharge                         | NIL                                     |
| No. of Days granted Medical Leave | 04                         | Degree of Injury                       | Slight                                  |
| <b>Driver</b>                     |                            |                                        |                                         |
| Name                              | Tan Thiam Heng             | ID No.                                 | S7043298F                               |
| Related Vehicle                   | NIL                        | Contact No.                            | 96899078                                |
| Hospital/Clinic                   | NIL                        | Class of Driving Licence & Expiry Date | Class: NIL<br>Date of Expiry: NIL       |
| Date Treatment                    | NIL                        | Date Discharge                         | NIL                                     |
| No. of Days granted Medical Leave | NIL                        | Degree of Injury                       | NIL                                     |

**Brief Details.**

On 10/01/2018 at about 2345hrs, I was riding along Soon Lee Road. It is a Y-junction.

I was riding straight when a Comfort Taxi plated SHC7031D turn right suddenly without signaling, therefore resulting me in bumping onto the side of the car and hence falling.

We exchange particulars thereafter.



**SINGAPORE  
POLICE FORCE**



T/20180115/2121

Police Station Of Origin:  
Ang Mo Kio South N.P.C  
81 Ang Mo Kio Avenue 3 SINGAPORE  
569929  
Tel No: 1800-4519999

3 of 3

Report No. T/20180115/2121

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:  
F /  
Sgt 2 TAY HUI KEE, JEANIE

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:  
TP / AEIT /  
SSI 2 SITIMARSITA BINTE BOHARI  
Contact No.: 65476219

Signature Of Informant:

Date/Time:  
15/01/2018 15:53

Classification Of Case:

SN 005

Authentication Stamp  
NP168



Signature:

Singapore Police Force

## Denise Tay (LKKAUTO)

---

**From:** Sg Motor <sgmotor2000@yahoo.com.sg>  
**Sent:** Thursday, 20 September 2018 12:47 PM  
**To:** Rasul (LKKAUTO); Denise Tay (LKKAUTO)  
**Cc:** Sg Motor  
**Subject:** Please finalize bike JSB 5231 \*LKK REF: CS/FCI18001153/Gtd3

Dear Rasul/Denise

Please finalize bike JSB 5231.

Thank You

Regards  
Linda

### **SG 98 Motor Pte Ltd**

Blk 4001 #01-21  
Ang Mo Kio Industrial Park 1  
Singapore 569622  
Tel: 64524898 Fax: 64526898

On Friday, 31 August 2018, 12:51:28 PM GMT+8, Sg Motor <sgmotor2000@yahoo.com.sg> wrote:

Dear Rasul/Denise

Please finalize bike JSB 5231.

Thank You

Regards  
Linda

### **SG 98 Motor Pte Ltd**

Blk 4001 #01-21  
Ang Mo Kio Industrial Park 1  
Singapore 569622  
Tel: 64524898 Fax: 64526898

On Thursday, 26 April 2018, 5:01:23 PM GMT+8, Sg Motor <sgmotor2000@yahoo.com.sg> wrote:

Dear Rasul/Denise

fax on 09/00/18 @ 1530

# SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg\_motor\_enterprise@yahoo.com.sg

Date: 26 January 2018

To : LKK

Attn : Rasul

By Fax: 6256-4315

Tel: 90010068

VEHICLE NO : JSB 5231

Yamaha FZ 150l

ACCIDENT DATE: 10 January 2018

| Description      | Qty   | Quotation \$         |
|------------------|-------|----------------------|
| 1 Handle Bar     | 1     | 195.00 <i>X 2</i>    |
| 2 Brake Lever    | 1     | 85.00 <i>scr</i>     |
| 3 Mirror         | 1     | 90.00 <i>scr</i>     |
| 4 Front Mudguard | 1     | 135.00 <i>repair</i> |
| 5 Front Signal   | 1     | 75.00 <i>scr</i>     |
| 6 Brake Disc     | 1     | 265.00 <i>X 2</i>    |
| 7 Fork Tube      | 1 set | 480.00 <i>X 2</i>    |
| 8 Exhaust Cover  | 1     | 195.00 <i>scr</i>    |
| 9 Footrest RH    | 1     | 75.00 <i>scr</i>     |
| 10 Balancer      | 1     | 95.00 <i>scr</i>     |
| Sub-Total        |       | 1,690.00 <i>540</i>  |
| Less 10%         |       | 169.00 <i>10%</i>    |
| Sub-Total        |       | 1,521.00 <i>486</i>  |

## Nett items

|                                     |                       |
|-------------------------------------|-----------------------|
| 1 Rear box                          | 350.00 <i>150 scr</i> |
| 2 Touch up paint scratches          | 350.00 <i>150</i>     |
| 3 Labour for dismantle & fix up     | 250.00 <i>150</i>     |
| 4 Labour for fork & top up fork oil | 230.00 <i>X 2</i>     |

Sub-Total *Rasul* 1,180.00  
Nett Total *Hp 90010068* 2,701.00

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion. Thank you

SG 98 MOTOR PTE LTD

*2 days*  
*4/5*  
*24/01/18 @ 1550*  
*486*  
*450*  
*900*  
*20%*  
*720*  
*45-700*

Attn: Mr. Rasool  
Deception, pls pursue

# SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg\_motor\_enterprise@yahoo.com.sg

TKP

Rasul

22/01/18

Date: 26 January 2018

To : LKK

Attn: Rasul

By Fax: 6256-4315

Tel: 90010068

VEHICLE NO : JSB 6231

Yamaha FZ 150i

ACCIDENT DATE: 10 January 2018

| Description      | Qty   | Quotation \$  |
|------------------|-------|---------------|
| 1 Handle Bar     | 1     | 195.00 X      |
| 2 Brake Lever    | 1     | 85.00 scd     |
| 3 Mirror         | 1     | 90.00 scd     |
| 4 Front Mudguard | 1     | 135.00 repair |
| 5 Front Signal   | 1     | 75.00 scd     |
| 6 Brake Disc     | 1     | 265.00 X      |
| 7 Fork Tube      | 1 set | 480.00 X      |
| 8 Exhaust Cover  | 1     | 195.00 scd    |
| 9 Footrest RH    | 1     | 75.00 scd     |
| 10 Balancer      | 1     | 95.00 scd     |
| Sub-Total        |       | 1,690.00 540  |
| Less 10%         |       | 169.00 10%    |
| Sub-Total        |       | 1,521.00 486  |

## Nett items

- 1 Rear box
- 2 Touch up paint scratches
- 3 Labour for dismantle & fix up
- 4 Labour for fork & top up fork oil

350.00 150 scd  
350.00 150  
250.00 150  
230.00 X 450

Sub-Total 1,180.00  
Nett Total 2,701.00

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion. Thank you

SG 98 MOTOR PTE LTD

Rasul  
Hp 90010068  
X 2 days  
45  
24/01/18 @ 1550  
486  
450  
900  
202  
720

45-700  
OK Rasul

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                                                                      |                                                                                         |                              |            |                                                                                     |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|------------------------------|------------|-------------------------------------------------------------------------------------|
| FIRST CAPITAL INSURANCE LTD                                                                                                                                                            |                                                                                         | Ref : CS/FCI18001153/R1td3s2 |            |                                                                                     |
| 36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877                                                                                                                                  |                                                                                         | Date : 05-11-2018            |            |  |
|                                                                                                                                                                                        |                                                                                         | Code : FCI2                  |            |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                                                                      |                                                                                         |                              |            |                                                                                     |
| Insured Veh.                                                                                                                                                                           | SHC 7031D                                                                               | Veh. Inspected               | JSB 5231   |                                                                                     |
| Policy No.                                                                                                                                                                             |                                                                                         | Coverage (\$)                | 0.00       |                                                                                     |
| Claim No.                                                                                                                                                                              | D18000368MFSH/1                                                                         | Excess (\$)                  | 0.00       |                                                                                     |
| Assign From                                                                                                                                                                            | SITHARA                                                                                 | Assign Date                  | 25/01/2018 |                                                                                     |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                                                                          |                                                                                         |                              |            |                                                                                     |
| Make & Model                                                                                                                                                                           | YAMAHA / FZ150I (S)                                                                     | c.c                          | 150        |                                                                                     |
| Engine No.                                                                                                                                                                             | HIDDEN                                                                                  | Year of Reg.                 | 2017       |                                                                                     |
| Chassis No.                                                                                                                                                                            | PMYRG3410H0010822                                                                       | Colour                       | RED        |                                                                                     |
| Odometer                                                                                                                                                                               | 27184                                                                                   | Steering                     | IN ORDER   |                                                                                     |
| Brakes                                                                                                                                                                                 | IN ORDER                                                                                | Modification                 | SPORTS RIM |                                                                                     |
| General                                                                                                                                                                                | FAIR                                                                                    |                              |            |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                                                                          |                                                                                         |                              |            |                                                                                     |
|                                                                                                                                                                                        | Size                                                                                    | Make                         | Balance    |                                                                                     |
| R/H Front Tyre                                                                                                                                                                         | 90-80/17                                                                                | MAXXIS                       | 3 mm       |                                                                                     |
| L/H Front Tyre                                                                                                                                                                         |                                                                                         |                              | mm         |                                                                                     |
| R/H Rear Tyre                                                                                                                                                                          | 90-80/17                                                                                | MAXXIS                       | 3 mm       |                                                                                     |
| L/H Rear Tyre                                                                                                                                                                          |                                                                                         |                              | mm         |                                                                                     |
| <b>4. Description of Damages</b>                                                                                                                                                       |                                                                                         |                              |            |                                                                                     |
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND O/S BODY.<br>DAMAGES SEE DETAILS.                                                                                               |                                                                                         |                              |            |                                                                                     |
| <b>5. General Information</b>                                                                                                                                                          |                                                                                         |                              |            |                                                                                     |
| Accident Date                                                                                                                                                                          | 10/01/2018                                                                              | Inspection Date              | 24/01/2018 |                                                                                     |
| Survey held at                                                                                                                                                                         | SG 98 MOTOR PTE LTD<br>BLK 4001 ANG MO KIO INDUSTRIAL PARK 1<br>#01-21 SINGAPORE 569622 |                              |            |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                                                                     |                                                                                         |                              |            |                                                                                     |
| A) DAMAGES CONSISTENT TO ACCIDENT REPORT.<br>B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                         |                              |            |                                                                                     |
| <b>5b. Estimate Days of Repair</b>                                                                                                                                                     |                                                                                         |                              |            |                                                                                     |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                                                                    |                                                                                         | <b>2 Working Days</b>        |            |                                                                                     |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. JSB 5231

| Qty                                                                         | Description of Parts                                                      | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------------------------------------------------------|---------------------------------------------------------------------------|----------------------|---------------------------|-------------------|
| <b>REPLACEMENT OF PARTS</b>                                                 |                                                                           |                      |                           |                   |
| 1                                                                           | HANDLE BAR                                                                | SERVICEABLE          | 195.00                    | -                 |
| 1                                                                           | BRAKE LEVER                                                               | SCRATCHED            | 85.00                     | 85.00             |
| 1                                                                           | MIRROR                                                                    | SCRATCHED            | 90.00                     | 90.00             |
| 1                                                                           | FRONT MUDGUARD                                                            | TO REPAIR SEE LABOUR | 135.00                    | -                 |
| 1                                                                           | FRONT SIGNAL                                                              | SCRATCHED            | 75.00                     | 75.00             |
| 1                                                                           | BRAKE DISC                                                                | SERVICEABLE          | 265.00                    | -                 |
| 1                                                                           | SET FORK TUBE                                                             | SERVICEABLE          | 480.00                    | -                 |
| 1                                                                           | EXHAUST COVER                                                             | SCRATCHED            | 195.00                    | 195.00            |
| 1                                                                           | FOOTREST RH                                                               | SCRATCHED            | 75.00                     | 75.00             |
| 1                                                                           | BALANCER                                                                  | SCRATCHED            | 95.00                     | 95.00             |
|                                                                             | LESS 10% DISCOUNT                                                         |                      | -169.00                   | -61.50            |
|                                                                             |                                                                           |                      | 1,521.00                  | 553.50            |
| <b>SPECIAL NETT ITEMS</b>                                                   |                                                                           |                      |                           |                   |
| 1                                                                           | REAR BOX (SN)                                                             | SCRATCHED            | 350.00                    | 150.00            |
|                                                                             |                                                                           |                      | 350.00                    | 150.00            |
| <b>LABOUR</b>                                                               |                                                                           |                      |                           |                   |
|                                                                             | TOUCH UP PAINT SCRATCHES.                                                 |                      | 350.00                    | 150.00            |
|                                                                             | LABOUR FOR DISMANTLE & FIX UP. INCLUSIVE OF THE REPAIR OF FRONT MUDGUARD. |                      | 250.00                    | 150.00            |
|                                                                             | LABOUR FOR FORK & TOP UP FORK OIL.                                        | NOT NECESSARY        | 230.00                    | -                 |
|                                                                             |                                                                           |                      | 830.00                    | 300.00            |
| <b>GRAND TOTAL</b>                                                          |                                                                           |                      | <b>2,701.00</b>           | <b>1,003.50</b>   |
| <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b> |                                                                           |                      |                           | <b>700.00</b>     |

Report Ref No. CS/FCI18001153/R1td3s2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.