





| EDIT                                                                                | SR NO | REPAIR/REPLACE (LABOUR) | PART NAME                                                                                                                                      | LABOUR R&R | LABOUR REPAIR | PAINT | ACTION (LABOUR) | COMMENT | REMOVE                                                                            |
|-------------------------------------------------------------------------------------|-------|-------------------------|------------------------------------------------------------------------------------------------------------------------------------------------|------------|---------------|-------|-----------------|---------|-----------------------------------------------------------------------------------|
|  | 2     |                         | TOWING.                                                                                                                                        | 55         | 0             | 0     | Reviewing       |         |  |
|  | 3     |                         | TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS, INCLUDING TO KNOCK-OUT, STRAIGHTEN, REPAIR OF THE FRONT RH WHEEL HOUSING, REAR RH DOOR, ETC. | 800        | 0             | 0     | Reviewing       |         |  |
|  | 4     |                         | TO CHECK WIRING. (NPA)                                                                                                                         | 0          | 0             | 0     | Reviewing       |         |  |
|  | 5     |                         | TO REMOVE & REFIT FRONT RH UNDERCARRIAGE ITEMS.                                                                                                | 0          | 0             | 0     | Reviewing       |         |  |
|  | 6     |                         | TO SPRAY PAINTING ON THE AFFECTED AREA.                                                                                                        | 1100       | 0             | 0     | Reviewing       |         |  |

| EDIT | SR NO | QUAN TITY | MATERIAL | SIDE | PART NAME                        | PART NUMBER | REPAIR/REPLACE (PARTS) | CONDITION   | LIST PRICE | DEPL/ BTR% | DISC QUNT% | SALV AGE% | PART PRICE(NET) | ACTION (PARTS) | REMOVE |
|------|-------|-----------|----------|------|----------------------------------|-------------|------------------------|-------------|------------|------------|------------|-----------|-----------------|----------------|--------|
|      |       | 11        | 1        |      | FRONT RH DOOR                    |             |                        | Bent        | 970        |            | 20         |           | 77%             | Reviewing      |        |
|      |       | 12        | 1        |      | FRONT RH DOOR WEATHERSTRIP FRT   |             |                        | Cut         | 45         |            | 20         |           | 36              | Reviewing      |        |
|      |       | 13        | 1        |      | FRONT RH DOOR WEATHERSTRIP TOP   |             |                        | Serviceable | 0          |            | 20         |           | 0               | Reviewing      |        |
|      |       | 14        | 1        |      | FRONT RH DOOR WEATHERSTRIP LWR   |             |                        | Serviceable | 0          |            | 20         |           | 0               | Reviewing      |        |
|      |       | 15        | 1        |      | FRONT RH DOOR WEATHERSTRIP RR    |             |                        | Serviceable | 0          |            | 20         |           | 0               | Reviewing      |        |
|      |       | 16        | 1        |      | FRONT RH DOOR HINGE UPPER        |             |                        | Repair      | 0          |            | 20         |           | 0               | Reviewing      |        |
|      |       | 17        | 1        |      | FRONT RH DOOR HINGE LOWER        |             |                        | Repair      | 0          |            | 20         |           | 0               | Reviewing      |        |
|      |       | 18        | 1        |      | FRONT RH DOOR CHECKER            |             |                        | Serviceable | 0          |            | 20         |           | 0               | Reviewing      |        |
|      |       | 19        | 1        |      | FRONT RH DOOR LOCK               |             |                        | Repair      | 0          |            | 20         |           | 0               | Reviewing      |        |
|      |       | 20        | 1        |      | FRONT RH DOOR POWER WINDOW MOTOR |             |                        | Serviceable | 0          |            | 20         |           | 0               | Reviewing      |        |
|      |       | 21        | 1        |      | REAR RH DOOR                     |             |                        | Repair      | 0          |            | 20         |           | 0               | Reviewing      |        |
|      |       | 22        | 1        |      | RH ROCKER PANEL GARNISH          |             |                        | Denied      | 480        |            | 20         |           | 384             | Reviewing      |        |
|      |       | 23        | 10       |      | RH ROCKER PANEL GARNISH CLIPS    |             |                        | Necessary   | 5          |            | 20         |           | 40              | Reviewing      |        |
|      |       | 24        | 1        |      | REAR RH WHEEL ARCH MOULDING      |             |                        | Repair      | 0          |            | 20         |           | 0               | Reviewing      |        |



| CATEGORY     | POLICY INFORMATION             | ASSESSMENT INFORMATION | CATEGORY                | FNOL INFORMATION                        | POST SURVEY INFORMATION                 |
|--------------|--------------------------------|------------------------|-------------------------|-----------------------------------------|-----------------------------------------|
| Sum Insured  | <input type="text" value="0"/> |                        | License Type            |                                         | <input type="text"/>                    |
| Market Value | <input type="text" value="0"/> |                        | License Issue Date      | <input type="text" value="mm/dd/yyyy"/> | <input type="text" value="mm/dd/yyyy"/> |
|              |                                |                        | License Expiration Date | <input type="text" value="mm/dd/yyyy"/> |                                         |
|              |                                |                        | Address                 | <input type="text"/>                    |                                         |
|              |                                |                        | Address type            | <input type="text"/>                    |                                         |
|              |                                |                        | Gender                  | Unknown                                 | <input type="text"/>                    |
|              |                                |                        | Marital status          | Unknown                                 | <input type="text"/>                    |
|              |                                |                        | Identification #        | S2685108D                               | <input type="text"/>                    |

| CREATED USER | VERSION DATE    | ESTIMATED AMOUNT | APPROVED AMOUNT | STATUS | SHARE            | CLONE            |
|--------------|-----------------|------------------|-----------------|--------|------------------|------------------|
| NG Stacey    | 1/18/18 4:39 PM | 5439             | 5439            | Open   | <div>Share</div> | <div>Clone</div> |

| NAME                                                        | TYPE                          | SUB-TYPE                | AUTHOR                               | DATE<br>UPLOADED    |
|-------------------------------------------------------------|-------------------------------|-------------------------|--------------------------------------|---------------------|
| TP ESTIMATE - MARKED (REVISED).pdf                          | Reports & Statement           | Others                  | LKK AUTO CONSULTANTS PTE LTD<br>(TP) | June 29, 2018       |
| Immediate Advice with Mandate.pdf                           | Reports & Statement           | Others                  | LKK AUTO CONSULTANTS PTE LTD<br>(TP) | June 29, 2018       |
| LKK Resurvey Photo 1.pdf                                    | Reports & Statement           | Others                  | LKK AUTO CONSULTANTS PTE LTD<br>(TP) | June 29, 2018       |
| LKK Survey Photo.pdf                                        | Reports & Statement           | Others                  | LKK AUTO CONSULTANTS PTE LTD<br>(TP) | June 29, 2018       |
| LKK Resurvey Photo.pdf                                      | Reports & Statement           | Others                  | LKK AUTO CONSULTANTS PTE LTD<br>(TP) | June 29, 2018       |
| GIA SEARCH.pdf                                              | Forms / Claim<br>Documents    | Others                  | LKK AUTO CONSULTANTS PTE LTD<br>(TP) | June 29, 2018       |
| SLQ 2621M.mp4                                               | Evidence                      | Videos                  | LKK AUTO CONSULTANTS PTE LTD<br>(TP) | April 17, 2018      |
| TP ESTIMATE - MARKED.pdf                                    | Forms / Claim<br>Documents    | Estimate /<br>Quotation | LKK AUTO CONSULTANTS PTE LTD<br>(TP) | January 23,<br>2018 |
| Preliminary Advice.pdf                                      | Forms / Claim<br>Documents    | Others                  | LKK AUTO CONSULTANTS PTE LTD<br>(TP) | January 23,<br>2018 |
| SLQ2621M TP GIA.PDF                                         | Forms / Claim<br>Documents    | Claim Form              | PATIL Anol                           | January 18,<br>2018 |
| SJQ1896S INSD GIA.PDF                                       | Forms / Claim<br>Documents    | Claim Form              | PATIL Anol                           | January 18,<br>2018 |
| email received from workshop with TP Estimasia &<br>GIA.msg | Letters and<br>Correspondence | Others                  | PATIL Anol                           | January 18,<br>2018 |