

Taylor

AXA

APPENDIX

From: Date: 18/01/2018

Policy No: SHC4720T Reg: 2014 Sep

Estimated Cost:

Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Other

OD: (P) WS / TP RES / OD RES / EVA / INV / M /

Truck / Trailer

To inspect vehicle No: SHC 4720T

Make: Toyota Prius Hybrid 1798

at: Workshop No: SMRT

Colour: Maroon - AD Insured, Std N / NA

at: Woodlands SMRT Depot

St. Reading: 398267 TP Res Insured, Std N / NA

Insured:

Engine:

Policy No:

CNO:

Claims No:

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering, Inords: (P) Jammed / Leaked / Burnt or

Client's Record:

Brake, Inords: (P) Jammed / Leaked / Burnt or


Make of Veh:

Mod: Nil / SR / STD A / Rim or

Conflicting Reports; To obtain TP video to confirm Liability

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Tyre Size: F: 195/65 R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / ORTSU / PIR / SUM

TOYO / YOKO or

Fallen

Salv or Market value:

Front:

Rear:

IDAO Accident Report: Consistent? : Yes or No

R.Bal:

R.Bal:

GIA PP Seen: Consistent? : Yes or No

L.Bal:

L.Bal:

Est. Repairs: days Res: Yes or No

D.O.A:

D.O.A:

Sum Sur: % 3 val: Yes or No

Survey held at:

SMRT

CA / REV / REP. / 24 HRS Wp

Des of Damages: Fr / Rear / (P) N/S / U/C / Roof top or

o/s

Date: Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision

Date Time Action / Instruction

TP AXA SHD 92732

* Video in folder

TAX 01/18/2010

Date Time File Pass to: ☐ : Preli. Report

Days Of Repair:

☐ : Final Report

Resurvey No. of Trip:

Date Time File Return to:

Sum. Fee

Transport:

Add Fee:

☐

Site Fee: \$

☐

Mane: \$

☐

Tax: \$

☐

Acc: \$

Record Format:

Life Sum: LB: \$

