

INS. CASE OWNER:

Cherini

CC 4 / III18001195 / Uu43

LKK:

IDAC:

Surveyor:

MARCUS

DOI:

19/01/18

Date / Time:

19/01/18

Registered in Merimen:

19/01/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHA 3772K

Claim No.:

MCT18010976

Name of Insured:

CTPL

Policy No.:

Insured Tel No.:

HP:

Make / Model:

HYUNDAI 240

Excess Sec II :SS

D.O.A.:

18/01/18

Place of Accident:

JURONG EAST ST 24 X JURONG CTS

Is driver the owner?

(YES NO)

Nature of Accident:

AVE 1

If NO, Driver Name / Age: V MATHIALAGAN

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L YES / NO)

Insured Liability:

% Final ? Yes / No

STH 6016E



INSRS:

WSP: Spru zee

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STH 6016E - N/A/INC 4027781 - OSA 24/1/18
SHA 3772K - CCR/US 1702306/1/18 OSA 03/2/18
- CCR/US 15020110/1/18 OSA 21/1/18
- CCR/US 1702306/1/18 OSA 21/1/18
- N/A/INC 4027781/1/18 OSA 21/1/18

22/01/18 (THUR THUR)

OI turning right and collide with TP which was driving along main road.

RECEIVED 05 MAR 2018

RECEIVED 03 APR 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

28/3/18

Confirm with:

Christina

Email

Call

Final Liability:

%

100

(

Agreed / Assessed

BOLA S/N No.:

9 (d)

If NO or B 28. Ass. Lia

Repair Cost:

SS

6800.00

Loss of Rental (LOR):

SS

802.50

(

5

days)

x 150 + GST

Loss of Use (LOU):

SS

(5

x

days)

Loss of Income (LOI):

SS

(5

x

days)

LOR only

LOU only

LOR + LOU

LOR + LO

(Tick only one)

GIA/LTA Search

SS

7.45

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

SS

7609.95

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

7609.95

Name 1:

SUPER ZEE MOTOR SERVICE

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

COPY SENT

ASS. REC. BY *MORIS*

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *SM 6016*at Workshop m/s *Super 2ee*

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: *50k.*

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: *4* days Res.: Yes or NoLum Sum: *20* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: *SM 6016E* Yr Regn: *15/8/08*Type: ☒ M. Car / ☐ M. Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /Truck / Trailer or *(A)*Make: *new bent 3300cc 2997*Colour: *silver* A/C: ☐ Insured / ☐ Std / ☐ NI / ☐ NASp. Reading: *176826* T/Radio: ☐ Insured / ☐ Std / ☐ NI / ☐ NA

Eng/No: _____

C/No: *WD. 2211542A236446*Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ Insured / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ Insured / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim orTyre Size: F: *235/55R17*

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or *continental*Front *6* Rear *6*R/Bal. *6* mm R/Bal. *6* mmL/Bal. *6* mm L/Bal. *6* mmD.O.A. *18/1/18* D.O.I. *19/1/18*

Survey held at _____

Des. of Damages: ☐ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or*front 2/5*

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction *LTA 42350**Dep 16k. net 7650**21/1/18 conf. and 2/5 \$ 6800 with Christine.**(Red: \$ 6018.30 / 47%)*Date/Time, File Pass to? ☐ : Preli. Report1) ☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee: _____

Transportation: _____

S + RS. SI

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I.: (\$)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL		Ref : CC4/III18001195/Uus3		
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 19-01-2018		
		Code : III2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 3772K	Veh. Inspected	SJH 6016E	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	19/01/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer		Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	18/01/2018	Inspection Date	19/01/2018	
Survey held at	SUPER-ZEE MOTOR SERVICE BLK 14 DEFU LANE 10 #01-402 SINGAPORE 539195			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1917Z
Vehicle Details	
Vehicle No.:	SJH6016E
Vehicle to be Exported:	No
Intended De-registration Date:	19 Jan 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	S300L
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	27294630977346
Chassis No.:	WDD2211542A236446
Maximum Power Output:	170.0 kW (227 bhp)
Open Market Value:	\$82,934.00
Original Registration Date:	15 Aug 2008
First Registration Date:	15 Aug 2008
Transfer Count:	3
Actual ARF Paid:	\$82,934.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Aug 2018
PARF Rebate Amount:	\$41,467.00
Intended COE Rebate Details	
COE Expiry Date:	14 Aug 2018
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$15,501.00
COE Rebate Amount:	\$883.00
Total Rebate Amount:	\$42,350.00

The information contained herein is correct as at 19 Jan 2018

OK

FREE VALUATION

Let us tell you how much your car can sell for!

No obligations and it's FREE!

How much is my car worth?



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Volkswagen Jetta 1.4A TSI, Beautiful Unit, \$22,800!



Cheapest In The Market! Very
Well Maintained! Inside Out, Low
Deprec, Must View!
Speedo Monitoring! Start!



Browse by Category

Sort by Date Posted

20 results/page

7 vehicles

MERCEDES BENZ S300

Advanced Search

Submit

Make	Model	Price	Deprecation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	MERCEDES BENZ S300	Any	Any	2008	Any	Any	Any	Available



Mercedes-Benz S-Class S300L \$53,800 N.A. 15-Feb-2008 2,997 cc 150,000 km Luxury Available

2nd Owner Only. Price Negotiable. Exporters Welcome. Regular Maintenance Done. Good To Renew 10 Years COE. Front And Rear Face Lifted To New Type LED And Xenon Lights. Airmatic Changed. Brake Pads And...

View Details

Posted: 12-Jan-2018 Tags: 2008 Mercedes-Benz S300L, Mercedes-Benz S300L, Mercedes-Benz S300L, Used Mercedes-Benz



Mercedes-Benz S-Class S300L \$56,800 \$17,600 /yr 04-Dec-2008 2,997 cc - Luxury Available

Low Mileage, 100% Quality Buy, Immediate Delivery! 100% Accident Free! Call For Viewing And Test Drive

Posted: 05-Jan-2018 Tags: 2008 Mercedes-Benz S300L, Mercedes-Benz S300L, Mercedes-Benz S300L, Used Mercedes-Benz



Mercedes-Benz S-Class S300L \$53,800 N.A. 13-Mar-2008 2,997 cc 140,000 km Luxury Available

Minimum PARF Rebate At \$45203 (About \$4k Higher Than Other S300L). Body At \$5k. Total Take Back \$50203! Only \$3557 To Drive For 4 Months. Plus! C&C Agent Unit, Pristine Interior With Sunroof, Low Mileage...

Posted: 06-Jan-2018 Tags: 2008 Mercedes-Benz S300L, Mercedes-Benz S300L, Mercedes-Benz S300L, Used Mercedes-Benz



Mercedes-Benz S-Class S300L \$111,800 \$11,170 /yr 11-Jan-2008 2,997 cc 171,000 km Luxury Available

A C&C Premium Sedan, 5 Yrs COE At \$83800. Sunroof, Sunshade, 18" AMG Rims. New Paintwork. All Wears And Tears Fixed With Own Workshop & Year Engine Gearbox Warranty. Low Mileage, Excellent Condition, ...

Posted: 27-Dec-2017 Tags: 2008 Mercedes-Benz S300L, Mercedes-Benz S300L, Mercedes-Benz S300L, Used Mercedes-Benz

Car Buying


Car Selling

Car Aftermarket

Car Ownership

On The Move

Lifestyle



Mercedes-Benz S-Class S300L \$52,000 \$15,890 /yr 19-Sep-2008 2,997 cc - Luxury Available

About \$25000 Worth Of Wear And Tear Receipts Done In Year 2017 Available. Sunroof Unit. High Buy Back Guaranteed, Meaning Ultra Low Depreciation. \$5000 Drive Away Option Available. Please Call To Arr...

Posted: 12-Dec-2017 Tags: 2008 Mercedes-Benz S300L, Mercedes-Benz S300L, Mercedes-Benz S300L, Used Mercedes-Benz



Mercedes-Benz S-Class S300L \$54,000 \$17,070 /yr 15-Oct-2008 2,997 cc - Luxury Available

Buy With A Peace Of Mind. 100% Quality Buy! STA And VICOM Evaluation Welcome. Immediate Delivery! 100% Accident Free! \$30,000 Parts Replaced. New Gearbox, Radiator, Suspension System, Batteries, Brake...

View Details

Posted: 07-Dec-2017 Tags: 2008 Mercedes-Benz S300L, Mercedes-Benz S300L, Mercedes-Benz S300L, Used Mercedes-Benz



Mercedes-Benz S-Class S300L \$55,800 \$22,550 /yr 09-Sep-2008 2,997 cc 103,123 km Luxury Available

Balloon Scheme Available! Buy With No Worries! No Hidden Cost! Car In Original Condition! Low Mileage! In House Loan Or Bank Loan Available! Low Down Payment.

Tai Hual Automobile

Posted: 03-Dec-2017 Tags: 2008 Mercedes-Benz S300L, Mercedes-Benz S300L, Mercedes-Benz S300L, Used Mercedes-Benz

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Deprecation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

SUPER-ZEE MOTOR SERVICE

BLK 14 DEFU LANE 10 #01-402 SINGAPORE 539195 TEL: 6383 1913 FAX: 6383 9565
EMAIL: superzeemotor@gmail.com

18 Jan 2018

India International Insurance Pte Ltd
#04-05 IOB Building
64 Cecil Street
Singapore 049711
Att: Motor Claims Dept

Our staff will notify the Repairer of the following:
• To resurvey car after spray painting
• To assy damaged part(s) during resurvey
• Third party survey on a "without Prejudice" basis
• No illegal publication(s) is allowed
• Supplementary claims must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer: _____
Signature: _____
Date: _____
Email: motorclaim@iii.com.sg

Not valid
2/5 x 6800/2
4000
18/1/18
Theophilus A. Theophilus

THIRD PARTY CLAIM

OWNER NAME : NG YEW CHEONG
VEHICLE REG NO : SJH 6016 E
DATE OF ACCIDENT : 18 JAN 2018
PLACE OF ACCIDENT : JURONG EAST AVE 1
INVOLVING VEH NO : SHA 3772 K

We append herewith our estimate for repairs of Vehicle No SJH6016E as follows:

Materials Required

1 pc	Front Bumper	1615.32	Dis	SS1,925.00	✓
1 pc	Front Bumper Reinforcement	1219.31	Swf/100	SS1,595.00	✓
1 pc	Front Bumper Sponge	247.11	To 100	SS 258.90	✓
2 pcs	Front Bumper Brackets	58.90	n/s 100	SS 117.80	1pc
2 pcs	Front Bumper Retainers	73.30	n/s 100	SS 146.60	1pc
1 pc	Front Bumper Grille		100	SS 189.00	✓
1 pc	Front Bumper Fog Lamp LH	39.5	100	SS 588.80	✓
2 pcs	Front Bumper Parking Sensors LH	195 x 2 = 390	Swf	SS 565.40	✓
10 pcs	Front Bumper Clips		100	SS 65.00	✓
1 pc	Front Fender LH	1342.66	Swf/100	SS1,587.10	✓
1 pc	Front Fender Inner Shield LH	266.50	To 100	SS 290.30	✓
1 pc	Headlamp LH	2010.15	100	SS2,283.80	✓
1 pc	Headlamp Wiper Cover LH	48.50	100	SS 164.50	✓
1 pc	Washer Tank		100/100	SS 194.40	✓
1 pc	Horn		100	SS 136.70	✓
1 pc	Front Tyre LH		Swf	SS 500.00SN	✓
				SS10,608.30	

8063.25
7258.74

Labour Charges

Towing Charge (with receipt)	SS 150.00	100
To dismantle & replace damaged parts & panelbeating	SS 800.00	550
To putty, apply primer & spraypaint affected portion	SS 1,000.00	600
To apply rustproofing on repaired, replaced panel	SS 180.00	30
To check electrical wiring functions	SS 80.00	20
		SS12,818.30

1300

8528.74

SUPER-ZEE MOTOR SERVICE
Business Registration No. 47959700J



24 Hrs TOWING SERVICE

CASH SALE/WORK ORDER

標準快捷拖車服務 STANDARDISE EXPRESS TOWING SERVICE

BLK 3020 A UBI ROAD 1 #01-34, SINGAPORE 408714
REB: 5152 7000L Email: standardisetow@parific.net.sg

24 hours Hotline 6788 2233

No: 27650

Date: 18/01/18

寶號

Messrs:

車號

Vehicle No

由

From

時間 (日/夜)

Time (day/night)

其他

Others

CASH \$

150/-

SJH 606 E 車型 S2000s

10H Guan to ubi 到 UBI To 307A

K/R

NOTE: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misadventure to your vehicle whilst being towed. ERP Fees, Car park fees, Cancellation of job and other miscellaneous charges incurred while performing the services shall be borne by the customer.

經手人

Authorised by:

收貨人

Received by:

Print Received Message

This mail is associated with :

*SJH6016E (MCT18010516)
[SHA3772K]

TP

NG YEW CHEONG

Jan 18 2018 9:00AM

[COMFORT TRANSPORTATION PTE LTD]

Super Zee Motor Service

From India International Insurance Pte Ltd (HQ) (IH_SG), sent on 23/03/2018 14:11 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (\$\$7770.45) - SJH6016E - Claim Handler: Sherini Pillai

Approved: 7770.45.

Thin Thin (LKKAUTO)

From: Christina Low <superzeemotor@gmail.com>
Sent: Monday, 29 January 2018 4:21 PM
To: Thin Thin (LKKAUTO)
Subject: Third Party Claim against Ill insured Vehicle No SHA3772K Accident on 18 Jan 2018
Attachments: SJH6016E Docs.pdf

Dear Ms Thin Thin

We have been authorized by the owner of Vehicle No SJH6016E to claim for damages against your insured Vehicle No SHA3772K as follows:

Repair Cost @	S\$6,800.00
Vehicle Rental @	S\$ 963.00
Search Fee @	S\$ 7.45

	S\$7,770.45
	=====

We attach herewith the necessary documents for your perusal. Kindly revert at your earliest convenience. Thank you.

Regards

Christina Low
Super-Zee Motor Service
Tel: 68381913
Fax: 63839565



LETTER OF AUTHORISATION

Date: 18 Jan 2018

To: Indra International Insurance Pte Ltd

THIRD PARTY CLAIM


OWNER'S NAME : Ng Yew Cheong
VEHICLE REG NO : SJH 6016E
DATE OF ACCIDENT : 18 Jan 2018
PLACE OF ACCIDENT : Jurong East Ave 1
INVOLVING VEH NO : SJH 3792K

I, Ng Yew Cheong, NRIC No S1421917Z, hereby fully authorize **Super-Zee Motor Service** of Blk 14 Defu Lane 10 #01-402 Singapore 539195 to repair my damaged Vehicle No SJH 6016E which was involved in the above-mentioned accident.

The repairing of my vehicle is satisfactory to me and I hereby request you to settle The cost of repairs, rental car payment and all charges relating to my Vehicle No SJH 6016E to **Super-Zee Motor Service**.

I thank you in advance and hope that you will forward your cheque in favour of **Super-Zee Motor Service** at your earliest convenience.

Yours faithfully


Name: Ng Yew Cheong
Address: Blk 287D Jurong East St 21
04-314
8 pax 604287

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III-Direct Settlement (PODS)

India Ref: MCT18010516
Claimant Ref: SJH 6016E

We/I, Super Zee Motor Service ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK Auto Consultants Pte Ltd (name of Surveyor) with respect to the amount claimed for S\$ 6,800.00 (repair cost), S\$ 802.50 (loss of use/rental), S\$ 7.45 (search fee) vehicle no. SJH 6016E that was damaged pursuant to the accident which occurred on 18/01/2018 (date) at JURONG EAST ST 24 & JURONG EAST AVE 1 (location) involving vehicle no. SHA 3772K (insured vehicle). This is pursuant to the inspection conducted on 19/01/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner NG YEW CHEONG ("the third party claimant") of vehicle no. SJH 6016E to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SJH 6016E (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 7,609.95 to Super Zee Motor Service

Dated this 29 day of Mar 2018
SUPER-ZEE MOTOR SERVICE

CLAIMANT:

Signature:

Name:

NRIC:

Address:

Nationality:

Occupation:

[Signature]
Signed by "the workshop" (with chop)
Low Oi Kwan
S11818194
9 Lorong 27A Geylang
#05-10 Spore 388134
S'porean
Self-Employed

WITNESS:

Signature:

Name:

NRIC:

Address:

Nationality:

Occupation:



Signed by appointed Surveyor

LKK Auto Consultants Pte Ltd

199607198R

Blk 51, Paya Ubi Industrial Park,
Ubi Avenue 1, #02-25 | S(408933)

-

-

SUPER-ZEE MOTOR SERVICE

BLK 14 DEFU LANE 10 #01-402 SINGAPORE 539195 TEL: 6383 1913 FAX: 6383 9565
EMAIL: superzeemotor@gmail.com

29 Jan 2018

India International Insurance Pte Ltd
#04-05 IOB Building
64 Cecil Street
Singapore 049711
Att: Motor Claims Dept

INVOICE NO CTP501/18

THIRD PARTY CLAIM

OWNER NAME	:	NG YEW CHEONG
VEHICLE REG NO	:	SJH 6016 E
DATE OF ACCIDENT	:	18 JAN 2018
PLACE OF ACCIDENT	:	JURONG EAST AVE 1
INVOLVING VEH NO	:	SHA 3772 K

To cost of repairs to Vehicle No SJH6016E which was involved
in the accident on 18 Jan 2018, including the supply of necessary
auto spare parts, labour charges and spraypainting at a lumpsum
price of S\$ 6,800.00

SINGAPORE DOLLARS SIX THOUSAND EIGHT HUNDRED ONLY

Please make your cheque payable to "Super-Zee Motor Service"

SUPER-ZEE MOTOR SERVICE

Business Registration No.47959700J



GOLDBELL CAR RENTAL

10,000 Leasing Clients Served.
And Counting.

GOLDBELL CAR RENTAL PTE LTD

Main Office: 10 Raffles Park #02-01 Singapore 088702 Tel: 6838 6300 Fax: 6225 1029

Finance: 18 Tuas Avenue 10 Singapore 639142 Tel: 6316 3000 Fax: 6862 3500

Website: www.gbr.com.sg

Co. Reg No. 200710651D

Page 1 / 1

SUPER-ZEE MOTOR SERVICE
BLK 14, DEFU LANE 10 #01-402
SINGAPORE 539195
CHRISTINE

TAX INVOICE

GST Reg No. : M9-0002514-E
Invoice No. : CXI00029102
Invoice Date. : 24-01-2018
Account No. : C00009627
Our Ref. : CPVS1801124
Your Ref. :
Credit Term. : CASH
Salesman. : MARCUSNGSY

PARTICULARS		AMOUNT SGD
Asset Description	: HONDA ACCORD 2.4L 5AT	
Reg No/ID No	: SKP4767E	
Chassis No	: MRHCR2630EP000017	
Engine No	: K24W31200720	
Agreement No	: CPVS1801124	
Contract Period	: 18-01-2018 To 23-01-2018	
Type Of Lease	: Short Term	
BEING RENTAL CHARGES FOR THE ABOVE		900.00
GST @7.00% for \$ 900.00		63.00
E.& O.E		
TOTAL		\$ 963.00

Please make all cheques payable to GOLDBELL CAR RENTAL PTE LTD

When making payment, please quote our invoice numbers.

No receipts will be issued for Cheque Payments.

This is a computer generated document. No signature is required.



GOLDBELL CAR RENTAL

10,000 Leasing Clients Served.
And Counting.

GOLDBELL CAR RENTAL PTE LTD

Main Office: 10 Raffles Park #02-01 Singapore 088702 Tel: 6338 6300 Fax: 6325 1029

Finance: 18 Tuas Avenue 10 Singapore 639142 Tel: 6316 3000 Fax: 6862 3500

Website: www.gbcr.com.sg

Cs Reg No: 200710651D

DELIVERY ORDER

To Messrs:

SUPER-ZEE MOTOR SERVICE
BLK 14, DEFU LANE 10 #01-402
SINGAPORE
539195

DO NO
OUR REF CPVS1801124
YOUR REF
DATE 18/01/2018

Please acknowledge receipt of the following goods in good order and condition.

HONDA ACCORD 2.4L 5AT
Rental Agreement : CPVS1801124
Model : ACCORD 2.4
Vehicle No. : SKP4767E
Chassis No : MRHCR2630EP000017
Engine No : K24W31200720
Contact Person : CHRISTINE
Place Of Delivery : BLK 14, DEFU LANE 10 #01-402
SINGAPORE
539195

SECURITY DEPOSIT PAID	: Y / N	CHECKED OUT BY:
FIRST MONTH RENTAL PAID	: Y / N	DATE & TIME :
PERIOD OF HIRE	: 5 Days	KM OUT :
AGREEMENT RETURNED	: Y / N	

REMARKS

I/We acknowledge having received goods as described above in good order and condition. Goods sold are non-refundable

DATE:.....

NAME:.....

NRIC NO:.....

18 Jan 2018

Ng Yew Chong

S14219172



SIGN HERE
PLEASE!

SIGNATURE & COMPANY'S STAMP

GOLDBELL CAR RENTAL PTE LTD

[Signature]

18/01/18

DELIVERY ORDER

Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 18 Jan 2018 / 14:22:51

Receipt Date/Time : 18 Jan 2018 / 14:22:51

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180118-000997

Previous Receipt No. :

**S/N Item Description/
Business Transaction Reference
No.**

Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
-------------------------------	------------------------	------------------------------

Result of Insurance Enquiry - SHA3772K

As at 18 Jan 2018/09:15:00

Insurance Co: INDIA INT'L INS PTE LTD

1 Insurance Enquiry - SHA3772K
Enquiry Fee
20180118142113463923

Sub-Total	7.00	0.49	7.49
Total Before Rounding	7.00	0.49	7.49
Rounding Difference			0.04
Total Amount Payable			7.45

Paid By

xxxxxxxxxxxx2005	Credit Card: Visa/MasterCard	7.45
------------------	---------------------------------	------

Total	7.45
Cash Change	0.00
Tendered Amount	7.45
Excess Refundable Amount	0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Jan 2018 Edit Reg		19 Jan 2018 00:00 Edit Adj Rpt	\$56,800.00 Edit Estimates	\$56,800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R								
Main Claimant:	NG YEW CHEONG , ID: S14219172								
Vehicle Reg. No.:	SJH6016E	Date of Loss:	18/01/2018 09:00 - :59 [113 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT18010516	Policy/Cover Note No.:							
Vehicle Reg. No. (Insured):	SHA3772K	Policy No. (Claimant):	GA052162						
		Excess:							
Repairer:	Super Zee Motor Service (HQ) BLK 14 DEFU LANE 10 #01-402, 539195 Defu Lane - Tel: 63831913								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sherini Pillai]								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 30/01/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- III_SG (23/03/2018): Alert - Adj Mandate Approved (\$57770.45) - SJH6016E - Claim Handler: Sherini Pil... - III_SG (23/01/2018): Alert - Adj Mandate Approved (\$50.00) - SJH6016E - Claim Handler: Sherini Pillai									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJH6016E (MCT18010516)
[SHA3772K]
TP
NG YEW CHEONG
Jan 18 2018 9:00AM
[COMFORT TRANSPORTATION PTE LTD]
Super Zee Motor Service

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	22/03/18 09:47	Chassis Number	 Load JPG	☒
2	22/03/18 09:47	General View	 Load JPG	☒
3	22/03/18 09:47	Odometer Reading	 Load JPG	☒
4	22/03/18 09:47	General View	 Load JPG	☒
5	22/03/18 09:47	General View	 Load JPG	☒
6	22/03/18 09:47	General View	 Load JPG	☒
7	22/03/18 09:47	General View	 Load JPG	☒
8	22/03/18 09:47	General View	 Load JPG	☒
9	22/03/18 09:47	General View	 Load JPG	☒
10	22/03/18 09:47	General View	 Load JPG	☒
11	22/03/18 09:47	General View	 Load JPG	☒
12	22/03/18 09:47	General View	 Load JPG	☒
13	22/03/18 09:47	General View	 Load JPG	☒
14	22/03/18 09:47	General View	 Load JPG	☒
15	22/03/18 09:47	General View	 Load JPG	☒
16	22/03/18 09:47	General View	 Load JPG	☒
17	22/03/18 09:47	General View	 Load JPG	☒
18	22/03/18 09:47	General View	 Load JPG	☒
19	22/03/18 09:47	General View	 Load JPG	☒
20	22/03/18 09:47	General View	 Load JPG	☒
21	22/03/18 09:47	General View	 Load JPG	☒
22	22/03/18 09:47	General View	 Load JPG	☒
23	22/03/18 09:47	General View	 Load JPG	☒
24	22/03/18 09:47	General View	 Load JPG	☒
25	22/03/18 09:47	General View	 Load JPG	☒
26	22/03/18 09:47	General View	 Load JPG	☒
27	22/03/18 09:47	General View	 Load JPG	☒
28	22/03/18 09:47	General View	 Load JPG	☒
29	22/03/18 09:47	General View	 Load JPG	☒
30	22/03/18 09:47	General View	 Load JPG	☒
31	22/03/18 09:47	General View	 Load JPG	☒
32	22/03/18 09:47	General View	 Load JPG	☒
33	22/03/18 09:47	General View	 Load JPG	☒
34	22/03/18 09:47	General View	 Load JPG	☒
35	22/03/18 09:47	General View	 Load JPG	☒
36	22/03/18 09:47	General View	 Load JPG	☒
37	22/03/18 09:47	General View	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	22/03/18 09:47	General View	 Load JPG	☒
39	22/03/18 09:47	Reinspection Photo	 Load JPG	☒
40	22/03/18 09:47	Reinspection Photo	 Load JPG	☒
41	22/03/18 09:47	Reinspection Photo	 Load JPG	☒
42	22/03/18 09:47	Reinspection Photo	 Load JPG	☒
43	22/03/18 09:47	Reinspection Photo	 Load JPG	☒
44	22/03/18 09:47	Reinspection Photo	 Load JPG	☒
45	22/03/18 09:47	Reinspection Photo	 Load JPG	☒
46	22/03/18 09:47	Reinspection Photo	 Load JPG	☒
47	22/03/18 09:47	Reinspection Photo	 Load JPG	☒
48	22/03/18 09:47	Reinspection Photo	 Load JPG	☒
49	22/03/18 09:47	Reinspection Photo	 Load JPG	☒
50	22/03/18 09:48	Reinspection Photo	 Load JPG	☒
51	22/03/18 09:48	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/01/18 10:29	TP GIA REPORT	 Load PDF	
2	23/01/18 10:29	TP ESTIMATE- MARKED + TOWING	 Load PDF	
3	20/03/18 16:10	WORKSHOP INVOICE	 Load PDF	
4	20/03/18 16:10	RENTAL RECEIPT	 Load PDF	
5	20/03/18 16:10	LTA SEARCH	 Load PDF	
6	03/04/18 14:14	AUTHORISATION TO ACT FORM	 Load PDF	
7	03/04/18 14:14	DISCHARGE VOUCHER	 Load PDF	
8	03/04/18 14:14	LOD	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	22/01/18 09:05	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd

(Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18001195/UUB3Q2

Date: 03/04/2018

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant Vehicle No : SJH6016E

Insured Vehicle No : SHA3772K

Date of Loss: 18/01/2018

Nature of Claim: TP

Claim No: MCT18010516

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJH6016E

Make & Model: MERCEDES-BENZ S300L, 3.0 (A)

Engine No: 27294630977346

Reg. Date: 15/08/2008 (Man. Year: 2008)

Chassis No: WDD2211542A236446

Colour: Silver

Odometer: 176826 km

Engine Capacity: 2997 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R17

Rear Tyre Size: 235/55 R17

Front Left Side: Continental 6 mm

Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm

Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,608.30	7,256.74	3,351.56	31.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,210.00	1,300.00	910.00	41.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,818.30	8,556.74	4,261.56	33.25
Approved Total (Overridden) (S\$)		6,800.00		
Nett Amount (S\$)	12,818.30	6,800.00	6,018.30	46.95
+ Car Rental (5.0 x S\$150.00/day + 7.00% GST) (S\$)		802.50		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		7,609.95		

INSPECTION

Date of Assignment: 19/01/2018

Date Inspected: 19/01/2018 Inspected At:

Super Zee Motor Service (HQ)
BLK 14 DEFU LANE 10 #01-402
Singapore 539195

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** THIN THIN HLAING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Mar 2018)
Parts:	143	MERCEDES-BENZ S300L 3.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJH6016E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,925.00 F	*1,615.32 FL
2	1		*FRONT BUMPER REINFORCEMENT	Bent / Dented	1,595.00 F	*1,219.31 FL
3	1		*FRONT BUMPER SPONGE	Torn	258.90 F	*247.11 FL
4	1		*FRONT BUMPER BRACKETS	N/S Bent	117.80 F	*58.90 FL
5	1		*FRONT BUMPER RETAINERS	N/S Bent	146.60 F	*73.30 FL
6	1		*FRONT BUMPER GRILLE	Not Necessary	189.00 F	*- FL
7	1		*FRONT BUMPER FOG LAMP LH	Broken	588.80 F	*395.00 FL
8	2		*FRONT BUMPER PARKING SENSOR LH	Shorted	565.40 F	*390.00 FL
9	10		*FRONT BUMPER CLIPS	Necessary	65.00 F	*65.00 FL
10	1		*FRONT FENDER LH	Bent / Warped	1,587.10 F	*1,342.66 FL
11	1		*FRONT FENDER INNER SHIELD LH	Torn	290.30 F	*266.50 FL
12	1		*HEADLAMP LH	Broken	2,283.80 F	*2,010.35 FL
13	1		*HEADLAMP WIPER COVER LH	Twisted	164.50 F	*48.50 FL
14	1		*WASHER TANK	Dented / Torn	194.40 F	*194.40 FL
15	1		*HORN	Cracked	136.70 F	*136.70 FL
16	1		*FRONT TYRE LH	Serviceable	500.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,608.30	8,063.05
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	806.31
Total Parts (\$\$)	10,608.30	7,256.74

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING CHARGE (WITH RECEIPT)	New	150.00	100.00
2	TO DISMANTLE & REPLACE DAMAGED PARTS & PANELBEATING	New	800.00	550.00
3	TO PUTTY,APPLY PRIMER & SPRAYPAINT AFFECTED PORTION	New	1,000.00	600.00
4	TO APPLY RUSTPROOFING ON REPAIRED ,REPLACED PANEL	New	180.00	30.00
5	TO CHECK ELECTRICAL WIRING FUNCTIONS	New	80.00	20.00
Gross Labour Cost (S\$)			2,210.00	1,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >