

22/03/2018

ASS. REC. BY:

REF:

CS / SPF18001199 / Svbmr

Special Instruction:

SURVEYOR

## ASSIGNMENT (Office)

From (Person):

Abdul Rahman

of

SPF

Date/Time:

19/01/2018

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

XD 22688

Insured:

QX 2021E

at Workshop in/s

Lee Kuan Hwa motor

Tel:

6269 9192

of

24 Sungai Kadut St 4

Policy No:

Claim No:

AEMD / 105 / 009 / 2018 / QX2021E

Sum Insured:

Excess:

Make of Veh:

D.O.A.

10-01-2018

(Client's Record)

CA / REV / REP. / REV 24 HRS w/p

H.O.D. Endorsement:

Date/Time:

19.01.2018 1.34pm

Person Contacted:

Shue Ting

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

XD 22688 - x

QX 2021E - x

1/2/18

check with Sebastian submit \$ 2060.50 (No LS)



# **Survey Department Check List (Case Handler)**

Reference No.: CS / SPF / 8001199 / Svb  
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

**Admin (** ): Case handler to make sure all information created by the assignment team are **ACCURATE**.

## **(1) Office Assign Form**

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From	✓			
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A				
C	Policy No	✓			
C	Claim No				
C	Insurance Authorisation (CA /REV/REP)	✓			
C	Report Type				
C	Weekend Charges	✓			
N	Survey held at/Repairer				
C	Excess				

**Surveyor (** ): Case handler to make sure the surveyor completed all required information.

## **(1) Assignment Form**

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages				

## **(2) System - (Views/Merimen)**

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

## **(3) Workshop Estimate/Assignment Form**

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)	✓			
C	Days of repair				
C	Finalised Amount				
C	Re-inspection Cases to Finalize within 5 Days				

## **(4) System - (Views/Merimen)**

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By:

VERON

Case Handler

12/18  
Date

\*C: Critical \*N: Non-Critical

21/05/2014



# SINGAPORE POLICE FORCE

SPF Accidents Claims Section  
Automotive Engg & Mgmt Div  
Police Logistics Department  
No. 1 Mount Pleasant Road  
Block 8 Old Police Academy  
#02-12 Singapore 298333

Your Ref : XD2268B

Our Ref : AEMD/105/009/2018/QX2021E

Date : 19 January 2018

Tel: 64784840

Fax: 64784848

M/s LKK Auto Consultants Pte Ltd  
Paya Ubi Industrial Park  
51 Ubi Avenue 1 #01/02-25  
Singapore 408933

Via Fax only: 62564315

Dear Sir/Madam,

## ACCIDENT ON 10 JANUARY 2018 INVOLVING GOVT VEHICLE QX2021E AND OTHER VEHICLE XD2268B

We refer to the above matter.

- 2 Please assist to arrange for a PRI of Vehicle no. XD2268B at M/s Lee Kuan Hwa Motor Service of 24 Sungei Kadut Street 4, Singapore 729050.
- 3 For appointment please contact Tel: 62699192.
- 4 Estimates were provided by the workshop.
- 5 Thank you.

Yours faithfully,

Abdul Rahman  
Accident Claims Officer  
for Assistant Director

A FORCE FOR THE NATION

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3504Z
Vehicle Details	
Vehicle No.:	XD2268B
Vehicle to be Exported:	No
Intended De-registration Date:	25 Jan 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	FV51JJD4RDEA
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	6M70414390
Chassis No.:	FV51JJA00148
Maximum Power Output:	-
Open Market Value:	\$85,156.00
Original Registration Date:	05 May 2008
First Registration Date:	05 May 2008
Transfer Count:	0
Actual ARF Paid:	\$4,258.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	04 May 2018
COE Category:	C - Goods Vehicle & Bus

COE Period(Years):	10
QP Paid:	\$17,610.00
COE Rebate Amount:	\$483.00
<b>Total Rebate Amount:</b>	<b>\$483.00</b>

The information contained herein is correct as at 25 Jan 2018

OK

# Register New Vehicle (Acknowledgement)

## Vehicle Particulars

Vehicle No.:	XD2268B	Vehicle Scheme:	Normal
Vehicle Type:	B33 - Goods (Open) Tipper/Dumper Truck		
Vehicle Attachment 1:	No Attachment	Vehicle Attachment 3:	-
Vehicle Attachment 2:	-	Vehicle Model:	FV81JJD4RDEA
Vehicle Make:	MITSUBISHI	Engine No.:	6M70414390
Chassis No.:	FV81JJA00148	Trailer Chassis No.:	-
Motor No.:	-	Passenger Capacity:	2
Propellant:	Diesel	Power Rating:	-
Engine Capacity:	12882 cc	Maximum Laden Weight:	28000 kg
Unladen Weight:	11280 kg	Secondary Colour:	-
Primary Colour:	White	Original Registration Date:	06 May 2008
First Registration Date:	05 May 2008	Open Market Value:	\$95,156.00
Manufacturing Year:	2008	Minimum PARF Benefit:	\$0.00
PARF Eligibility:	No		
No. of Transfers:	0		

## Owner Particulars

Owner Name:	TAN LIANG CHUANG
Owner ID Type:	Singapore NRIC
Owner ID:	S1323804Z
Registered Address Type:	HDB / HUDC
Registered Block/House No.:	418
Registered Street Name:	FAJAR ROAD
Registered Unit No.:	# 00 - 441
Registered Building Name:	-
Registered Postal Code:	670418
COE No. / Expiry Date:	2008040106000632D / 04 May 2018
COE Bid Category:	C - Goods Vehicle & Bus
QP Paid:	\$17,810.00

## Transaction Details

Business Transaction Ref. No.:	20080608185409108493
Business Transaction Date:	06 May 2008
Business Transaction Time:	15:54:09

## Message

The above vehicle has been successfully registered.

Please note that \$13,835.00 will be deducted from your GIRO account.

OK

[https://italink.vd.lta.gov.sg/ita/vrl/action/acknowledgeNewReg?FUNCTION\\_ID=F0101001TC&bizTran...](https://italink.vd.lta.gov.sg/ita/vrl/action/acknowledgeNewReg?FUNCTION_ID=F0101001TC&bizTran...) 05-May-(

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	15/01/2018 15:14
Date Of Accident	10/01/2018 13:50
Exact Location Of Accident	PIE EXIT PIONEER RD NORTH
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	XD2268B
Insured/Policyholder	
Name Of Registered Owner	TAN LIANG CHUANG
NRIC No	S1323504Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96141105
Alternative Phone No	OFFICE-97300120

### Vehicle Particulars

Manufacturer	MITSUBISHI
Model	FV51JJD4RDEA-12.9 D (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VCB/P1754358
Cover Note Number	

### Driver

Name of Driver	SEAH THIAM HOCK
NRIC No	S0969516H
Date Of Birth	07/01/1950
Occupation	OUTDOOR
Date Of Driving Pass	29/03/1975
Driving Experience	42 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96141105
Fax Number	
Contact Number	
Email Address	NOEMAIL



Address NO  
 Postcode  
 Was driver an employee of the Insured's Company YES  
 If No, Relationship of the Driver with the Insured  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

#### General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR  
 Weather Conditions RAINING  
 Road Surface WET

#### Other Information

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance?  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. YES  
 Number of Passengers (Including Driver) 1

#### Details of Police Action

Was the accident reported to the police? YES  
 If Yes, Please state which Police Station  
 POLICE STATION NAME [OTHER] BUKIT BATOK NPC  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

#### Circumstances of Accident

REFER TO POLICE REPORT

#### Attachment(s)

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number QX1021E  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category GOVERNMENT  
 Name of Driver  
 NRIC/Passport Number  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:


Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# SKETCH PLAN

PIE exit Pioneer Road North

A = XD 2268 B

B = QX 1021 E



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police report. I am claiming against the vehicle B  
QX 1021 E insurance policy.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

*[Signature]*

Policyholder's Signature  
Date & Time:

*[Signature]*

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



# SINGAPORE POLICE FORCE



T/20180110/2122

1 of 3

Police Station Of Origin:  
Bukit Batok N.P.C  
21 Bukit Batok East Avenue 4 SINGAPORE  
659840  
Tel No: 1800-6659999

Report No. T/20180110/2122

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 10/01/2018 16:51	Vide Report No.: J/20180110/0128	Station Diary No.: 85
--------------------------------------------	-------------------------------------	--------------------------

**Informant's Particulars**

Name of Informant: SEAH THIAM HOCK			Address: APT BLK 288D BUKIT BATOK STREET 25 #07-52 SINGAPORE 653288	
ID Type / ID No.: NRIC NO / S0969516H			Contact No.: Home/Office: Mobile: 96141105	
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 68	Date of Birth: 07/01/1950	Type of Informant: Driver	
Race: Chinese		Language: English	Institution / School Name:	
Occupation: Lorry driver		Driving Licence Information: Class: 3,4,5 Date of Expiry:		

**General Information of the Accident**

General Information of the Accident				
Type of Accident:	Non-Injury Government Vehicle	Drink Drive: No	Date/Time of Accident: 10/01/2018 13:50	Type of Location: X-Junction
Location: Along Road 1 PAN ISLAND EXPRESSWAY  Towards Changi at Pioneer Road North Exit				
Weather: Drizzling		Road Surface: Wet	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Traffic Light - Working	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
QX1021E	Car				Seriously Damaged	1
XD2268B	Lorry				Slightly Damaged	0

**Details of Person Involved**

Any Pedestrian Involved: No	Use of Pedestrian Crossing: NA
No. of Pedestrians Injured: NIL	



**SINGAPORE  
POLICE FORCE**



T/20180110/2122

Police Station Of Origin:  
Bukit Batok N.P.C  
21 Bukit Batok East Avenue 4 SINGAPORE  
659840  
Tel No: 1800-6659999

2 of 3

Report No. T/20180110/2122

**CONTINUATION OF REPORT**

Driver			
Name	SEAH THIAM HOCK	ID No.	S0969516H
Related Vehicle	XD2268B (Lorry)	Contact No.	96141105
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3,4,5 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 10/01/2018 at about 1353hrs, I was driving my vehicle (XD2268B), along PIE towards Changi at Pioneer Road North exit, when a collision happened under the overhead bridge. I was stationary at the traffic light while waiting for the traffic lights to turn green. I heard sirens of police vehicle and I look at my rear view mirror and saw a police vehicle (QX1021E). Suddenly, the police vehicle skidded to the right and crashed into the right rear side of my lorry.

Traffic Police and ambulance were at scene. Nobody was injured nor conveyed by the ambulance. However, the left side of the police vehicle was seriously damaged. Traffic police issued me an NP 364 note and instructed me to make a police report. The case (J/20180110/0128) is under Traffic Police IO Saiful (65476180).



**SINGAPORE  
POLICE FORCE**



T/20180110/2122

3 of 3

Police Station Of Origin:  
Bukit Batok N.P.C  
21 Bukit Batok East Avenue 4 SINGAPORE  
659840  
Tel No: 1800-6659999

Report No. T/20180110/2122

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J /

Sr Staff Sgt SHANIZA BINTE SITAL

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIA /

Staff Sgt TANG SIEW PING

Contact No.: 65476430

Signature Of Informant:

Date/Time:

10/01/2018 16:51

Classification Of Case:

Authentication Stamp

NP168

SN 114

Singapore Police Force



# LEE KUAN HWA MOTOR SERVICE

Mailing Add: 39, Westwood Ave Singapore 648719

Workshop: 24, Sungei Kadut Street 4 Singapore 729050

Tel: 6269 9192 Fax: 6269 2239 H/P: 9631 1712

Business Reg. No: 36463500B

LKK Auto Consultants hence notify

to the effect of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

M/s: Mr Rahmin  
Mount Pleasant Road  
Blk 8 Old Police Academy  
Singapore 298333

Date : 18.01.2018

SPF Accident Claim Section

Tel: 6478 4840

Fax: 6478 4848

Vehicle number : XD 2268 B  
Make/Model : MITSUBISHI FV51JJ  
Date of accident : 10.01.2018  
Claim Type : TP Claim

Sebastian 23/1/18.  
- Lump Sum Repair.  
- Photo After Paint.  
9003621  
Sebastianyang@lkkauto.com

Accident involving XD 2268 B & QX 1021 E along PIE on 10.01.2018.

Re: Estimate for XD 2268 B

1.	1 pc	Rear mudguard RH ✓ BT	\$	800.00
2.	1 pc	Rear mudflat RH ✓ TN	\$	60.00
3.	1 pc	Rear mudguard bracket RH R	\$	60.00
4.	1 pc	Rear lamp RH ✓ CRK	\$	285.00
5.	1 pc	Rear lamp bracket RH R	\$	120.00
6.	1 pc	Rear canvas RH X NE nn	\$	400.00
7.	1 pc	Rear canvas bracket RH X NE nn	\$	500.00
				-----
				\$ 2,225.00

To wiring services

To repair and replace labour charges

To putty and spray painting

\$ 30 50.00 ✓

\$ 850.00 600

\$ 600.00 400

Total

\$ 3,725.00

Yours Faithfully,

李光華 廖嘜燒焊

LEE KUAN HWA MOTOR SERVICE  
39, Westwood Avenue, Singapore 648719  
TEL: 6269 9192 FAX: 6269 2239 H/P: 9631 1712

# LEE KUAN HWA MOTOR SERVICE

Mailing Add: 39, Westwood Ave Singapore 648719  
Workshop: 24, Sungei Kadut Street 4 Singapore 729054  
Tel: 6269 9192 Fax: 6269 2239 H/P: 9631 1712  
Business Reg. No: 36463500B

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

M/s: Mr Rahmin  
Mount Pleasant Road  
Blk 8 Old Police Academy  
Singapore 298333

Date : 18.01.2018

SPF Accident Claim Section

Tel: 6478 4840 Fax: 6478 4848

Vehicle number : XD 2268 B  
Make/Model : MITSUBISHI FV51JJ  
Date of accident : 10.01.2018  
Claim Type : TP Claim

Part by part  
- Lamp & Repair.  
- Photo After Paint.  
90036121  
Sebastian.yang@lkkauto.com

Accident involving XD 2268 B & QX 1021 E along PIE on 10.01.2018.

Re: Estimate for XD 2268 B

1.	1 pc	Rear mudguard RH ✓ BT	\$ 800.00
2.	1 pc	Rear mudflat RH ✓ TN	\$ 60.00
3.	1 pc	Rear mudguard bracket RH R	\$ 60.00
4.	1 pc	Rear lamp RH ✓ CRK	\$ 285.00
5.	1 pc	Rear lamp bracket RH R	\$ 120.00
6.	1 pc	Rear canvas RH X NC	\$ 400.00
7.	1 pc	Rear canvas bracket RH X NC	\$ 500.00
			\$ 2,225.00

1145  
- 10%  
1) 1030.50

To wiring services  
To repair and replace labour charges  
To putty and spray painting

\$ 30 50.00 ✓  
\$ 850.00 600  
\$ 600.00 400

Total

\$ 3,725.00 2) 1030

Yours Faithfully,

李光華 廖嘜燒焊

LEE KUAN HWA MOTOR SERVICE  
39, Westwood Avenue, Singapore 648719  
TEL: 6269 9192 FAX: 6269 2239 H/P: 9631 1712

Parts: \$ 1030.50  
Labour: \$ 1030.50

2060.50  
Lamp & Repair  
16 98.50  
1/5 = \$ 1650





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGINEERING & MGT DIVISION

Ref : CS/SPF18001199/Svbn2

ACCIDENT CLAIM SECTION  
(SINGAPORE POLICE FORCE)

1 MOUNT PLEASANT ROAD  
BLK 8 OLD POLICE ACADEMY SINGAPORE 298333

Date : 14-02-2018



Code : SPF

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	QX 2021E	Veh. Inspected	XD 2268B
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2018/QX2021E	Excess (\$)	0.00
Assign From	ABDUL RAHMAN	Assign Date	19/01/2018

### 2. Vehicle Particulars & Condition

Make & Model	mitsubishi FV51JJD4RDEA	c.c	12882
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	FV51JJA00148	Colour	GREEN
Odometer	522322	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	295/80 R22.5	CHAO YANG	6 mm
L/H Front Tyre	295/80 R22.5	CHAO YANG	6 mm
R/H Rear Tyre	295/80 R22.5 (D)	CHAO YANG	6/6 mm
L/H Rear Tyre	295/80 R22.5 (D)	CHAO YANG	6/6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
----------------------------------------------------------------------------

### 5. General Information

Accident Date	10/01/2018	Inspection Date	23/01/2018
Survey held at	LEE KUAN HWA MOTOR SERVICE 24 SUNGEI KADUT ST. 4 SINGAPORE 729050		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
----------------------------------------------------------------------------------------------------------------------------------------

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XD 2268B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR MUDGUARD RH	BENT	800.00	800.00
1	REAR MUDFLAT RH	TORN	60.00	60.00
1	REAR MUDGUARD BRACKET RH	TO REPAIR SEE LABOUR	60.00	-
1	REAR LAMP RH	CRACKED	285.00	285.00
1	REAR LAMP BRACKET RH	TO REPAIR SEE LABOUR	120.00	-
1	REAR CANVAS RH	NOT NECESSARY	400.00	-
1	REAR CANVAS BRACKET RH	NOT NECESSARY	500.00	-
	LESS 10% DISCOUNT		-	-114.50
			2,225.00	1,030.50
<b>LABOUR</b>				
	TO WIRING SERVICES.		50.00	30.00
	TO REPAIR AND REPLACE LABOUR CHARGES.INCLUSIVE OF THE REPAIR OF REAR MUDGUARD BRACKET RH AND REAR LAMP BRACKET RH.		850.00	600.00
	TO PUTTY AND SPRAY PAINTING.		600.00	400.00
			1,500.00	1,030.00
<b>GRAND TOTAL</b>			<b>3,725.00</b>	<b>2,060.50</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>2,060.50</b>

Report Ref No. CS/SPF18001199/Svbn2

YEANG WAI KEEN  
Automotive Assessor

ADRIAN LING WAI PING  
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI  
Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.