

COMFORTDELGRO ENGINEERING PTE LTD

Date: 18.01.2018

Time: 15:26:06

REPAIR ESTIMATE

Page: 12

China Taiping-45
LKK-Kalvin

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305108282
 REGN NO : SH 6980P
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 15.01.2015
 DATE/TIME IN : 18.01.2018 09:40
 ACCIDENT DATE : 17.01.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-0579-G	REAR BUMPER	1	603.60	20.00	482.88	/
0002	04-01-0103-0738-G	REAR BUMPER LOWER	1	225.00	20.00	180.00	/
0003	04-01-0101-0111-G	REAR BUMPER CLIPS	10 L	22.00	20.00	17.60	/
0004	04-01-0103-0783-G	REAR BUMPER SIDE BRKT RH	1	49.00	20.00	39.20	?
0005	04-01-0103-0907-G	REAR BUMPER SIDE BRKT LH	1	49.00	20.00	39.20	?
0006	04-01-0103-1150-A	R/BUMPER PROTECTOR MAT	1	50.00	2.00	50.00	/
0007	09-01-9999-0068-A	REVERSE SENSOR	1	135.70	0.20	135.70	/
0008	04-01-0103-0739-G	REAR BUMPER SPONGE	1	143.40	20.00	114.72	?
0009	04-01-0103-0740-G	REAR BUMPER REINFORCEMENT	1	504.35	20.00	403.48	?
0010	04-01-0103-0743-G	REAR BUMPER REIN-BRKT RH	1	180.00	20.00	144.00	?
0011	04-01-0103-0742-G	REAR BUMPER REIN-BRKT LH	1	180.00	20.00	144.00	?

SUB-TOTAL : 1,750.78

JOB NATURE

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

China Taiping-LTS

Date: 18.01.2018

Time: 15:26:06

Page: 2 TS

LKK - Kalvin

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305108282
 REGN NO : SH 6980P
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 15.01.2015
 DATE/TIME IN : 18.01.2018 09:40
 ACCIDENT DATE : 17.01.2018

JOB / PARTS DESCRIPTION		QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0000 20-05	Rear Fender Adv.Sticker RH/LH	200.00	✓			
0001 20-05	Rear Bumper Adv.Sticker	50.00	✓			
0002 L	PANEL BEATING	280.00		200		
0003 23-502	SPRAYPAINT ON AFFECTED AREA	200.00		180		
0004 L	R/I REVERSE SENSOR	120.00		20		
SUB-TOTAL :						850.00

TOTAL : 2,600.78

MVA NAME & SIGNATURE
 DATE :

AUTHORISED : YES / NO
 SURVEYOR NAME & SIGNATURE
 DATE :

Kalvin LKK

18/1/18 1530 hrs

2 Days

PIP

Before Paint photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: