

INS. CASE OWNER:

ONK LI LI

CC4/LPC18001220

10/23/02

LKK:

IDAC:

## ASSIGNMENT

Surveyor:

MARCUS

DOI:

22/01/18

Date / Time:

19/01/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

XD 3964T

Claim No.:

17/18/18/VC10/020342

Name of Insured:

SAB LOGISTICS PTE LTD

Policy No.:

Insured Tel No.:

HP: 9440 5822

Make / Model:

SCANIA PRIME MOWER

Excess Sec II :\$S

D.O.A.: 13/01/18

Place of Accident:

JURONG HALL RD TWD AYE FROM WEST COAST HIGHWAY

Is driver the owner?

( YES )

Nature of Accident:

If NO, Driver Name / Age:

PERUMAL ROUNGAR NATARAJAN

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability:

%

Final ? Yes / No

SLK 7214D



INSRS:

WSP: peragus

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE DATE / PIC

24/01/18 (later)

SLK 7214D-X; XD 3964T-X

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

RECEIVED 14 SEP 2018

RECEIVED 17 APR 2018

PRELIMINARY ADVICE Date/Time:

24/01/18

Sent By:

Shirley Hwee

FINALIZATION

Date/Time:

24/1/18

Confirm with: N/A

Confirm by: EWS

Repair Cost:

US \$53,500

( 4 days) Reduction:

48 %

Email ☐Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with

Email ☐Call ☐

Total Liability:

US \$0

(Agreed / Assessed) BOLA S/N No.:

NIL

If NO or B 28, Ass. Lia:

Repair Cost:

SS

(CONTINUING VERSION)

Cost of Rental (LOR):

SS

( days)

Cost of Use (LOU):

SS

(\$ x days)

Cost of Income (LOI):

SS

(\$ x days)

LOR only ☐LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GFA/LTA Search

SS

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Total Cost:

SS

Total:

SS

Global Sum \$S:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐Call ☐

Payee 1:

SS

Name 1:

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Settlement

2) Report Format:

TP

3) Survey fee:

+ 350

CE 14/9/18

LPC

## ASSIGNMENT

From: Date: 22/01/2018

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLK 7214D  
at Workshop: Pegasus Engineering  
of: 51 Defu Lane 10

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Ven:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

|    |    |
|----|----|
|    |    |
| NS | OS |
|    |    |

Bal. or Market Value

IDAC Accident Report: Consistent? Yes or No

GIA / PR Seen: Consistent? Yes or No

Est. Repair: 4 days Res: Yes or No

Lump Sum: 20 % 3 Val: Yes or No

CA / REV / REP / 24 HRS'wp 71000

Date: Person Contacted:

Vehicle IN / OUT

Veh No: SLK 7214D Reg: 1 17

Type: M / Cycle / Bus / Van / Lorry / Taxi / Prime Mover

Truck / Trailer or CA /

Make: mercedes

id: 1496

Colour: Grey

R/O: Insured / Std / Nil / NA

So Reading: 67360

T Radio: Insured / Std / Nil / NA

Eng No:

Ch No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In / Jammed / Leaked / Burnt or

Brake: In / Jammed / Leaked / Burnt or

Mod: Nil / SRim / STD A/Rim or

Tyre Size: F:

R:

BS / SUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUM /

TOYO / YOKO or

Front

Rear

R/Bal:

R/Bal:

L/Bal:

L/Bal:

D/OA:

D/OA:

Surveyed at:

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

22/1/18 confirmed 25 @ 3500 with Sam.

(Res: 43,204 48%)

Data Time / Re Pass of

☐

Preli. Report

☐

Final Report

Data Time / Re Pass of

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Lump Sum /

Other:

Other:

Other:

Other:

Other:

Report Format:

Lump Sum /

Add Fee:

☐

Site Visit:

☐

Travel:

☐

Test:

☐

Repair:

☐

Other:



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                              |                            |                                                                                     |  |
|----------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------|----------------------------|-------------------------------------------------------------------------------------|--|
| LONPAC INSURANCE BHD                                                                                                                   |                                                                              | Ref : CC4/LPC18001220/Ues3 |                                                                                     |  |
| 300 BEACH ROAD<br>#17-04/07 THE CONCOURSESINGAPORE 199555                                                                              |                                                                              | Date : 19-01-2018          |  |  |
|                                                                                                                                        |                                                                              | Code : LPC2                |                                                                                     |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                              |                            |                                                                                     |  |
| Insured Veh.                                                                                                                           | XD 3964T                                                                     | Veh. Inspected             | SLK 7214D                                                                           |  |
| Policy No.                                                                                                                             |                                                                              | Coverage (\$)              | 0.00                                                                                |  |
| Claim No.                                                                                                                              | 17/18/18/VC10/020342                                                         | Excess (\$)                | 0.00                                                                                |  |
| Assign From                                                                                                                            |                                                                              | Assign Date                | 19/01/2018                                                                          |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                              |                            |                                                                                     |  |
| Make & Model                                                                                                                           |                                                                              | c.c                        | 0                                                                                   |  |
| Engine No.                                                                                                                             | HIDDEN                                                                       | Year of Reg.               |                                                                                     |  |
| Chassis No.                                                                                                                            |                                                                              | Colour                     |                                                                                     |  |
| Odometer                                                                                                                               | -                                                                            | Steering                   |                                                                                     |  |
| Brakes                                                                                                                                 |                                                                              | Modification               |                                                                                     |  |
| General                                                                                                                                |                                                                              |                            |                                                                                     |  |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                              |                            |                                                                                     |  |
|                                                                                                                                        | Size                                                                         | Make                       | Balance                                                                             |  |
| R/H Front Tyre                                                                                                                         |                                                                              |                            | mm                                                                                  |  |
| L/H Front Tyre                                                                                                                         |                                                                              |                            | mm                                                                                  |  |
| R/H Rear Tyre                                                                                                                          |                                                                              |                            | mm                                                                                  |  |
| L/H Rear Tyre                                                                                                                          |                                                                              |                            | mm                                                                                  |  |
| <b>4. Description of Damages</b>                                                                                                       |                                                                              |                            |                                                                                     |  |
|                                                                                                                                        |                                                                              |                            |                                                                                     |  |
| <b>5. General Information</b>                                                                                                          |                                                                              |                            |                                                                                     |  |
| Accident Date                                                                                                                          | 18/01/2018                                                                   | Inspection Date            | 22/01/2018                                                                          |  |
| Survey held at                                                                                                                         | PEGASUS ENGINEERING & TRADING PTE LTD<br>51 DEFU LANE 10<br>SINGAPORE 539216 |                            |                                                                                     |  |
| <b>5a. Remarks</b>                                                                                                                     |                                                                              |                            |                                                                                     |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                              |                            |                                                                                     |  |



Auto  
Consultants  
Pte Ltd

Company Registration No. 109607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62563315

Your ref: 17/18/18/VC10/020342  
Our ref: CC4/LPC18001220/Ues3

Date: 24.01.2018

The Motor Claims Department  
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO.**

**SLK 7214D**

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 22.01.2018 at the premises of M/s Pegasus Engineering & Trading Pte Ltd - (Defu Lane) have the following to report:-

|                          |       |          |
|--------------------------|-------|----------|
| Workshop Estimate Amount | : S\$ | 6,704.00 |
| Revised Estimate Amount  | : S\$ | 4,382.00 |
| "Check" Items Amount     | : S\$ | -        |
| Market Value             | : S\$ | -        |
| LTA Reimbursement Value  | : S\$ | -        |
| Nett Value               | : S\$ | -        |

**Description of Damage:**

The vehicle sustained damages at the  
O/S Rear Portion



**Comments/Present Status:**

Damages Consistent

Estimated normal period for repairs: 4.0 days

Yours faithfully,

**MARCUS CHUA**  
**Licensed Appraiser**

## Nivitha (LKK Auto)

---

**From:** ONG LI LI <llong@lonpac.com>  
**Sent:** Friday, 19 January 2018 12:22 PM  
**To:** Pegasus Engineering; MT\_Claim\_SG; assignments@lkkauto.com; 'SUR' (sur@lkkauto.com)  
**Subject:** RE: Third Party Survey - SLK7214D Your insured - XD3964T DOA 18.01.2018 17/18/18/VC10/020342  
**Attachments:** 19012018120456.pdf; SLK7214D 18.01.2018.pdf

12.25pm @ 19/01/2018  
vehicle Not In  
person @ William  
merge on 22/01/18

Without Prejudice  
Save as to Costs

Dear Alvin

We will appoint LKK to attend to the survey.

They will look into the liability and quantum.

Kindly liaise with them directly.

Dear LKK

fya

Regards,  
Ong Li Li  
Senior Claims Executive | Lonpac Insurance Bhd  
300 Beach Road #17-04/07 The Concourse Singapore 199555  
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

**From:** Pegasus Engineering [mailto:claims@pegasusengrg.com.sg]  
**Sent:** Friday, 19 January, 2018 12:04 PM  
**To:** MT\_Claim\_SG  
**Subject:** Third Party Survey - SLK7214D Your insured - XD3964T DOA 18.01.2018

Your Ref: XD3964T

Our Ref: SLK7214D

DOA 18.01.2018

Without Prejudice

Dear Sir/Madam,

We refer to the above matter.  
We enclose the following documents for your attention:-

- a. Copy of our client's SAS report and damaged photos;
- b. Copy of the estimated cost of repair.

Please arrange for a Pre-Repair Inspection under the NIMA Protocol and confirm in writing whether you are agreeable to direct settle with us at 100% liability for this case.

We await for your favourable reply.

**Please arrange for survey on 22.01.2018**

Thanks & Regards,

Alvin Low  
-CO

Pegasus Engineering & Trading Pte Ltd  
51 Defu Lane 10  
Singapore 539216

Tel : 6858 1846  
Fax : 6487 6070  
Email : [claims@pegasusengrg.com.sg](mailto:claims@pegasusengrg.com.sg)

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 7200G

### Vehicle Details

Vehicle No.: SLK7214D

Vehicle to be Exported: Yes

Intended De-registration Date: 22 Jan 2018

Vehicle Make: MAZDA

Vehicle Model: MAZDA3 4-DOOR SEDAN 1.5L SP6EAT

Primary Colour: Grey

Manufacturing Year: 2016

Engine No.: P520421544

Chassis No.: JM6BN22A8H0136078

Maximum Power Output: 88.0 kW (118 bhp)

Open Market Value: \$14,777.00

Original Registration Date: 24 Jan 2017

First Registration Date: 24 Jan 2017

Transfer Count: 0

Actual ARF Paid: \$9,777.00

### Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 23 Jan 2027

PARF Rebate Amount: \$7,332.00

### Intended COE Rebate Details

COE Expiry Date: 23 Jan 2027

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$48,000.00

COE Rebate Amount: \$38,400.00

**Total Rebate Amount: \$45,732.00**

The information contained herein is correct as at 22 Jan 2018

## Enquire PARF/COE Rebate for Registered Vehicle

|                                |                                         |
|--------------------------------|-----------------------------------------|
| Vehicle Owner Particulars      |                                         |
| Owner ID Type:                 | Company                                 |
| Owner ID:                      | 7200G                                   |
| Vehicle Details                |                                         |
| Vehicle No.:                   | SLK7214D                                |
| Vehicle to be Exported:        | Yes                                     |
| Intended De-registration Date: | 22 Jan 2018                             |
| Vehicle Make:                  | MAZDA                                   |
| Vehicle Model:                 | MAZDA3 4-DOOR<br>SEDAN 1.5L 5P.6EAT     |
| Primary Colour:                | Grey                                    |
| Manufacturing Year:            | 2016                                    |
| Engine No.:                    | P520421544                              |
| Chassis No.:                   | JM6BN22A8H0136078                       |
| Maximum Power Output:          | 88.0 kW (118 bhp)                       |
| Open Market Value:             | \$14,777.00                             |
| Original Registration Date:    | 24 Jan 2017                             |
| First Registration Date:       | 24 Jan 2017                             |
| Transfer Count:                | 0                                       |
| Actual ARF Paid:               | \$9,777.00                              |
| Intended PARF Rebate Details   |                                         |
| PARF Eligibility:              | Yes                                     |
| PARF Eligibility Expiry Date:  | 23 Jan 2027                             |
| PARF Rebate Amount:            | \$7,332.00                              |
| Intended COE Rebate Details    |                                         |
| COE Expiry Date:               | 23 Jan 2027                             |
| COE Category:                  | A - Car up to 1600cc &<br>97kW (130bhp) |
| COE Period(Years):             | 10                                      |
| QP Paid:                       | \$48,000.00                             |
| COE Rebate Amount:             | \$38,400.00                             |
| <b>Total Rebate Amount:</b>    | <b>\$45,732.00</b>                      |

The information contained herein is correct as at 22 Jan 2018



# PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

## Quotation

|                                                                        |
|------------------------------------------------------------------------|
| From :                                                                 |
| PEGASUS ENGINEERING & TRADING PTE LTD<br>C/O 51 DEFU LANE 10<br>539216 |
| Officer in Charge : ALVIN LOW WAI LUN                                  |
| Tel :                                                                  |
| Email :                                                                |

|                                                                                     |
|-------------------------------------------------------------------------------------|
| Customer :                                                                          |
| GRAB RENTALS PTE LTD<br>18 SIN MING LANE<br>#01-08 MIDVIEW CITY<br>SINGAPORE 573960 |
| Attn :                                                                              |
| Tel :                                                                               |
| Fax :                                                                               |

not added  
2/5 \$3500  
4 day  
whip to other  
22/1/18  
LUA  
@ 10.30am

21/01 -  
Confirmed  
LS \$3500.00

|                                                                                          |                                |                       |
|------------------------------------------------------------------------------------------|--------------------------------|-----------------------|
| Quotation No : QO18/01-1136                                                              | Quotation Date : 18/01/2018    | Terms : 30 DAYS       |
| Vehicle No : SLK7214D                                                                    | Chassis No : JM6BN22A8H0136078 | Third Party Insurer : |
| Model : MAZDA 3                                                                          |                                | Date of Accident :    |
| Remarks : TP INSURER: LONPAC ; TP VEHICLE NUMBER: XD3964T ; DATE OF ACCIDENT: 18.01.2018 |                                |                       |

| ITEM | DESCRIPTION                                                                            | QTY | UNIT PRICE | AMOUNT (SGD) |
|------|----------------------------------------------------------------------------------------|-----|------------|--------------|
| 1    | REAR FENDER O/S <i>300500/rent</i>                                                     | 1   | 1,175.0000 | 1,175.00     |
| 2    | REAR FENDER INNER LINER O/S <i>11</i>                                                  | 1   | 146.0000   | 146.00       |
| 3    | REAR FENDER INNER LINER CLIPS <i>11</i>                                                | 4   | 5.0000     | 20.00        |
| 4    | REAR FENDER AIR VENT O/S <i>11</i>                                                     | 1   | 72.0000    | 72.00        |
| 5    | REAR FENDER LOWER PANEL O/S <i>12</i>                                                  | 1   | 102.0000   | 102.00       |
| 6    | REAR BUMPER <i>Deep cut</i>                                                            | 1   | 1,075.0000 | 1,075.00     |
| 7    | REAR BUMPER SIDE RETAINER O/S <i>rent</i>                                              | 1   | 37.0000    | 37.00        |
| 8    | REAR BUMPER SIDE HOLDER O/S <i>11</i>                                                  | 1   | 46.0000    | 46.00        |
| 9    | REAR BUMPER SIDE HOLDER RIVETS <i>11</i>                                               | 4   | 6.0000     | 24.00        |
| 10   | REAR DOOR O/S <i>12</i>                                                                | 1   | 1,006.0000 | 1,006.00     |
| 11   | REAR DOOR OUTER WEATHERSTRIP MOLDING CHROME <i>11</i>                                  | 1   | 141.0000   | 141.00       |
| 12   | REAR DOOR WINDOW GLASS CHANNEL WEATHERSTRIP <i>11</i>                                  | 1   | 117.0000   | 117.00       |
| 13   | REAR WHEEL HUB CAP O/S <i>cre</i>                                                      | 1   | 120.0000   | 120.00       |
| 14   | REAR LAMP O/S <i>cre</i>                                                               | 1   | 509.0000   | 509.00       |
| 15   | REAR LAMP CLIP HOLDER <i>11</i>                                                        | 2   | 8.0000     | 16.00        |
| 16   | REAR WINDSHIELD GLASS WEATHERSTRIP <i>ru</i>                                           | 1   | 124.0000   | 124.00       |
| 17   | LESS 20% (ITEMS 1-16)                                                                  | 1   | -946.0000  | -946.00      |
| 18   | REAR WINDSHIELD GLASS WEATHERSTRIP SEALANT <i>ru</i>                                   | 1   | 180.0000   | 180.00       |
| 19   | REAR WINDSHIELD GLASS WEATHERSTRIP SPONGE <i>ru</i>                                    | 1   | 100.0000   | 100.00       |
| 20   | TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.                               | 1   | 120.0000   | 120.00       |
| 21   | TO REMOVE AND REFIT REAR WINDSCREEN GLASS.                                             | 1   | 180.0000   | 180.00       |
| 22   | TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR. | 1   | 150.0000   | 150.00       |

P-3040 S.N 70  
2432.00 labor - 1880  
4312

# PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

## Quotation

|                                                                                                                                                                         |                                                                                                                                                     |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>From :</b><br><br><b>PEGASUS ENGINEERING &amp; TRADING PTE LTD</b><br>C/O 51 DEFU LANE 10<br>539216<br><br>Officer in Charge : ALVIN LOW WAI LUN<br>Tel :<br>Email : | <b>Customer :</b><br><br><b>GRAB RENTALS PTE LTD</b><br>18 SIN MING LANE<br>#01-08 MIDVIEW CITY<br>SINGAPORE 573960<br><br>Attn :<br>Tel :<br>Fax : |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------|

|                                                                                                 |                                       |                              |
|-------------------------------------------------------------------------------------------------|---------------------------------------|------------------------------|
| <b>Quotation No :</b> QO18/01-1136                                                              | <b>Quotation Date :</b> 18/01/2018    | <b>Terms :</b> 30 DAYS       |
| <b>Vehicle No :</b> SLK7214D                                                                    | <b>Chassis No :</b> JM6BN22A8H0136078 | <b>Third Party Insurer :</b> |
| <b>Model :</b> MAZDA 3                                                                          | <b>Date of Accident :</b>             |                              |
| <b>Remarks :</b> TP INSURER: LONPAC ; TP VEHICLE NUMBER: XD3964T ; DATE OF ACCIDENT: 18.01.2018 |                                       |                              |

| ITEM | DESCRIPTION                                                                                                             | QTY | UNIT PRICE | AMOUNT (SGD) |
|------|-------------------------------------------------------------------------------------------------------------------------|-----|------------|--------------|
|      |                                                                                                                         |     |            | B/F 0.00     |
| 23   | TO CHECK ELECTRICAL LIGHTING CONCERNED.                                                                                 | 1   | 50.0000    | 20 50.00     |
| 24   | TO TRANSFER OF REAR DOOR FITTINGS AND PERFORM WATER SEEPAGE TEST.                                                       | 1   | 120.0000   | 11 X 120.00  |
| 25   | TO REINSTALL OF REAR BUMPER PARKING SENSOR                                                                              | 1   | 120.0000   | 50 120.00    |
| 26   | PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. | 1   | 900.0000   | 700 900.00   |
| 27   | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION                                                                        | 1   | 1,000.0000 | 850 1,000.00 |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Work prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Any repair modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorized by Repairer

Signature:

|                    |          |
|--------------------|----------|
| <b>Sub Total</b>   | 6,704.00 |
| <b>GST(7.00%)</b>  | 469.28   |
| <b>Total (SGD)</b> | 7,173.28 |

Please conduct the survey at  
Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216

## **Shirley Hiew (LKK Auto)**

---

**From:** ONG LI LI <llong@lonpac.com>  
**Sent:** Wednesday, 24 January 2018 11:07 AM  
**To:** Shirley Hiew (LKK Auto); 'mt\_claim@lonpac.com'  
**Cc:** 'llong@lonpac.com'; GERALD POH WEE BIN; Asher Sng (LKKAuto); Vic (LKKAuto); Admin A  
**Subject:** RE: Third Party Survey - SLK7214D Your insured - XD3964T DOA 18.01.2018 17/18/18/VC10/020342  
**Attachments:** XD3964T 180118.PDF

Dear Shirley

Attached is our Insured's GIA report for your necessary action.

Regards,  
Ong Li Li  
Senior Claims Executive | Lonpac Insurance Bhd  
300 Beach Road #17-04/07 The Concourse Singapore 199555  
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

---

**From:** Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]  
**Sent:** Wednesday, 24 January, 2018 10:30 AM  
**To:** 'mt\_claim@lonpac.com'  
**Cc:** 'llong@lonpac.com'; GERALD POH WEE BIN; Asher Sng (LKKAuto); Vic (LKKAuto); Admin A  
**Subject:** RE: Third Party Survey - SLK7214D Your insured - XD3964T DOA 18.01.2018 17/18/18/VC10/020342

**Your ref:** 17/18/18/VC10/020342  
**LKK ref:** CC4/LPC18001220/Ues3

### **WITHOUT PREJUDICE**

Dear Sir / Madam,

We refer to the above matter.

This is a third party direct settlement case.

Enclosed revert of vehicle: SLK 7214D

Date of survey: 22/01/2018

Enclosed for your perusal is:

- TP's GIA report
- TP estimated cost of repair
- Preliminary advice
- Photographs of TP vehicle in its damaged condition

Meanwhile, Kindly assist to verify validity of our insured's policy, and let us have a copy of insured's accident report for our necessary action.

Kindly take note that the case handler in-charge is Asher and she can be contacted at DID: 6841 6051.

*To check availability of the case handler, you may contact the undersigned.*

Thank you.

Best Regards,

Shirley Hiew | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366-0055 | email: [ShirleyHiew@lkkauto.com](mailto:ShirleyHiew@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Admin-D (LKKAuto)

**Sent:** Friday, 19 January 2018 12:27 PM

**To:** 'ONG LI LI' <[llong@lonpac.com](mailto:llong@lonpac.com)>; 'MT\_Claim\_SG' <[mt\\_claim@lonpac.com](mailto:mt_claim@lonpac.com)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>

**Cc:** Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>

**Subject:** RE: Third Party Survey - SLK7214D Your insured - XD3964T DOA 18.01.2018 17/18/18/VC10/020342

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer arrange on 22/01/2018.

BEST REGARDS,

G.Nivitha | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** ONG LI LI [<mailto:llong@lonpac.com>]

**Sent:** Friday, 19 January 2018 12:22 PM

**To:** Pegasus Engineering <[claims@pegasusengrg.com.sg](mailto:claims@pegasusengrg.com.sg)>; MT\_Claim\_SG <[mt\\_claim@lonpac.com](mailto:mt_claim@lonpac.com)>; assignments@lkkauto.com; 'SUR' ([sur@lkkauto.com](mailto:sur@lkkauto.com)) <[sur@lkkauto.com](mailto:sur@lkkauto.com)>

**Subject:** RE: Third Party Survey - SLK7214D Your insured - XD3964T DOA 18.01.2018 17/18/18/VC10/020342

Without Prejudice

Save as to Costs

Dear Alvin

We will appoint LKK to attend to the survey.

They will look into the liability and quantum.

Kindly liaise with them directly.

Dear LKK

fya

Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

**From:** Pegasus Engineering [<mailto:claims@pegasusengrg.com.sg>]

**Sent:** Friday, 19 January, 2018 12:04 PM

**To:** MT\_Claim\_SG

**Subject:** Third Party Survey - SLK7214D Your insured - XD3964T DOA 18.01.2018

Your Ref: XD3964T

Our Ref: SLK7214D

DOA 18.01.2018

Without Prejudice

Dear Sir/Madam,

We refer to the above matter.

We enclose the following documents for your attention:-

- a. Copy of our client's SAS report and damaged photos;
- b. Copy of the estimated cost of repair.

Please arrange for a Pre-Repair Inspection under the NIMA Protocol and confirm in writing whether you are agreeable to direct settle with us at 100% liability for this case.

We await for your favourable reply.

**Please arrange for survey on 22.01.2018**

Thanks & Regards,

Alvin Low

-CO

Pegasus Engineering & Trading Pte Ltd  
51 Defu Lane 10  
Singapore 539216

Tel : 6858 1846

Fax : 6487 6070

Email : [claims@pegasusengrg.com.sg](mailto:claims@pegasusengrg.com.sg)

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC18001220/Uea3n2

300 BEACH ROAD  
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 18-09-2018



Code : LPC2

**1. Policy Particulars :- THIRD PARTY CLAIM**

|              |                      |                |            |
|--------------|----------------------|----------------|------------|
| Insured Veh. | XD 3964T             | Veh. Inspected | SLK 7214D  |
| Policy No.   |                      | Coverage (\$)  | 0.00       |
| Claim No.    | 17/18/18/VC10/020342 | Excess (\$)    | 0.00       |
| Assign From  | ONG LI LI            | Assign Date    | 19/01/2018 |

**2. Vehicle Particulars & Condition**

|              |                   |              |          |
|--------------|-------------------|--------------|----------|
| Make & Model | MAZDA 3 (A)       | c.c          | 1496     |
| Engine No.   | HIDDEN            | Year of Reg. | 2017     |
| Chassis No.  | JM6BN22A8H0136078 | Colour       | GREY     |
| Odometer     | 67360             | Steering     | IN ORDER |
| Brakes       | IN ORDER          | Modification | NIL      |
| General      | GOOD              |              |          |

**3. Conditions of Tyres**

|                | Size       | Make | Balance |
|----------------|------------|------|---------|
| R/H Front Tyre | 205/60 R16 | TOYO | 7 mm    |
| L/H Front Tyre | 205/60 R16 | TOYO | 7 mm    |
| R/H Rear Tyre  | 205/60 R16 | TOYO | 7 mm    |
| L/H Rear Tyre  | 205/60 R16 | TOYO | 7 mm    |

**4. Description of Damages**

|                                                                                |
|--------------------------------------------------------------------------------|
| THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.<br>DAMAGES SEE DETAILS. |
|--------------------------------------------------------------------------------|

**5. General Information**

|                |                                                                              |                 |            |
|----------------|------------------------------------------------------------------------------|-----------------|------------|
| Accident Date  | 18/01/2018                                                                   | Inspection Date | 22/01/2018 |
| Survey held at | PEGASUS ENGINEERING & TRADING PTE LTD<br>51 DEFU LANE 10<br>SINGAPORE 539216 |                 |            |

**5a. Remarks**

|                                                                                                                                        |
|----------------------------------------------------------------------------------------------------------------------------------------|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|----------------------------------------------------------------------------------------------------------------------------------------|

**5b. Estimate Days of Repair**

|                                     |                       |
|-------------------------------------|-----------------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | <b>4 Working Days</b> |
|-------------------------------------|-----------------------|



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLK 7214D

| Qty                                | Description of Parts                                      | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|-----------------------------------------------------------|----------------------|---------------------------|-------------------|
| <b><u>REPLACEMENT OF PARTS</u></b> |                                                           |                      |                           |                   |
| 1                                  | REAR FENDER O/S                                           | BADLY DENTED / BENT  | 1,175.00                  | 1,175.00          |
| 1                                  | REAR FENDER INNER LINER O/S                               | NOT NECESSARY        | 146.00                    | -                 |
| 4                                  | REAR FENDER INNER LINER CLIPS @\$5.00                     | NOT NECESSARY        | 20.00                     | -                 |
| 1                                  | REAR FENDER AIR VENT O/S                                  | NOT NECESSARY        | 72.00                     | -                 |
| 1                                  | REAR BUMPER LOWER PANEL O/S                               | TO REPAIR SEE LABOUR | 102.00                    | -                 |
| 1                                  | REAR BUMPER                                               | DEEP CUT             | 1,075.00                  | 1,075.00          |
| 1                                  | REAR BUMPER SIDE RETAINER O/S                             | BENT                 | 37.00                     | 37.00             |
| 1                                  | REAR BUMPER SIDE HOLDER O/S                               | NOT NECESSARY        | 46.00                     | -                 |
| 4                                  | REAR BUMPER SIDE HOLDER RIVETS @\$6.00                    | NOT NECESSARY        | 24.00                     | -                 |
| 1                                  | REAR DOOR O/S                                             | TO REPAIR SEE LABOUR | 1,006.00                  | -                 |
| 1                                  | REAR DOOR OUTER WEATHERSTRIP MOLDING CHROME               | NOT NECESSARY        | 141.00                    | -                 |
| 1                                  | REAR DOOR WINDOW GLASS CHANNEL WEATHERSTRIP               | NOT NECESSARY        | 117.00                    | -                 |
| 1                                  | REAR WHEEL HUB CAP O/S                                    | CRACKED              | 120.00                    | 120.00            |
| 1                                  | REAR LAMP O/S                                             | CRACKED              | 509.00                    | 509.00            |
| 2                                  | REAR LAMP CLIP HOLDER @\$8.00                             | NOT NECESSARY        | 16.00                     | -                 |
| 1                                  | REAR WINDSHIELD GLASS WEATHERSTRIP                        | NECESSARY            | 124.00                    | 124.00            |
|                                    | LESS 20% DISCOUNT                                         |                      | -946.00                   | -608.00           |
|                                    |                                                           |                      | 3,784.00                  | 2,432.00          |
| <b><u>SPECIAL NETT ITEMS</u></b>   |                                                           |                      |                           |                   |
| 1                                  | REAR WINDSHIELD GLASS WEATHERSTRIP SEALANT (SN)           | NECESSARY            | 180.00                    | 40.00             |
| 1                                  | REAR WINDSHIELD GLASS WEATHERSTRIP SPONGE (SN)            | NECESSARY            | 100.00                    | 30.00             |
|                                    |                                                           |                      | 280.00                    | 70.00             |
| <b><u>LABOUR</u></b>               |                                                           |                      |                           |                   |
|                                    | TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT . |                      | 120.00                    | 60.00             |
|                                    | TO REMOVE AND REFIT REAR WINDSCREEN GLASS .               |                      | 180.00                    | 120.00            |

Report Ref No. CC4/LPC18001220/Uea3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 2

| Qty                                                                  | Description of Parts                                                                                                                                                                              | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|----------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------------|-------------------|
|                                                                      | TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR.                                                                                                            | NOT NECESSARY | 150.00                    | 80.00             |
|                                                                      | TO CHECK ELECTRICAL LIGHTING CONCERNED.                                                                                                                                                           |               | 50.00                     | 20.00             |
|                                                                      | TO TRANSFER OF REAR DOOR FITTINGS AND PERFORM WATER SEEPAGE TEST.                                                                                                                                 |               | 120.00                    | -                 |
|                                                                      | TO REINSTALL OF REAR BUMPER PARKING SENSOR.                                                                                                                                                       |               | 120.00                    | 50.00             |
|                                                                      | PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME, INCLUSIVE OF THE REPAIR OF REAR BUMPER LOWER PANEL O/S AND REAR DOOR O/S. |               | 900.00                    | 700.00            |
|                                                                      | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.                                                                                                                                                 |               | 1,000.00                  | 850.00            |
|                                                                      |                                                                                                                                                                                                   |               | 2,640.00                  | 1,880.00          |
| GRAND TOTAL                                                          |                                                                                                                                                                                                   |               | 6,704.00                  | 4,382.00          |
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) |                                                                                                                                                                                                   |               |                           | 3,500.00          |

Report Ref No. CC4/LPC18001220/Uea3n2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.