REF: AXA

ASSIGNMENT

From: Date: 23/01/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGP 9968 G

at Workshop m/s STUTTGART

of 12 Sungei Kadut Ave

Insured:

Policy No.:

Claims No.:

Sum Insured: Excess:

(Client's Record) Eva

Make of Veh: 10-10.30 am @ owner waiting

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS lwp

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SGP9968G Yr Regn: 28/1/2013

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Porsche Panamera V6 cc 3605

Colour: Black. A/C: Insured / Std / NI / NA

Sp Reading: 82072 T Radio: Insured / Std / NI / NA

Eng No:

C No: WP0ZZZ97ZCL002817

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 255/45R 20 ZR19

R: 285/40 ZR19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	8 mm	R/Bal.	8 mm
L/Bal.	8 mm	L/Bal.	8 mm
D.O.A.	15/1/18	D.O.I.	23/1/2018

Survey held at STUTTGART

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction

Date/Time File Pass to? : Preli. Report

: Final Report

Date/Time File Return to?

Report Format :

Lump Sum / I.B / $

Days Of Repair:

Resurvey No. of Trip:

Add Fee: Site Insp. /$

Interview /$

Tech. Insp. /$

Assistance /$

Survey Fee

Transportation

$ - Pt $

Photos

Other

TOTAL