

CAS, CASE OWNER:

CC 6 /AIG1800 1254, 1/2/18

LKK:

IDAC:

Surveyor:

MARLUS

DOI:

22/1/18

Date / Time:

21/1/18

Registered in Merimen:

22/1/18

Pre-assign / CCU / FTE:



Insured Vehicle No.:

SLM 28675

Name of Insured:

NEW SEMI TRUCK ADRIANO

Insured Tel No.:

HP:

92286118

Excess Sec II :\$5

D.O.A:

20/1/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

LAYDEN PAMM PTE WFE

Driver Tel No.:

98222524

(V/L-YES) NO)

Claim No.:

92508167056

Policy No.:

1300187001

Make / Model:

MILAR

Place of Accident:

KALAMUN WAVE MARUP

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SL7 688X



INSRS:

WSP:

Tel:

Liability:

RMKS:

Din Auto



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time		STAGE	DATE / PIC
22/1/18	5926582-X	Non-Reporting ltr (1st):	
		Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
		Call OI:	
030318	call did confirm accident detail did was at stop line when he in turn out and collided with TP. Inform about TP claim. did from NCD 1551. letter sent to OI.	After call ltr to OI:	7/2/18 CH 143.
		Documentation Check List:	Handler Typist
		Notification ltr (if non-pickup)	
		After call ltr to OI:	
		Authorisation To Act:	
		Release Voucher:	
		Final Repair Bill:	
		Car Rental Invoice:	
		Towing Invoice:	
		LTA / GIA:	
		Medical Bill:	
		PIR:	
		Mandate/Reject Instruction:	
		LOD	
		Payment Breakdown Form:	
		Post-Repair Photos:	
		Others:	

PRELIMINARY ADVICE		Date/Time:	Sent By:
FINALIZATION		Date/Time:	Confirm with:
Repair Cost:	SS	() days	Reduction: %
FINAL SETTLEMENT		Date/Time: 9/9/19	Confirm with: Jopis
Final Liability:	%	(Agreed / Assessed)	BOLA S/N No.:
Repair Cost:	SS 2942.50		
Loss of Rental (LOR):	SS 500.00	(5 days)	x \$100
Loss of Use (LOU):	SS -	(\$ x days)	
Loss of Income (LOI):	SS -	(\$ x days)	
LOR only ☒ LOU only ☐	LOR + LOU ☐ LOR + LOI ☐	[Tick only one]	
GIA/LTA Search	SS -		
Medical:	SS -		
Disbursement:	SS -	(e.g. Tow/Independent)	
Legal Cost:	SS -		
Total:	SS 3442.50	Global Sum SS:	
FINAL PAYMENT		Date/Time:	Confirm with:
Payee 1:	SS 3442.50	Name 1:	Sin Auto Services Pte Ltd
Payee 2: (Strike if N.A.)	SS	Name 2:	
Payee 3: (Strike if N.A.)	SS	Name 3:	

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SGZ 688Xat Workshop m/s: Jin An

of: _____

Insured: SLU 28875

Policy No: _____


Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 60

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res: Yes or NoLum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: 1727786BDate / Time Action / Instruction: 172 42209Date / Time Action / Instruction: Dej 6500 v/c ?Date / Time Action / Instruction: 30/9/2027Date / Time Action / Instruction: L/S - \$2750 (Red \$2338.60 / 46%)Veh No: SGZ 688X Yr Regn: 2007 10Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or (M)Make: Suzuki Swift cc: 1586Colour: yellow A/C: _____ Insured / Std / NI / NASp Reading: 201720 T/Radio: Insured / Std / NI / NA

Eng No: _____

C No: 2C315114678Gen. Cond: Good / Fair / Poor / BurntSteering: Good / Jammed / Leaked / Burnt orBrake: Good / Jammed / Leaked / Burnt orMod: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/55-215

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO

Front: 6 mmR/Bal: 6 mmL/Bal: 6 mmD.O.A: 20/1/18Survey held at: 22/1/18

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

nil body

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time File Pass to?



Preli. Report

1)



Final Report

Date/Time File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee:



Site Insp (\$



Interview (\$



Tech. Insp (\$



Weekend (\$

) \$ + \$ = \$

) Photo

) Other

Report Format: _____

Lump Sum / I.B.I. (\$) _____

TOTAL

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC8/AIG18001254/Uyb3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 22-01-2018	
		Code : AIG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLU 2887S	Veh. Inspected	SGZ 688X
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	22/01/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	20/01/2018	Inspection Date	22/01/2018
Survey held at	JIN AUTO SERVICES PTE LTD BLK 14 DEFU LANE 10 #01-412 SINGAPORE 539195		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62898126 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

Date : 5/7/2019

M/SAIG

Estimate repair Cost For SGZ688X

Qty	No	DESCRIPTION	Nett item
1	1 PC	REAR LH DOOR	\$ 628.00
2	1 PC	FRONT LH DOOR	\$ 659.00
3	1 PC	LH SIDE SKIRT	\$ 267.00
			\$ 1,554.00
		LESS 10% PARTS DISCOUNT	\$ (155.40)
			\$ 1,398.60
REPAIR ITEM:			
4	1 PC	REAR LH FENDER	\$ -
5	1 PC	FRONT LH FENDER	\$ -
6	1 PC	REAR BUMPER	\$ -
7	1 PC	LH ROCKER PANEL	\$ -
8	1 PC	RIM	\$ 670.00
9		Check wiring	\$ 50.00
10		To apply rust proofing	\$ 120.00
11		Spray painting	\$ 1,750.00
12		To Remove And renew Damage parts	\$ 980.00
13		ALIGNMENT	\$ 120.00
			\$ 5,088.60

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before repair spray painting
- To display damaged part(s) during resurvey
- Part prices are subject to confirmation
- Third party survey is on a "without prejudice" basis
- No Disputes will be allowed
- Supplementary works must be authorised and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Page 1 of 1

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7786B
Vehicle Details	
Vehicle No.:	SGZ688X
Vehicle to be Exported:	No
Intended De-registration Date:	22 Jan 2018
Vehicle Make:	SUZUKI
Vehicle Model:	SWIFT SPORT 1.6 M
Primary Colour:	Yellow
Manufacturing Year:	2007
Engine No.:	M16A1253353
Chassis No.:	ZC31S114678
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$15,788.00
Original Registration Date:	01 Oct 2007
First Registration Date:	01 Oct 2007
Transfer Count:	4
Actual ARF Paid:	\$17,367.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Sep 2027
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$44,081.00
COE Rebate Amount:	\$42,709.00
Total Rebate Amount:	\$42,709.00

The information contained herein is correct as at 22 Jan 2018

OK



Swift Price Range Depreciation > 10 year Vehicle Type Submit Advanced Search

Home > Used Cars > Tay Motor & Credit Pte Ltd > Suzuki Swift Sport 1.6A (COE till 11/2027)

Tools & Tips

- [Car Buying](#)
- [Car Selling](#)
- [Car Aftermarket](#)
- [Car Ownership](#)
- [On The Move](#)
- [Lifestyle](#)

Car Leasing



Suzuki Swift Sport 1.6A (COE till 11/2027)

[Overview](#) [Financial](#) [Accessories](#) [Similar](#) [Research](#) [Photos](#) [Map](#)

TAY MOTOR & CREDIT PTE LTD

Our Accreditation:



[Add to Shortlist](#) [Add to Compare](#) [Add a Note](#) [Report Error](#) [More Actions](#) [Share](#)

Car Details

Price	\$60,800
Depreciation	\$6,170 /yr
Reg Date	26-Nov-2007 (9yrs 10mths 3days COE left)
Manufactured	2007
Mileage	89,000 km (8.8k /yr)
Transmission	Auto
Engine Cap	1,586 cc
Road Tax	\$810 /yr
Power	92.0 kW (123 bhp) View specs of the Suzuki Swift
Curb Weight	1,100 kg
Features	Powerful 1.6L DOHC VVT Engine Producing 121 Bhp, Smooth Auto Transmission, 8 x Airbags, Twin Exhausts, Knockdown Rear Seats, ABS Plus EBD, Fog Light
Accessories	Original Factory Fitted Sports Seats, Integrated Factory Audio System, Factory Original Bodykit And Spoiler, Multi Steering Control, Solar Film
Description	Too Good To Be Miss! Beautiful Original Condition, Accident Free, Low Depreciation, Easy To Maintain, Nice Number.
COE	\$41,994
OHV	\$13,131
ARF	\$14,447
Dereg Value	\$41,350 as of today (margin)
No. of Owners	2
Type of Veh	HATCHBACK
Category	COE Car, Low Mileage Car
Availability	Available

[Add to Shortlist](#) [Add to Compare](#) [Add a Note](#)

Posted on: 23-Jan-2018 | Last Updated on: 24-Jan-2018
Type: Suzuki Swift, 2007 Suzuki Swift, Suzuki Swift, Used Suzuki



Seller Information

Company	Tay Motor & Credit Pte Ltd	
	• dealer's profile	
	• 25 vms sold 32 vms available	
Address	210 Turf Club Road Lot A3/A5/B20	
	Search cars nearby this location	
Location	Car Mall @ The Greenfield	
Contact Person(s)	Dennis Huang	91175113
	Ben Poh	90602520

Upfront Payment

[View Finance Info](#)

Transfer Fee	\$25
Down Payment	\$18,240 (margin)
1st Instalment	\$640
Total Upfront Payment	\$18,905 (including insurance)

Estimates based on 20% loan at 3.75% interest rate. Check with seller for exact figure.

Items for Suzuki Swift

[View All](#)

	Driver FPG 15" / 16" / 18" Wires
	From \$280
	Swift Plate
	\$100

[Used Car List](#) | [Compare Profile](#)



Make sure of the car condition with STA Evaluation

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62898126 Fax :62870590

Business Registration No:200704370C GST Registration No:200704370C

16/07/2019

Your ref: *LKK REF:CC6/AIG18001254/Umb3

Without Prejudice

C/O LKK Auto Consultants Pte Ltd
51 Ubi Ave 1
#01-25 Paya Ubi Industrial Park
(S) 408933

Dear Sirs,

ACCIDENT INVOLVING VEHICLE SGZ688 X AND SLU287S ON 20/1/2018

. we are now seeking the total amount of claim as follow:

Repair cost	S\$2942.50(with gst)
Rental	600.00

TOTAL S\$ 3542.50

We shall appreciate if you could kindly consider our claim at your earliest convenience and kindly let us have your acknowledgement of receipt of this letter within 14days of your receipt of this letter.

Yours faithfully



Jouis Seow (Email: jouis@jinauto.com.sg)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC6/AIG18001254//Umb3

09 MARCH 2018

LIEW SENG TECK ADRIAN
209 ANG MO KIO AVENUE 3
#09-1588
SINGAPORE 560209

Dear Sir/Madam,

ACCIDENT INVOLVING SLU 2887S AND SGZ 688X ON 20/01/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Bevan Lim
Case Handler
DID: 6749 4274
FAX: 6741 4108
Email: vicalpeh@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

LETTER OF AUTHORISATION

To: Jin Auto Services Pte Ltd

Dear Sir

ACCIDENT INVOLVING SG7Z688X & SLU28875 ON 20/1/18.

I/We, the owner of Vehicle Registration Number SG7Z688X hereby authorise you to repair my/our vehicle repair, submit, correspond, negotiate and settle my/our claim for cost of repair and/or uninsured losses arising from the above accident.

I/We further authorise you M/S Jin Auto Services Pte Ltd, to execute, sign, seal and deliver all documents whatsoever in relation to this matter and to accept and receive any payment due to me/us in respect of my/our claim above.

I/We hereby declare that all acts and documents done by virtue of this Letter of Authorisation on my /our behalf shall be good valid and effectual to all intents and purposes whatsoever as if the same had been done or executed by me/us in person.

I/We further confirm that the acceptance by M/s Jin Auto Services Pte Ltd of the settlement amount in respect of such claim shall constitute the full discharge of my/our claim in respect of such loss and damage.

Signed by:

Name:

NRIC NO:

Date:

Chiaf Wee Hwa
SG7Z688X
20/1/18

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, JIN AUTO SERVICES PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$2,942.50 (Repair Cost), S\$500.00 (Loss of Use/Rental), S\$ - (Disbursement) for vehicle no. SGZ 688X that was damaged pursuant to the accident which occurred on 20/01/2018 (date) along KALLANG WAVE MALL (location) involving vehicle no/s SLU 2887S. This is pursuant to the inspection conducted on 22/01/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner CHIANG WEE HWA ("the third party claimant") of vehicle no. SGZ 688X make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SGZ 688X (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 4th (day) of Sept (month) 2019 (year)



CKS

Signed by appointed surveyor



Signed by "the workshop" (with chop)

JIN AUTO SERVICES PTE LTD



DAWN ENTERPRISES

21 Seletar West Farmway 1
Singapore 798125

Tel: 63832661 Fax: 64842836
Reg No. 430058/00D

Nº 35244

RENTAL AGREEMENT

DATE

22/1/18

HIRER'S PARTICULARS

Name Chiang Wee Hwa.
Address Blk 121 McNair Road #
#02-21 (S) 320121.

I/C or Passport No. S77277868 Country S'pore.

Occupation -

Date of Birth - Age -

Driving Licence No. - Date Passed -

Tel: (HP) - (Residence) -

DRIVER'S PARTICULARS

Name -

Address -

I/C or Passport No. - Country -

Occupation -

Date of Birth - Age -

Driving Licence No. - Date Passed -

Tel: (Office) - (Residence) -

IMPORTANT NOTES:

1. No insurance coverage if the driver is below 24yrs old or less than 2 years driving license.
2. This vehicle is licensed to carry passengers only.
3. Hirer is liable to pay first \$ as excess all claims any accident plus cost of repairing while damaged vehicle is under repair.
4. For usage in Malaysia subject to higher excess all claims of \$25,000.00 and different rental rate.
5. Please notify our office should there be any accident involving this hired vehicle within 24 hrs.
6. No refund will be given for vehicle returns early.
7. No refund will be given for petrol left in vehicle.
8. Hirer is liable to pay all parking fee and traffic summonses.
9. Vehicles to be return during office hour only.
10. No Service on Public Holiday and Sunday.

SCHEDULE

MODEL

334 S730T T/A11S

Date	Time	Mileage
<u>22/1/18</u>	<u>1pm</u>	
<u>27/1/18</u>	<u>2:40pm</u>	

CHARGES

<u>\$</u> Day at <u>\$ 120</u> per days	<u>\$ 600.00</u>
Day at \$ per week	
Day at \$ per month	

TOTAL AMOUNT

\$ 600.00

AMOUNT PAID

\$ 600.00

BALANCE DUE

Days Extension From To

Amount Deposit (refundable) \$

FROM

22/1/18

TO

27/1/18

I/we have read and understood the terms and conditions above and hereby agreed to abide

X H

Hirer's Signature

Driver/Gurantor's Signature

DAWN ENTERPRISES

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Jan 2018 Edit Reg		22 Jan 2018 00:00 Edit Adj Rpt	S\$2,750.00 Edit Estimates	S\$2,750.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:

LIEW SENG TECK ADRIAN (LIU CHENGZHU ADRIAN), Co. Reg. No.: S74327853

Main Claimant:

CHIANG WEE HWA, ID: S77277868

Vehicle Reg. No.:

SGZ688X

Date of Loss:

20/01/2018 00:00 - :59
[123 Months and 19 Days From LTA Reg Date (Man Yr)]

Claim Type:

TP / 8450816710SG

Policy/Cover Note No.:

1700087461 (Comprehensive)
Coverage: 28/11/2017 - 27/11/2019

Vehicle Reg. No. (Insured):

SLU28875

Policy No. (Claimant):

PNPV2017-00002632

Excess:

Repairer:

Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412, 539195 Defu Lane - Tel: 6289 8126

Handling Insurer:

AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Wui, Shawn-KJ] Shawnkaijye.Wui@aig.com

Claimant's Insurer:

FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 31/01/2018]

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

- AIG_SG (23/01/2018): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGZ688X (8450816710SG)

[SLU2887S]

TP

CHIANG WEE HWA

Jan 20 2018 12:00AM

[LIEW SENG TECK ADRIAN (LIU CHENGZHU ADRIAN)]

Jin Auto Services Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View [View in Browser](#)

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	(Draft)	Third Party Express Settlement – Payment Breakdown		Edit	

Assessment Reports				1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print	
1	23/01/18 13:49	Accident Statement From: OD - Reg. No: SLU2887S, Claimant: LIEW SENG TECK ADRIAN		Load HTM	

Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	22/01/18 15:37	Odometer Reading		Load JPG	☒
2	22/01/18 15:37	General View		Load JPG	☒
3	22/01/18 15:37	Chassis Number		Load JPG	☒
4	22/01/18 15:37	General View		Load JPG	☒
5	22/01/18 15:37	General View		Load JPG	☒
6	22/01/18 15:37	General View		Load JPG	☒
7	22/01/18 15:37	General View		Load JPG	☒
8	22/01/18 15:37	General View		Load JPG	☒
9	22/01/18 15:37	General View		Load JPG	☒
10	22/01/18 15:37	General View		Load JPG	☒
11	22/01/18 15:37	General View		Load JPG	☒
12	22/01/18 15:37	General View		Load JPG	☒
13	22/01/18 15:37	General View		Load JPG	☒
14	22/01/18 15:37	General View		Load JPG	☒
15	22/01/18 15:37	General View		Load JPG	☒
16	22/01/18 15:37	General View		Load JPG	☒
17	22/01/18 15:37	General View		Load JPG	☒
18	22/01/18 15:37	General View		Load JPG	☒
19	22/01/18 15:37	General View		Load JPG	☒
20	22/01/18 15:37	General View		Load JPG	☒
21	22/01/18 15:37	General View		Load JPG	☒
22	22/01/18 15:37	General View		Load JPG	☒
23	22/01/18 15:37	General View		Load JPG	☒
24	22/01/18 15:37	General View		Load JPG	☒
25	22/01/18 15:37	General View		Load JPG	☒
26	22/01/18 15:37	General View		Load JPG	☒
27	22/01/18 15:37	General View		Load JPG	☒
28	22/01/18 15:37	General View		Load JPG	☒
29	22/01/18 15:37	General View		Load JPG	☒
30	22/01/18 15:37	General View		Load JPG	☒
31	22/01/18 15:37	General View		Load JPG	☒
32	22/01/18 15:37	General View		Load JPG	☒
33	22/01/18 15:37	General View		Load JPG	☒
34	22/01/18 15:37	General View		Load JPG	☒
35	22/01/18 15:37	General View		Load JPG	☒
36	22/01/18 15:37	General View		Load JPG	☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				☒
37	22/01/18 15:37	General View	 Load JPG	☒
38	22/01/18 15:37	General View	 Load JPG	☒
39	22/01/18 15:37	General View	 Load JPG	☒
40	22/01/18 15:37	General View	 Load JPG	☒
41	22/01/18 15:37	General View	 Load JPG	☒
42	22/01/18 15:37	General View	 Load JPG	☒
43	22/01/18 15:37	General View	 Load JPG	☒
44	23/01/18 15:48	Reinspection Photo	 Load JPG	☒
45	23/01/18 15:48	Reinspection Photo	 Load JPG	☒
46	23/01/18 15:48	Reinspection Photo	 Load JPG	☒
47	23/01/18 15:48	Reinspection Photo	 Load JPG	☒
48	23/01/18 15:48	Reinspection Photo	 Load JPG	☒
49	23/01/18 15:48	Reinspection Photo	 Load JPG	☒
50	23/01/18 15:48	Reinspection Photo	 Load JPG	☒
51	23/01/18 15:48	Reinspection Photo	 Load JPG	☒
52	23/01/18 15:48	Reinspection Photo	 Load JPG	☒
53	23/01/18 15:48	Reinspection Photo	 Load JPG	☒
54	23/01/18 15:48	Reinspection Photo	 Load JPG	☒
55	10/07/19 07:53	Reinspection Photo	 Load JPG	☒
56	10/07/19 07:54	Reinspection Photo	 Load JPG	☒
57	10/07/19 07:54	Reinspection Photo	 Load JPG	☒
58	10/07/19 07:54	Reinspection Photo	 Load JPG	☒
59	10/07/19 07:54	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/01/18 10:57	TP GIA REPORT	 Load PDF	
2	08/03/18 15:53	LETTER TO OI	 Load PDF	
3	18/09/19 09:50	WORKSHOP INVOICE	 Load PDF	
4	18/09/19 09:50	AUTHORISATION TO ACT FORM	 Load PDF	
5	18/09/19 09:50	Release Voucher	 Load PDF	
6	18/09/19 09:50	RENTAL RECEIPT	 Load PDF	
7	18/09/19 09:50	LOD	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLU2887S (Insd veh)	Model:	SUZUKI SWIFT 1.2 (A)
	SGZ688X (TP veh)		
Date of Accident:	20/01/2018		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	5,444.80
Final Repair Cost	:	\$	2,942.50
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	500.00 5 days
LTA / GIA Search Fee	:	\$	0.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	3,442.50

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For **Non GIA Registered Workshop**: Agreed Liability _____ 100 _____ (%)

B) For **GIA Registered Workshop**: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Jin Auto Services Pte Ltd	:	\$ 3,442.50
2)		:	\$

JOANNE LEE KHANG MIN

18 Sep
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18001254/JDB3Q2

Date: 18/09/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700087461
Claimant SGZ688X **Insured Vehicle No :** SLU2887S
Vehicle No : **Date of Loss:** 20/01/2018 **Nature of Claim:** TP **Claim No:** 8450816710SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGZ688X**
 Make & Model: SUZUKI SWIFT, 1.2 (A) Engine No: M16A1253353
 Reg. Date: 01/10/2007 (Man. Year: 2007) Chassis No: ZC31S114678
 Colour: Yellow Odometer: 201720 km
 Engine Capacity: 1586 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55 R15 Rear Tyre Size: 195/55 R15
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,068.60	1,800.90	267.70	12.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,020.00	1,640.00	1,380.00	45.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,088.60	3,440.90	1,647.70	32.38
Approved Total (Overridden) (S\$)		2,750.00		
(S\$)	5,088.60	2,750.00	2,338.60	45.96
+ GST 7.00/7.00% (S\$)	356.20	192.50	163.70	45.96
Nett Amount (S\$)	5,444.80	2,942.50	2,502.30	45.96
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
Nett Liability (S\$)		3,442.50		

INSPECTION

Date of Assignment: 22/01/2018
 Date Inspected: 22/01/2018 Inspected At: Jin Auto Services Pte Ltd (Defu)
 Blk 14 Defu Lane 10, #01-410/412
 Singapore 539195
 Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR LH DOOR	Dented / Bent	628.00 FL	*628.00 FL
2	1		*FRONT LH DOOR	Badly Dented	659.00 FL	*659.00 FL
3	1		*LH SIDE SKIRT	Deformed / Warped	267.00 FL	*267.00 FL
4	1		*REAR LH FENDER (NPA)	Repair	0.00 FS	*- FS
5	1		*FRONT LH FENDER (NPA)	Not Necessary	0.00 FS	*- FS
6	1		*REAR BUMPER (NPA)	Not Necessary	0.00 FS	*- FS
7	1		*LH ROCKER PANEL (NPA)	Repair	0.00 FS	*- FS
8	1		*RIM	Cut	670.00 FS	*480.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,224.00	2,034.00
- List Item Discount on L Items 10.00/15.00% (\$\$)	155.40	233.10
Total Parts (\$\$)	2,068.60	1,800.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK WIRING	New	50.00	20.00
2	TO APPLY RUST PROOFING	New	120.00	60.00
3	SPRAY PAINTING	New	1,750.00	1,000.00
4	TO REMOVE AND RENEW DAMAGE PARTS	New	980.00	500.00
5	ALIGNMENT	New	120.00	60.00
Gross Labour Cost (S\$)			3,020.00	1,640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >