

Form

ASS. REC. BY:

REF: CS/MSG18001263/Rlad3

Special Instruction:

Signature: Meimen Rasul

ASSIGNMENT (Office)

From (Person): Jocelyn Ng

of MSIG

Date/Time: 19/01/18 @ 3:57pm

Estimated Cost:

Bill to:

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLN 972D

Insured:

at Workshop m/s Volkswagen

Tel: 6305 7288

of 247 Alexandra Road

Policy No: A28947081AVW

Claim No: 545988

Sum Insured:

Excess: \$1,500.00

Make of Veh:
(Client's Record)

D.O.A. 13/01/2018

CA / ☒ REV / REP. / REV 24 HRS

H.O.B. Endorsement:

Date/Time: 5:47pm @ 19/01/18

Person Contacted:

May Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimat
	<u>SLN 972D -x</u>
<u>23/1/18 @ 12:18pm</u>	<u>Verent to Jocelyn Ng via Meimen.</u>
<u>23/1/18 @ 5:07pm</u>	<u>Keng Ong informed C/A via Meimen.</u>
<u>24/1/18 @ 9:32am</u>	<u>Informed May C/A & Ex: \$1500 by email.</u>
<u>16/4/18 @ 2:20pm</u>	<u>confirmed with Jocelyn final fig \$7505.71, 4 days.</u>
	<u>ided \$4543.36, 38%.</u>

✓ 16/4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18001263/R1qd3		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 22-01-2018		
		Code : MSG		
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.	Veh. Inspected		SLN 972D	
Policy No.	A28947081AVW	Coverage (\$)	0.00	
Claim No.	545988	Excess (\$)	1,500.00	
Assign From	MERIMEN (JOCELYN NG)"	Assign Date	22/01/2018	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	Steering			
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	13/01/2018	Inspection Date	22/01/2018	
Survey held at	VOLKSWAGEN CENTRE SINGAPORE 247 ALEXANDRA ROAD SINGAPORE 159934			
5a. Remarks				
A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Jan 2018		19 Jan 2018 15:57 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured: RICHARD BUCKLEY, ID: S2745150J, Tel: +6596230450, Email: rbuckley@singnet.com.sg		[Created by insurer]	
Vehicle Reg. No.: SLN972D	Date of Loss: 13/01/2018 09:00 - :59		
Claim Type: OD / 545988	Policy/Cover Note No.: A28947081AVW (Comprehensive) Coverage: 21/04/2017 - 20/04/2018		
	Excess: S\$1,500.00		
Repairer: Volkswagen Centre Singapore (HQ) 247 Alexandra Road, 159934 Alexandra - Tel: 63057288			
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jocelyn Ng Shin Bun]			
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 20/01/2018]			
Driver/Custodian: RICHARD BUCKLEY (50 / Male), NRIC: S2745150J, Tel: +6596230450			
Adj Asg. Remarks: Please revert, thank you			

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Jocelyn Ng

From: Eliza Ho
Sent: Tuesday, 16 January, 2018 5:23 PM
To: Wong, Mei (VWG Singapore)
Cc: Jocelyn Ng
Subject: RE: SURVEY FOR VEHICLE SLT9729A -OD CLAIM

Dear Mei,

Content noted, surveyor admin will contact you to arrange for survey.
PIC – Jocelyn
Vehicle: SLT972A

Eliza Ho
Assistant Executive, Claims Services (Motor)
D: +65 6594 2554 | F: +65 6225 7402 | eliza_ho@sg.msig-asia.com



MSIG



Insurer Claims
Team of the Year
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

From: Woon Choo Kwok
Sent: Tuesday, 16 January, 2018 5:09 PM
To: Eliza Ho <Eliza_Ho@sg.msig-asia.com>
Cc: Christopher Chionh <christopher_chionh@sg.msig-asia.com>; Foo Ai Ngoh <aingoh_foo@sg.msig-asia.com>; Jason Sim <Jason_Sim@sg.msig-asia.com>
Subject: FW: SURVEY FOR VEHICLE SLT9729A -OD CLAIM

Dear EH

FYA

Best Regards

Kwok Woon Choo
Senior Administrative Officer, Claims Services
Direct line +65 6643 1330 | Direct fax +65 6225 7402 | woonchoo_kwok@sg.msig-asia.com



MSIG



Insurer Claims
Team of the Year
2016



A Member of **MS&AD** INSURANCE GROUP

From: Agnes Lee

Sent: Tuesday, January 16, 2018 4:38 PM

To: Woon Choo Kwok <WoonChoo_Kwok@sg.msig-asia.com>

Subject: FW: SURVEY FOR VEHICLE SLT9729A -OD CLAIM

From: Wong, Meiy (VWG Singapore) [<mailto:meiy.wong@vw.com.sg>]

Sent: 16 January 2018 15:49

To: Claims <claims@sg.msig-asia.com>

Cc: Cheong, Pearlyn (VWG Singapore) <Pearlyn.cheong@vw.com.sg>; Kong, Charmaine (VWG Singapore) <charmaine.kong@vw.com.sg>; Goh, Edmund (VWG Singapore) <edmund.goh@vw.com.sg>

Subject: SURVEY FOR VEHICLE SLT9729A -OD CLAIM

Dear Claims,

Please kindly assign surveyor for this claim(Car not in workshop)

Thanks and Best Regards,

Meiy
Insurance Service Advisor
Aftersales

Volkswagen Group Singapore Pte Ltd
247 Alexandra Road
Singapore 159934


Direct line: +65 6305 7216

Main Line: +65 6305 7299

Main Fax: +65 6474 3643

meiy.wong@vw.com.sg

<http://www.vw.com.sg>



It's not e-mail, if you print it. Think Blue.

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Monday, 16 April 2018 2:20 PM
To: 'Cheong, Pearlyn (VWG Singapore)'; Rasul (LKKAuto); SUR; Admin A; Admin-D (LKKAuto)
Cc: Kong, Charmaine (VWG Singapore); Wong, Mei (VWG Singapore); Foo, John (VWG Singapore)
Subject: RE: SLN972D - FINALISE

Dear Pearlyn,

Confirm final fig \$7,505.71 before excess \$1,500.00 & GST and 4 repair days.

Please send the relevant documents to insurance company.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Cheong, Pearlyn (VWG Singapore) [mailto:Pearlyn.cheong@vw.com.sg]
Sent: Tuesday, 10 April 2018 3:31 PM
To: Rasul (LKKAuto) <Rasul@lkkauto.com>; SUR <sur@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>
Cc: Kong, Charmaine (VWG Singapore) <charmaine.kong@vw.com.sg>; Wong, Mei (VWG Singapore) <meiy.wong@vw.com.sg>; Foo, John (VWG Singapore) <John.Foo@vw.com.sg>
Subject: SLN972D - FINALISE

Dear Rasul,

Please confirmed

COR \$6005.71 after excess before GST.

Best regards,

Pearlyn Cheong
Service Advisor
Aftersales Body & Paint Department

Volkswagen Group Singapore (Alexandra)
247 Alexandra Road
Singapore 159934

Direct line: +65 6305 7288
Mobile : +65 9236 1336
Main line: +65 6305 7299
Main Fax: +65 6474 3643
pearlyn.cheong@vw.com.sg
<http://www.vw.com.sg>

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Wednesday, 24 January 2018 9:35 AM
To: Cheong, Pearlyn (VWG Singapore); Kong, Charmaine (VWG Singapore); Wong, Meiy (VWG Singapore); Tang, Shu Shi (VWG Singapore); Ong, Germaine (VWG Singapore)
Cc: Foo, John (VWG Singapore); SUR
Subject: VEHICLE SLN 972D (DOA: 13/01/2018)

Dear Meiy,

As instructed by our client, please proceed to repair the insured vehicle **SLN 972D (Excess \$1,500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sjewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	15 Jan 2018 11:15	Cim Veh Model Changed	(204324) VOLKSWAGEN PASSAT B8 1.8 TFSI (A).	[I] Jocelyn Ng Shin Bun
2	15 Jan 2018 11:15	Cim Created	Reg No: SLN972D. Policy No: A28947081AVW. Acct Date: 2018/01/13. Claim Type: SC. Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ). Ins.Status => Notification. Created from SAS:MVGSI8006576	[I] Jocelyn Ng Shin Bun
3	16 Jan 2018 17:29	Notification Status Changed	Ins.Status => Incoming Claim	[I] Jocelyn Ng Shin Bun
4	16 Jan 2018 17:29	Cim Registration Modified	Setl.Type:3->0. Rep:1137->200843. Claim Type:SC->OD.	[I] Jocelyn Ng Shin Bun
5	16 Jan 2018 17:32	Adj Co Assigned	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor):a if c	[I] Jocelyn Ng Shin Bun
6	16 Jan 2018 17:32	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2018/01/17	[I] Jocelyn Ng Shin Bun
7	16 Jan 2018 17:32	Adj Mandate Set	Approved:25000.00,Reinsp:Adj decides.	[I] Jocelyn Ng Shin Bun
8	17 Jan 2018 09:32	Assignment 1st Accessed		[A] Ho Pei Fang
9	19 Jan 2018 15:54	Adj Assignment Cancelled	Survey - Owner waiting 9.30am on 22/1/18 (AL-See doc, ET-Appt full, DC-W/sh op visit excluding VW & PML)	[I] Jocelyn Ng Shin Bun
10	19 Jan 2018 15:54	Adj Est Details Deleted	Deleting Est Details For Cancelling Adjuster Assignment	[I] Jocelyn Ng Shin Bun
11	19 Jan 2018 15:57	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):Please revert, thank you	[I] Jocelyn Ng Shin Bun
12	19 Jan 2018 15:57	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2018/01/20	[I] Jocelyn Ng Shin Bun
13	19 Jan 2018 15:57	Adj Mandate Set	Approved:25000.00,Reinsp:Adj decides.	[I] Jocelyn Ng Shin Bun
14	19 Jan 2018 15:58	Assignment 1st Accessed		[A] CATHERINE CHONG KAI LING
15	22 Jan 2018 15:26	Adj Adjuster Assigned	[None] -> MOHD RASUL	[A] Nivitha Govindasamy
16	23 Jan 2018 12:14	Adj Rpt Initiated		[A] SHIAU CHAN
17	23 Jan 2018 12:17	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/02/18	[A] SHIAU CHAN
18	23 Jan 2018 12:17	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/02/18	[A] SHIAU CHAN
19	23 Jan 2018 12:18	Adj Mandate Request	Cur.Req:9674.07:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
20	23 Jan 2018 17:07	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/02/18. Mandate Remarks: A IF C	[I] Keny Ong Thiam Beng
21	23 Jan 2018 17:07	Adj Mandate Set	Approved:8506.03:A IF C	[I] Keny Ong Thiam Beng

ACTIVITY

[19/01/2018 09:55] Ho Pei Fang:
Mely confirmed survey appt next monday at 9.30am, owner waiting. Refer email attached.
[17/01/2018 09:33] Ho Pei Fang:
Pending for workshop to arrange survey appt.

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1702811	23/01/2018 12:14	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLN972D		10.70

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607138R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jocelyn Ng Shin Bun

Date: 23 Jan 2018

Preliminary Advice

Vehicle No	: SLN972D	Accident Date	: 13/01/2018
Make	: VOLKSWAGEN PASSAT B8	Policy No.	: A28947081AVW
Assignment Date	: 19/01/2018	Excess	: S\$1,500.00
Date of Inspection	: 22/01/2018	Est. Duration of Repair	: 4.00
Inspection At	: VOLKSWAGEN CENTRE SINGAPORE (HQ) 247 ALEXANDRA ROAD SINGAPORE 159934		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,099.07
Revised Amount	:S\$	8,506.03
Check Items (Estimated)	:S\$	1,168.04
Total	:S\$	9,674.07
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	139,000.00
COE / PARF Rebate	:S\$	73,522.00
Salvage Value	:S\$	
Margin for Repair	:S\$	65,478.00

Remarks

- (X) The vehicle is economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.
WE HAVE NOT AUTHORISE REPAIR.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5150J
Vehicle Details	
Vehicle No.:	SLN972D
Vehicle to be Exported:	No
Intended De-registration Date:	23 Jan 2018
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	PASSAT B8 1.8 TFSI AT SR NAV 17W 3G24JZ
Primary Colour:	Brown
Manufacturing Year:	2016
Engine No.:	CJS178778
Chassis No.:	WVWZZZ3CZHE055622
Maximum Power Output:	132.0 kW (177 bhp)
Open Market Value:	\$31,412.00
Original Registration Date:	21 Apr 2017
First Registration Date:	21 Apr 2017
Transfer Count:	0
Actual ARF Paid:	\$30,977.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Apr 2027
PARF Rebate Amount:	\$23,232.00
Intended COE Rebate Details	
COE Expiry Date:	20 Apr 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$54,405.00
COE Rebate Amount:	\$50,290.00
Total Rebate Amount:	\$73,522.00

The information contained herein is correct as at 23 Jan 2018

OK

MSG (winner)
OD onf

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/01/2018 11:53
Date Of Accident	13/01/2018 09:15
Exact Location Of Accident	AT GIM MOH HDB MULTISTOREY CAR PARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLN972D
Insured/Policyholder	
Name Of Registered Owner	RICHARD BUCKLEY
NRIC No	S2745150J
Email Address	RBUCKLEY@SINGNET.COM.SG
Mobile Phone No	(LOCAL) +65-96230450
Alternative Phone No	OFFICE-96230450

Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	PASSAT 1.8 TSI HIGHLINE17IN
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A 28947081 AVW
Cover Note Number	

Driver

Name of Driver	RICHARD BUCKLEY
NRIC No	S2745150J
Date Of Birth	31/10/1967
Occupation	INDOOR
Date Of Driving Pass	06/01/1998
Driving Experience	20 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96230450
Fax Number	
Contact Number	OFFICE-96230450
Email Address	RBUCKLEY@SINGNET.COM.SG

Address	22 WILBY ROAD #01-15
Postcode	276306
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : JENNIFER BUCKLEY GENDER: : FEMALE
Passenger 2	NAME: : BRENNAN BUCKLEY GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
if Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

FOR MORE DETAILS PLEASE REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Parked next to a bollard which was lower than line of sight. When pulled out of parking space moving forward with left turn the side hit the bollard.

Bollard = Pillar

Gim Moh HDB Multi Story car park top floor next to lift lobby

Sat 13TH JAN 2018 @ 09.12

DECLARATION

I/We declare the foregoing particulars are true in every respect.

R Buckle
Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

my
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Class 2B
Class 2A
Class 2
Class 1

Motorcycles - 200 cc
Motorcycles between 201 cc and 400 cc
Motorcycles - 400 cc
Motor Cycles - 200 kg with not passengers, weight of the driver, and other driver vehicles - 200 kg

Valid Date
01 Jan 1990
01 Jan 1990
01 Jan 1990
01 Jan 1990



NP 425A

SLN 972D

A 28147081 km

\$1.5k excess

50% - Yes protected

96230450

22 WILBY ROAD

#01-15

~~SEITE~~



rbuckley@singnet.com.sg

Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo




Accident Photo




Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



02/01/18 -> Invoice.

MSIG (winner)

PDI TUAS

OD email: 16/01/18

PDI TUAS

RICHARD BUCKLEY
22 WILBY ROAD
#01-15
Singapore, 276306
Singapore

96230450
27/01/18 - 9:30am

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV037073
Quote No. SER/QUO/1800074
QuoteDate 13/01/18
Salesperson Shawn Lim
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	Passat 1.8 TSI Highline17in	6,551	Cheong Pearlyn
License No.	VIN	Initial Registration	Sales Advisor
SLN972D	WVWZZZ3CZHE055622	21/04/17	Shawn Lim
Engine Code	Labor Type	Engine No.	Model Code
	1P	CJS 178778	3G24JZ

No.	Description	Qty.	UoM	Unit Price	Amount
P B&P ALEX LABOUR	LABOUR	4	UNIT		950 1,900.00
P B&P ALEX LABOUR	TRANSFER DOOR PARTS	2	UNIT		475 950.00
P B&P ALEX PAINT	SPRAY PAINT	4	UNIT		100 400.00
P B&P DIAG	PROGRAMMING & CALIBRATION COMPULSORY TO DO AFTER AC	1	Time Un		360.00
P B&P MECH	ELECT WIRING & MECH COMPO	1	Time Un		200.00
	Nett				
	Sum Labor				5,410.00
P 3G0831055R	DOOR LHF Use Predecessor 3G0831055Q	1	Pieces	1932.74	2,421.45
P 3G0837461C	WINDOW REGULATOR LHF Predecessor 3G0837461C	1	Pieces	for ?	613.83
P 3G0837651C	DOOR LOWER SEAL LHF Use Predecessor 3G0837651B	1	Pieces	151.93	211.02
P 3G0837701C 5AP	DOOR SEAL LHF Predecessor 3G0837701B 5AP	1	Pieces	201.55	279.93
P 3G0837915B	INNER COVER FOR LHF DOOR WINDOW REGULATOR LHF	1	Pieces	for ?	44.89
P 3G0839699B	DOOR LOWER SEAL LHR Use Predecessor 3G0839699A	1	Pieces	66.12	91.84
P 3G0853267 GRU	COVER MOULDING LHF DOOR	1	Pieces	66.03	92.26
P 3G0853331A 3Q7	MOLDING LHF DOOR	1	Pieces	107.34	204.64
P 3G0853333A 3Q7	MOLDING LHR DOOR	1	Pieces	74.79	103.87
P 3G0853777 GRU	COVER MOULDING LHR DOOR	1	Pieces	2078	30.25
P 3G5833055AC	DOOR LHR Use Predecessor 3G5833055R	1	Pieces	1131.24	1,571.16

Sum carried forward

11,075.14

Payments to: - BBN: - Acc.-No.:

PDI TUAS

PDI TUAS

RICHARD BUCKLEY
22 WILBY ROAD
#01-15
Singapore, 276306
Singapore

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV037073
Quote No. SER/QUO/1800074
QuoteDate 13/01/18
Salesperson Shawn Lim
Page 2

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	Passat 1.8 TSI Highline17in	6,551	Cheong Pearlyn
License No.	VIN	Initial Registration	Sales Advisor
SLN972D	WVWZZZ3CZHE055622	21/04/17	Shawn Lim
Engine Code	Labor Type	Engine No.	Model Code
	1P	CJS 178778	3G24JZ

		Continued	11,075.14
P 3G5839701B 5AP	DOOR SEAL LHR	1 Pieces	154.88 <i>see</i> 215.11
P 510837205K GRU	HANDLE LHF	1 Pieces	419.49 <i>see</i> 582.63
	Use Predecessor 510837205G GR		
P 8X4833407B	HINGE UPPER LH REAR DOOR	1 Pieces	83.95 <i>see</i>
P D 378500A2	DOOR INSULATOR	2 Pieces	103.42 <i>see</i> 142.24
	Sum Item		6,689.07

Sum Labor	5,410.00
Sum Item	6,689.07

Total	SGD	12,099.07
7% GST	12,099.07	846.93
Total SGD Incl. GST		12,946.00

Explanations

P = Proportionately Charged

Payment Terms

No Credit

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Payments to:

- BBN: - Acc.-No.:

Resue
Hp 90010068
4 days
22/01/18 @ 0930
EXCESS: 1500
Repair
Repairing by paint

Service Order Confirmation

SERVICE ORDER NO: 18IP0211
 CUSTOMER NO.: CV037073
 CUSTOMER NAME: RICHARD BUCKLEY
 TELEPHONE NO.:
 ADDRESS: 22 WILBY ROAD #01-15
 Singapore

VEH No.: SLN972D

Order Date: 22/01/18
 Reg Date: 21/04/17 KM: 11,466
 VIN NO.: WVVZZZ3CZHE055622 ENGINE NO:
 MODEL: Passat 1.8 TSI Highline 17In MODEL NO.: 3Q24JZ

SA: Cheong Pearllyn

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
Labor						
1	B&P DIAG PROGRAMMING & CALIBRATION- NETT	1	TU	360		360
2	B&P MECH ELECT WIRING & MECH COMPONENT CHECK NETT	1	TU	200		200
3	B&P INSURANCE EXCESS INSURANCE EXCESS / DEDUCTIBLE	1	TU	-1,500		-1,500
4	B&P ALEX LABOUR LABOUR	2	UNIT	475		950
5	B&P ALEX LABOUR TRANSFER DOOR PARTS	1	UNIT	475		475
6	B&P ALEX PAINT SPRAY PAINT	2	UNIT	500		1,000
7	EXT00037 Tow SVC- Quality Recovery Services	1	UNIT	0		0
8	EXT00037 Tow SVC- Quality Recovery Services	1	UNIT	0		0
Rem						
9	3Q0831055AE DOOR LHF (Improve version)	1	PCS	2,753.81	28	1,982.74
10	3Q0837701C 5AP DOOR SEAL LHF	1	PCS	279.93	28	201.55
11	D 378500A2 DOOR INSULATOR	2	PCS	71.12	28	102.41
12	3Q5833055AC DOOR LHR	1	PCS	1,571.18	28	1,131.24
13	3Q5839701B 5AP DOOR SEAL LHR	1	PCS	215.11	28	154.88
14	3Q0853331A 3Q7 MOLDING LHF DOOR	1	PCS	204.64	28	147.34
15	3Q0853333A 3Q7 MOLDING LHR DOOR	1	PCS	103.87	28	74.78
16	510837205K GRU HANDLE LHF	1	PCS	582.63	28	419.49
17	3Q0837851C DOOR LOWER SEAL LHF	1	PCS	211.02	28	151.93
18	3Q0839699B DOOR LOWER SEAL LHR	1	PCS	91.84	28	66.12
19	3Q0853267 GRU COVER MOLDING LHF DOOR	1	PCS	92.26	28	66.43
20	3Q0853777 GRU COVER MOLDING LHR DOOR	1	PCS	30.25	28	21.78

Remarks : MSIG WINNER OD

DOA 13/01/2018

SURVEYOR LKK RASUL

EXCESS \$1500

Service Order Confirmation

SERVICE ORDER NO.: 18P0211

CUSTOMER NO.: CV037073

CUSTOMER NAME: RICHARD BUCKLEY

TELEPHONE NO.:

ADDRESS: 22 WILBY ROAD #01-15
Singapore

VEH No.: SLN972D

Order Date: 22/01/18

Reg Date: 21/04/17

KM: 11,486

SA: Cheong Pearlyn

VIN NO.: WVVZZZ3CZHE055622

ENGINE NO:

MODEL: Passat 1.8 TSi Highline17m

MODEL NO.: 3G24JZ

<u>No.</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>UOM</u>	<u>UNIT PRICE</u>	<u>DISC %</u>	<u>AMOUNT</u>
------------	--------------------	------------	------------	-------------------	---------------	---------------

TOTAL	6,005.71
GST AMOUNT	420.40
TOTAL AMOUNT	6,426.11

On Behalf Of "COMPANY"

Certified Goods/Service received:

Authorized Signature

Customer

NOTE: THIS IS NOT AN OFFICIAL RECEIPT

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Jan 2018		19 Jan 2018 15:57 Edit Adj Rpt	\$47,505.71 Edit Estimates	\$47,505.71 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:

RICHARD BUCKLEY, ID: S2745150J, Tel: +6596230450, Email: rbuckley@singnet.com.sg

Vehicle Reg. No.:

SLN972D

Claim Type:

OD / 545988

Repairer:

Volkswagen Centre Singapore (HQ) 247 Alexandra Road, 159934 Alexandra - Tel: 63057288

Handling Insurer:

MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jocelyn Ng Shin Bun]

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 18/02/2018]

Driver/Custodian:

RICHARD BUCKLEY (50 / Male), NRIC: S2745150J, Tel: +6596230450

Adj Asg. Remarks:

Please revert, thank you

Date of Loss:

13/01/2018 09:00 - :59
[8 Months and 23 Days From LTA Reg Date (Man Yr)]

Policy/Cover Note No.:

A28947081AVW (Comprehensive)
Coverage: 21/04/2017 - 20/04/2018

Excess:

\$1,500.00

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

- MSIG_SG (23/01/2018): Alert - Adj Mandate Approved (\$48506.03) - SLN972D - Claim Handler: Jocelyn Ng S...

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLN972D (545988)
 OD
 Jan 13 2018 9:00AM
 [RICHARD BUCKLEY]
 Volkswagen Centre Singapore

Upload Documents			Upload Photos			Compose New Letter			View		View in Browser	
Assessment Reports									1 per page		☒	
No	Finalized On	Volkswagen Centre Singapore (HQ)								Thumbnail	Print	
1	13/01/18 12:06	Accident Statement								Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print	
1	23/01/18 12:17	Adjuster Immediate Advice								Load HTM		
Photos/Images									3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print	
1	23/01/18 12:17	Odometer Reading								Load JPG	☒	
2	23/01/18 12:17	Chassis Number								Load JPG	☒	
3	23/01/18 12:17	General View								Load JPG	☒	
4	23/01/18 12:17	General View								Load JPG	☒	
5	23/01/18 12:17	General View								Load JPG	☒	
6	23/01/18 12:17	General View								Load JPG	☒	
7	23/01/18 12:17	General View								Load JPG	☒	
8	23/01/18 12:17	General View								Load JPG	☒	
9	23/01/18 12:17	General View								Load JPG	☒	
10	23/01/18 12:17	General View								Load JPG	☒	
11	23/01/18 12:17	General View								Load JPG	☒	
12	23/01/18 12:17	General View								Load JPG	☒	
13	23/01/18 12:17	General View								Load JPG	☒	
14	23/01/18 12:17	General View								Load JPG	☒	
15	23/01/18 12:17	General View								Load JPG	☒	
16	23/01/18 12:17	General View								Load JPG	☒	
17	23/01/18 12:17	General View								Load JPG	☒	
18	23/01/18 12:17	General View								Load JPG	☒	
19	23/01/18 12:17	General View								Load JPG	☒	
20	23/01/18 12:17	General View								Load JPG	☒	
21	23/01/18 12:17	General View								Load JPG	☒	
22	23/01/18 12:17	General View								Load JPG	☒	
23	23/01/18 12:17	General View								Load JPG	☒	
24	23/01/18 12:17	General View								Load JPG	☒	
25	23/01/18 12:17	General View								Load JPG	☒	
26	23/01/18 12:17	General View								Load JPG	☒	
27	23/01/18 12:17	General View								Load JPG	☒	
28	23/01/18 12:17	General View								Load JPG	☒	
29	23/01/18 12:17	General View								Load JPG	☒	
30	23/01/18 12:17	General View								Load JPG	☒	
31	23/01/18 12:17	General View								Load JPG	☒	
32	23/01/18 12:17	General View								Load JPG	☒	
33	23/01/18 12:17	General View								Load JPG	☒	
34	23/01/18 12:17	General View								Load JPG	☒	

Assessment Reports			1 per page	☒
No	Finalized On	Volkswagen Centre Singapore (HQ)	Thumbnail	Print
				☒
35	23/01/18 12:17	General View		☒
36	16/04/18 14:24	Reinspection Photo		☒
37	16/04/18 14:24	Reinspection Photo		☒
38	16/04/18 14:24	Reinspection Photo		☒
39	16/04/18 14:24	Reinspection Photo		☒
40	16/04/18 14:24	Reinspection Photo		☒
41	16/04/18 14:24	Reinspection Photo		☒
42	16/04/18 14:24	Reinspection Photo		☒
43	16/04/18 14:24	Reinspection Photo		☒
44	16/04/18 14:24	Reinspection Photo		☒
45	16/04/18 14:24	Reinspection Photo		☒
46	16/04/18 14:24	Reinspection Photo		☒
47	16/04/18 14:24	Reinspection Photo		☒
48	16/04/18 14:24	Reinspection Photo		☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	15/01/18 11:21	PARF COE		☒
2	15/01/18 11:21	Enquire Transfer Fee Details		☒
3	16/01/18 17:31	Estimate Repair Cost		☒
4	16/01/18 17:31	Email from VW (Meiy) - To arrange survey		☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print
1	19/01/18 09:57	Email - Survey appt		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/01/18 12:17	ESTIMATE		☒

Linked Accident Report Documents

View

Assessment Reports			1 per page	☒
No	Finalized On	Volkswagen Centre Singapore (HQ)	Thumbnail	Print
1	13/01/18 12:06	Accident Statement		☒
Photos/Images			3 per page	☒
No	Finalized On	Volkswagen Centre Singapore (HQ)	Thumbnail	Print
1	13/01/18 11:58	Accident Photo		☒
2	13/01/18 11:58	Accident Photo		☒
3	13/01/18 11:58	Accident Photo		☒
4	13/01/18 11:59	Accident Photo		☒
5	13/01/18 11:59	Accident Photo		☒
6	13/01/18 11:59	Accident Photo		☒
7	13/01/18 11:59	Accident Photo		☒
8	13/01/18 11:59	Accident Photo		☒
9	13/01/18 11:59	Accident Photo		☒
10	13/01/18 11:59	Accident Photo		☒
11	13/01/18 11:59	Accident Photo		☒
12	13/01/18 12:05	Accident Photo		☒
13	13/01/18 12:05	Accident Photo		☒
Documentation			1 per page	☒
No	Finalized On	Volkswagen Centre Singapore (HQ)	Thumbnail	Print
1	13/01/18 11:58	Sketch Plan		☒

Documents Checklist

DOCUMENTS CHECKLIST[Reset](#)[Save](#)[Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG18001263/R1QD3Q2

Date: 24/04/2018

REFERENCE

Insured/Claimant:	RICHARD BUCKLEY	Policy No:	A28947081AVW	
Date of Loss:	13/01/2018	Nature of Claim:	OD	Claim No: 545988

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN972D		
Make & Model:	VOLKSWAGEN PASSAT B8, 1.8 TFSI (A)	Engine No:	CJS178778
Reg. Date:	21/04/2017 (Man. Year: 2016)	Chassis No:	WVWZZZ3CZHE055622
Colour:	Black	Odometer:	9370 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	S\$139,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,689.07	4,520.71	2,168.36	32.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,410.00	2,985.00	2,425.00	44.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,099.07	7,505.71	4,593.36	37.96
- Excess (S\$)	1,500.00	1,500.00	0.00	0.00
(S\$)	10,599.07	6,005.71	4,593.36	43.34
+ GST 7.00/7.00% (S\$)	741.93	420.40	321.53	43.34
Nett Amount (S\$)	11,341.00	6,426.11	4,914.89	43.34

INSPECTION

Date of Assignment:	19/01/2018	
Date Inspected:	22/01/2018	Inspected At: Volkswagen Centre Singapore (HQ) 247 Alexandra Road Singapore 159934
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 24 Apr 2018)
Parts: 143	VOLKSWAGEN PASSAT B8 1.8 TFSI (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLN972D)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DOOR LHF	Bent	2,421.45 FS	*1,982.74 FS
2	1		*WINDOW REGULATOR LHF	Serviceable	613.83 FS	*- FS
3	1		*DOOR LOWER SEAL LHF	Necessary	211.02 FS	*151.93 FS
4	1		*DOOR SEAL LHF	Necessary	279.93 FS	*201.55 FS
5	1		*INNER COVER FOR LHF DOOR INNER COVER FOR LHF DOOR	Serviceable	44.89 FS	*- FS
6	1		*DOOR LOWER SEAL LHR	Cracked	91.84 FS	*66.12 FS
7	1		*COVER MOULDING LHF DOOR	Cut	92.26 FS	*66.43 FS
8	1		*MOLDING LHF DOOR	Scratched	204.64 FS	*147.34 FS
9	1		*MOLDING LHR DOOR	Scratched	103.87 FS	*74.79 FS
10	1		*COVER MOULDING LHR COVER	Necessary	30.25 FS	*21.78 FS
11	1		*DOOR LHR	Bent	1,571.16 FS	*1,131.24 FS
12	1		*DOOR SEAL LHR	Necessary	215.11 FS	*154.88 FS
13	1		*HANDLE LHF	Scratched	582.63 FS	*419.49 FS
14	1		*HINGE UPPER LH REAR DOOR	Serviceable	83.95 FS	*- FS
15	2		*DOOR INSULATOR	Necessary	142.24 FS	*102.42 FS
					Total Parts (S\$)	6,689.07 4,520.71

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR	New	1,900.00	950.00
2	TRANSFER DOOR PARTS	New	950.00	475.00
3	SPRAY PAINT	New	2,000.00	1,000.00
4	PROGRAMMING & CALIBRATION COMPULSORY TO DO AFTER AC	New	360.00	360.00
5	ELECT WIRING & MECH COMPO	New	200.00	200.00
Gross Labour Cost (S\$)			5,410.00	2,985.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >