

22/05/2002

ASS. REC. BY:

REF: CS/MSG18001267/ Kvd3n2 Special Instruction:

SUPERVISOR:

Kenneth

ASSIGNMENT (Office)

From (Person):

Elaine Ngu

of

MSG

Date/Time: 22/01/18 @ 11:26am

Estimated Cost:

Bill to:

OD / TP AWS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKA 1169E

Insured:

SKJ 2490Y

at Workshop m/s

Lai Huet (Meng Kee)

Tel:

64538110

of

160 Sin Ming Drive #04-01

Policy No:

B27476579SMP

Claim No:

546117

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 14/01/2018

23/01/2018

CA / REV / REP. / REV 24 HRS

wps

H.O.D. Endorsement:

Date/Time:

11:50am @ 22/1/18

Person Contacted:

jenny

Vehicle IN (OUT)

Date/Time

Action/Instruction (✓) Estimate

SKA 1169E -X

SKJ 2490Y -X

24/1/18

Send preli revised by merimen

7/5/18

Final fig \$ 1940.25 Confirmed by email

(Ref 250 11/18)

CUT in 07/05/18

REF: MS1G

## ASSIGNMENT

From: Date: 23/01/2018

Estimated Cost:

OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MVTo inspect Vehicle No: SKA1169E  
at Workshop no: Lai Huat (Meng Kee)  
of: 160 Sin Ming Drive # 04-01

Insured:

Policy No:


Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / FR. Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lump Sum: % 3.Val: Yes or No

CA / REV / REP. / 24 HRS <sup>1 up</sup>

Date: Person Contacted:

Vehicle IN / OUT

Veh No: SKA 1169E Vn Regn: 01 11

Type: ☒ Car ☐ M.Cycle ☐ Bus ☐ Van ☐ Lorry ☐ Taxi ☐ Prime Mover

Truck / Trailer or:

Make: Chevrolet Cruze or 1398

Colour: M. Blue A/C Insured / Std / NI / NA

Sp. Reading: 155935 T. Radio: Insured / Std / NI / NA

Eng No:

C.No: KL1JA6961BK 074511

Gen. Cond: ☒ Good ☐ Fair ☐ Poor ☐ BurntSteering: ☒ In order ☐ Jammed ☐ Leaked ☐ Burnt orBrake: ☒ In order ☐ Jammed ☐ Leaked ☐ Burnt orMod: Nil / S/Rim / STD ☒ A/Rim or

Tyre Size: F: 205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU ☒ PR / SUMI /

TOYO / YOKO or

Front:

R/Bal: 3 mm

Rear:

R/Bal: 4 mm

L/Bal: 3 mm

L/Bal: 4 mm

D.O.A: 14/1/18

D.O.A: 23/1/18

Survey held at: ☒

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear n/s

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

24/1 File pass to Catherine

RECEIVED 07 MAY 2018

Date/Time File Pass to:

☐

: Preli. Report

☐

: Final Report

Date/Time File Return to:

75 - typist

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee

Transportation

S - P - L

Block

Sheet

Add Fee:

☐

Site Insp: \$

☐

Inten. Insp: \$

☐

Tech. Insp: \$

☐

T/Rep. Insp: \$

Report Format:

merimen

Lump Sum I.B.I. \$

1940.25

200  
10

210

## Survey Department Check List (Case Handler)

Reference No.: CS/MSG/8001267/Krd3  
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

**Admin (** ): Case handler to make sure all Information created by the assignment team are ACCURATE.

### (1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No				
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

**Surveyor (** ): Case handler to make sure the surveyor completed all required information.

### (1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

### (2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

### (3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)	✓			
C	Days of repair	✓			
C	Finalised Amount				
C	Re-inspection Cases to Finalize within 5 Days				

### (4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 7/5/18  
Case Handler Date

\*C: Critical \*N: Non-Critical

21/05/2014



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSG INSURANCE (SINGAPORE) PTE LTD			Ref : CS/MSG18001267/Kvd3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 22-01-2018	
			Code : MSG	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SKJ 2490Y	Veh. Inspected	SKA 1169E	
Policy No.	B27476579SMP	Coverage (\$)	0.00	
Claim No.	546117	Excess (\$)	0.00	
Assign From	MERIMEN (ELAINE NGU)	Assign Date	22/01/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	14/01/2018	Inspection Date		
Survey held at	LAI HUAT (MENG KEE) MOTOR PTE LTD 160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Elaine Ngu Siau Mei

Date: 24 Jan 2018

**Preliminary Advice**

Insured Vehicle No	: SKJ2490Y	Accident Date	: 14/01/2018
TP Vehicle No	: SKA1169E	Assignment Date	: 22/01/2018
Make	: CHEVROLET CRUZE	Est. Duration of Repair	: 3.00
Date of Inspection	: 23/01/2018		
Inspection At	: LAI HUAT (MENG KEE) MOTOR PTE LTD (SIN MING) 160 SIN MING DRIVE #04-01, SIN MING AUTOCITY SINGAPORE 575722		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,190.25
Revised Amount	:S\$	1,940.25
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,940.25

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

**Remarks**

( ) The vehicle is economical/not economical for repair.

( X ) The above survey was conducted on a 'without prejudice' basis.

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Jan 2018 15:18 <a href="#">Sendback Est</a>	19 Jan 2018 15:28 <b>S\$2,190.25</b>	22 Jan 2018 11:26 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

Insured:	SHEPHERD MUHAMMAD PASHA PETER, ID: S2737325I, Tel: +6597871634		
Main Claimant:	SALMI BINTE REKH, ID: S7807834J		
Vehicle Reg. No.:	SKA1169E	Date of Loss:	14/01/2018 18:00 - :59
Claim Type:	TP / 546117	Policy/Cover Note No.:	B27476579SMP (Comprehensive) Coverage: 08/03/2017 - 07/03/2018
Vehicle Reg. No. (Insured):	SKJ2490Y	Policy No. (Claimant):	2017-V0087463-VDP-R005
		Excess:	S\$14.00
Repairer:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64538110		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]		
Claimant's Insurer:	Great Eastern General Insurance Limited (HQ) - Tel: +65 248 2888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 23/01/2018]		
Driver/Custodian (Insured):	SHEPHERD MUHAMMAD PASHA PETER (53 / Male), NRIC: S2737325I, Tel: +6597871634		
Adj Asg. Remarks:	REQUEST TO SUVERY AFTER 12 PM TODAY (22/01/18)		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

**Veron Chen (LKKAUTO)**

---

**From:** Veron Chen (LKKAUTO)  
**Sent:** Monday, 7 May 2018 1:18 PM  
**To:** SUR; Jenny Lim  
**Subject:** RE: Finalisation - SKA 1169E / Chevrolet Cruze

Dear Jenny,

WITHOUT PREJUDICE

Confirmed \$1940.25@ 3 working days.

**Final invoice and all supporting documents sent over to MSIG**

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Kenneth Kong (LKKAUTO)  
**Sent:** Monday, 7 May 2018 12:28 PM  
**To:** Veron Chen (LKKAUTO) <veronchen@lkkauto.com>  
**Subject:** FW: Finalisation - SKA 1169E / Chevrolet Cruze

---

**From:** Jenny Lim [<mailto:jenny.lim@laihuat.com.sg>]  
**Sent:** Thursday, 3 May, 2018 4:29 PM  
**To:** Kenneth Kong (LKKAUTO)  
**Subject:** Finalisation - SKA 1169E / Chevrolet Cruze

Dear Sir

For your confirmation, please:

- Parts: \$1035.00
- 15%: \$ 155.25
- L&P: \$ 750.00

**Sub-total: \$1940.25 / 3 days**

Supporting documents and photographs are enclosed for your reference.

Thank you.

Kind regards.

Jenny Lim  
for LAI HUAT (MENG KEE) MOTOR PTE LTD  
160 Sin Ming Drive

#04-01, #04-02 & #07-03  
Sin Ming Autocity  
Singapore 575722  
Tel: 64538110  
Fax: 64596267



## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 7834J

### Vehicle Details

Vehicle No.: SKA1169E

Vehicle to be Exported: Yes

Intended De-registration Date: 15 Jan 2018

Vehicle Make: CHEVROLET

Vehicle Model: CRUZE 1.6L AT ABS D/AB 2WD 4DR

Primary Colour: Blue

Manufacturing Year: 2010

Engine No.: F16D38103701

Chassis No.: KL1JA6961BK074511

Maximum Power Output: 80.0 kW (107 bhp)

Open Market Value: \$12,406.00

Original Registration Date: 21 Jan 2011

First Registration Date: 21 Jan 2011

Transfer Count: 0

Actual ARF Paid: \$12,406.00

### Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 20 Jan 2021

PARF Rebate Amount: \$8,063.00

### Intended COE Rebate Details

COE Expiry Date: 20 Jan 2021

COE Category: A - Car (1600cc & below)

COE Period(Years): 10

QP Paid: \$34,001.00

COE Rebate Amount: \$10,246.00

**Total Rebate Amount: \$18,309.00**

The information contained herein is correct as at 15 Jan 2018

**Enquire Vehicle Insurer**

Vehicle No.	Incident Date/Time	Search Status	Insurance Company Code	Insurance Company Name
SKJ2490Y	14 Jan 2018 / 18:47:00	Successful	I01	MSIG INSURANCE (SINGAPORE) PTE LTD

[Previous](#)   [OK](#)

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GlA Records Management Centre established by the General Insurance Association of Singapore (GlA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	15/01/2018 17:12
Date Of Accident	14/01/2018 18:45
Exact Location Of Accident	BIDEFORD ROAD
Country/State of Loss	SINGAPORE


### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKA1169E
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SALMI BINTE REKH
NRIC No	S7807834J
Email Address	JOSHUA_HHH@YAHOO.COM
Mobile Phone No	(LOCAL) +65-91908289
Alternative Phone No	OTHERS-91908289
<b>Vehicle Particulars</b>	
Manufacturer	CHEVROLET
Model	CRUZ 1.6L
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	GREAT EASTERN GENERAL INSURANCE LIMITED
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2017-V0087463-VDP-R005
Cover Note Number	
<b>Driver</b>	
Name of Driver	HAZLAN BIN HAMDAN
NRIC No	S7620246Z
Date Of Birth	13/07/1976
Occupation	OUTDOOR
Date Of Driving Pass	21/03/1997
Driving Experience	20 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98166750
Fax Number	
Contact Number	
EMail Address	JOSHUA_HHH@YAHOO.COM

NRIC/Passport Number	S2737325I
Contact Number	97871634
Address	189 JOO CHIAT PLACE
Postcode	427901
Insurance Company Name	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	

# Sketch Plan Pg. 2

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

14<sup>th</sup> JANUARY 2018 @ 1847hrs. At 9 along Bloeford Rd towards CTE. opposite Paragon Shopping Centre.

Rear Left of my car was knocked by another vehicle.

I was turning right, coming out from Al-Falah Mosque carpark and stopped inside Yellow Box as traffic light was at RED. Upon turning into GREEN, I move off and stop as the front vehicle stop. At this point of time, the rear vehicle knocked into my vehicle.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 15/01/18

Driver's Signature

(If driver is not the policyholder)  
Date & Time: 15/01/2018

Reporting Centre Personnel's Signature

Name: Poh Kwee Choo  
NRIC/FIN No.: S6840583A

Printed Name of Policyholder

# 來發(明記)摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sin Ming Autocity  
160 Sin Ming Drive #04-01/#04-02/#07-03 Singapore 575722  
Tel: 64538110 Fax: 64596267 Email: info@laihuat.com.sg  
UEN: 199407592C

TP INSURER: MSIG Insurance (Singapore) Pte. Ltd. (HQ)

--  
--  
Singapore

Claimant Insurer: Great Eastern General Insurance Limited

## PARTICULARS OF CLAIM

Claim Type: Third Party	Ref. No: 69157
Policy No:	Date of Loss: 14/01/2018
Vehicle Reg. No.: SKA1169E	Driveable?
Party At Fault: UNKNOWN	
Driver (TP): HAZLAN BIN HAMDAN	

---

Make/Model: CHEVROLET CRUZE, 1.6 L (A)	Vehicle Reg. Date: 21/01/2011
Vehicle Colour: Blue	
Engine No: F16D38103701	Chassis No: KL1JA6961BK074511
Odometer: 0 KM	

*Not Authorized*  
*1-B.1*  
*Resony B4 paint*

Paint Type:	
Total Loss? NO	
Est. Duration of Repair (day) 3	

---

Description of Accident/Loss: 14TH JANUARY 2018 AT 1847HRS. AT ALONG BIDEFORD ROAD TOWARDS CTE OPPOSITE PARAGON SHOPPING CENTRE. REAR LEFT OF MY CAR WAS KNOCKED BY ANOTHER VEHICLE. I WAS TURNING RIGHT, COMING OUT FROM AL-FALAH MOSQUE CARPARK AND STOPPED INSIDE YELLOW BOX AS TRAFFIC LIGHT WAS AT RED. UPON TURNING INTO GREEN, I MOVE OFF AND STOP AS THE FRONT VEHICLE STOP. AT THIS POINT OF TIME THE REAR VEHICLE KNOCKED INTO MY VEHICLE.

Present Location: LAI HUAT (MENG KEE) MOTOR PTE LTD (SIN MING) / DERRICK TAY

COST OF CLAIMS	Amount
Parts	1,190.25
Miscellaneous Items	0.00
Labour	500.00
Paintwork Labour	500.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>2,190.25</b>
<b>+ GST 7.00% (S\$)</b>	<b>153.32</b>
<b>Nett Amount (S\$)</b>	<b>2,343.57</b>

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 19 Jan 2018)  
**Parts:** 143      CHEVROLET CRUZE 1.6 L (A) (Catalogue:Merimen Singapore 1.0)  
**Labour:** Repairer's      (Price-denominated Standard List)  
**Print Code:** Lai Huat (Meng Kee) Motor Pte Ltd/SKA1169E/19/01/2018 15:28  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Rear bumper	0.00	0.00	*700.00 F ✓
2	1		*Rear tail lamp LH	0.00	0.00	*335.00 F ✓
Sub Total (S\$)						1,035.00
+ Margin on L,N Items 15.00% (S\$)						155.25
Total Parts (S\$)						1,190.25

F=Franchise part.

Lai Huat (Meng Kee) Motor Pte Ltd/SKA1169E/19/01/2018 15:28. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	To spray paint	New	500.00
<u>Labour Items</u>			
2	To knock dents on rear fender LH and renew of parts	New	500.00
Gross Labour Cost (S\$)			1,000.00

400  
350

Lai Huat (Meng Kee) Motor Pte Ltd/SKA1169E/19/01/2018 15:28. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:



## REPAIR DETAILS

### Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 19 Jan 2018)

Parts: 143

CHEVROLET CRUZE 1.6 L (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's

(Price-denominated Standard List)

Print Code: Lai Huat (Meng Kee) Motor Pte Ltd/SKA1169E/19/01/2018 15:28

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Rear bumper	0.00	0.00	<i>Bu/nt</i> *700.00 F ✓
2	1		*Rear tail lamp LH	0.00	0.00	<i>cpt</i> *335.00 F ✓
Sub Total (S\$)						1,035.00
+ Margin on L,N Items 15.00% (S\$)						155.25
Total Parts (S\$)						1,190.25

F=Franchise part.

Lai Huat (Meng Kee) Motor Pte Ltd/SKA1169E/19/01/2018 15:28. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	To spray paint	New	500.00
<u>Labour Items</u>			
2	To knock dents on rear fender LH and renew of parts	New	500.00
Gross Labour Cost (S\$)			1,000.00

Lai Huat (Meng Kee) Motor Pte Ltd/SKA1169E/19/01/2018 15:28. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >



松義汽車機件私人有限公司  
SONG YI AUTO PARTS PTE LTD

Block 637 Veerasamy Road #01-119 Singapore 200637  
Tel: 6297 3700 Fax: 6297 3839 Email: songyi@singnet.com.sg

**TAX INVOICE**

REG NO: 200922086G  
GST NO: 200922086G

LAI HUAT (MENG KEE) MOTOR PTE LTD  
160, SIN MING DRIVE,  
#04-01  
SIN MING AUTOCITY  
SINGAPORE 575722

Goods Delivery To: 04-02

Invoice No: SAL18-081846  
Date: 23/01/2018 11:38  
Account No: L002  
Sales person: SKM  
Order By:  
Vehicle No: SKA1169E  
P/O No:

Page 1 of 1

No.	Part No.	Description	Location	Qty	Price	Amount
1	C95479273	BUMPER COVER-REAR	WH	1	700.00	700.00
2	C95039730	TAIL LAMP ASSY-LH	WH	1	335.00	335.00

Sub Total: 1,035.00

Add GST @7%: 72.45

Grand Total: 1,107.45

  
Issued By

Goods sold returned are to be in full packaging  
original condition within SEVEN working days

  
Received By

Received the above mentioned goods in order and good condition



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18001267/KVD3N2

Date: 09/05/2018

## REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	B27476579SMP
Claimant Vehicle No :	SKA1169E	Insured Vehicle No :	SKJ2490Y
Date of Loss:	14/01/2018	Nature of Claim:	TP
		Claim No:	546117

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SKA1169E	Engine No:	F16D38103701
Make & Model:	CHEVROLET CRUZE, 1.6 L (A)	Chassis No:	KL1JA6961BK074511
Reg. Date:	21/01/2011 (Man. Year: 2010)	Odometer:	155935 km
Colour:	Metallic Blue		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Pirelli 3 mm	Rear Left Side:	Pirelli 4 mm
Front Right Side:	Pirelli 3 mm	Rear Right Side:	Pirelli 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,190.25	1,190.25	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	500.00	350.00	150.00	30.00
Paintwork Labour	500.00	400.00	100.00	20.00
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>2,190.25</b>	<b>1,940.25</b>	<b>250.00</b>	<b>11.41</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>153.32</b>	<b>135.82</b>	<b>17.50</b>	<b>11.41</b>
<b>Nett Amount (S\$)</b>	<b>2,343.57</b>	<b>2,076.07</b>	<b>267.50</b>	<b>11.41</b>

## INSPECTION

Date of Assignment:	22/01/2018	Present Location:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)
Date Inspected:	23/01/2018	Inspected At:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	3.0 days		

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 09 May 2018)
<b>Parts:</b> 143	CHEVROLET CRUZE 1.6 L (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKA1169E)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Rear bumper (WCP)	Buckled/Dented	700.00 F	*700.00 F
2	1		*Rear tail lamp LH (WCP)	Cracked	335.00 F	*335.00 F
					<b>Sub Total (\$\$)</b>	<b>1,035.00</b>
					<b>+ Margin on L,N Items 15.00/15.00% (\$\$)</b>	<b>155.25</b>
					<b>Total Parts (\$\$)</b>	<b>1,190.25</b>

F=Franchise part.

Report was unsubmitted during this print-out.

**Recommended Miscellaneous Items**

There are no new miscellaneous items selected.

**Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	To spray paint	New	500.00	400.00
<u>Labour Items</u>				
2	To knock dents on rear fender LH and renew of parts	New	500.00	350.00
Gross Labour Cost (\$\$)			1,000.00	750.00

Report was unsubmitted during this print-out.

&lt; END OF ESTIMATES &gt;