

20/01/2000

ASS. REC. BY:

REF: CS/ASM18001270/ b

Special Instruction:

SURVIVOR

ASSIGNMENT (Office)

Smart claim

From (Person):

Ernest Tay

of

ASM

Date/Time: 21.01.2018 3:32pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

XE 22668

Insured:

XD 2333X

at Workshop m/s

Mova

Tel:

6272 3892

of

Bk 1018 Bukit Meigh Lane 3 #01-01

Policy No:

Claim No:

57MD05SL

Sum Insured:

Excess:

Make of Veh:

D.O.A.

13.12.2017

(Client's Record)

CA / REV / REP. / REV 24 HRS wpi

H.O.D. Endorsement:

Date/Time:

22.01.2018 9:09am

Person Contacted:

Nitha

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	XE 22668 - X
	XD 2333X - X
20/1/18	Received email from Stacy Ng, owner convert to OD claim
	Cancelled / 18/6



TP CONVERTED TO OD CLAIM

Type

Information

Message

please submit WP report.

Reply



Service Request Details

Claim

S7M005SL

Reference

None

Loss Date

December 13, 2017

Request Date

January 22, 2018

Due Date

January 22, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Standard workshop survey

Actions

Next Step

Finish the work.

Complete Work

More

Vehicle Information

Incident Vehicle Registration #

XE2266B

Make

TPVD SCANIA

Service Address

145 SERANGOON AVENUE 3, . . 556122

Primary Contact/Insured

HAN HONG GOH

145 SERANGOON AVENUE 3, #12-08, 556122, Singapore, Singapore

CHS1818@HOTMAIL.COM

Claim Handler

Stacey NG

6568804351

stacey.ng@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)