

ASS. REC. BY:

REF:

CS3/AIG18001276/M1d32

VHR & Aug.

Special Instruction:

Surveyor: Mr. MA

ASSIGNMENT (Office)

MGM

From (Person): Manesa Abu Karim

AIG

Date/Time: 22/01/18 @ 11:42am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJS 6611D

Insured:

SKX 8795E

at Workshop m/s

Nexwave Auto

Tel:

9138 4382

of No. 160, Sin Ming Drive #05-15

Policy No: 2100445405-02

Claim No:

183528633184

Sum Insured:

Excess:

Make of Veh:

D.O.A. 16/01/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time: 11:46am @ 22/1/18

Person Contacted:

jeanne Tan

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate	
	SJS 6611D - CCG/AIG 09025106/Kpn	D.O.A: 04/11/2009
	SKX 8795E - X	
	Dismantle: 23/1/2018.	

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SSS 6611D Yr Regn: Aug 2009Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Kim Forte C.C. 1591Colour: Black A/C: Insured / Std / NI / NASp. Reading: 157907 T. Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNAFW4UMAS112052Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/45/17AR: 205/45/17A

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

NEXEN

Front

Rear

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 16/1/2018 D.O.I. 22/1/2018

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 10 MAY 2018

Date/Time, File Pass to?

☐ : Preli. Report

1) _____

☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 5Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp \$☐ : Interview \$☐ : Tech Invs \$☐ : Weekend \$

Photos

Others

Report Format : _____

Lump Sum / I.B.I: \$ _____

TOTAL

180

20

200



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG18001276/M1d3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 22-01-2018



Code : AIG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SKX 8795E	Veh. Inspected	SJS 6611D
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	MARIESA ABU KASIM	Assign Date	22/01/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	16/01/2018	Inspection Date	22/01/2018
Survey held at	NEXWAVE AUTO 160 SIN MING DRIVE #05-15 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

Nivitha (LKK Auto)

From: Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>
Sent: Monday, 22 January 2018 11:42 AM
To: 'assignments@lkkauto.com'; 'admin-a@lkkauto.com'
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Lim, Sheng Yang; Md Ishak, Mohd Imran; Chan, Yoke Shi; Supramaniam, Darshene
Subject: aigencrypt - Pre repair inspection request - SJS6611D VS SKX8795E (OI) DOA: 16/01/2018
Attachments: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKX87... (63.1 KB); FaxE46B.TIF

Hi,

Please refer to the enclosed request from **Island Law LLC**

Kindly carry out Policy coverage verification **first** before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

Thank you.

Best Regards,

Mariesa Abu Kassim

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto

Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)

Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia

Tel +6 03 2719 6000 | Ext 1012202 | Fax +6 03 2685 5898

NoorMariesa.AbuKassim@aig.com | www.aig.com

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

ISLAND LAW LLC**Advocates & Solicitors**

(UEN No. 200918269D)

(GST Reg No. 200918269D)

KIRPAL SINGH SHARMA**NG KWONG LOONG****KERUSHNAN S/O SIVALINGKAM**Our Ref : KS. 06611D.18. PD (NWM). ~~22~~

Your Ref : SKX 8795E

Date: 19/1/2018

101 Upper Cross Street
 #04-04 People's Park Centre
 Singapore 058357
 Tel: (65) 6221 3211
 Fax: (65) 6225 3210
 (65) 6225 3054

ALG ASIA PACIFIC INSURANCE PTE LTD

(BY FAX: 6835 7417)

Attn: Motor Claims Department

()

Dear Sirs,

ACCIDENT INVOLVING SIS 6611D AND SKX 8795E ALONG THOMSON ROAD
AND WHITLEY ROAD ON 16 JANUARY 2018 @ 1920 HRS

(NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS
 PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES)

We act for NG WEE FENG (WU WEIFENG) who has appointed the undermentioned
 workshop to repair his/her motor vehicle no. SIS 6611D.

Please be informed that the said vehicle can be inspected at:

Name : NEXWAVE AUTO
 Address : NO. 160 SIN MING DRIVE
#05-15 SIN MING AUTOCITY
SINGAPORE 575722
 Person to contact : JEANNE TAN
 Tel : 9138 4382

If you failed to conduct the pre-repair inspection within the next 2 working days excluding any
 intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter
 without further reference to you.

Yours faithfully

ISLAND LAW LLC

cc: Client (SIS 6611D.) (By fax: 6909 0049)

For Surveyor
Please initial here after completion
of pre-repair inspection. Thank you.

Appointed surveyor :
 (Name & Signature)

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
Lim Kok Chong	AIG Asia Pacific Insurance Pte Ltd
Kumar Uthaya	AIG Asia Pacific Insurance Pte Ltd
Ken Wong	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Ricky Teng	RT Appraisal Pte Ltd
Elson Teng	RT Appraisal Pte Ltd
Michael Cheong	RT Appraisal Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Henry Ng	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Steven Foong	LKK Auto Consultants Pte Ltd
Wei Jie	LKK Auto Consultants Pte Ltd
Ma Chin Fook	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Best Regards,

Mariesa Abu Kassim

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto

Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)

Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia

Tel +6 03 2719 6000 | Ext 1012202 | Fax +6 03 2685 5898

NoorMariesa.AbuKassim@aig.com | www.aig.com

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/01/2018 17:00
Date Of Accident	16/01/2018 19:20
Exact Location Of Accident	JUNCTION OF THOMSON ROAD AND WHITLEY ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJS6611D
Insured/Policyholder	
Name Of Registered Owner	NG WEE FENG (WU WEIFEN)
NRIC No	S7422925E
Email Address	NGWEEFENG@GMAIL.COM
Mobile Phone No	(LOCAL) +65-87268672
Alternative Phone No	OTHERS-87268672

Vehicle Particulars

Manufacturer	KIA
Model	CERATO FORTE 1.6
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100159547-08
Cover Note Number	

Driver

Name of Driver	NG WEE FENG (WU WEIFEN)
NRIC No	S7422925E
Date Of Birth	27/07/1974
Occupation	INDOOR
Date Of Driving Pass	26/08/1999
Driving Experience	18 YEARS AND 4 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-87268672
Fax Number	
Contact Number	OTHERS-87268672
Email Address	NGWEEFENG@GMAIL.COM

Address	BLK 682C WOODLANDS DRIVE 62 #03-157
Postcode	733683
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	WOODLANDS EAST N.P.C
Police Station Address	ROAD: 3 WOODLANDS DRIVE 63 , POSTCODE: 737890 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN AND POLICE REPORT: T/20180116/2199.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKX8795E
Vehicle Make/Model/Colour	SUBARU FORESTER XT
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	YAK JUN WEI
NRIC/Passport Number	S7914304I
Contact Number	91129981
Address	
Postcode	
Insurance Company Name	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	NG WEE FENG
Approximate Age	43
Injuries Sustain	NECK SHOULDER AND LOW BACK
Injured person in which vehicle?	SJS6611D
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	BLK 683C WOODLANDS DRIVE 62 #03-157
Postcode	733683

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

17/11/2018

17:00 hrs.

Driver's Signature

(If driver is not the policyholder)


Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Poh Kwee Choo
S6840583A



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please refer to police report number: T/20180116/2499

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

17/1/2018

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Poh Kwee Choo
S6840583A



CERTIFICATE OF INSURANCE

AUTOPLUS PRIVATE VEHICLE

Name of Policyholder : Ng Wee Feng (Wu WeiFen)
 Period of Insurance : 25 Aug 2017 To 24 Aug 2018
 Engine No. : G4FC9H283530
 Chassis No. : KNAFW411MA5112052

Vehicle No. : SJS6611D
 Policy No. : 2100159547-08
 Endorsement No. :
 Issued Date : 26 Jul 2017

ABOUT THE COVER

Make/Model : KIA CERATO FORTE 1.6
 Engine Capacity/Tonnage : 1,591.00 CC Sum Insured : Market Value First Year of Registration : 2009
 Driver Restriction : NA Off Peak Car : No Insuring with COE/PAF : Yes

Person or Classes of Persons Entitled to Drive*

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Inexperienced Driver Excess" ("IDR") if You are or Your Authorised Driver (named or unnamed) has less than 2 years' driving experience.

Age Condition : 35 years old and above

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, paco-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use (10 days) 1500cc - 1800cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
 Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2
 Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Ng Wee Feng (Wu WeiFen) - \$600 (Own Damage) Ng Ah Kan - \$600 (Own Damage) Wong Lys Kian - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

Approved Reporting Centres/ AIG Authorised Repairers (For claims related repairs)

Any accident repairs to the Vehicle must be carried out by one of our Authorised Repairers. Within the first 3 years of the first registration of the Vehicle in Singapore, You have the option of having the accident repairs carried out at the Sole Agent's workshop.
 For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, You may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: MayBank

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0503197000

KIM HEOK ENG FELIX
 51 SCOTTS ROAD #03-23
 SINGAPORE 228241

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Mobile

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

S9C5YK

REPUBLIC OF SINGAPORE
IDENTITY CARD NO: S7422925E



Name
NG WEE FENG
(WU WEIFEN)
伍 薇 芬

Race
CHINESE

Date of birth
27-07-1974

Sex
F

Country of birth
SINGAPORE




REPUBLIC OF SINGAPORE DRIVING LICENCE

Current Number: S7422925E



Name
NG WEE FENG
(WU WEIFEN)

Valid Date: 27 Jul 1974

Expiry Date: 26 Jul 2005



001357844H

3754735



NRIC No: S7422925E



Date of issue
26-07-2005

Address
APT BLK 683C WOODLANDS DRIVE 62
#03-157
SINGAPORE 733683

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS

PASS DAT

Class 3 Motor cars <= 3000 kg with <= 7 passengers, exclusive of the driver; and motor tractors / vehicles <= 2500 kg

26 Aug 19

Blood Type
B+

NP 428A

Licence No: S7422925E



POLICE REPORT Pg. 1



**SINGAPORE
POLICE FORCE**



T/20180116/2199

1 of 4

Police Station Of Origin:
Woodlands East N.P.C.
3 Woodlands Drive 63 SINGAPORE 737890
Tel No: 1800-7679999

Report No. T/20180116/2199

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 16/01/2018 23:38		Vide Report No.:		Station Diary No.: 249
Name of Informant: NG WEE FENG		Address: APT BLK 683C WOODLANDS DRIVE 62 #03-157 SINGAPORE 733683		
ID Type / ID No.: NRIC NO / S7422925E		Contact No.: Home/Office: Mobile: 87268672		
Nationality: SINGAPORE CITIZEN		Email:		
Sex: Female	Age: 43	Date of Birth: 27/07/1974	Type of Informant: Driver	
Race: Chinese		Language:	Institution / School Name:	
Occupation: PROJECT MANAGER		Driving Licence Information: Class: 3 Date of Expiry:		

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 16/01/2018 19:20	Type of Location: Y-Junction
Location: Junction of Road 1 and Road 2 THOMSON ROAD WHITLEY ROAD Before the junction of Thomson Road towards Marymount Road, and Whitley Road				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Traffic Light - Working	Traffic Volume: Heavy	
Type of Collision: Between Stationary and Moving Vehicles - Head to Rear			Anyone conveyed by ambulance: No	

SJS6611D	Car	KIA	CERATO FORTE 1.6 AT SX ABS D/AB 2WD 4DR	Black	Seriously Damaged	0
SKX8795E	Car	SUBARU	FORESTER 2.0XT CVT AWD SR	Black	Seriously Damaged	0



**SINGAPORE
POLICE FORCE**



T/20180116/2199

4 of 4

Police Station Of Origin:
Woodlands East N.P.C.
3 Woodlands Drive 63 SINGAPORE 737890
Tel No: 1800-7679999

Report No. T/20180116/2199

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J/ [Signature]
Sgt 4 TOH CHAI TEE

Signature Of Informant

[Signature]

Signature Of Interpreter:

Not applicable

Date/Time:

16/01/2018 23:38


Officer In Charge Of Case:

TP / AEIT /
Staff Sgt WONG SIEU LUI
Contact No.: 65476423

Classification Of Case:

S/ 130

Authentication Stamp
NP168



MEDICAL CERTIFICATE Pg. 1

DRS KOO & NEOH MEDICAL GROUP
70 Woodlands Ave 7 #01-01 ADMIRALTY MRT STN S(738344)
TEL:63677077 FAX:62142143

Medical Certificate

Date : 16 Jan 2018
MC No. : 0000330550

This is to certify that :

Name : NG WEE FENG

NRIC : S7422925E

is Unfit for Duty for 3 days

from 17/01/2018 to 19/01/2018 inclusive.

DR MORSHIDAH YOUSOF

**This certificate is not valid for absence from court or other judicial proceedings unless specifically stated*

Accident Photo



Accident Photo



Accident Photo




215/45/R 7.

12, 80.

4FERO

NEXON.

CHASSIS NUMBER



SJS 6611D

DOI 22.1.18

1. Rear bootlid lock - BT
2. Rear tail lamp x 2, N/S & O/S - CRA mounting
3. Rear bootlid lamp x 2, N/S & O/S - CRA mounting
4. Reverse sensor x 2 PCS - Dm
5. Rear bumper sponge - Tn
6. Rear bumper reinforcement - Dm
7. Rear end panel - Dm
8. Rear end panel inner trim - Dm
9. clip set for panel inner trim - nec
10. Rear bootlid - DIS
11. Rear bootlid KIA log - nec
12. Rear bootlid FORTE emblem - nec
13. Rear bootlid CERATO emblem - nec
14. Rear bumper clipset - nec

Paintwork 2 panels
5 days workmanship



BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636
Tel: 6559 8944 / Fax: 6269 2404

AXA Insurance Singapore Pte Ltd
8 Shenton Way
#27-01 AXA Tower
Singapore (068811)
ATTN: MOTOR CLAIM DEPARTMENT
Tel : 6338 7288 Fax : 6880 4838

For
Authorized
1-B.1
Resony Bepaim
6 days

DEAR SIR / MADAM :

OD Claim

Fax: 62564315

ACCIDENT REPAIR ON: SKA5127A
MODEL : TOYOTA CAMRY 2.0
POLICY NO : GA058543/1
CHASSIS NO : MR053BK4107016818
ENGINE NO : 1AZE058834

Date: 17/01/2018
Page : 1 of 2

DATE / TIME OF ACCIDENT: 13/01/2018 Time: 1250Hrs ALONG ANG MO KIO AVE 6 TWDS SIN MING
THIRD PARTY VEHICLE NO: OD

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts

S/N	Quantity	Unit Price	Condition	Amount
		S\$		S\$
1 Bonnet	1	400.00		<i>An</i> 400.00 ✓
2 Bonnet Hinge LH *	1	30.00		<i>R</i> 30.00 ✓
3 Bonnet Hinge RH *	1	30.00		<i>R</i> 30.00 ✓
4 Bonnet Lock Assy	1	50.00		<i>An</i> 50.00 ✓
5 Bonnet Damper X2ps	1	110.00		<i>In</i> 110.00 x
6 Bonnet Insulator *	1	165.00		<i>In</i> 165.00 x
7 Bonnet Insulator Clips	10	2.00		<i>An</i> 20.00 ✓
8 Front Fender LH	1	185.00		<i>R</i> 185.00 x
9 Front Fender Shield LH	1	70.00		<i>In</i> 70.00 x
10 Front Fender Shield Clips	10	2.00		<i>An</i> 20.00 x
11 Front Fender RH	1	185.00		<i>R</i> 185.00 x
12 Front Fender Shield RH	1	70.00		<i>In</i> 70.00 x
13 Front Fender Shield Clips	10	2.00		<i>An</i> 20.00 x
14 Headlamp LH	1	275.00		<i>CR</i> 275.00 ✓
15 Headlamp RH	1	275.00		<i>CR</i> 275.00 ✓
16 Front Bumper	1	190.00		<i>CR</i> 190.00 ✓
17 Front Bumper Clips	10	2.00-1.50		<i>CR</i> 20.00 ✓ 15
18 Front Bumper Side Retainer LH	1	30.00		<i>CR</i> 30.00 ✓
19 Front Bumper Side Retainer RH	1	30.00		<i>CR</i> 30.00 ✓
20 Front Bumper Upper Grille Chrome	1	140.00		<i>CR</i> 140.00 ✓
21 Front Bumper Emblem	1	55.00		<i>An</i> 55.00 ✓ 3
22 Front Bumper Lower Grille	1	40.00		40.00 7
23 Front Bumper Tow Cover	1	10.00		<i>In</i> 10.00 x
24 Fog Lamp LH	1	100.00		<i>In</i> 100.00 x
25 Fog Lamp Cover LH *	1	30.00		<i>In</i> 30.00 ✓
26 Fog Lamp Cover Lining Chrome LH *	1	45.00		<i>In</i> 45.00 ✓
27 Fog Lamp RH	1	100.00		<i>In</i> 100.00 x
28 Fog Lamp Cover RH	1	30.00		<i>In</i> 30.00 x
29 Fog Lamp Cover Lining Chrome RH	1	45.00		<i>In</i> 45.00 x
30 Front Bumper Reinforcement *	1	145.00		<i>An</i> 145.00 ✓
31 Front Bumper Sponge	1	50.00		<i>CR</i> 50.00 ✓
32 Support Panel	1	310.00		<i>An</i> 310.00 ✓
33 Support Panel Top Garnish	1	130.00		130.00 7

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	06 Mar 2018 Edit Reg		22 Jan 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [\[Created by adjuster\]](#)

Insured:	YAK JUN WEI (YI JUNWEI), ID: S7914304I		
Main Claimant:	NG WEE FENG (WU WEIFEN), ID: S7422925E		
Vehicle Reg. No.:	SJS6611D	Date of Loss:	16/01/2018 13:00 - :59 [100 Months and 22 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 1835286331SG	Policy/Cover Note No.:	2100445405-02 (Comprehensive)
Vehicle Reg. No. (Insured):	SKX8795E	Policy No. (Claimant):	
		Excess:	
Repairer:	Nexwave Auto (HQ) 160, Sin Ming Drive, #05-15, Sin Ming Autocity, 575722 Sin Ming - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Wui, Shawn-KJ] Shawnkaijye.Wui@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MA CHIN FOOK] ... [Final Rpt due 15/03/2018]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (07/03/2018): No OI GIA Report
- AIG_SG (07/03/2018): Request To Upload TP GIA Report






















ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJS6611D (1835286331SG)**
[SKX8795E]
TP
NG WEE FENG (WU WEIFEN)
Jan 16 2018 1:10PM
[YAK JUN WEI (YI JUNWEI)]
Nexwave Auto

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser <input type="button" value="v"/>	
Assessment Reports			1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		
1	15/03/18 16:45	Accident Statement <small>From: SC - Reg. No: SKX8795E, Claimant: YAK JUN WEI (YI JUNWEI)</small>	<input checked="" type="checkbox"/> Thumbnail Load HTM	<input type="checkbox"/> Print
Photos/Images			3 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		
1	08/05/18 12:52	General View	<input checked="" type="checkbox"/> Thumbnail Load JPG	<input checked="" type="checkbox"/> Print
2	08/05/18 12:52	General View	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>
3	08/05/18 12:52	General View	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>
4	08/05/18 12:52	General View	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>
5	08/05/18 12:52	General View	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>
6	08/05/18 12:52	General View	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>
7	08/05/18 12:52	General View	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>
8	08/05/18 12:52	General View	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>
9	08/05/18 12:52	General View	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>
10	08/05/18 12:52	General View	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>
11	08/05/18 12:52	General View	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>
12	08/05/18 12:52	General View	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>
13	08/05/18 12:52	General View	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>
14	08/05/18 12:52	General View	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>
15	08/05/18 12:52	General View	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>
16	08/05/18 12:52	General View	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>
17	08/05/18 12:52	General View	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>
18	08/05/18 12:52	General View	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>
19	08/05/18 12:52	General View	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>
20	08/05/18 12:52	General View	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>
21	08/05/18 12:52	General View	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>
22	08/05/18 12:52	General View	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>
23	08/05/18 12:52	General View	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>
24	08/05/18 12:52	Photographs of Damaged Parts	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>
25	08/05/18 12:52	Photographs of Damaged Parts	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>
26	08/05/18 12:52	Photographs of Damaged Parts	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>
27	08/05/18 12:52	Photographs of Damaged Parts	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>
28	08/05/18 12:52	Photographs of Damaged Parts	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>
29	08/05/18 12:52	Photographs of Damaged Parts	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>
30	08/05/18 12:52	Photographs of Damaged Parts	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>
31	08/05/18 12:52	Photographs of Damaged Parts	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>
32	08/05/18 12:52	Photographs of Damaged Parts	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>
33	08/05/18 12:52	Photographs of Damaged Parts	<input checked="" type="checkbox"/> Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
34	08/05/18 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	08/05/18 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	08/05/18 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	08/05/18 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	08/05/18 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	08/05/18 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	08/05/18 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	08/05/18 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	08/05/18 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	08/05/18 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	08/05/18 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	08/05/18 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	08/05/18 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	08/05/18 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	08/05/18 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	08/05/18 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	08/05/18 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	08/05/18 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	08/05/18 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	08/05/18 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	08/05/18 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18001276/M1D3E2

Date: 11/05/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100445405-02

Claimant Vehicle No : SJS6611D

Insured Vehicle No : SKX8795E

Date of Loss: 16/01/2018

Nature of Claim: TP

Claim No: 1835286331SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJS6611D**

Make & Model: KIA CERATO FORTE, 1.6 EX (A)

Engine No: G4FC9H283530

Reg. Date: 25/08/2009 (Man. Year: 2009)

Chassis No: KNAFW411MA5112052

Colour: Black

Odometer: 157907 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45 R17

Rear Tyre Size: 215/45 R17

Front Left Side: Nexen 7 mm

Rear Left Side: Nexen 7 mm

Front Right Side: Nexen 7 mm

Rear Right Side: Nexen 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 22/01/2018

Date Inspected: 22/01/2018 Inspected At:

Nexwave Auto (HQ)
160, Sin Ming Drive, #05-15, Sin Ming
Autocity
Singapore 575722

Estimated Period of Repair: 5.0 days

Adjuster: MA CHIN FOOK

Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID LOCK	Bent	0.00 F	*- F
2	2		*REAR TAIL LAMP N/S & O/S	MTG Cracked	0.00 F	*- F
3	2		*REAR BOOTLID LAMP N/S & O/S	MTG Cracked	0.00 F	*- F
4	2		*REVERSE SENSOR	Damaged	0.00 F	*- F
5	1		*REAR BUMPER SPONGE	Torn	0.00 F	*- F
6	1		*REAR BUMPER REINFORCEMENT	Damaged	0.00 F	*- F
7	1		*REAR END PANEL	Damaged	0.00 F	*- F
8	1		*REAR END PANEL INNER TRIM	Damaged	0.00 F	*- F
9	1		*CLIP SET FOR PANEL INNER TRIM	Necessary	0.00 F	*- F
10	1		*REAR BOOTLID	Distorted	0.00 F	*- F
11	1		*REAR BOOTLID KIA LOG	Necessary	0.00 F	*- F
12	1		*REAR BOOTLID FORTE EMBLEM	Necessary	0.00 F	*- F
13	1		*REAR BOOTLID CERATO EMBLEM	Necessary	0.00 F	*- F
14	1		*SET REAR BUMPER CLIP	Necessary	0.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >