

ASS. REC. BY:

REF: CS3 / SMO18001282 / Wber

Special Instruction:

1 mly &amp; dms

Surveyor:

Wilson

## ASSIGNMENT (Office)

From (Person): Grace Teo

of

SMO

Date/Time: 22/01/2018 @ 2.06 pm

Estimated Cost:

Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKU 94644

Insured:

SJV 4566Z

at Workshop m/s

Twincor Automotive

Tel:

68420051

of

2 Kaki Blk Ave 2 # 01-17, 417921

Policy No:

Claim No:

CM7D1800337/GPL

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

19/01/2018

CA / REV / REP. / REV 24 HRS

w/p

H.O.D. Endorsement:

Date/Time: 2.37pm @ 22/1/18

Person Contacted:

Amely

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

SKU 94644 - X

SJV 4566Z - CA / CA11/002208/V

D.O.A 3/02/11

Dismantle Part: 23012018

After Repair: 26012018

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD/TP/WS/TP RES/OD RES/EVA/INV/MV  
 To inspect Vehicle No. SKU 94644  
 at Workshop mis NSI  
 of \_\_\_\_\_  
 Insured \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

Ball or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lump Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No SKU 94644 Yr Regn: 24/8/2015  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or

Make Hyundai Elantra cc 1591

Colour Dark Grey A/C Insured / Std / NI / NA

Sp. Reading 51590 T. Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No KM HDM 41CM 64590704

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55 AT6

R: 205/55 R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or H2FLY (R)

Front

Rear

R/Bal 4 mm R/Bal 4 mm

L/Bal 4 mm L/Bal 4 mm

D.O.A. 19/1/2018 D.O.A. 22/1/18

Survey held at: As Above

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Roottop or 432 pin

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

#8500 - #9500

9 Days Repair

RECEIVED 03 APR 2018

John  
3/4/2018

Date/Time File Pass to:

03042018

Date/Time File Return to:

☐ : Prell. Report  
☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transporter

1. S - R - S

2. Photo

3. Diagram

Add Fee: ☐ Site Insp /S

☐ Interview /S

☐ Tech Insp /S

☐ Weekend /S

Report Format: RS

Lump Sum / I.B.I: /S

## Nivitha (LKK Auto)

---

**From:** Teo, Grace <grace.teo@sompo.com.sg>  
**Sent:** Monday, 22 January 2018 2:06 PM  
**To:** Chin Hui Xin (huixin@n51.com.sg); admin-d@lkkauto.com; assignments@lkkauto.com  
**Cc:** Gnoh, Pau Loong; Henry, Irene James  
**Subject:** CMTD1800337/GPL - ACCIDENT INVOLVING SJV4566Z & SKU9464U ON 19.01.2018  
**Attachments:** 22012018123438.pdf; 19012018175944-0001.pdf

Our Reference : CMTD1800337/GPL  
Your Reference: SKU9464U

Without Prejudice

Date: 22<sup>nd</sup> January 2018

**Attention:**  
**M/S TWINCAR AUTOMOTIVE PTE LTD**

Dear Melody,

**ACCIDENT INVOLVING SJV4566Z & SKU9464U ON 19.01.2018**

Dear Yvonne,

We refer to your email reply dated 22/01/2018.

We do not agree to your list of surveyors.

As such, we will be appointing our motor surveyor, **LKK AUTO CONSULTANTS** to conduct the pre-repair survey of your client's vehicle.

The pre-repair survey will include a survey of the vehicle when its damaged parts are being dismantled prior to the commencement of repairs.

We would like our motor surveyor to conduct a post repair inspection once your client's vehicle has been repaired.

The survey is conducted on a without Prejudice basis and without any admission of liability.

Best Regards

**Grace Teo**

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

**SOMPO**

**A Century of Trust**

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

**From:** Chin Hui Xin [mailto:huixin@n51.com.sg]

**Sent:** Monday, January 22, 2018 12:36 PM

**To:** Teo, Grace

**Cc:** Gnoh, Pau Loong; Henry, Irene James

**Subject:** Re: CMTD1800337/GPL - ACCIDENT INVOLVING SJV4566Z & SKU9464U ON 19.01.2018

Dear Sir/Madam,

We refer to your list of motor surveyors proposed.

We do not agree to your list of motor surveyors.

Please see attached.

Thank you

Regards,


Melody Chin

N-51 Automotive Pte Ltd

Office : 6842 0051

Fax : 6741 0510

**[www.n51.com.sg](http://www.n51.com.sg)**



On Mon, Jan 22, 2018 at 11:49 AM, Teo, Grace <[grace.teo@sompo.com.sg](mailto:grace.teo@sompo.com.sg)> wrote:

Our Reference : CMTD1800337/GPL

Your Reference: SKU9464U

**Without Prejudice**

Date: 22<sup>nd</sup> January 2018

Attention:  
M/S TWINCAR AUTOMOTIVE PTE LTD

**ACCIDENT INVOLVING SJV4566Z & SKU9464U ON 19.01.2018**

Dear Melody,

We refer to your Notice of Accident dated 19/01/2018.

Please be informed that Gnoh Pau Loong the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

**Pre-Repair Survey**

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

**Grace Teo**

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

**SOMPO**

**A Century of Trust**

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

**From:** Chin Hui Xin [mailto:[huixin@n51.com.sg](mailto:huixin@n51.com.sg)]

**Sent:** Friday, January 19, 2018 6:02 PM

**To:** Claims - Motor Survey

**Subject:** SKU9464U & SJV4566Z - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS

Dear Sir/Madam,

As per above subject,

Please refer attachment and:-

Kindly propose / provide your 10 surveyors.

Thank you...

Regards,

Melody Chin

TWINCAR Automotive Pte Ltd

Office : 6842 0051

Fax : 6741 0510

**[www.n51.com.sg](http://www.n51.com.sg)**



# TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit Autohub

2 Kaki Bukit Ave 2, #01-17

Singapore 417921

Tel No. : +65 6744 0510 / 6842 0051 Fax No. : +65 6741 0510

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

Our Ref: **SKU 9464 U**

Your ref: **SJV 4566 Z**

19 January 2018

## TENET SOMPO INSURANCE PTE. LTD.

50 RAFFLES PLACE #05-01/06

SINGAPORE LAND TOWER

SINGAPORE 099253

Attn: Motor Claims Department

BY EMAIL [motorsurvey@sompo.com.sg](mailto:motorsurvey@sompo.com.sg) ONLY

Dear Sir/Madam,

**DATE OF ACCIDENT: 19 Jan 2018**

**NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS**

**PURSUANT TO PARAGRAPH 2.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES**

We are instructed by **KONG JIONG MUN** to notify you of a road traffic accident on **19 Jan 2018** at about **10:00 HOURS** At **KPE TUNNEL TOWARDS CITY** involving our client's vehicle **SKU 9464 U & SJV 4566 Z** driven by you/your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please be inform that we don't excess to Merimen System and kindly reply to us by Email / Fax.

Yours faithfully,



.....  
**Twincar Automotive Pte Ltd**



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	19/01/2018 16:37
Date Of Accident	19/01/2018 10:00
Exact Location Of Accident	KPE TUNNEL TOWARDS CITY
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKU9464U
<b>Insured/Policyholder</b>	
Name Of Registered Owner	KONG KIONG MUN
NRIC No	S1651576J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97698082
Alternative Phone No	OFFICE-97698082
<b>Vehicle Particulars</b>	
Manufacturer	HYUNDAI
Model	ELANTRA 1.6 AT ABS D/AB 2WD 4DR
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D17MTPV01009040
Cover Note Number	

### Driver

Name of Driver	KONG YU JIAN
NRIC No	S9421282J
Date Of Birth	19/06/1994
Occupation	INDOOR
Date Of Driving Pass	09/10/2015
Driving Experience	2 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97698082
Fax Number	
Contact Number	
E-Mail Address	KONGYUJIAN94@GMAIL.COM

Address	BLK 172B EDGEDALE PLAINS #12-490 SINGAPORE 822172
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

I (SKU9464U) WAS STATIONARY IN KPE TUNNEL TOWARDS CITY ON THE MOST RIGHT LANE AS THERE WERE A TRAFFIC JAM AHEAD WHEN SUDDENLY A CAR (SJV4566Z) HIT ME FROM THE BACK. DUE TO THE IMPACT, MY CAR MOVED FORWARD AND HIT THE A TAXI IN FRONT OF ME. NO INJURIES INVOLVED.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJV4566Z
Vehicle Make/Model/Colour	FORD/FOCUS TREND 1.6L AUTO/WHITE
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MUHAMMAD ZULFADHLI BIN MOHAMED BADRUZAMAM
NRIC/Passport Number	S9131510F
Contact Number	96230543
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	UNKNOWN
-----------------------------	---------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

TAXI

Name of Driver

UNKNOWN

NRIC/Passport Number

Contact Number

UNKNOWN

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

### Sketch Plan

### IMPORTANT NOTICE

- VERIFIED BY AJAX MARS  
REPORTING OFFICER  
MOHAMMAD SULHANDI BIN  
MOHD AFFANDI

---

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

### Sketch Plan



→ ?  
→ 5k494644  
→ 50V4566Z

Common Statement

ACCIDENT STATEMENT (2000 characters)

I (SKU9464U) WAS STATIONARY IN KPE TUNNEL TOWARDS CITY ON THE MOST RIGHT LANE AS THERE WERE A TRAFFIC JAM AHEAD WHEN SUDDENLY A CAR (SJV4566Z) HIT ME FROM THE BACK. DUE TO THE IMPACT, MY CAR MOVED FORWARD AND HIT THE A TAXI IN FRONT OF ME. NO INJURIES INVOLVED.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -  
MOHAMMAD SULHANDI BIN MOH AFFANDI

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

19 January 2018 at 4:07 PM

Date/Time:

19 January 2018 at 4:07 PM



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
SOMPO INSURANCE SINGAPORE PL		Ref: CS3/SMO18001282/Wbe2		
50 RAFFLES PLACE#05-01/06SINGAPORE LAND TOWERSINGAPORE 048623		Date: 03-04-2018		
		Code: SMO		
<b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>				
Insured Veh.	SJV 4566Z	Veh. Inspected	SKU 9464U	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD1800337/GPL	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	22/01/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HYUNDAI ELANTRA	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	KMHDH41CMGU590704	Colour	DARK GREY	
Odometer	51590 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	HIFLY	4 mm	
L/H Front Tyre	205/55 R16	HIFLY	4 mm	
R/H Rear Tyre	205/55 R16	HIFLY	4 mm	
L/H Rear Tyre	205/55 R16	HIFLY	4 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.				
<b>5. General Information</b>				
Accident Date	19/01/2018	Inspect Date / Time	22/01/2018 ( 04:32 PM )	
Survey held at	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$8,500-\$9,500				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			9 Working Days	

Report Ref No. CS3/SMO18001282/Wbe2

**Inspected By**

WILSON TEO CHENG MING

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MinstAE, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.