ASS. REC. BY:	REF: CS CT1	18001284/	Hd3 Decial Instruction:	
Surveyor:	ASSIG	NMENT (Office)	2	
From (Person): Perg	Peng of	CTI	Date/Time: _ 1910	1/18@ 2.51PM
Territaries Cost.		Bill to:		
OD/TP/WS/TP RES / OI	D RES / EVA / INV / N	IV / CS		
To Inspect Vehicle No:	STC	2581T	Insured: Public i	ability
at Workshop m/s	Motor I	nage	Tel: 6703 810	9
of 19 borong	& Toa payo	h		•
Policy No:	, O	Claim No:	SNEI7DOUGE2	
Sum Insured:		Excess:		
Make of Veh: (Client's Record)	2		D.O.A. 16/12	2017
CA / REV / REP. / REV		•	H.O.D. Endorsement:	3
Date/Time: 10.21am®	22/1/18 Person Conta	cted: Sayed	Vehicle IN OUT	
Date/Time Action/Instruc		mate.		
SLC 258	31T-X	8		
Malarial a	. (00.1			ν
- TI- VENICIE	not gent 1	n for vepo	XIV.	
41/19 Sulamit	preli repor	4.		

0.41-1.6	SUC 25817 05 16
Establish Control	The Mider of Circle Busy services Texas Remains as
OD (F) WS TF RES / OD RES ! EVA / INV M)	
51C 2581 T	On A. Wyen
Motor Image	
10 Tou Day of Amage	, , , , , ,
19 700 Payoh' Lorong &	St. Peacing 46747 TPass (Taured) \$15 N. N.L.
Policy from	JE1GP3KC5GG-168514
Diama No.	· · · · · · · · · · · · · · · · · · ·
	Sen Cont Fain Room Burns Steering India
	Stare Indian Jemmed Leaked Burn or
ary tu	Mod Nil 8 R m STOKER or
10.30 am - Ilam owner waiting	Tyre 8 cs = 225/55R17
Policy Condition	003/33/4
Remark. The ven had commenced its N.S. C.S.	BS DUN / EXNOVA G + FS LIZA MIC CHTSL PIR SUM
repair at the time of inspection	TOYO KOKO:
Ballior Market value	Est:
DAID Adddent Pports Consistent? : Yes or No	Esa 9 3
GLA FR Seen: Consistant? (Yes or No	LBa 4 LBa 3
Est Recars days Res. Yes or No	224 16h2117 = 27/2/18
Lim Sum 1.B11 % 3 Value Yes on No	Survey held at
OA / REV / REP. / 24 HRS /wr'	Design Damages Rt. Rear D/S N.S. U.C. Rooftool of
Venicle IN OUT Cate Person Contacted	Pri els
Date Time Action Instruction	The U.O. I Chassis frame I Body Structure affected questions is on
28/2 File pass to Carperine	
	0040
RECEIVED 0 4	JAN 2019
ì	
IslaTine Fia Passion	Days Of Recart
41 Typst	Days Of Recair 3
Date Time Pie Patum (g)	
And Fee	Signal Si
Report Former	0.27
.u-1:5 B 1	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Intern	nationale Des Experts En Autor	mobile
CHI	NA TAIPING INSU	JRANCE (S) PTE LTD	Ref : CS/CTI180012	284/Ktd3
	NSON ROAD #16- RINGLEAF TOWER	00 RSINGAPORE 079909	Date: 22-01-2018 Code: CTI	
1.		Policy Particul	ars :- THIRD PARTY CLA	IM
	Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	SLC 2581T
	Policy No.		Coverage (\$)	0.00
	Claim No.	SNE17D00062	Excess (\$)	0.00
	Assign From	PENG PENG	Assign Date	22/01/2018
2.		Vehicle Pa	articulars & Condition	
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	I.E.	Steering	
	Brakes		Modification	
	General			
3.		Con	ditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
1.		Descri	ption of Damages	
5.		Gen	eral Information	
	Accident Date	16/12/2017	Inspection Date	
	Survey held at	MOTOR IMAGE ENTERPRIS		
		19 TOA PAYOH LORONG 8 SINGAPORE 319255		
ā.			Remarks	
	A)THE INSPECTIO	ON WAS CONDUCTED ON A"\ CE TO YOUR INSTRUCTIONS	WITHOUT PREJUDICE" BAS	IS.

Catherine Chong (LKK Auto)

From: Peng Peng <peng.peng@sg.cntaiping.com> on behalf of Claims Dept of CTI

<claimsdept@sg.cntaiping.com>

Sent: Friday, 19 January, 2018 2:51 PM

To: assignments@lkkauto.com
Cc: Josephine Lee; Peng Peng

Subject: NEW ASSIGNMENT -- SLC2581T-SOMPO-3RD PARTY CLAIM-TP(CHINA TAIPING)

PRS (OUR REF: SNE17D00062)

Attachments: SLC2581T 3RD PARTY GIA REPORT.PDF; SLC2581T ESTIMATE.JPG

Importance: High

Dear Sirs.

We would like to engage your service for a third party survey (SLC2581T).

Estimate from the workshop is attached herewith for your necessary arrangement.

Kindly be noted that this case is not under our motor policy. As such, appreciate that you can email your survey report together with your bill to the undersigned for processing/settlement.

Looking forward to hearing from you soon.

Regards,

Peng Peng (Mr.)
Claims Department
China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00
Springleaf Tower
Singapore 079909

Co. Reg. No. 200208384E

DID: 6389 6185

Fax: 6224 7175/6224 7478

Email: <u>claimsdept@sg.cntaiping.com</u> <u>peng.peng@sg.cntaiping.com</u>

Website: www.sg.cntaiping.com

Disclaimer:

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore)
Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore)
Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately

From: Sayedinah Bin Ali [mailto:sayedinah@motorimage.net]

Sent: Friday, January 19, 2018 8:42 AM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Cc: Daniel Lim <daniellim@motorimage.net>; Rey Ricamora <reyricamora@motorimage.net>; Oliver Zubiri

<oli>ergracilla@motorimage.net>

TAIDING DES	
ubject: SLC2581T-SOMPO-3RD PARTY CLAIM-TP(CHINA TAIPING) PRS	
nportance: High	
i Claims Team,	
indly advise when can we arrange PRS.	
mary author man and a second	
egards	
ayedinah Ali	
ervice Executive	
Notor Image Enterprises Pte Ltd	
9 Lorong 8 Toa Payoh Singapore 319255	
HP;92992693 DID:67038109 FAX:+65-62535535	
Email:sayedinah@motorimage.net	
Website:www.tanchong.com :: www.motorimage.net	
veosite.www.tailenoig.com	
	f disclose
Disclaimer: This e-mail is confidential. It may also be legally privileged. If you are not the addressee	you may not copy, forward, disclose to
Disclaimer: This e-mail is confidential. It may also be legally privileged. If you are not the databases use any part of this message. If you have received this message in error, please delete it and all consender immediately by return e-mail. Internet communications cannot be guaranteed to be timely, so	ecure, error-free or virus-free. The
sender immediately by return e-mail. Internet communications cannot be guaranteed to be timely sender does not accept liability for any errors or omissions.	
sender does not accept hability for any entere or emissions.	
This email has been scanned by the Symantec Email Security cloud service.	
For more information please visit http://www.symanteccloud.com	
For more information please visit http://www.symantecoloud.com	

Denise Tay (LKKAuto)

From:

Sayedinah <sayedinah@motorimage.net>

Sent:

Friday, 4 January 2019 10:57 AM

To:

Denise Tay (LKKAuto)

Cc:

TPY Insurance Team; Mohamed Isman

Subject:

Re: SLC 2581T / CHINA TAI PING / DOA:16/12/2017

Importance:

High

Hi Denise,

as spoken earlier my insured did not sens in car for repair. Please close case on both ends . Thank you.

Regards

Sayedinah Ali

Service Executive

Motor Image Enterprises Pte Ltd

19 Lorong 8 Toa Payoh Singapore 319255

HP;92992693 DID:67038109 FAX:+65-62535535

Email:sayedinah@motorimage.net

Website:www.tanchong.com :: www.motorimage.net

From: Denise Tay (LKKAuto) <denisetay@lkkauto.com>

Sent: Friday, 4 January 2019 10:05 AM

To: Sayedinah Cc: Daniel Jude

Subject: RE: SLC 2581T / CHINA TAI PING / DOA:16/12/2017

Dear Sayed,

Can check for me if finalize ready?

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>denisetay@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAuto)

Sent: Friday, 21 December 2018 5:35 PM

To: 'Sayedinah' <sayedinah@motorimage.net>

Subject: RE: SLC 2581T / CHINA TAI PING / DOA:16/12/2017

Dear Sayedinah,

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

foresaid.	
	ACCIDENT STATEMENT
Date Of Report	20/12/2017 11:31
Date Of Accident	16/12/2017 16:25
Exact Location Of Accident	BLK 4A HOUGANG STREET 11 #01-83 S(538754)
Country/State of Loss	SINGAPORE
D	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SLC2581T
Insured/Policyholder	
Name Of Registered Owner	SOH HWEE TIN
NRIC No	\$17031131
Email Address	GU9560@SINGNET.COM.SG
Mobile Phone No	(LOCAL) +65-98537642
Alternative Phone No	OFFICE-NOPHONE
Vehicle Particulars	
Manufacturer	SUBARU
Model	XV-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	LEISURE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D17MTPV01005759
Cover Note Number	

Driver

Name of Driver SOH HWEE TIN NRIC No S1703113I Date Of Birth 21/02/1965 Occupation INDOOR Date Of Driving Pass 23/04/1985

Driving Experience 32 YEARS AND 7 MONTHS

Gender **FEMALE**

Mobile Number (LOCAL) +65-98537642

Fax Number

Contact Number OFFICE-NOPHONE

EMail Address GU9560@SINGNET.COM.SG Address

50 CHOA CHU KANG NORTH 7 #01-09 S(689527)

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

-

Insurance Company of Driver's Own Vehicle

-

General Information of the Accident

Type Of Accident

HIT BY FALLEN TREE / OTHER OBJECTS

Weather Conditions

RAINING

Road Surface

WET

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

Was any other material or property damaged?

NO

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

2

Number of Passengers (Including Driver)

Passenger 1

NAME:

: N/A

GENDER:

: MALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- 1. Rease report correctly the details of the accident to speed up the claims process.
- This Formmust be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may sllow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the ladgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me. which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

older's Signature /

Policyholder's Signature / Date & Time

Driver's Signature (# driver is not the policyholder) / Date 8 Time

Witnessed by Reporting Centre Personnel

Sketch Plan

Common Statement

H-g-	NPE	000	mark .	100		000	15	0.0	0100		
	F+1 2	KOM	-11	CF	الرك	1.		1841	2121216	-1	
BARR	12/4		アルト	7	UP		PM	0	I	onove Dno!	
RASS		BUT		841	DOW	5		200	212/2	Drop	61
any		(CAR	- 1							
											-
-											

Declaration

We declare the foregoing particulars are true in every respect.

4


Policyholder's Signature / Date & Time

Driver's Signature (# driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



19 Lorong 8 Toa Payoh Singapore 319255





ESTIMATE COST OF REPAIRS

REG NO: SLC2581T	MODEL : SUBARU XV
ENGINE NO:FB16Y229720	CHASSIS NO:JFIGP3KC5GG169514
DATE IN:26/12/2017	

S/N	NATURE OF JOB	AMOUNT
1	TO REPAIR & RESPRAY FRT RH 'A' PILLAR	\$350.00
2	REMOVE & REFIX FRT WINDSCREEN	\$300.00
3	SUPPLY & INSTALL FRT WINDSCREEN TINTED FILM WITH ANTI	\$145.00
	GLARE	
4	REMOVE, REFIX & RESPRAY SIDE MIRROR COVER/ASSY A pille	\$150.00 _
	Total labour	\$945.00

S/N	PARTS DESCRIPTIO		PRICE		
			QTY	LIST	S/NETT
1	GLASS FRT WINDOW	Sh.	1	\$1800.00	X
2	MOULDING FRT WINDOW	NE	1	\$108.00	_
3	DAM RUBBER FRT LOWER	M	1	\$14.40	
4	DAM RUBBER FRT UPPER	N	1	\$10.80	
5	SHEET SILICON	No	\ 1	\$14.30	_
6	DOOR MIRROR UNIT -RIGHT	2	1	\$363.60	X
7	LED SIDE MIRROR GLASS	Sy	1	\$500.00	1
8	COVER-CAP OUT MIRROR, RIGHT	1	\$64.80	*	
9	LAMP ASSY SIDE TURN, MIRROR RI	, 1	\$102.00	1	
10	COVER -CAP OUT MIRROR, RIGHT L	OWER SL	- 1	\$33.90	X
	LKK Auto Consultants hence notify the Repairer of the following:	SUB TO	OTAL:	\$3011.80	
	To resurvey before/after spray painting				i -
	To display damaged part(s) during resurvey	LABOUR T	OTAL	\$945.00	
	Parts prices are subject to confirmation Third party survey is on a "Without Prajurice" basis.	PARTS T	OTAL	\$3011.80	
	No illegal modification(s) is allowed	T	OTAL	\$3956.80	
	Supplementary item(s) must be resurveyed and	G	ST 7%	\$ 276.98	
	is subject to final approval from insurance dompany Acknowledged by Repairer	GRAND TO	OTAL	\$4233.78	

DATE APPROVAL:	The state of the s
TIME APPROVAL:	
CONTACT PERSON:	SAYEDINAH ALI (SERVICE EXECUTIVE)
DID / FAX / EMAIL:	DID:67038109 FAX:62535535 Email:Sayedinah@motorimage.net



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Intern	ationale Des Experts En Automo	bile
СНІІ	NA TAIPING INSU	RANCE (S) PTE LTD	Ref : CS/CTI18001284	/Ktd3e2
	NSON ROAD #16-0 RINGLEAF TOWER	00 RSINGAPORE 079909	Date: 04-01-2019 Code: CTI	
1.	SELECTION OF THE	Policy Particula	ars :- THIRD PARTY CLAIM	
	Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	SLC 2581T
	Policy No.		Coverage (\$)	0.00
	Claim No.	SNE17D00062	Excess (\$)	0.00
	Assign From	PENG PENG	Assign Date	19/01/2018
2.		Vehicle Pa	articulars & Condition	
	Make & Model	SUBARU XV (A)	c.c	1600
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	JF1GP3KC5GG169514	Colour	METALLIC SILVER
	Odometer	46747	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3.		Con	ditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	225/55 R17	YOKOHAMA	4 mm
	L/H Front Tyre	225/55 R17	YOKOHAMA	4 mm
	R/H Rear Tyre	225/55 R17	YOKOHAMA	3 mm
	L/H Rear Tyre	225/55 R17	YOKOHAMA	3 mm
4.			ption of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE	FRONT O/S PORTION.	
	DAMAGES SEE D	ETAILS.		
5.		Gen	eral Information	
	Accident Date	16/12/2017	Inspection Date	27/02/2018
	Survey held at	MOTOR IMAGE ENTERPRIS	SES PTE LTD	
		19 TOA PAYOH LORONG 8 SINGAPORE 319255	Ŧ	
5a.			Remarks	
	B)THE INSPECTION		AIRS. WITHOUT PREJUDICE" BASIS S, WE HAVE NOT AUTHORISE	
5b.		Estima	ate Days of Repair	THE MANAGEMENT OF THE PARTY.
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLC 2581T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	GLASS FRT WINDOW	SERVICEABLE	1,800.00	-
1	MOULDING FRT WINDOW	NECESSARY	108.00	108.00
1	DAM RUBBER FRT LOWER	NECESSARY	14.40	14.40
1	DAM RUBBER FRT UPPER	NECESSARY	10.80	10.80
1	SHEET SILICON	NECESSARY	14.30	14.30
1	DOOR MIRROR UNIT - RIGHT	SERVICEABLE	363.60	-
1	LED SIDE MIRROR GLASS	SERVICEABLE	500.00	-
1	COVER-CAP OUT MIRROR, RIGHT	SERVICEABLE	64.80	-
1	LAMP ASSY SIDE TURN, MIRROR RIGHT	SERVICEABLE	102.00	-
1	COVER-CAP OUT MIRROR, RIGHT LOWER	SERVICEABLE	33.90	-
			3,011.80	147.50
	LABOUR			
	TO REPAIR & RESPRAY FRT RH 'A' PILLAR.		350.00	350.00
	REMOVE & REFIX FRT WINDSCREEN.		300.00	300.00
	SUPPLY & INSTALL FRT WINDSCREEN TINTED FILM WITH ANTI GLARE.		145.00	145.00
	REMOVE, REFIX & RESPRAY A PILLAR.		150.00	150.00
			945.00	945.00
	GRAND TOTAL		3,956.80	1,092.50

<u> </u>	
RECOMMENDED COST OF REPAIRS	1,092.50
(REPAIR COST NOT CONCLUDE)	

Report Ref No. CS/CTI18001284/Ktd3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.