### SINGAPORE ACCIDENT STATEMENT

# IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

alulesalu.	
	ACCIDENT STATEMENT
Date Of Report	22/01/2018 12:28
Date Of Accident	21/01/2018 16:15
Exact Location Of Accident	PIE TWDS AIRPORT BEFORE JLN EUNOS EXIT
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SLG8229B
Insured/Policyholder	
Name Of Registered Owner	TAN CHEE HUA CLEMENCE
NRIC No	S7528197H
Email Address	CLEMTCH@YAHOO.COM
Mobile Phone No	(LOCAL) +65-96269825
Alternative Phone No	OFFICE-91839275
Vehicle Particulars	
Manufacturer	BMW
Model	4201
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	CN793561
Cover Note Number	
Dulyan	

### Driver

Name of Driver TAN CHEE HUA CLEMENCE

NRIC No S7528197H
Date Of Birth 24/09/1975
Occupation INDOOR
Date Of Driving Pass 21/01/1998

Driving Experience 20 YEARS AND 0 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-96269825

Fax Number

Contact Number OFFICE-91839275

EMail Address CLEMTCH@YAHOO.COM

50 LORONG 40 GEYLANG #02-16 Address

Postcode 398074

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured **OWNER** 

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

### **General Information of the Accident**

Type Of Accident **CHAIN COLLISION** 

Weather Conditions **CLEAR** Road Surface DRY

### Other Information

Was any foreign vehicle involved in this accident? NO Number of vehicles involved in the accident 2 Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance?

NO

YES Was any other material or property damaged? I have been approached by unknown person(s) soliciting/offering accident claims assistance.

YES

Number of Passengers (Including Driver) 1

### **Details of Police Action**

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

# **Circumstances of Accident**

REFER TO ATTACH.

# Attachment(s)

YES Are accident photos available for attachment? Was there any video captured by Car Camera? YES Was there any audio recorded? NO

# **DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SLE3694J

TOYOTA COROLLA ALTIS SILVER Vehicle Make/Model/Colour

**Details Of Properties** 

PRIVATE HIRE Vehicle Category Name of Driver THENG YEW PIOW

NRIC/Passport Number S1319645A Contact Number 96155706

Address BLK 717A WOODLANDS DR 70#12-06

731717 Postcode

Insurance Company Name AIG ASIA PACIFIC INSURANCE PTE. LTD.

FRONT REAR Nature Of Damage

No. Of Passenger (Including Driver)

# **DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number SLT8980X

Vehicle Make/Model/Colour TOYOTA PRIUS SIVLER **Details Of Properties** 

Vehicle Category PRIVATE HIRE
Name of Driver TAN AH GUAN
NRIC/Passport Number S1776641D
Contact Number 93675201

Address BLK 534 ANG MO KIO AVE 10 #12-2535

Postcode 560534

Insurance Company Name

Nature Of Damage FRONT

No. Of Passenger (Including Driver)

### SKETCH PLAN

# IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:


22 JAN 2018, 10 am

Driver's Signature (If driver is not the policyholder)

Date & Time:

Reporting Ce rsonnel's Signature Name:

NRIC/FIN No.:



# DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On Sunday 21 DAN 2018. I was driving along ple towards airport. About 4.10-4.15 pm. the cars in front of me On the fastest right-most lane Jam break, and I Jam-break as well. I managed to do so on time, and did not hit the car in front. I then saw the Car behind me also stationizing, but very shortly thereafter. I felt my car was hit from behind.  There were 2 knocks I heard, which I believe one was from the car behind onto the rear of my car. and the other was from the 3rd car knocking onto the 2nd car between my cor and the 3rd car in the chain collision: The accident site is before the Dalan Euros exit.  I have captured pictures and videos of the accident and the two drivers (of the 2nd and 3rd
airpoint. About 4.10-4.15 pm. the cors in front of me on the fastest right-most lane Jam break, and I Jam-break as well. I managed to do so on time, and did not hit the car in front. I then saw the car behind me also stationary, but very shortly thereafter. I felt my car was hit from behind.  There were 2 knocks I heard, which I believe one was from the car behind onto the rear of my car, and the other was from the 3rd car knocking onto the 2nd car between my cor and the 3rd car in the chain collision. The accident site is before the Jalan Eunos exit.  I have captured pictures and videos of the
Jam-break as well. I managed to do so on time, and did not hit the car in front. I then saw the car behind me also startionary, but very shortly thereafter. I felt my car was hit from behind.  There were 2 knocks I heard, which I believe one was from the car behind onto the rear of my car, and the other was from the 3rd car knocking onto the 2nd car between my cor and the 3rd car in the chain collision. The accident site is before the Jalan Eunos exit.  I have captured pictures and videos of the
Jam-break as well. I managed to do so on time, and did not hit the car in front. I then saw the car behind me also stationizing, but very shortly thereafter. I felt my car was hit from behind.  There were 2 knocks I heard, which I believe one was from the car behind onto the rear of my car, and the other was from the 3rd car knocking onto the 2nd car between my cor and the 3rd car in the chain collision. The accident site is before the Dalan Euros exit.  I have captured pictures and videos of the
and did not hit the car in front. I then saw the car behind me also stationary, but very shortly thereafter. I felt my car was hit from behind.  There were 2 knocks I heard, which I believe one was from the car behind onto the rear of my car, and the other was from the 3rd car knocking onto the 2nd car between my cor and the 3rd car in the chain collision. The accident site is before the Jalan Euros exit.  I have captured pictures and videos of the
car behind me also stationary, but very shorthy thereafter. I felt my car was hit from behind.  There were 2 knocks I heard, which I believe one was from the car behind onto the rear of my car, and the other was from the 3rd car knocking onto the 2nd car between my cor and the 3rd car in the chain collision. The accident site is before the Dalan Euros exit.  I have captured pictures and videos of the
thereafter. I felt my car was hit from behind.  There were 2 knocks I heard, which I believe one was from the car behind onto the rear of my car.  and the other was from the 3rd car knocking onto the 2nd car between my cor and the 3rd car in the chain collision: The accident site is before the Jalan Euros exit.  I have captured pictures and videos of the
There were 2 knocks I heard, which I believe one was from the car behind onto the rear of my car. and the other was from the 3rd car knocking onto the 2nd car between my cor and the 3rd car in the chain collision. The accident site is before the Jalan Eunos exit.  I have captured pictures and videos of the
was from the car behind onto the rear of my car.  and the other was from the 3rd car knocking onto the 2nd car between my cor and the 3rd car in the chain collision: The accident site is before the Jalan Euros exit.  I have captured pictures and videos of the
and the other was from the 3rd car knocking onto the 2nd car between my cor and the 3rd car in the chain collision. The accident site is before the Jalan Euros exit.  I have captured pictures and videos of the
the 2nd car between my cor and the 3rd car in the chain collision. The accident site is before the Jalan Eunos exit.  I have captured pictures and videos of the
the chain collision. The accident site is before the Jalan Eunos exit.  I have captured pictures and videos of the
The Dalon Euros exit.  I have captured pictures and videos of the
I have captured pictures and videos of the
accident and the two drivers (of the 2nd and 3rd
car respectively) on my mobile phone. Car plate for
2rd car is SLE36947 and the 3rd car is SLT8980X.
A traffic marshol and on EMAS Petrol Officer
arrived and advised us to move the cars to
the road shoulder after taking the photos and videos.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature Date & Time:

Driver's Signature

(If driver is not the policyholder)


27 DAN 2018, 10.15 om Date & Time:

Name: NRIC/FIN No.:

Reporting Centre Personnel's Signature













# Accident Photo 27 91. 20/18 11:144

