

CASE OWNER:

LKK:
IDAC:

Surveyor:

ASSIGNMENT

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :S\$

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

Global Sum S\$:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2 (Strife if 1 A.)

S\$

Name 2:

Payee 3 (Strife if 1 A.)

S\$

Name 3:

ASSIGNMENT

From: Date: 23/01/2018

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SJU 4482L

at Workshop: Kikim Hin Auto

at 160 Sin Ming Drive #02-20

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Van:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Sal. or Market Value: \$30k

OAC Accident Report: Consistent? Yes or No

SIA / PR Seen: Consistent? Yes or No

Est. Repairs: 6 days Res: Yes or No

Lump Sum: 28.2% 3 Val: Yes or No

CA / REV / REP. / 24 HRS / wp

Date: Person Contacted:

Vehicle: IN / OUT

Date / Time Action / Instruction

24/1 File pass to Catherine

30/1/18 Submit 28.2% 6611.28 with 6 working days exclude check item \$1681.26.

Date / Time File Pass to:

☐

Prel. Report

☐

Final Report

Date / Time File Return to:

Date / Time File Return to:

Report Format:

Lump Sum / 1.8 / 1

Ref: SJU 4482L 12 09

Type: Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover

Truck / Trailer of:

Make:

NIS Tean

1997

Colour:

M. Silver

A/C Insured / Std / Nil / NA

So Reading:

211582

T-Radio Insured / Std / Nil / NA

Eng No:

JN1BDUJ32Z0001101

O No:

Gen Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / R/Rim or

Tyre Size:

215/55R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI

TOYO / YOKO or

Dayton

Front:

Rear:

R/Bal:

2 mm

R/Bal:

3 mm

L/Bal:

2 mm

L/Bal:

3 mm

D/OA:

17/1/18

D/OA:

23/1/18

Survey held at:

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Roctop or

The U/C / Chassis frame / Body Structure affected due to collision

(Red- \$ 7250.89
51%)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transporter:

Add Fee:

Site Insp: \$

Interf: \$

Techn: \$

Lab: \$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL		Ref : CC4/III18001305/Kka3		
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 22-01-2018		
		Code : III2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8825Z	Veh. Inspected	SJU 4482L	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	22/01/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	17/01/2018	Inspection Date	23/01/2018	
Survey held at	K KIM HIN AUTOMOTIVE PTE LTD BLK 34 SIN MING DRIVE, #01-114, SINGAPORE 575708			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9145C
Vehicle Details	
Vehicle No.:	SJU4482L
Vehicle to be Exported:	No
Intended De-registration Date:	19 Jan 2018
Vehicle Make:	NISSAN
Vehicle Model:	TEANA 2.0L CVT ABS D/AIRBAG 2WD
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	MR20768734A
Chassis No.:	JN1BDUJ32Z0001101
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$29,624.00
Original Registration Date:	09 Dec 2009
First Registration Date:	09 Dec 2009
Transfer Count:	1
Actual ARF Paid:	\$29,624.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	08 Dec 2019
PARF Rebate Amount:	\$16,293.00
Intended COE Rebate Details	
COE Expiry Date:	08 Dec 2019
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$21,301.00
COE Rebate Amount:	\$3,414.00
Total Rebate Amount:	\$19,707.00

The information contained herein is correct as at 19 Jan 2018



CO. REG. NO: 199402370D
GST NO: M2-0123250-3

AUTO PTE LTD

金興(興)汽車私人有限公司

160 Sin Ming Drive, #02-18/19/20/21,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

TP INSURER: India International Insurance Pte Ltd (HQ)
NIL

Singapore

Claimant Insurer: Tokio Marine Insurance Singapore Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	17/01/2018
Vehicle Reg. No.:	SJU4482L	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	TEO CHOON KHNG		
Make/Model:	NISSAN TEANA, 2.0 (A)	Vehicle Reg. Date:	09/12/2009
Vehicle Colour:	SILVER	Chassis No:	JN1BDUJ32Z0001101
Engine No:	MR20768734A		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	86		
Description of Accident/Loss	PLEASE REFER TO SKETCH PLAN.		
Remarks:	VEHICLE IS IN, KINDLY ARRANGE FOR SURVEY. THANK YOU.		
Present Location:	K KIM HIN AUTO PTE LTD (HQ)		

*Not Notified
61 days & ?
Resurvey After Paint*

COST OF CLAIMS

	Amount
Parts	10,998.17
Miscellaneous Items	10.00
Labour	2,670.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	13,678.17
+ GST 7.00% (S\$)	957.47
Nett Amount (S\$)	14,635.64

This claim is handled by: **WONG SHU MAN**

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 22 Jan 2018)
 Parts: 143 NISSAN TEANA 2.0 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SJU4482L)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars		%Disc	%Depr	Amount	
1	2		*REAR NUMBER PLATE LAMP (LH/RH)	Sm	0.00	0.00	*156.80 F	X
2	1		*REAR BUMPER	Bu	0.00	0.00	*840.00 F	✓
3	2		*REAR BUMPER SIDE RETAINER (LH/RH)	NIS Di	0.00	0.00	*92.60 F	✓
4	10		*REAR BUMPER CLIPS	Mc	0.00	0.00	*44.00 F	✓
5	2		*REAR BUMPER CHROME MOULDING (LH/RH)	Mc	0.00	0.00	*291.00 F	✓
6	1		*REAR BUMPER SPONGE	CM	0.00	0.00	*139.00 F	✓
7	1		*REAR BUMPER REINFORCEMENT		0.00	0.00	*330.90 F	?
8	2		*REAR BUMPER REINFORCEMENT BRACKET (LH/RH)		0.00	0.00	*190.40 F	?
9	2		*TAILLAMP ASSY (LH/RH)	OIS M	0.00	0.00	*1,146.20 F	✓
10	2		*TAILLAMP SIDE COVER (LH/RH)	NIS Di	0.00	0.00	*76.00 F	✓
11	1		*BOOTLID	B	0.00	0.00	*1,000.70 F	✓
12	1		*BOOTLID LOGO	Mc	0.00	0.00	*50.70 F	✓
13	1		*BOOTLID TEANA EMBLEM	Mc	0.00	0.00	*105.20 F	✓
14	1		*BOOTLID 200XL EMBLEM	Mc	0.00	0.00	*80.90 F	✓
15	1		*BOOTLID OUTER CHROME MOULDING-TOP		0.00	0.00	*369.10 F	?
16	1		*BOOTLID OUTER CHROME MOULDING-BOTTOM	Mc	0.00	0.00	*252.80 F	✓
17	2		*BOOTLID HINGES (LH/RH)	R	0.00	0.00	*340.60 F	X
18	2		*BOOTLID DAMPER (LH/RH)	Sm	0.00	0.00	*364.60 F	X
19	1		*BOOTLID LOCK	Mc	0.00	0.00	*112.00 F	✓
20	1		*BOOTLID LOCK CATCH	R	0.00	0.00	*57.90 F	X
21	1		*BOOTLID WEATHERSTRIP	OIS Di	0.00	0.00	*1,568.00 F	50%
22	1		*BOOTLID INNER TRIM	Sm	0.00	0.00	*288.20 F	X
23	10		*BOOTLID INNER TRIM CLIPS	Mc	0.00	0.00	*44.00 F	X
24	1		*REAR END PANEL	B	0.00	0.00	*550.20 F	✓
25	1		*REAR END PANEL TOP GARNISH	Mc	0.00	0.00	*95.30 F	✓
26	1		*SPARE TYRE PANEL	R	0.00	0.00	*979.40 F	X
27	1		*SPARE TYRE PANEL TOP SPONGE COMPARTMENT-CENTRE		0.00	0.00	*462.00 F	?
28	2		*SPARE TYRE PANEL TOP SPONGE COMPARTMENT (LH/RH)	Sm	0.00	0.00	*231.00 F	X
29	1		*SPARE TYRE PANEL TOP BOARD	Sm	0.00	0.00	*564.60 F	X
30	2		*REAR FENDER INNER TRIM LINING	Sm	0.00	0.00	*591.20 F	X
31	1		*REAR NUMBER PLATE	Mc	0	0.00	*40.00 FS	✓
32	1		*REVERSE SENSOR	Ta 200Sn	0	0.00	*220.00 FS	
33	1		*REVERSE CAMERA		0	0.00	*380.00 FS	?
34	1		*REAR END PANEL SMART KEYLESS ANTENNA		0	0.00	*84.40 FS	?

F=Franchise part, S=Spchelt.

Sub Total (\$\$) 12,139.70
 - Add. Disc. on L,N Items 10.00% (\$\$) 1,141.53
 Total Parts (\$\$) 10,998.17

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	10.00
Sub Total (S\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIT AND TO RENEW AFFECTED PARTS.	New	1,100.00
2	TO FOCUS TAILLAMPS. TO CHECK WIRING AND LIGHTING OPERATION.	New	200 50.00
3	TO APPLY UNDERSEALING.	New	600 120.00
4	TO REMOVE AND REFIT REAR UPHOLSTERY TRIMMING, ROOF LINING, SEATS, SPEAKER BOARD IN ORDER TO FACILITATE REPAIRING WORKS.	New	600 120.00
5	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.	New	900 1,200.00
6	TO REMOVE AND REFIT REVERSE SENSOR ASSY.	New	500 80.00
Gross Labour Cost (S\$)			2,670.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Vivian Lau (LKKAUTO)

From: Vivian Lau (LKKAUTO)
Sent: Thursday, 30 May, 2019 3:10 PM
To: Manivel Priyadarshini
Cc: Hsiao Tong (LKKAUTO)
Subject: Your ref: MCT18010507, Our Ref: CC4/III18001305/Kwa3, ACCIDENT INVOLVING SHC 8825Z AND SJU 4482L ON 17/01/2018 ALONG UPPER PAYA LEBAR RD

Your ref: MCT18010507
Our Ref: CC4/III18001305/Kwa3

Dear Priya,

ACCIDENT INVOLVING SHC 8825Z AND SJU 4482L ON 17/01/2018 ALONG UPPER PAYA LEBAR RD

We refer to the above matter.

Be informed that till date TP's repairer had not finalised with our surveyor since 23/01/2018 after inspection .

In view of no further development, we will proceed to temporary close the file and submit the report to your office.

If any new development in future, we will keep you informed for an update and follow up the matter accordingly.

Thank you

Best Regards,

Vivian Lau | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-8625 | email: Vivianlau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Monday, 22 January 2018 2:50 PM
To: admin1@kkimhin.com.sg; 'sur@lkkauto.com'; Catherine Chong (LKK Auto)
Cc: service@kkimhin.com.sg; sandrakhong@gmail.com; Manivel Priyadarshini
Subject: RE: Accident involving SJU 4482 L and SHC 8825 Z on 17/1/2018
Attachments: GIA REPORT.PDF

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SJU4482L and let us have your report urgently.

This claim will be handled by Ms Priya.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

2.57pm @ 22/01/2018
vehicle In
person @ shuman
arrange on 23/01/2018

From: admin1@kkimhin.com.sg [mailto:admin1@kkimhin.com.sg]
Sent: 22 January, 2018 2:45 PM
To: Motor Claim - III <motorclaim@iii.com.sg>; Manivel Priyadarshini <manivel@iii.com.sg>
Cc: service@kkimhin.com.sg; sandrakhong@gmail.com
Subject: RE: Accident involving SJU 4482 L and SHC 8825 Z on 17/1/2018

Dear Gabriel,

We had chosen LKK Auto Consultants Pte Ltd previously.

Thank you.

Best Regards,

Shuman

K. Kim Hin Auto Pte Ltd

Tel: 6452 7018 Fax: 6458 3895

From: Motor Claim - III [mailto:motorclaim@iii.com.sg]
Sent: 22 January, 2018 2:43 PM
To: admin1@kkimhin.com.sg; Manivel Priyadarshini
Cc: service@kkimhin.com.sg; sandrakhong@gmail.com
Subject: RE: Accident involving SJU 4482 L and SHC 8825 Z on 17/1/2018

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

From: admin1@kkimhin.com.sg [mailto:admin1@kkimhin.com.sg]

Sent: 22 January, 2018 2:25 PM

To: Motor Claim - III <motorclaim@iii.com.sg>; Manivel Priyadarshini <manivel@iii.com.sg>

Cc: service@kkimhin.com.sg; sandrakhong@gmail.com

Subject: RE: Accident involving SJU 4482 L and SHC 8825 Z on 17/1/2018

Dear Gabriel,

Estimate has been submitted through Merimen.

Kindly arrange for survey.

Dear Ms Priya,

Kindly advise liability.

Thank you.

Best Regards,

Shuman

K. Kim Hin Auto Pte Ltd

Tel: 6452 7018 Fax: 6458 3895

From: Motor Claim - III [mailto:motorclaim@iii.com.sg]

Sent: 22 January, 2018 11:39 AM

To: admin1@kkimhin.com.sg

Cc: service@kkimhin.com.sg; sandrakhong@gmail.com; simon@kkimhin.com.sg; survey@kkimhin.com.sg

Subject: RE: Accident involving SJU 4482 L and SHC 8825 Z on 17/1/2018

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SJU4482L and let us have your report urgently.

This claim will be handled by Ms Priya.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

From: admin1@kkimhin.com.sg [mailto:admin1@kkimhin.com.sg]

Sent: 22 January, 2018 10:41 AM

To: Motor Claim - III <motorclaim@iii.com.sg>

Cc: service@kkimhin.com.sg; sandrakhong@gmail.com; simon@kkimhin.com.sg; survey@kkimhin.com.sg

Subject: RE: Accident involving SJU 4482 L and SHC 8825 Z on 17/1/2018

Dear Gabriel,

Kindly assign LKK Auto Consultants Pte Ltd.

Thank you.

Best Regards,

Shuman

K. Kim Hin Auto Pte Ltd

Tel: 6452 7018 Fax: 6458 3895

From: Motor Claim - III [mailto:motorclaim@iii.com.sg]

Sent: 22 January, 2018 9:26 AM

To: admin1@kkimhin.com.sg

Cc: service@kkimhin.com.sg; sandrakhong@gmail.com; simon@kkimhin.com.sg; survey@kkimhin.com.sg

Subject: RE: Accident involving SJU 4482 L and SHC 8825 Z on 17/1/2018

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

From: admin1@kkimhin.com.sg [<mailto:admin1@kkimhin.com.sg>]
Sent: 20 January, 2018 10:30 AM
To: Motor Claim - III <motorclaim@iii.com.sg>
Cc: service@kkimhin.com.sg; sandrakhong@gmail.com; simon@kkimhin.com.sg; survey@kkimhin.com.sg
Subject: Accident involving SJU 4482 L and SHC 8825 Z on 17/1/2018

Your ref: SHC 8825 Z
Our ref: SJU 4482 L

Dear all,

Enclosed the GIA report of our client SJU 4482 L, who was hit by your insured SHC 8825 Z, on 17/1/18.

Vehicle is in and working on the estimate, we will be submitting it in Merimen and arrange for survey once ready.

Kindly advise liability.

Thank you.

Best Regards,
Shuman
K. Kim Hin Auto Pte Ltd
Tel: 6452 7018 Fax: 6458 3895

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be

intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est. Submitted	Adj. Assigned	Adj. Rpt	Adj. Submitted	Ins. Auth'd	Status
Main	22 Jan 2018 12:00 Sendback Est	22 Jan 2018 14:19 S\$13,678.17	22 Jan 2018 14:50 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	NIL, Co. Reg. No.: 0		
Main Claimant:	TEO CHOON KHNG, ID: S1279145C		
Vehicle Reg. No.:	SJU4482L	Date of Loss:	17/01/2018 22:00 - :59
Claim Type:	TP	Policy/Cover Note No.:	Coverage: 09/06/2017 - 08/06/2018
Vehicle Reg. No. (Insured):	SHC8825Z	Policy No. (Claimant):	MV002639
		Excess:	
Repairer:	K Kim Hin Auto Pte Ltd (HQ) 160 Sin Ming Drive #02-20, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64527018		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Priya]		
Claimant's Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 31/01/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

...CLAIM SUBFOLDER...(Pending for Survey Report)

WP

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Jan 2018 Sendback Est	22 Jan 2018 14:19 \$513,678.17	22 Jan 2018 14:50 Edit Adj Rpt	\$56,611.28 Edit Estimates	\$56,611.28 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R								
Main Claimant:	TEO CHOON KHNG , ID: S1279145C								
Vehicle Reg. No.:	SJU4482L	Date of Loss:	17/01/2018 22:00 - :59 [97 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT18010507	Policy/Cover Note No.:	MCOM0015 Coverage: 09/06/2017 - 08/06/2018						
Vehicle Reg. No. (Insured):	SHC8825Z	Policy No. (Claimant):	MV002639						
		Excess:							
Repairer:	K Kim Hin Auto Pte Ltd (HQ) 160 Sin Ming Drive #02-20, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64527018								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Priya]								
Claimant's Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 31/01/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• III_5G (29/01/2018): Alert - Adj Mandate Approved (\$10209.62) - SJU4482L - Claim Handler: Priya									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SJU4482L (MCT18010507)
 [SHC8825Z]
 TP
 TEO CHOON KHNG
 Jan 17 2018 10:00PM
 [COMFORT TRANSPORTATION PTE LTD]
 K Kim Hin Auto Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
1	22/01/18 14:19	Repairer Estimates	Load HTML	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/05/19 15:07	General View	Load JPG	<input checked="" type="checkbox"/>
2	30/05/19 15:07	General View	Load JPG	<input checked="" type="checkbox"/>
3	30/05/19 15:07	General View	Load JPG	<input checked="" type="checkbox"/>
4	30/05/19 15:07	General View	Load JPG	<input checked="" type="checkbox"/>
5	30/05/19 15:07	General View	Load JPG	<input checked="" type="checkbox"/>
6	30/05/19 15:07	General View	Load JPG	<input checked="" type="checkbox"/>
7	30/05/19 15:07	General View	Load JPG	<input checked="" type="checkbox"/>
8	30/05/19 15:07	General View	Load JPG	<input checked="" type="checkbox"/>
9	30/05/19 15:07	General View	Load JPG	<input checked="" type="checkbox"/>
10	30/05/19 15:07	General View	Load JPG	<input checked="" type="checkbox"/>
11	30/05/19 15:07	General View	Load JPG	<input checked="" type="checkbox"/>
12	30/05/19 15:07	General View	Load JPG	<input checked="" type="checkbox"/>
13	30/05/19 15:07	General View	Load JPG	<input checked="" type="checkbox"/>
14	30/05/19 15:07	General View	Load JPG	<input checked="" type="checkbox"/>
15	30/05/19 15:07	General View	Load JPG	<input checked="" type="checkbox"/>
16	30/05/19 15:07	General View	Load JPG	<input checked="" type="checkbox"/>
17	30/05/19 15:07	General View	Load JPG	<input checked="" type="checkbox"/>
18	30/05/19 15:07	General View	Load JPG	<input checked="" type="checkbox"/>
19	30/05/19 15:07	General View	Load JPG	<input checked="" type="checkbox"/>
20	30/05/19 15:07	General View	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	22/01/18 14:48	Singapore Accident Statement	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	22/01/18 17:47	TP GIA REPORT	Load PDF	
2	22/01/18 17:47	ACKNOWLEDGEMENT EMAIL TO AXA DD 22.01.2018	Load PDF	
3	30/05/19 15:31	Email to III to Temporary close file -SJU 4482L.	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Repairer ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18001305/KWA3Q2

Date: 19/06/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No: MCOM0015

Claimant Vehicle No : SJU4482L

Insured Vehicle No : SHC8825Z

Date of Loss: 17/01/2018

Nature of Claim: TP

Claim No: MCT18010507

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJU4482L

Make & Model: NISSAN TEANA, 2.0 (A)

Engine No: MR20768734A

Reg. Date: 09/12/2009 (Man. Year: 2009)

Chassis No: JN1BDUJ32Z0001101

Colour: Metallic Silver

Odometer: 211582 km

Engine Capacity: 1997 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17

Rear Tyre Size: 215/55 R17

Front Left Side: Dayton 2 mm

Rear Left Side: Dayton 3 mm

Front Right Side: Dayton 2 mm

Rear Right Side: Dayton 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,998.17	4,821.28	6,176.89	56.16
Miscellaneous Items	10.00	10.00	0.00	0.00
Labour	2,670.00	1,790.00	880.00	32.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,678.17	6,621.28	7,056.89	51.59
Approved Total (Overridden) (S\$)		6,611.28		
(S\$)	13,678.17	6,611.28	7,066.89	51.67
+ GST 7.00/7.00% (S\$)	957.47	462.79	494.68	51.67
Nett Amount (S\$)	14,635.64	7,074.07	7,561.57	51.67
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 22/01/2018 Present Location:

K Kim Hin Auto Pte Ltd (HQ)

Date Inspected: 23/01/2018 Inspected At:

K Kim Hin Auto Pte Ltd (HQ)

160 Sin Ming Drive #02-20, Sin Ming

AutoCity

Singapore 575722

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG**Manager:** VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Jun 2019)
Parts:	143	NISSAN TEANA 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJU4482L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*REAR NUMBER PLATE LAMP (LH/RH)	Serviceable	156.80 F	*- F
2	1		*REAR BUMPER	Buckled	840.00 F	*840.00 F
3	1		*REAR BUMPER SIDE RETAINER (LH/RH)	N/S Distorted	92.60 F	*46.30 F
4	10		*REAR BUMPER CLIPS	Necessary	44.00 F	*44.00 F
5	2		*REAR BUMPER CHROME MOULDING (LH/RH)	Dented	291.00 F	*291.00 F
6	1		*REAR BUMPER SPONGE	Cracked	139.00 F	*139.00 F
7	1		*REAR BUMPER REINFORCEMENT	*Check	330.90 F	*- F
8	2		*REAR BUMPER REINFORCEMENT BRACKET (LH/RH)	*Check	190.40 F	*- F
9	1		*TAILLAMP ASSY (LH/RH)	O/S Cracked	1,146.20 F	*573.10 F
10	1		*TAILLAMP SIDE COVER (LH/RH)	N/S Dented	76.00 F	*38.00 F
11	1		*BOOTLID	Bent	1,000.70 F	*1,000.70 F
12	1		*BOOTLID LOGO	Necessary	50.70 F	*50.70 F
13	1		*BOOTLID TEANA EMBLEM	Necessary	105.20 F	*105.20 F
14	1		*BOOTLID 200XL EMBLEM	Necessary	80.90 F	*80.90 F
15	1		*BOOTLID OUTER CHROME MOULDING-TOP	*Check	369.10 F	*- F
16	1		*BOOTLID OUTER CHROME MOULDING-BOTTOM	Dented	252.80 F	*252.80 F
17	2		*BOOTLID HINGES (LH/RH)	Repair	340.60 F	*- F
18	2		*BOOTLID DAMPER (LH/RH)	Serviceable	364.60 F	*- F
19	1		*BOOTLID LOCK	Dented	112.00 F	*112.00 F
20	1		*BOOTLID LOCK CATCH	Repair	57.90 F	*- F
21	1		*BOOTLID WEATHERSTRIP (50%)	Distorted / Dented	1,568.00 F	*784.00 FS
22	1		*BOOTLID INNER TRIM	Serviceable	288.20 F	*- F
23	10		*BOOTLID INNER TRIM CLIPS	Not Necessary	44.00 F	*- F
24	1		*REAR END PANEL	Bent	550.20 F	*550.20 F
25	1		*REAR END PANEL TOP GARNISH	Dented	95.30 F	*95.30 F
26	1		*SPARE TYRE PANEL	Repair	979.40 F	*- F
27	1		*SPARE TYRE PANEL TOP SPONGE COMPARTMENT-CENTRE	*Check	462.00 F	*- F
28	2		*SPARE TYRE PANEL TOP SPONGE COMPARTMENT (LH/RH)	Serviceable	231.00 F	*- F
29	1		*SPARE TYRE PANEL TOP BOARD	Serviceable	564.60 F	*- F
30	2		*REAR FENDER INNER TRIM LINING	Serviceable	591.20 F	*- F
31	1		*REAR NUMBER PLATE	Dented	40.00 FS	*40.00 FS
32	1		*REVERSE SENSOR	Torn	220.00 FS	*200.00 FS
33	1		*REVERSE CAMERA	*Check	380.00 FS	*- FS
34	1		*REAR END PANEL SMART KEYLESS ANTENNA	*Check	84.40 FS	*- FS

F=Franchise part. S=SpcNett.

Sub Total (\$\$) 12,139.70 5,243.20

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- Add. Disc. on L,N Items				10.00/10.00% (S\$)	1,141.53	421.92
Total Parts (S\$)					10,998.17	4,821.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	10.00	10.00
Sub Total (S\$)			10.00	10.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIT AND TO RENEW AFFECTED PARTS.	New	1,100.00	700.00
2	TO FOCUS TAILLAMPS. TO CHECK WIRING AND LIGHTING OPERATION.	New	50.00	20.00
3	TO APPLY UNDERSEALING.	New	120.00	60.00
4	TO REMOVE AND REFIT REAR UPHOLSTERY TRIMMING, ROOF LINING, SEATS, SPEAKER BOARD IN ORDER TO FACILITATE REPAIRING WORKS.	New	120.00	60.00
5	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.	New	1,200.00	900.00
6	TO REMOVE AND REFIT REVERSE SENSOR ASSY.	New	80.00	50.00
Gross Labour Cost (S\$)			2,670.00	1,790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >