

ASS. REC. BY:

REF: CS

EGIL8001334/M/vd321

Special Instruction:

SUNWATER: Mr MA

ASSIGNMENT (Office)

From (Person):

Yee Pei Li

of

EGI

Date/Time:

22/01/2018 @ 1:58pm

Estimated Cost:

Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBC 6978A

Insured:

YP 3293X

at Workshop m/s

Seng Kin Motor Works

Tel:

6453 6238

of

B/K L. Sin Ming Ind. Est. #01-131

Policy No:

Claim No:

YP3293X/SE/pl

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 18/01/2018

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

24/1/18 @ 22/1/18

Person Contacted:

Ms. Lim

Vehicle IN / OUT

Date/Time

Action/Instruction

✓ ESI 24/1/18

GBC 6978A - X

YP 3293X - X

24/1/18

Email preli revised to Pei Li

20/3/18

@ 4:24pm. Final fig \$ 3709.92 confirmed with Ms Lee

(Fed 1024.91, 22/3) (No LS)

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lump Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GRC 6778A Yr Reg: JUL 2013

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: NISSAN NISSAN 1461Colour: SILVER A/C Insured / Std / NI / NASp. Reading: 100637 T-Radio: Insured / Std / NI / NA

Eng. No: _____

C.No: 15KYBAM 2040648625

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 175/70R14

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 18/01/2012 D.O.I. 28/1/2012

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date: Time Action / Instruction

Date/Time: File Pass to?

☐

Preli. Report

☐

Final Report

Date/Time: File Return to?

2013- typist

Report Format: TPLump Sum / L.B. / S 3709.92Days Of Repair: 4Resurvey No. of Trip: 1

Survey Fee

Transportation

L.B. - P.S. / S

Photos

Others

Add Fee: ☐ Site Insp. \$☐ Interview \$☐ Technician \$☐ Weekend \$

TOTAL

290

RECEIVED 2013

Survey Department Check List (Case Handler)

Reference No.: CS/ EGI 18001334/ M/Vd3

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 20/3/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ERGO INSURANCE PTE LTD		Ref : CS/EG118001334/M1vd3	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 23-01-2018	
		Code : EGI	
1. Policy Particulars - THIRD PARTY CLAIM			
Insured Veh.	YP 3293X	Veh. Inspected	GBC 6978A
Policy No.		Coverage (\$)	0.00
Claim No.	YP3293X/SE/pl	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	23/01/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Engine No.	HIDDEN	Accident Date	18/01/2018
		Inspection Date	23/01/2018
Survey held at	SENG KIN MOTOR WORKS BLOCK 1, SIN MING INDUSTRIAL ESTATE #01-131 SINGAPORE 575636		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Monday, 22 January 2018 1:58 PM
To: 'admin-d@lkkauto.com'
Subject: OI : YP3293X / TP : GBC6798A/LKK / DOA : 18/01/2018
Attachments: YP3293X - SAS.pdf; GBC6978A - SAS.pdf; GBC6978A - PRS FORM.pdf

Dear Catherine

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANCY PTE LTD** to be the "Single Joint Expert".

ADDRESS : SENG KIN MOTOR WORKS
BLK 1 SIN MING INDUSTRIAL ESTATE
#01-131
SINGAPORE 575636

PERSON TO CONTACT : 6453 6238

ERGO OFFICER-IN-CHARGE : ROHAINI

Note: To survey on without prejudice basis. Please advise the consistency of damages to third party vehicle. Try to obtain estimate and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please update the survey status via Survey.Report@ergo.com.sg.

Attached are insured's and TP's SAS (note: reports not to be released to any Third Party). No estimates was provided.

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

ERGO

Date: 22.01.2018
Our Reference: YP 3293X/SE/pl
Your Reference: GBC 6798A
To: SENG KIN MOTOR WORKS

Sent via Fax ☐
or
Email ☐ sengkin2017@gmail.com

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: GBC 6798A
Insured's Vehicle: YP 3293X
Date Of Accident: 18.01.2018


We acknowledge receipt of your request for PRS on: 22.01.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

* LKK Auto

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPk	JP Knights Pte Ltd	VAC	Vicom Ltd

<input checked="" type="checkbox"/>	Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
<input type="checkbox"/>	Your request for inspection does not have your client's complete GIA report, kindly forward a copy.
<input type="checkbox"/>	We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
<input type="checkbox"/>	Our Insured's driver has not reported the accident to us to date.
<input checked="" type="checkbox"/>	Others: <u>OFFICER-IN-CHARGE - STEVE LIM</u>

Prepared by:		Pei Li	6829 9194	<u>claims@ergo.com.sg</u>
Signature:				<u>FAX : 6829 9247</u>

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job.

Seng Kin Motor Works
BLK 1 SIN MING INDUSTRIAL ESTATE 01-131
SINGAPORE 575636
TEL: 6453 6238, 6453 2961, FAX: 6458 0456

Workshop Acknowledgement & Stamp

Note: Our Inspection is on a without admission to liability basis.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 24 January 2018 3:46 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'
Cc: SUR
Subject: RE: OI : YP3293X / TP : GBC6798A/LKK / DOA : 18/01/2018
Attachments: GBC 6978A PRELI REVISED.pdf

Dear Pei Li,

Enclosed preliminary revised of vehicle GBC 6978A

Date of survey: 23/1/2018

Number of days:4 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [mailto:Survey.Report@ergo.com.sg]

Sent: Monday, 22 January 2018 1:58 PM

To: Admin-D (LKKAUTO) <admin-d@lkkauto.com>

Subject: OI : YP3293X / TP : GBC6798A/LKK / DOA : 18/01/2018

Dear Catherine

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANCY PTE LTD** to be the "Single Joint Expert".

ADDRESS : **SENG KIN MOTOR WORKS**
BLK 1 SIN MING INDUSTRIAL ESTATE
#01-131
SINGAPORE 575636

PERSON TO CONTACT : 6453 6238

ERGO OFFICER-IN-CHARGE : ROHAINI

Note: To survey on without prejudice basis. Please advise the consistency of damages to third party vehicle. Try to obtain estimate and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please update the survey status via Survey.Report@ergo.com.sg.

Attached are insured's and TP's SAS (note: reports not to be released to any Third Party). No estimates was provided.

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

Registration No. 199607198R

63561 FAX : (065) 62564315

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: YP3293X/SE/pl

Our ref: CS/EGH18001334/M1vd3

Date: 24/1/2018

The Motor Claims Department
M/s: ERGO Insurance Pte Ltd

Without Prejudice

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO : GBC 6978A


We thank you for your instruction on 22/1/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 23/1/2018 at the premises of M/s SENG KIN MOTOR WORKS and have the following to report:-

Workshop Estimate Amount	: S\$4,734.83
Revised Estimate Amount	: S\$3,659.92
"Check" Items Amount	: S\$50.00
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the n/s body



Comments/Present Status:

Damages Consistent

Yours faithfully,

MA CHIN FOOK
Automotive Assessor



高嶺摩哆貿易公司

KAOLIN MOTOR TRADING CO.

THOMSON ROAD POST OFFICE P.O.BOX NO. 95 SINGAPORE 915704

TEL : 6452 0716 / 6458 4013

Registration No. 216452/00K

STATEMENT

Messrs. SENG KIN MOTOR WORKS

Date

31-Jan-2018

Invoice No.K

48045

[illegible]

SIGNATURE

24 HRS TOWING SERVICE

Thank You For Your Business!

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/01/2018 14:49
Date Of Accident	18/01/2018 11:50
Exact Location Of Accident	CIVIL DEFENCE ACADEMY AT JALAN BAHAR
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBC6978A
Insured/Policyholder	
Name Of Registered Owner	JA LAN TIONG PTE LTD
Co Reg No	199303540G
Email Address	SENGKIN@YMAIL.COM
Mobile Phone No	
Alternative Phone No	OFFICE-62688700
Vehicle Particulars	
Manufacturer	NISSAN
Model	NV200-1.5 D L ABS AIRBAG 2WD 6DR (M)
Exact Purpose for which vehicle was being used at time of accident	PARKED STATIONARY
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	B28780031MKC
Cover Note Number	
Driver	
Name of Driver	CHU WAI KENT
NRIC No	S9276386B
Date Of Birth	16/04/1992
Occupation	OUTDOOR
Date Of Driving Pass	25/01/2016
Driving Experience	1 YEAR AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91727962
Fax Number	
Contact Number	
Email Address	SENGKIN@YMAIL.COM

Address 13 SARACA TERRACE

Postcode 805475

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -
-
-

Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 0

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

Please Refer to Sketch Plan

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

Details of Witness 1

Name ZAKI

Phone Number 91774644

Email Address

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YP3293X

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category COMMERCIAL VEHICLE

Name of Driver LEYAKATH ALIKHAN SHEIK ABDULLAH

NRIC/Passport Number G2251400H

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

Describe Circumstances of the Accident

On 18.01.2018 Time 6:55am, Vehicle NO GBC 6978A Parked at CAR park 'B' of Civil defence academy.

About 11:50am, I went back to collect my vehicle and realized my vehicle GRB 6978A was badly damaged as the front left portion

A witness, Mr. Zaki told me it was a lorry NO YP 3393x hit my vehicle and the driver name Hayatullah Alikhan Shouk Abdulah admitted he damaged my vehicle.

He told me that he making a three point turn and his rear
Axle Collided onto my feet and parham.

Declaration

We declare the foregoing particulars are true in every respect.

JA LAN TIONG PTE LTD
69, QUALITY ROAD, JURONG TOWN
SINGAPORE 618822
TEL 62688700 FAX 62634427 62680769

Psychologist's Signature / Date &
Time

Driver's Signature (If driver is not the policyholder, Date & Time:

Witnessed by Reporting Centre
Personnel:

New York Secy
81 559 200

Sketch Plan #2

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to reputate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of the report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' law firms/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;


(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or


(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")


(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' law firms/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their law firms/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

JA LAN TIONG PTE LTD
69, QUALITY ROAD, JURONG TOWN,
SINGAPORE 618222
TEL: 62686780 FAX: 62684427, 62680788


Policyholder's Signature / Date & Time


Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

Sketch Plan

							
---	---	---	---	---	---	--	---

Civil Defense Academy



成金摩嘜 Seng Kin Motor Works

Block 1, Sin Ming Industrial Estate
#01-131 Singapore 575636.
TEL: 64536238, 64532961 FAX: 64580453
B. Reg. No. 111182/OOW

JA LAN TIONG PTE LIMITED
69 QUALITY ROAD, JURONG TOWN
SINGAPORE 618822

Attention : Motor Claim Department
Contact : 62688700

Estimate : ES000081

Date : 19/01/2018
Vehicle Num. : GBC 6978A
Make/Model : NISSAN NV 200-2012
Chassis/Eng# : VSKYBAM20U0048625/K9KF276D1270
Accident Date : 18/01/2018
Claim No. :
Reference : TP/SK/ERGO/2018/002
Policy No. : B28780031 MKC

S/N	Quantity	Particular	Unit Price	Amount S\$
NETT ITEMS :				
1.	1 PCE	FRT. N/S DOOR VIEW MIRROR ASSY	crd/ dts ✓	351.80
2.	1 PCE	FRT. N/S DOOR GLASS OUTER WEATHER STRIP.	aut ✓	93.10
3.	1 PCE	FRT. N/S QUATER GLASS	ave ✓	250.80
4.	1 PCE	FRT. N/S QUATER GLASS LOWER GARNISH.	aut dts ✓	77.40
5.	1 PCE	FRT. N/S FENDER	dts ✓	507.40
6.	1 PCE	FRT. N/S FENDER BOTTOM SHIELD	ave ✓	99.10
7.	1 PCE	FRT. N/S FENDER SIGNAL LIGHT	ave ✓	57.30
8.	1 PCE	FRT. N/S HEADLAMP	aut ✓	454.50
9.	1 PCE	FRT. N/S HEADLAMP LOWER PROTECTOR	dts ✓	348.60
10.	1 PCE	FRT. N/S BUMPER SIDE RETAINER	dts ✓	35.20
11.	1 PCE	FRT. BUMPER	aut ✓	563.50
Nett Total S\$:				2,838.70
10.00% Discount S\$:				283.87
				2,554.83
LABOUR :				
TOWING CHARGES			X (P) 50.00	
LABOUR CHARGES TO KNOCK AND STRAIGHTEN FRT. SUPPORT PANEL, FRT. N/S DOOR AND DISTORTED PARTS. TO REMOVE BODY DAMAGED PARTS, REPLACE AND REFIX SAME.			500.00	900.00

CONTINUE / ...



成金摩嘜 Seng Kin Motor Works

Block 1, Sin Ming Industrial Estate
#01-131 Singapore 575636.
TEL: 64536238, 64532961 FAX: 64580453
B. Reg. No. 111182/OOW

JA LAN TIONG PTE LIMITED
69 QUALITY ROAD, JURONG TOWN
SINGAPORE 618822

Attention : Motor Claim Department
Contact : 62688700

Estimate : ES000081

Date : 19/01/2018
Vehicle Num. : GBC 6978A
Make/Model : NISSAN NV 200-2012
Chassis/Eng# : VSKYBAM20U0048625/K9KF276D1270
Accident Date : 18/01/2018
Claim No. :
Reference : TP/SK/ERGO/2018/002
Policy No. : B28780031 MKC

S/N	Quantity	Particular	Unit Price	Amount S\$
		TO PUTTY AND SPRAY PAINT	550.	800.00
		TO RE WRITE THE ADVERTISEMENT FOR THE DOOR & FENDER	✓	350.00
		TO SPRAY UNDERSEAL	20.	80.00
		Labour Total S\$:		2,180.00

Vs Author
P/P Repair
Before paint job
Hk Auto.
4w/day S.
23/1/2018.
25/1/18

[Signature]
for Seng Kin Motor Works

E. & O.E. Total S\$: 4,734.83
=====

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

23/1/2018

3709.92




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ERGO INSURANCE PTE LTD		Ref : CS/EGI18001334/M1vd3e2	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 26-03-2018	
		Code : EGI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	YP 3293X	Veh. Inspected	GBC 6978A
Policy No.		Coverage (\$)	0.00
Claim No.	YP3293X/SE/pl	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	22/01/2018
2. Vehicle Particulars & Condition			
Make & Model	NISSAN NV200	c.c	1461
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	VSKYBAM20U0048625	Colour	SILVER
Odometer	100637	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	175/70 R14	HIFLY	7 mm
L/H Front Tyre	175/70 R14	HIFLY	7 mm
R/H Rear Tyre	175/70 R14	HIFLY	7 mm
L/H Rear Tyre	175/70 R14	HIFLY	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	18/01/2018	Inspection Date	23/01/2018
Survey held at	SENG KIN MOTOR WORKS BLOCK 1, SIN MING INDUSTRIAL ESTATE #01-131 SINGAPORE 575636		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBC 6978A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRT N/S DOOR VIEW MIRROR ASSY (N)	CRACKED / DISTORTED	351.80	351.80
1	FRT N/S DOOR GLASS OUTER WEATHER STRIP (N)	CUT	93.10	93.10
1	FRT N/S QUATER GLASS (N)	SERVICEABLE	250.80	-
1	FRT N/S QUATER GLASS LOWER GARNISH (N)	CUT / DISTORTED	77.40	77.40
1	FRT N/S FENDER (N)	DENTED	507.40	507.40
1	FRT N/S FENDER BOTTOM SHIELD (N)	SERVICEABLE	99.10	-
1	FRT N/S FENDER SIGNAL LIGHT (N)	CRACKED	57.30	57.30
1	FRT N/S HEADLAMP (N)	CUT	454.50	454.50
1	FRT N/S HEADLAMP LOWER PROTECTOR (N)	DISTORTED	348.60	348.60
1	FRT N/S BUMPER SIDE RETAINER (N)	DISTORTED	35.20	35.20
1	FRT BUMPER (N)	CUT	563.50	563.50
	LESS 10% DISCOUNT		-283.87	-248.88
			2,554.83	2,239.92
	LABOUR			
	TOWING CHARGES.		50.00	50.00
	LABOUR CHARGES TO KNOCK AND STRAIGHTEN FRT. SUPPORT PANEL, FRT N/S DOOR AND DISTORTED PARTS. TO REMOVE BODY DAMAGED PARTS, REPLACE AND REFIX SAME.		900.00	500.00
	TO PUTTY AND SPRAY PAINT.		800.00	550.00
	TO RE WRITE THE ADVERTISEMENT FOR THE DOOR & FENDER.		350.00	350.00
	TO SPRAY UNDERSEAL.		80.00	20.00
			2,180.00	1,470.00
	GRAND TOTAL		4,734.83	3,709.92

RECOMMENDED COST OF REPAIRS			3,709.92
------------------------------------	--	--	-----------------

Report Ref No. CS/EGI18001334/M1vd3e2

MA CHIN FOOK

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.