





| EDIT                                                                                | SR NO                                                                               | REPAIR/REPLACE (LABOUR) | PART NAME                                                                                                                                                                                         | LABOUR R&R | LABOUR REPAIR | PAINT | ACTION (LABOUR) | COMMENT |
|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|---------------|-------|-----------------|---------|
|  |  | 1                       | TO REMOVE / REPLACE FRONT DAMAGED BUMPER, BONNET & OTHER AFFECTED BODY PARTS, INCLUDING PANEL BEAT / STRAIGHTEN BODY PANELS & FITTINGS WHICHEVER NECESSARY INCLUDING ALIGNMENT OF BODY STRUCTURE. | 3120       | 0             | 0     | Reviewing       |         |
|  |  | 2                       | TO SPRAY PAINT FRONT BUMPER & BONNET.                                                                                                                                                             | 2400       | 0             | 0     | Reviewing       |         |
|  |  | 3                       | TO CHECK ELECTRICAL WIRING SYSTEM FOR PROPER FUNCTION ABILITY INCLUDING PARKING ASSIST SENSORS.                                                                                                   | 250        | 0             | 0     | Reviewing       |         |
|  |  | 4                       | TO RE-PROGRAMMED SYSTEM & ERASE FAULT CODES AFTER ACCIDENT REPAIR.                                                                                                                                | 600        | 0             | 0     | Reviewing       |         |



Detailed Assessment

Condition of Vehicle at time of survey

Inspection Date \*

01/23/2018



General condition

Good

Total Loss

Yes No

Steering (Serviceable)

Yes No

Towing Charges

0

Footbrake (Serviceable)

Yes No

Voluntary Excess

0

Handbrake (Serviceable)

Yes No

Compulsory Excess

2000

Engine Modification

Yes No

Young/Inexperienced/Unnamed Driver Excess

0

Pre-accident condition

Good

Other Excess

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

265/40R21

Rear Tyre Size

295/35R21



POST SURVEY INF...

CATEGORY Address type  
FNOL INFORMATION... Residential  
POST SURVEY INF...

CATEGORY Gender  
FNOL INFORMATION... Male  
POST SURVEY INF...

CATEGORY Marital status  
FNOL INFORMATION... Married  
POST SURVEY INF...

CATEGORY Identification #  
FNOL INFORMATION... S1779089G  
POST SURVEY INF...

|                                                     |                         |  |
|-----------------------------------------------------|-------------------------|--|
| CATEGORY                                            | Make                    |  |
| POLICY INFORMAT... PORSCHE MACAN S 3.0 A/T ABS      |                         |  |
| ASSESSMENT INFO... PORSCHE                          |                         |  |
| CATEGORY                                            | Model                   |  |
| POLICY INFORMAT... PORXXX                           |                         |  |
| ASSESSMENT INFO... MACAN S 3.0 A/T ABS D/AIRBAG 4WE |                         |  |
| CATEGORY                                            | Type                    |  |
| POLICY INFORMAT...                                  |                         |  |
| ASSESSMENT INFO...                                  |                         |  |
| CATEGORY                                            | Type of Paint           |  |
| POLICY INFORMAT...                                  |                         |  |
| ASSESSMENT INFO...                                  |                         |  |
| CATEGORY                                            | Chassis No              |  |
| POLICY INFORMAT... WP1ZZZ95ZHLB2197                 |                         |  |
| CATEGORY                                            | Date of Birth           |  |
| FNOL INFORMATI... July 24, 1966                     |                         |  |
| POST SURVEY INF... mm/dd/yyyy                       |                         |  |
| CATEGORY                                            | Age                     |  |
| FNOL INFORMATI... 51                                |                         |  |
| POST SURVEY INF...                                  |                         |  |
| CATEGORY                                            | Occupation              |  |
| FNOL INFORMATI... Unknown                           |                         |  |
| POST SURVEY INF...                                  |                         |  |
| CATEGORY                                            | Education Qualification |  |
| FNOL INFORMATI... Other                             |                         |  |
| POST SURVEY INF... ▾                                |                         |  |
| CATEGORY                                            | Driving Experience      |  |

Accelerated survey  
and authorize

ALPHA148@SINGNET.COM.SG

Claim Handler

ANG Yvonne  
6568804461  
yvonne.ang@axa.com.sg

- Messages
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes
- Add

Additional Instructions

EXCESS 2000

| CREATED<br>USER | VERSION<br>DATE        | ESTIMATED<br>AMOUNT | APPROVED<br>AMOUNT | STATUS | SHARE | CLONE |
|-----------------|------------------------|---------------------|--------------------|--------|-------|-------|
| ANG<br>Yvonne   | 1/22/18<br>11:15<br>AM | 7879.2              | 7879.2             | Open   | Share | Clone |



Accelerated survey and authorize

ALPHA148@SINGNET.COM.SG

Claim Handler

ANG Yvonne  
6568804461  
yvonne.ang@axa.com.sg

- Messages
- Assessment
- Document Type
- Invoices
- History
- Metrics
- Notes
- Documents

Additional Instructions

EXCESS 2000

Document SubType

Upload Documents

| NAME                  | TYPE                    | SUB-TYPE                         | AUTHOR                            | DATE<br>UPLOADED |
|-----------------------|-------------------------|----------------------------------|-----------------------------------|------------------|
| Accident Statement    | Reports & Statement     |                                  | Merimen                           |                  |
| DISCHARGE VOUCHER.pdf | Forms / Claim Documents | Satisfaction / Discharge Voucher | LKK AUTO CONSULTANTS PTE LTD (OD) | May 15, 2018     |
| WORKSHOP INVOICE.pdf  | Invoice                 | Repairer                         | LKK AUTO CONSULTANTS PTE LTD (OD) | May 15, 2018     |