

ISSUANCE

ASS. REQ. BY:

REF: CS/MSG18001338/Gvd307

ASSIGNMENT (Office)

Merimen

From (Person): Catherine Thia

MSIG

Date/Time: 22/1/18 @ 11:53am

Estimated Cost:

BEL to:

OD / ~~IP~~ WS / IP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FX 3338J

Insured:

SLT7976R

at Workshop in:

Ethicarz

Tel:

93261342

of

56 Juyung way #04-04

Policy No:

A29050805QMY

Claim No:

546796

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

DCA

18/01/2018

CA / REV / REP. REV 24 HRS

'wp'

24/1/2018

Full Endorsement

Date/Time:

2:22pm @ 22/1/18

Person Connected:

ERIC

Officer: ~~IP~~ OUT

Date/Time:

Action/Inspection

✓

IP

FX 3338J -X

SLT 7976R -X

25/1/18

Send preli. revised by merimen

Xbrl.

MSIG

AD-1000000000

Front: 24/01/2018

Estimated Cost:

OD TP WS TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: FX 3338J

at Workshop No:

56 Loyang Way #04-04

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Clients Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Sal. or Market Value:

ADAC Accident Report: Consistent? : Yes or No

GIA / PR / Seen: Consistent? : Yes or No

Est. Repair: 3 days Res: Yes or No

Lum Surg: 20 % B Valid: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

FX 3338J 30 Oct 2003

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover

Truck / Trailer or

Make:

Honda wave 125S 125

Colour:

Black

Sp/Reading:

Eng No:

NF 125 MD 0078 147

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: N / S/Rim / STD A/Rim or

Tyre Size:

80/90-17

90/80-17

BS / DUN / EXNOVA / GY / FS / LIZA / MID / OHTSU / PIP / SUMI /

TOYO / YOKO or

Front:

Rear:

R.Bal:

4

mm

R.Bal:

4

mm

L.Bal:

4

mm

L.Bal:

mm

D.O.A.:

D.O.A.:

24-01-18

Survey held at:

w/s

12pm

Des. of Damages: Front / Rear / D/S / U/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date: Time: Action: Instruction:

24/1 Finalized \$1200 with Eric. (Ref 2507-40, 6790)

RECEIVED 24 JAN 2018

Date/Time File Passed:



Preli. Report

Days Of Repair: 3



Final Report

Resurvey No. of Tric. -

Date/Time File Returned:

29/1- typist

Add Fee:



Site visit \$



Interim \$



Final \$



Agenda \$

Survey Fee

Transport

21-01-18

21-01-18

21-01-18

21-01-18

21-01-18

200
10
210

210

Survey Department Check List (Case Handler)

Reference No.: **CS** | **MSG 18001338** | **7743**
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all information created by the assignment team are ACCURATE.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded				
---	-------------------------	--	--	--	--

Check By:

VERON

25/1/18

Case Handler

Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD			Ref : CS/MSG18001338/Gvd3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 23-01-2018	
Code : MSG				
1. Policy Particulars : THIRD PARTY CLAIM				
Insured Veh.	SLT 7976R	Veh. Inspected	FX 3338J	
Policy No.	A29050805QMY	Coverage (\$)	0.00	
Claim No.	546796	Excess (\$)	0.00	
Assign From	MERIMEN (CATHERINE THIA)	Assign Date	23/01/2018	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	-	Steering		
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	18/01/2018	Inspection Date		
Survey held at	ETHICARZ PTE LTD 56 LOYANG WAY #04-04 LOYANG ENTERPRISE BUILDING SINGAPORE 508775			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Jan 2018		22 Jan 2018 11:53 Assign				New Assignment Cancel Case

MainReferenceClaim DetailsDocumentsShow All

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	MOO MANWEN IAN, ID: S9004510E, Tel: +6582999063, Email: IANMOO@AIA.COM.SG		
Main Claimant:	MUHAMMAD ZAKI BIN AZMAN, ID: S9300883I		
Vehicle Reg. No.:	FX3338J	Date of Loss:	18/01/2018 12:00 - :59
Claim Type:	TP / 546796	Policy/Cover Note No.:	A29050805QMY (Comprehensive) Coverage: 13/11/2017 - 12/11/2018
Vehicle Reg. No. (Insured):	SLT7976R	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	Ethicarz Pte Ltd (HQ) 56 LOYANG WAY #04-04 LOYANG ENTERPRISE BUILDING, 508775 Loyang - Tel: 63844404		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 23/01/2018]		
Driver/Custodian (Insured):	MOO MANWEN IAN (27 / Male), NRIC: S9004510E, Tel: +6582999063		
Adj Asg. Remarks:	Please appoint MR HENRY NG from LKK AUTO to conduct the survey.		

ASSOCIATED MAIL RECEIVED

View AllCompose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

View AllSearch TasksCreate New TaskComplete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Catherine Thia Shi Yi

Date: 25 Jan 2018

Preliminary Advice

Insured Vehicle No : SLT7976R

TP Vehicle No : FX3338J

Accident Date : 18/01/2018

Make : HONDA WAVE 125

Assignment Date : 22/01/2018

Date of Inspection : 24/01/2018

Est. Duration of Repair : 3.00

Inspection At : ETHICARZ PTE LTD (HQ)

56 LOYANG WAY #04-04 LOYANG ENTERPRISE BUILDING
SINGAPORE 508775**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion, o/s and n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,707.40
Revised Amount	:S\$	1,576.10
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,576.10

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 0883I

Vehicle Details

Vehicle No.: FX3338J

Vehicle to be Exported: Yes

Intended De-registration Date: 19 Jan 2018

Vehicle Make: HONDA

Vehicle Model: WAVE 125S A

Primary Colour: Blue

Manufacturing Year: 2003

Engine No.: NF125MDE0078147

Chassis No.: NF125MD0078147

Maximum Power Output: -

Open Market Value: \$1,778.00

Original Registration Date: 30 Oct 2003

First Registration Date: 30 Oct 2003

Transfer Count: 6

Actual ARF Paid: \$267.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 29 Oct 2018

1/19/2018

PARF/COE Rebate Enquiry

COE Category:	D - Motorcycle
COE Period(Years):	5
PQP Paid:	\$850.00
COE Rebate Amount:	\$132.00
Total Rebate Amount:	\$132.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 19 Jan 2018

OK

Items Search for an item, user or group

< Class 2B (/categories/motorbikes-108/motorbikes-for-sale-1592/class-2b-1595/)



A new version of the website is available! Refresh the website to make it yours!

Click to Refresh

Honda Wave 125 Motorbike

Used

gamotor (/gamotor/)

S\$1,500

Singapore

GETTING THIS

Meet-Up

Buy now

Chat with Seller (/login/?next=/inbox/new/149097722/)

15

Share This With Friends



(https://www.pinterest.com/pin/create/button/?

149097722%2F%3Fref%3Dsearch%26ref_query%3Dhonda%2520wave%26ref_referrer%3D%252Fsearch%252Fproducts%252F%253Fquery%253Dhonda%252520wave%26ref_reqld%3D2JzQZfJ3pheEMP1DWu11-2018%20nonrenewable.%20%241500.%20Accept%20

Description

Comments (0)

1/19/2018

Honda Wave 125 Motorbike, Motorbikes, Motorbikes for Sale, Class 2B on Carousell

Honda Wave 125 Motorbike. COE till 30-11-2018 nonrenewable. \$1500. Accept Downpayment + Installment. Good condition.

Blk 32 Sin Ming Drive #01-331. GA Motor. Enquire call 64539903.

Drop by to view if interested.

Make: Honda

Bike Type: Road Bike

A new version of the website is available! Refresh the website to make it yours!

Click to Refresh

DEAL OPTIONS



Meet-Up

📍 Singapore

Listed on Jan 13, 2018

MEET THE SELLER



GA Motor

😊 0 😊 0 😊 0

(/gamotor/)

YOU MAY ALSO LIKE

Enquire Transfer Fee

Vehicle Details

Vehicle No. :	FX3338J
Vehicle Type :	P00 - Passenger Motorcycle/Autocycle/Moped
Vehicle Attachment 1 :	No Attachment
Vehicle Scheme :	Normal
Vehicle Make :	HONDA
Vehicle Model :	WAVE 125S A
Chassis No. :	NF125MD0078147
Propellant :	Petrol
Engine No. :	NF125MDE0078147
Engine Capacity :	125 cc
Maximum Power Output :	-
Maximum Laden Weight :	-
Unladen Weight :	-
Year Of Manufacture :	2003
Original Registration Date :	30 Oct 2003
Lifespan Expiry Date :	-
COE Category :	D - Motorcycle
PQP Paid :	\$850.00
COE Expiry Date :	29 Oct 2018
Road Tax Expiry Date :	29 Oct 2018
Inspection Due Date :	06 Jan 2019
Intended Transfer Date :	25 Jan 2018
CO2 Emission :	-
CO Emission :	-
HC Emission :	-
NOx Emission :	-
PM Emission :	-

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use [Enquire Road Tax Payable](#) for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Record Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/01/2018 15:33
Date Of Accident	18/01/2018 12:20
Exact Location Of Accident	TAMPINES CONCOURSE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FX3338J
Insured/Policyholder	
Name Of Registered Owner	MUHAMMAD ZAKI BIN AZMAN
NRIC No	S9300883I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96882123
Alternative Phone No	OTHERS-96882123

Vehicle Particulars

Manufacturer	HONDA
Model	WAVE 125S A

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5092385857 TP
Cover Note Number	

Driver

Name of Driver	MUHAMMAD ZAKI BIN AZMAN
NRIC No	S9300883I
Date Of Birth	11/01/1993
Occupation	OUTDOOR
Date Of Driving Pass	05/08/2013
Driving Experience	4 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96882123
Fax Number	
Contact Number	OTHERS-96882123
EMail Address	NOEMAIL

Address	BLK 807 TAMPINES AVE 4 #04-125
Postcode	520807
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TAMPINES NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 6 TAMPINES AVE 4 , POSTCODE: 529682 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-5871999 - FAX NO: 65871699
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLT7976R
Vehicle Make/Model/Colour	HONDA CIVIC 1.5 TURBO VTIS SR
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MOO MANWEN, IAN
NRIC/Passport Number	S9004510E
Contact Number	82999063/83645672
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name MUHAMMAD ZAKI BIN AZMAN

Approximate Age

Injuries Sustain

Injured person in which vehicle? FX3338J

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders


Policyholder's Signature
Date & Time: **19 JAN 2018**

Driver's Signature
(If driver is not the policyholder)
Date & Time:


ROAD KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: vackb@singnet.com.sg

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN

Tampines Con Course



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Hand-drawn sketch of an accident scene on a grid background. It shows a vertical road and a horizontal road. A dashed line indicates a path or boundary. A car is shown in the middle of the intersection, with arrows indicating its movement. The car is labeled 'B' and 'SLT4436R'. There are also arrows pointing towards the car from the left and right. The sketch is drawn on a grid background.

Please refer to police report No: T/20180119/2082

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 19 JAN 2018

Driver's Signature

(If driver is not the policyholder)

Date & Time:

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4

Singapore 415933

Tel: 67416697 Fax: 67492305

Email: vackb@sinonet.com.sg

Reporting Centre Personnel's Signature

Name:

VRIC/FIN No:



SINGAPORE POLICE FORCE

Witness



T/20180119/7001

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 4

Report No. T/20180119/7001

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 19/01/2018 01:01		Vide Report No.: T/20180118/2106		Station Diary No.:	
Name of Informant: MUHAMMAD HARIZ BIN HUSAINI		Address: APT BLK 16 TELOK BLANGAH CRESCENT #02-324 SINGAPORE 090016			
ID Type / ID No.: NRIC NO / S93385031		Contact No.: Home/Office: Mobile: 83955604			
Nationality: SINGAPORE CITIZEN		Email: hariz001@e.ntu.edu.sg			
Sex: Male	Age: 24	Date of Birth: 21/10/1993	Type of Informant: Witness		
Race: Malay		Language: English		Institution / School Name:	
Occupation: Student		Driving Licence Information: Class:		Date of Expiry:	

General Information of the Accident

Type of Accident:	Injury Police Vehicle	Drink Drive: No	Date/Time of Accident: 18/01/2018 12:15	Type of Location: U-turn area
Location: TAMPINES CONCOURSE The accident occurred at the U-turn spot. The U-turn spot is right before the intersection. It happened on the side of the road that was opposite the entrance of the Tampines Downtown line.				
Weather: Sunny		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control:		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FX3338J	Motorcycle	HONDA	Wave 125S A	Blue	Slightly Damaged	0
	Car			Black	Slightly Damaged	1

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
-------------	-------------------	--------------	-----------	-------------



SINGAPORE POLICE FORCE



T/20180119/7001

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 4

Report No. T/20180119/7001

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No.	Effective Date	Expiry Date
FX3338J	NTUC Income Insurance Co-Operative Limited	5092385857	03/07/2017	29/10/2018

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Rider				
Name	Zaki		ID No.	NIL
Related Vehicle	FX3338J (Motorcycle)		Contact No.	96882123
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	Slight
Driver				
Name	Unknown Driver		ID No.	NIL
Related Vehicle	(Car)		Contact No.	NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL

Brief Details.

I was walking on the pavement near the end of the Tampines Concourse road when I heard a very loud horn. I turned and saw a motorcycle trying to swerve to the right but hit the right rear corner of a black car. I ran to the scene to help the rider of the motorcycle. Myself and two others lifted the motorcycle that was pining down the rider. I served in SCDF, so I did the standard checks for injuries. While doing the checks, the rider was in shock, couldn't speak for a few minutes and was curled up in a fetal position. The driver of the black car approached, squatted down and shook the rider's right shoulder even though the rider was groaning in pain and was hit less than 30 seconds ago. The driver then said to the rider, "Eh bro, you ride you never look ah bro?". I then told the driver that the rider was in shock, to which the driver responded, "He ride, never look, then see my car of course shock la!" in a sarcastic manner.

Once the rider was feeling better, I performed more injury checks on him before helping him up alone and sitting him at the side of the road. I sat with the rider until the ambulance and traffic police came and left. Throughout the whole time before the traffic police arrived, the driver tried to push the responsibility of the accident on the rider by asking him questions that might incriminate the rider multiple times. At one point, the driver aggressively said, "Bro can we exchange information?" and the rider responded, "I want to wait



**SINGAPORE
POLICE FORCE**



T/20180119/7001

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 4

Report No. T/20180119/7001

CONTINUATION OF REPORT

for traffic police first", to which the driver snapped while pointing his finger at the rider, "So you are refusing to exchange information ah!". The rider then calmly replied, "No I never said that, I want to wait for traffic police first".

Also, right before the ambulance arrived, the driver told the rider, "Sorry ah bro, no hard feelings but I will claim insurance against you. I will not private settle. Sorry ah bro".



**SINGAPORE
POLICE FORCE**



T/20180119/7001

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

4 of 4

Report No. T/20180119/7001

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPIB /
CHONG GUAN FATT
Contact No.: 65476198

Authentication Stamp
NP168

Signature Of Informant:
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
19/01/2018 01:01

Classification Of Case:



SINGAPORE
POLICE FORCE

Police Station Of Origin:
Tampines N.P.C
6 Tampines Avenue 4 SINGAPORE 520602
Tel No. 1800-5871588

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 19/01/2018 14:57
Video Report No: 1/20180118/210

Name of Informant: MUHAMMAD ZAKI BIN AZMAN		Address: APT. BLK 807 TAMPINES AVENUE 4 520807	
ID Type / ID No: NRIC NO / S93008831		Contact No: Home/Office: 67405118	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 25	Date of Birth: 11/01/1993	Type of Informant: Rider
Race: Javanese		Language: English	
Occupation: PART TIMER		Driving Licence Information: Class:	

Type of Accident: Injury Others	Drink Drive: No	Police Officer: Sgt. Tan Joo Keng
Location: Along Road 1: TAMPINES CONCOURSE		
Weather: Clear	Road Surface: Dry	Police Officer: Sgt. Tan Joo Keng
Traffic Flow: Two Way	Traffic Control: NA Controlled	Police Officer: Sgt. Tan Joo Keng
Type of Collision: Between Moving Vehicles - Head To Side		

FX3338J	Motorcycle	HONDA	WAVE 125S	Blue		
SLT7976R	Car					

FX3338J	NTUC Income Insurance Co-Operative Limited	5092385857	03/07/2017	28/10/2016
---------	--	------------	------------	------------




SINGAPORE
POLICE FORCE

Police Station Of Origin:
Tampines N.P.C
6 Tampines Avenue 4 SINGAPORE 529662
Tel No: 1800-5871999

CONTINUATION OF REPORT

Any Pedestrian Involved: No		
No. of Pedestrians Injured: NIL		
Use of Pedestrian Crossing		
Name	MUHAMMAD ZAKI BIN AZMAN	ID No
Related Vehicle	FX3338J (Motorcycle)	Code
Hospital/Clinic	TAMPINES MEDILIFE CLINIC	Clinic Doctor Name Initials Signature
Date Treatment	18/01/2018	Date Discharge
No. of Days granted Medical Leave	03	Degree of Injury
Name	MOO MANWEN, IAN	ID No
Related Vehicle	SLT7976R (Car)	Code
Hospital/Clinic	NIL	Clinic Doctor Name Initials Signature
Date Treatment	NIL	Date Discharge
No. of Days granted Medical Leave	NIL	Degree of Injury

Brief Details:
On 18/01/2018, I had lodged a traffic accident report with the Police which had happened to me while I was riding my motorcycle at 1220hrs along Tampines Concourse Junction, which had involved a car. I had managed to get the vehicle no. of the car that had hit me.
As such, I am now lodging this traffic accident report to help the Police.



**SINGAPORE
POLICE FORCE**

Police Station Of Origin
Tampines N.P.C.
6 Tampines Avenue 4 SINGAPORE 52006
Tel No: 1800-5871999

Sketch Plan
Informant is not able to provide sketch plan


IMPORTANT: Please attach a copy of this certificate with you now. Please take it to the relevant authorities.

Signature Of Officer Recording This Report
G7
Sgt 3 MUHAMMAD DANIAL BIN
BAHARUDDIN

Signature Of Interpreter
Not applicable

Officer In Charge Of Case
TP / AEIT /
Sgt 2 YEO KIA HUAT
Contact No: 65476325

Authentication Stamp
NP168



ETHICARZ PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Vehicle Nos FX 3888J
Model HONDA WAVE
Year 2003

1	Handle bar / BT	1	\$ 75.00	\$ 75.00	/
2	Handle bar balancer / Cut	1	\$ 48.00	\$ 48.00	/
3	Handle bar grip L/H X NN	2	\$ 28.00	\$ 56.00	/
4	Brake lever X	1	\$ 45.00	\$ 45.00	/
5	Mirror / Cut	1	\$ 60.00	\$ 60.00	/
6	Head lamp X NN	1	\$ 180.00	\$ 180.00	/
7	Signal lamp L/H / Sur	1	\$ 85.00	\$ 85.00	/
8	Front cover X NN	1	\$ 120.00	\$ 120.00	/
9	Front mudguard / Cut	1	\$ 80.00	\$ 80.00	/
10	Steering stem / NGL	1	\$ 98.00	\$ 98.00	/
11	Front fork assy / AT	1	\$ 280.00	\$ 280.00	/
12	Front wheel shaft / Cut	1	\$ 28.00	\$ 28.00	/
13	Front container / CPA	1	\$ 60.00	\$ 60.00	/
14	Front foot rest bar / AT	1	\$ 48.00	\$ 48.00	/
15	Front foot rest pad L/H / Cut	1	\$ 24.00	\$ 24.00	/
16	Front leg shield L/H / Cut	1	\$ 120.00	\$ 120.00	/
17	Tail cover L/H / Cut	1	\$ 140.00	\$ 140.00	/
18	Tail cover R/H / Cut	1	\$ 140.00	\$ 140.00	/
19	Tail box bracket X Repair	2	\$ 128.00	\$ 256.00	/
20	Rear foot rest bracket / AT	1	\$ 95.00	\$ 95.00	/
21	Rear foot rest pad / Mis	1	\$ 48.00	\$ 48.00	/

1428
10%: 1286.1
\$ 2,086.00
-10% -\$ 208.60
\$ 1,877.40

SPECIAL NETT

1	Front number plate X NN	\$ 20.00	/
2	Fork oil seal and dust cover / NGL	\$ 40 80.00	/
3	Rear tail box / NGL	\$ 140 220.00	/
4	Tyre X NN	\$ 180.00	/
5	Steering cone and bearing / NGL	\$ 50.00	/
6	Stickers / NGL	\$ 60 120.00	/
		\$ 670.00	/

LABOUR

1	Labour for dismantle and replace accident and affected parts	\$ 200 380.00	/
2	SPRAY WORKS	\$ X 350.00	/
3	Wiring	\$ X 80.00	/
4	LABOUR FOR BALANCING BODY ALIGNMENT	\$ X 350.00	/

Total: 1200.

24/1/18.

3 Days.

Lumpsum repair

After repair photo's.

Guarantee 8288002

LABOUR
SPECIAL NETT
PARTS

1726.1
20%: 1200

\$ 1,160.00
\$ 1,877.40
\$ 670.00
\$ 1,160.00
\$ 3,707.40

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Jan 2018		22 Jan 2018 11:53 Edit Adj Rpt	S\$1,200.00 Edit Estimates	S\$1,200.00 View Rpt		Pending for Survey Report Cancel Case

MainReferenceClaim DetailsDocumentsShow All

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	MOO MANWEN IAN, ID: S9004510E, Tel: +6582999063, Email: IANMOO@AIA.COM.SG		
Main Claimant:	MUHAMMAD ZAKI BIN AZMAN, ID: S9300883I		
Vehicle Reg. No.:	FX3338J	Date of Loss:	18/01/2018 12:00 - :59
Claim Type:	TP / 546796	Policy/Cover Note No.:	A29050805QMY (Comprehensive) Coverage: 13/11/2017 - 12/11/2018
Vehicle Reg. No. (Insured):	SLT7976R	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	Ethicarz Pte Ltd (HQ) 56 LOYANG WAY #04-04 LOYANG ENTERPRISE BUILDING, 508775 Loyang - Tel: 63844404		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 21/02/2018]		
Driver/Custodian (Insured):	MOO MANWEN IAN (27 / Male), NRIC: S9004510E, Tel: +6582999063		
Adj Asg. Remarks:	Please appoint MR HENRY NG from LKK AUTO to conduct the survey.		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FX3338J (546796)
[SLT7976R]
TP
MUHAMMAD ZAKI BIN AZMAN
Jan 18 2018 12:00PM
[MOO MANWEN IAN]
Ethicarz Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	22/01/18 11:47	Accident Statement From:SC - Reg. No: SLT7976R, Claimant: MOO MANWEN IAN	1	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	25/01/18 14:18	Adjuster Immediate Advice	1	Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	25/01/18 10:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
2	25/01/18 10:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
3	25/01/18 10:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
4	25/01/18 10:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
5	25/01/18 10:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
6	25/01/18 10:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
7	25/01/18 10:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
8	25/01/18 10:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
9	25/01/18 10:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
10	25/01/18 10:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
11	25/01/18 10:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
12	25/01/18 10:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
13	25/01/18 10:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
14	25/01/18 10:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
15	25/01/18 10:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
16	25/01/18 10:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
17	25/01/18 10:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
18	25/01/18 10:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
19	25/01/18 10:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
20	25/01/18 10:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
21	25/01/18 10:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
22	25/01/18 10:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
23	25/01/18 10:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
24	25/01/18 10:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
25	25/01/18 10:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
26	25/01/18 10:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
27	25/01/18 10:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
28	25/01/18 10:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
29	25/01/18 10:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
30	25/01/18 10:04	General View	1	Load JPG	

					<input checked="" type="checkbox"/>
31	25/01/18 10:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
32	25/01/18 10:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
33	25/01/18 10:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
34	25/01/18 10:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
35	25/01/18 10:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
36	25/01/18 10:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
37	25/01/18 10:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
38	25/01/18 10:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
39	25/01/18 10:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
40	25/01/18 10:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
41	25/01/18 10:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
42	25/01/18 10:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
43	25/01/18 10:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
44	25/01/18 10:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
45	25/01/18 10:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
46	25/01/18 10:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
47	25/01/18 10:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
48	25/01/18 10:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
49	25/01/18 10:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
50	25/01/18 10:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
51	25/01/18 10:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
52	25/01/18 10:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
53	25/01/18 10:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
54	25/01/18 10:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
55	25/01/18 10:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
56	25/01/18 10:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
57	25/01/18 10:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
58	25/01/18 10:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
59	25/01/18 10:04	General View	1	Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	22/01/18 11:47	TPD FX3338J GIA REPORT From:SC - Reg. No: SLT7976R, Claimant: MOO MANWEN IAN	1	Load PDF	
2	22/01/18 11:52	Pre-Repair Survey	1	Load PDF	
3	22/01/18 11:52	Reply email from TP workshop & appoint MR HENRY NG from LKK AUTO	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

^
v

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG18001338/GVD3E2**Date:** 01/02/2018**REFERENCE****Handling Insurer:** MSIG Insurance (Singapore) Pte. Ltd.**Policy No:** A29050805QMY**Claimant Vehicle No :** FX3338J**Insured Vehicle No :** SLT7976R**Date of Loss:** 18/01/2018**Nature of Claim:** TP**Claim No:** 546796**DESCRIPTION & IDENTIFICATION OF VEHICLE****Reg No:** FX3338J**Make & Model:** HONDA WAVE 125, 125cc**Engine No:** NF125MDE0078147**Reg. Date:** 30/10/2003 (Man. Year: 2003)**Chassis No:** NF125MD0078147**Colour:** Black**Odometer:** 0 km**Engine Capacity:** 125 cc**Market Value/New Car Price:** N/A**Sum Insured (S\$):** Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY****General Condition:** Steering (Serviceable):**Yes** **Footbrake (Serviceable):** **Yes****Handbrake (Serviceable):** **Yes** **Engine Modification:****No** **Pre-accident Condition:****CONDITION OF TYRES****Front Tyre Size:** 80/90-17**Rear Tyre Size:** 90/80-17**Front Left Side:** Pirelli 4 mm**Rear Left Side:** Pirelli 4 mm**Front Right Side:** 0 mm**Rear Right Side:** 0 mm*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,547.40	1,576.10	971.30	38.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,160.00	200.00	960.00	82.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,707.40	1,776.10	1,931.30	52.09
Approved Total (Overridden) (S\$)		1,200.00		
Nett Amount (S\$)	3,707.40	1,200.00	2,507.40	67.63

INSPECTION**Date of Assignment:** 22/01/2018**Date Inspected:** 24/01/2018 **Inspected At:**Ethicarz Pte Ltd (HQ)
56 LOYANG WAY #04-04 LOYANG
ENTERPRISE BUILDING
Singapore 508775**Estimated Period of Repair:** 3.0 days**Adjuster:** XING GUO QIANG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source: (Last Synchronised: 01 Feb 2018)
Parts: N/A HONDA WAVE 125 125cc (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for FX3338J)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HANDLE BAR	Bent	75.00 FL	*75.00 FL
2	1		*HANDLE BAR BALANCER	Cut	48.00 FL	*48.00 FL
3	2		*HANDLE BAR GRIP L/H	Not Necessary	56.00 FL	*- FL
4	1		*BRAKE LEVER	Not Necessary	45.00 FL	*- FL
5	1		*MIRROR	Cut	60.00 FL	*60.00 FL
6	1		*HEAD LAMP	Not Necessary	180.00 FL	*- FL
7	1		*SIGNAL LAMP L/H	Scratched	85.00 FL	*85.00 FL
8	1		*FRONT COVER	Not Necessary	120.00 FL	*- FL
9	1		*FRONT MUDGUARD	Cut	80.00 FL	*80.00 FL
10	1		*STEERING STEM	Necessary	98.00 FL	*98.00 FL
11	1		*FRONT FORK ASSY	Bent	280.00 FL	*280.00 FL
12	1		*FRONT WHEEL SHAFT	Cut	28.00 FL	*28.00 FL
13	1		*FRONT CONTAINER	Cracked	60.00 FL	*60.00 FL
14	1		*FRONT FOOT REST BAR	Bent	48.00 FL	*48.00 FL
15	1		*FRONT FOOT REST PAD L/H	Cut	24.00 FL	*24.00 FL
16	1		*FRONT LEG SHIELD L/H	Cut	120.00 FL	*120.00 FL
17	1		*TAIL COVER L/H	Cut	140.00 FL	*140.00 FL
18	1		*TAIL COVER R/H	Cut	140.00 FL	*140.00 FL
19	2		*TAIL BOX BRACKET	Repair	256.00 FL	*- FL
20	1		*REAR FOOT REST BRACKET	Bent	95.00 FL	*95.00 FL
21	1		*REAR FOOT REST PAD	Missing	48.00 FL	*48.00 FL
22	1		*FRONT NUMBER PLATE	Not Necessary	20.00 FS	*- FS
23	1		*FORK OIL SEAL AND DUST COVER	Necessary	80.00 FS	*40.00 FS
24	1		*REAR TAIL BOX	Missing	220.00 FS	*140.00 FS
25	1		*TYRE	Not Necessary	180.00 FS	*- FS
26	1		*STEERING CONE AND BEARING	Necessary	50.00 FS	*50.00 FS
27	1		*STICKERS	Necessary	120.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	2,756.00	1,719.00
- List Item Discount on L Items 10.00/10.00% (S\$)	208.60	142.90
Total Parts (S\$)	2,547.40	1,576.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR DISMANTLE AND REPLACE ACCIDENT AND AFFECTED PARTS	New	380.00	200.00
2	SPRAY WORKS	New	350.00	0.00
3	WIRING	New	80.00	0.00
4	LABOUR FOR BALANCING BODY ALIGNMENT	New	350.00	0.00
Gross Labour Cost (S\$)			1,160.00	200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >