

ASS. REC. BOM

REF: CS/CTI18001344/ M1+d3^{sz}

Special Instruction

Menimen
FROM (Person): MA
joel Goh

ASSIGNMENT (Office)

of CTI

Date/Time: 22/1/18 @ 8:56am

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SIF 800J

Insured:

SKR 1865P

at Workshop no:

LA Auto

Tel:

9100 4390

of 106 punggol walk # 09-16 Twin Waterfalls AMK 828793

Policy No: DMPCS N 3061551701

Claim No:

SNM18P00269C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 15/01/2018

24/01/18 @ Morning

CA / REV / REP. / REV 24 HRS 'wpr

RED Endorsement

Date/Time: 10:45am @ 22/1/18

Person Contacted:

Susan

Vehicle IN/OUT

Date/Time:

Action/Instruction

✓

SIF 800J - X

SKR 1865P - X

lump sum \$3000/- (Red: 3362.40, 52%)

RECEIVED 27 FEB 2018



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI18001344/M1td3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 23-01-2018	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKR 1865P	Veh. Inspected	SLF 800J
Policy No.	DMPCSN3001551701	Coverage (\$)	0.00
Claim No.	SNM18D00269C02	Excess (\$)	0.00
Assign From	MERIMEN (JOEL GOH)	Assign Date	23/01/2018
2. Vehicle Particulars & Condition			
Make & Model	c.c 0		
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	15/01/2018	Inspection Date	
Survey held at	-		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Jan 2018		22 Jan 2018 08:56 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	CHAN MEI LIN, ID: S7425119F		
Main Claimant:	MONG HENG TRANSPORTATION,	Co. Reg. No.: 53330638L	
Vehicle Reg. No.:	SLF800J	Date of Loss:	15/01/2018 08:00 - :59
Claim Type:	TP / SNM18D00269C02	Policy/Cover Note No.:	DMPCSN3001551701 (Comprehensive)
Vehicle Reg. No. (Insured):	SKR1865P	Policy No. (Claimant):	5091392456
		Excess:	S\$0.00
Repairer:	LA AUTO (HQ) 106 PUNGGOL WALK, #09-16 TWIN WATERFALLS, 828793 Ang Mo Kio - Tel: 9030 1020 / 9100 4390		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Joel Goh]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 31/01/2018]		
Driver/Custodian (Insured):	ONG KAY PENG (WANG QIPING) (45 / Male), NRIC: S7230395D, Tel: +6597461585		
Adj Asg. Remarks:	NO EST, ASSIGN TO MARCUS CHUA AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/01/2018 11:10
Date Of Accident	15/01/2018 08:30
Exact Location Of Accident	ALONG THOMSON ROAD (BESIDE NOVENA SQUARE)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLF800J
Insured/Policyholder	
Name Of Registered Owner	MONG HENG TRANSPORTATION
Co Reg No	53330638L
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-94565170

Vehicle Particulars

Manufacturer	HONDA
Model	STREAM
Exact Purpose for which vehicle was being used at time of accident	PERSONAL USE

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5091392456
Cover Note Number	

Driver

Name of Driver	GOH MONG ING
NRIC No	S0089116I
Date Of Birth	26/12/1947
Occupation	OUTDOOR
Date Of Driving Pass	12/08/1970
Driving Experience	47 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94565170
Fax Number	
Contact Number	OTHERS-98509926
Email Address	NOEMAIL

Address: BLK 984A #18-09
BUANGKOK LINK

Postcode: 531984

Was driver an employee of the Insured's Company: YES

If No, Relationship of the Driver with the Insured:

Vehicle Registration Number of Driver's Own Vehicle: -

Insurance Company of Driver's Own Vehicle: -

General Information of the Accident

Type Of Accident: COLLISION - HEAD TO REAR

Weather Conditions: CLEAR

Road Surface: DRY

Other Information

Was any foreign vehicle involved in this accident?: NO

Number of vehicles involved in the accident:

Was any body injured in the Accident?: YES

Was any injured conveyed to hospital by ambulance?: NO

Was any other material or property damaged?: YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance: NO

Number of Passengers (Including Driver): 1

Details of Police Action

Was the accident reported to the police?: YES

If Yes, Please state which Police Station:

Police Station Name: ANG MO KIO SOUTH NEIGHBOURHOOD POLICE CENTRE

Police Station Address: ROAD: 81 ANG MO KIO AVE 3 , POSTCODE: 569929 , COUNTRY: SINGAPORE

Police Station Contact: TEL NO: 1800-4519999 - FAX NO: 65535679

Was notice of intended Prosecution given?: NO

If Yes, against whom?:

Circumstances of Accident

PLEASE REFER TO ATTACHED ACCIDENT SKETCHPLAN

Attachment(s)

Are accident photos available for attachment?: YES

Was there any video captured by Car Camera?: NO

Was there any audio recorded?: NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number: SKR1865P

Vehicle Make/Model/Colour: HONDA/ SILVER

Details Of Properties:

Vehicle Category: PRIVATE CAR

Name of Driver: ONG KAY PENG

NRIC/Passport Number: S7230395D

Contact Number:

Address:

Postcode:

Insurance Company Name:

Nature Of Damage:

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	GOH MONG ING
Approximate Age	
Injuries Sustain	SPRAINED NECK
Injured person in which vehicle?	SLF800J
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: SEW HOON
NRIC/IN No.:

15.01.2018 11:00hrs

Sketch Plan #2

SKETCH PLAN

Along Thomson Rd (Beside Novena Square)



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 15.01.2018 @ around 08:20 hrs, I was traveling along Thomson Road (Beside Novena Square) when vehicle 'B' suddenly collide into the rear of my vehicle. That's all.

DECLARATION

I/We declare that the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: STEW HUN N
NRIC/TIN No.:

15.01.2018 11:00hrs



**SINGAPORE
POLICE FORCE**



T/20180115/2125

3 of 3

Report No. T/20180115/2125

Police Station Of Origin:
Ang Mo Kio South N.P.C
81 Ang Mo Kio Avenue 3 SINGAPORE
569929
Tel No: 1800-4519999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
F/
Sgt 2 TAN WEI REN

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
15/01/2018 16:14

Officer In Charge Of Case:
TP / AEIT /
SSI GOH GEOK LYE
Contact No.: 65476148

Classification Of Case:

SN 085

Authentication Stamp
NP168



Singapore Police Force

Addendum Sheet



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
 6 Raffles Quay #16-08 Singapore 048580
 Tel (65) 6224 0010 Fax (65) 6224 0090
 Operating Hours: Monday to Friday, 09:00 - 17:00
 MERN 5065200205 / GST Reg. No. S480017715

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No: MAPI8006959 Vehicle Registration No: SLF 8WJ
 Name (as shown in NRIC): Goh Mong Ing NRIC/FIN/Passport No: S00891161
 (*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
 Address: Blk 984A #12-09 BUANGKOK LINK Singapore ()
 Contact (Tel): - Mobile No: 9456 5190
 Email Address: -
 Date of Accident: 16-01-2018 Time of Accident: 08:30hrs
 Place of Accident: Along Thomson Road (Beside Novena Square)
 Insurance Company: NTUC Income Insurance Co-operative Ltd

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

- Addition of injured party's details
- Addition of police report no: T/20180115 / 2126



Policyholder / Driver's Signature
 Date:

Reporting Centre Personnel's Signature
 Name: STEVE HU GH
 NRIC/FIN No: -
 Date: 16-01-2018



SINGAPORE POLICE FORCE



T/20180115/2125

1 of 3

Police Station Of Origin:
Ang Mo Kio South N.P.C
81 Ang Mo Kio Avenue 3 SINGAPORE
569929
Tel No: 1800-4519999

Report No. T/20180115/2125

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 15/01/2018 16:14	Vide Report No.:	Station Diary No.: 108
--	------------------	---------------------------

Informant's Particulars			
Name of Informant: GOH MONG ING		Address: APT BLK 984A BUANGKOK LINK #18-09 SINGAPORE 531984	
ID Type / ID No.: NRIC NO / S00891161		Contact No.: Home/Office: Mobile: 94565170	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 70	Date of Birth: 26/12/1947	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: Taxi driver		Driving Licence Information: Class: 3 Date of Expiry:	

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 15/01/2018 08:30	Type of Location: Straight Road
Location: Along Road 1 THOMSON ROAD towards Bukit Timah Road				
Weather: Cloudy		Road Surface: Dry	Road Speed Limit: 50 Km/h	
Traffic Flow: Two Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
SKR1865P	Car				Slightly Damaged	1
SLF800J	Car				Slightly Damaged	1

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



Police Station Of Origin:
Ang Mo Kio South N.P.C
81 Ang Mo Kio Avenue 3 SINGAPORE
569929
Tel No: 1800-4519999

Report No. T/20180115/2125

CONTINUATION OF REPORT

Driver			
Name	ONG KAY PENG	ID No.	S7230395D
Related Vehicle	SKR1865P (Car)	Contact No.	97461585
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	GOH MONG ING	ID No.	S0089116I
Related Vehicle	SLF800J (Car)	Contact No.	94565170
Hospital/Clinic	MEDLIFE CLINIC & SURGERY	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	15/01/2018	Date Discharge	15/01/2018
No. of Days granted Medical Leave	03	Degree of Injury	Slight

Brief Details.

On 15/01/2018 at about 0825hrs, I was driving along Thomson Road (beside Novena Square) towards Bukit Timah Road. I was on the extreme left lane. I then signaled my intention and changed lane to the right lane. When I was travelling on the center lane, the car in front of me slowed down. I then proceeded to apply brakes and slow my vehicle down. However, the car behind me failed to slow down and the head of the car bumped into my right rear. Both of us then came out of our vehicles immediately and took photos of what that had happened. We also exchanged contact details before leaving as we did not want to hold up the upcoming traffic. However, after the bump, I felt a bit dizzy and I felt that I have sprained my neck. I then proceeded to see the doctor.

I wish to add that I have a video recording of the above incident and that I am lodging the report for insurance and my own record purpose.



**SINGAPORE
POLICE FORCE**



T/20180115/2125

3 of 3

Report No. T/20180115/2125

Police Station Of Origin:
Ang Mo Kio South N.P.C
81 Ang Mo Kio Avenue 3 SINGAPORE
569929
Tel No: 1800-4519999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

F /

Sgt 2 TAN WEI REN

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / AEIT /

SSI GOH GEOK LYE

Contact No.: 65476148

Authentication Stamp
NP168

Signature Of Informant:

Date/Time:

15/01/2018 16:14

Classification Of Case:

SN 085



Signature:

Singapore Police Force

LA Auto

Blk 209 B #06-1288 Punggol Place

Singapore 822209 HP 91004390/HP 91254449 Fax 64841482

Email : laautoamk@gmail.com

M/s China Taiping Insurance (S) Pte Ltd

DATE 25.01.2018

3 Anson Road #16-00 Springleaf Tower

CAR NO SLF 800 J

Singapore 079909

MAKE Honda Stream

ESTIMATE COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE.
YOUR INSURED : SKR 1865 P

Pc	Pcs	Description	UNIT PRICE	AMOUNT
1	pc	Tail gate	CA ✓	\$1,280.00
1	pc	Tail gate Honda logo	WIN X	\$38.00
1	pc	Tail gate Stream emblem	WLC ✓	\$45.00
1	pc	Tail gate top lock	SWC X	\$119.80
1	pc	Rear end panel	R X	\$408.60
1	pc	Rear end panel top garnish	SWC X	\$156.00
1	pc	Rear bumper	det ✓	\$950.00
1	pc	Rear bumper side retainer (right)	S/S ✓	\$35.00
1	set	Rear bumper reverse sensor	SWA 20	\$280.00
1	pc	Tail lamp (right)	SWC ✓	\$460.00
1	pc	Rear wind screen moulding	WLC ✓	\$56.00
1	pc	Rear boot lid cover Honda "H" logo	WLC ✓	\$39.00
1	pc	Towing cover	Grey ✓	\$35.00
1	pc	Rear exhaust pipe	X SWC	
		To check rear lightings and electrical wiring system include performing water leakage test.	30 ✓	\$60.00
		Labour for jacking, knocking rear right side mudguard, rear spare tyre tank panel, cutting rear end pane, dismantle and replace the above mentioned parts.	GOV	\$1,100.00
		Labour for respray rear boot lid cover (inner & outer), rear end panel, rear bumper & touch up rear right side mudguard panel.	GOV	\$1,000.00
		To apply silicon onto rear wind screen.	(2 tube) 60 ✓	\$120.00
		Labour for dismantle & refix rear wind screen.	120 ✓	\$180.00

Page 1 of 1 Total \$6,362.40

LA Auto.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Jan 2018		22 Jan 2018 08:56 Edit Adj Rpt	S\$3,000.00 Edit Estimates	S\$3,000.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	CHAN MEI LIN, ID: S7425119F		
Main Claimant:	MONG HENG TRANSPORTATION, Co. Reg. No.: 53330638L		
Vehicle Reg. No.:	SLF800J	Date of Loss:	15/01/2018 08:00 - :59
Claim Type:	TP / SNM18D00269C02	Policy/Cover Note No.:	DMPCSN3001551701 (Comprehensive)
Vehicle Reg. No. (Insured):	SKR1865P	Policy No. (Claimant):	5091392456
		Excess:	S\$0.00
Repairer:	LA AUTO (HQ) 106 PUNGGOL WALK, #09-16 TWIN WATERFALLS, 828793 Ang Mo Kio - Tel: 9030 1020 / 9100 4390		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Joel Goh]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 31/01/2018]		
Driver/Custodian (Insured):	ONG KAY PENG (WANG QIPING) (45 / Male), NRIC: S7230395D, Tel: +6597461585		
Adj Asg. Remarks:	NO EST, ASSIGN TO MARCUS CHUA AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Claim Documents

*SLF800J (SNM18D00269C02)
[SKR1865P]
TP
MONG HENG TRANSPORTATION
Jan 15 2018 8:00AM
[CHAN MEI LIN]
LA AUTO

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Assessment Reports			1 per page ▼	☒
No	Finalized On	AMK Autopoint Pte Ltd (HQ)	Thumbnail	Print
1	15/01/18 11:19	Accident Statement	Load HTM	
2	16/01/18 09:36	Addendum Sheet	Load JPG	☒
3	16/01/18 09:40	Accident Statement Addm. #1	Load HTM	
Photos/Images			3 per page ▼	☒
No	Finalized On	AMK Autopoint Pte Ltd (HQ)	Thumbnail	Print
1	15/01/18 11:15	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
2	15/01/18 11:15	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
3	15/01/18 11:15	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
4	15/01/18 11:15	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
5	15/01/18 11:15	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
6	15/01/18 11:15	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
7	15/01/18 11:15	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
8	15/01/18 11:15	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
9	15/01/18 11:15	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
10	15/01/18 11:15	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
11	15/01/18 11:15	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
12	15/01/18 11:15	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
13	15/01/18 11:15	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
14	15/01/18 11:15	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
15	15/01/18 11:15	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/02/18 17:16	General View	Load JPG	☒
2	26/02/18 17:16	General View	Load JPG	☒
3	26/02/18 17:16	General View	Load JPG	☒
4	26/02/18 17:16	General View	Load JPG	☒
5	26/02/18 17:16	General View	Load JPG	☒
6	26/02/18 17:16	General View	Load JPG	☒
7	26/02/18 17:16	General View	Load JPG	☒
8	26/02/18 17:16	General View	Load JPG	☒

9	26/02/18 17:16	General View	1	Load JPG	✓
10	26/02/18 17:16	General View	1	Load JPG	✓
11	26/02/18 17:16	General View	1	Load JPG	✓
12	26/02/18 17:16	General View	1	Load JPG	✓
13	26/02/18 17:16	General View	1	Load JPG	✓
14	26/02/18 17:16	General View	1	Load JPG	✓
15	26/02/18 17:16	General View	1	Load JPG	✓
16	26/02/18 17:16	General View	1	Load JPG	✓
17	26/02/18 17:16	General View	1	Load JPG	✓
18	26/02/18 17:16	General View	1	Load JPG	✓
19	26/02/18 17:16	General View	1	Load JPG	✓
20	26/02/18 17:16	General View	1	Load JPG	✓
21	26/02/18 17:16	General View	1	Load JPG	✓

Documentation

1 per page ▼



No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	22/01/18 08:56	OI GIA REPORT	1	Load PDF	
No	Finalized On	AMK Autopoint Pte Ltd (HQ)		Thumbnail	Print
1	15/01/18 11:17	Sketch Plan [Linked Accident Report Documents]	1	Load JPG	✓
2	15/01/18 11:17	Sketch Plan #2 [Linked Accident Report Documents]	1	Load JPG	✓
3	16/01/18 09:37	Accident Sketch Plan [Linked Accident Report Documents]	1	Load TIF	
4	16/01/18 09:37	Accident Sketch Plan [Linked Accident Report Documents]	1	Load TIF	
5	16/01/18 09:37	Accident Sketch Plan [Linked Accident Report Documents]	1	Load TIF	

Linked Accident Report Documents

View View in Browser ▼

Assessment Reports			1 per page ▼	☒
No	Finalized On	AMK Autopoint Pte Ltd (HQ)		Thumbnail Print
1	15/01/18 11:19	Accident Statement	1	Load HTM
2	16/01/18 09:36	Addendum Sheet	1	Load JPG ✓
3	16/01/18 09:40	Accident Statement Addm. #1	1	Load HTM

Photos/Images			3 per page ▼	☒
No	Finalized On	AMK Autopoint Pte Ltd (HQ)		Thumbnail Print
1	15/01/18 11:15	Accident Photo	1	Load JPG ✓
2	15/01/18 11:15	Accident Photo	1	Load JPG ✓
3	15/01/18 11:15	Accident Photo	1	Load JPG ✓
4	15/01/18 11:15	Accident Photo	1	Load JPG ✓
5	15/01/18 11:15	Accident Photo	1	Load JPG ✓
6	15/01/18 11:15	Accident Photo	1	Load JPG ✓
7	15/01/18 11:15	Accident Photo	1	Load JPG ✓
8	15/01/18 11:15	Accident Photo	1	Load JPG ✓
9	15/01/18 11:15	Accident Photo	1	Load JPG ✓
10	15/01/18 11:15	Accident Photo	1	Load JPG ✓
11	15/01/18 11:15	Accident Photo	1	Load JPG ✓
12	15/01/18 11:15	Accident Photo	1	Load JPG ✓
13	15/01/18 11:15	Accident Photo	1	Load JPG ✓

14	15/01/18 11:15	Accident Photo		Load JPG	☒
15	15/01/18 11:15	Accident Photo		Load JPG	☒
Documentation					
				1 per page ▼	☒
No	Finalized On	AMK Autopoint Pte Ltd (HQ)		Thumbnail	Print
1	15/01/18 11:17	Sketch Plan		Load JPG	☒
2	15/01/18 11:17	Sketch Plan #2		Load JPG	☒
3	16/01/18 09:37	Accident Sketch Plan		Load TIF	
4	16/01/18 09:37	Accident Sketch Plan		Load TIF	
5	16/01/18 09:37	Accident Sketch Plan		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118001344/M1TD3S2
Date: 28/02/2018

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSN3001551701
Claimant Vehicle No: SLF800J Insured Vehicle No: SKR1865P
Date of Loss: 15/01/2018 Nature of Claim: TP Claim No: SNM18D00269C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLF800J
Make & Model: HONDA STREAM, 1.8 (A) Engine No: R18A1729908
Reg. Date: 06/06/2007 (Man. Year: 2007) Chassis No: RN61026533
Colour: Black Odometer: 225212 km
Engine Capacity: 1799 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45R17 Rear Tyre Size: 225/45R17
Front Left Side: Michelin 8 mm Rear Left Side: Michelin 8 mm
Front Right Side: Michelin 8 mm Rear Right Side: Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,902.40	2,480.80	1,421.60	36.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,460.00	1,410.00	1,050.00	42.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,362.40	3,890.80	2,471.60	38.85
Approved Total (Overridden) (S\$)		3,000.00		
Nett Amount (S\$)	6,362.40	3,000.00	3,362.40	52.85

INSPECTION

Date of Assignment: 22/01/2018
Date Inspected: 25/01/2018 Inspected At: LA AUTO (HQ)
Estimated Period of Repair: 4.0 days 106 PUNGGOL WALK, #09-16 TWIN WATERFALLS
Singapore 828793

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Feb 2018)
Parts:	M1-MPV	HONDA STREAM 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLF800J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Dented	1,280.00 F	*1,280.00 FL
2	1		*TAIL GATE HONDA LOGO	Not Necessary	38.00 F	*- FL
3	1		*TAIL GATE STREAM EMBLEM	Necessary	45.00 F	*45.00 FL
4	1		*TAIL GATE TOP LOCK	Serviceable	119.80 F	*- FL
5	1		*REAR END PANEL	Repair	408.60 F	*- FL
6	1		*REAR END PANEL TOP GARNISH	Serviceable	156.00 F	*- FL
7	1		*REAR BUMPER	Deformed	950.00 F	*950.00 FL
8	1		*REAR BUMPER SIDE RETAINER (RIGHT)	Distorted	35.00 F	*35.00 FL
9	1		*TAIL LAMP (RIGHT)	Cut	460.00 F	*460.00 FL
10	1		*REAR WIND SCREEN MOULDING	Necessary	56.00 F	*56.00 FL
11	1		*REAR BOOT LID COVER HONDA H LOGO	Repair	39.00 F	*- FL
12	1		*TOWING COVER	Serviceable	35.00 F	*- FL
13	1		*REAR EXHAUST PIPE	Serviceable	0.00 F	*- FL
			(NPA)			
14	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*220.00 FS
					Sub Total (\$\$)	3,902.40 3,046.00
					- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00 565.20
					Total Parts (\$\$)	3,902.40 2,480.80

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK LIGHTINGS AND ELECTRICAL WIRING SYSTEM INCLUDE PERFORMING WATER LEAKAGE TEST.	New	60.00	30.00
2	LABOUR FOR JACKING, KNOCKING REAR RIGHT SIDE MUDGUARD, REAR SPARE TYRE TANK PANEL, CUTTING REAR END PANEL, DISMANTLE AND REPLACE THE ABOVE MENTIONED PARTS.	New	1,100.00	600.00
3	LABOUR FOR RESPRAY REAR BOOT LID COVER (INNER & OUTER), REAR END PANEL, REAR BUMPER & TOUCH UP REAR RIGHT SIDE MUDGUARD PANEL.	New	1,000.00	600.00
4	TO APPLY SILICON ONTO REAR WIND SCREEN.	New	120.00	60.00
5	LABOUR FOR DISMANTLE & REFIX REAR WIND SCREEN.	New	180.00	120.00
Gross Labour Cost (\$\$)			2,460.00	1,410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >