

ASS. REC. BY:

Surveyor

Tau Fik

ASSIGNMENT (Office)

From (Person):

Albert Hong

of

AGI

Date/Time: 22/01/18 @ 4:01pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKP 9655L

Insured:

SJM 1748H

at Workshop m/s

Sng Ah Tee

Tel:

6268 6183

of Blk 3, Pioneer Road North #01-18

Policy No:

Claim No:

C10001290

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 18/01/2018

23/01/2018 @ After 10am

CA / REV / REP. / REV 24 HRS

up

R.O.D. Endorsement:

Date/Time: 4:52pm @ 22/1/18

Person Contacted:

Janice

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SKP 9655L - X

SJM 1748H - X

31/1/18

LS \$2500 confirmed by email (Ref 2700.84, 52/0)

Taylth

REP: AGI

ASSIGNMENT

From: _____ Date: 23/01/18

Estimated Cost: _____

OD (T) / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKP 9655 L

at Workshop / Is: Sng Ah Tee

of: Blk 3, Pioneer Rd north #01-18

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

After 10 am

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bel. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / RR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res: Yes or No

Lump Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS ^{hwp}

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKP 9655 L Reg: 2014 OUT.

Type: ☒ M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer /

Make: Hunder City

1497

Colour: Black

Insured: Std / NI / NA

Sp. Reading: 81646

T. Radio: Insured: Std / NI / NA

Eng No: _____

C No: MK HGM 666 OF P000129

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Mod: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: 6 mm

Rear: 6 mm

R. Bal: 6 mm

R. Bal: 6 mm

L. Bal: 6 mm

L. Bal: 6 mm

D.O.A: _____

D.O.I: 23/1/18 @ 1615

Survey held at: Sng Ah Tee

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date Time Action / Instruction

RECEIVED 03 JUL 2018

Date/Time File Pass to:

☐ : Prel. Report
☐ : Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee

Transport

Food

Other

Date/Time File Return to:

3/7 - typist

Add Fee:

☐ Site Insp
☐ Interview
☐ Tech
☐ Test and

Site Insp

Interview

Tech

Test and

Report Format:

TP

Lump Sum / I.B.U

2500/2

250

Survey Department Check List (Case Handler)

Reference No.: **CS AGI 18001347 T1vd3**

Policy Type: **OD / TP / TP RES / TL / EVA**

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (

): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By:

VERON

3/7/18

Case Handler

Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI18001347/T1vd3

(BUDGET DIRECT INSURANCE)
190 CLEMENCEAU AVENUE #03-01
SINGAPORE SHOPPING CENTRESINGAPORE
239924

Date : 23-01-2018



Code : AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJM 1748H	Veh. Inspected	SKP 9655L
Policy No.		Coverage (\$)	0.00
Claim No.	C10001290	Excess (\$)	0.00
Assign From	ALBERT HONG	Assign Date	23/01/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	18/01/2018	Inspection Date	23/01/2018
Survey held at	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD BLK 3, PIONEER ROAD NORTH, #01-18 SINGAPORE 628457.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Nivitha (LKK Auto)

From: Albert Hong <albert.hong@budgetdirect.com.sg>
Sent: Monday, 22 January 2018 4:01 PM
To: assignments
Cc: SUR
Subject: Appoint LKK to conduct TP survey; Our Ref: C10001290

Hi Team,

Please accept assignment and liaise with Sng Ah Tee. Requested to be surveyed in the morning.

TP vehicle: SKP9655L.

Thank you.

Regards,

Albert Hong
Senior Executive, Claims

T +65 6540 2182
F +65 6725 0853
E albert.hong@budgetdirect.com.sg

**Budget
Direct**
insurance

Customer Care: +65 6221 2111
Claims: +65 6221 2199
Claims (Int.): +65 6540 2199

190 Clemenceau Avenue
#03-01, Singapore Shopping Centre
Singapore 239924
budgetdirect.com.sg

Auto & General Insurance (Singapore) Pte. Limited (co. Reg. No. 201626103G) trading as Budget Direct Insurance.

From: SAMANTHA TAN [mailto:sam@sngahtee.com]
Sent: Monday, 22 January, 2018 3:56 PM
To: Albert Hong <albert.hong@budgetdirect.com.sg>
Subject: RE: ACCIDENT INVOLVING OUR CLEINT'S VEHICLE SKP9655P & YOUR INSURED SJM1748H ON 18/01/2018

Hi,

Kindly arrange survey above vehicle on 23/01/2018.

Thank you.

Best Regards

Samantha Tan | sam@sngahtee.com

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD | BLK 3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457
TEL: 62686183 (4LINES) | FAX: 62681429 | Find us at <http://www.sngahtee.com>



From: Albert Hong [<mailto:albert.hong@budgetdirect.com.sg>]
Sent: Monday, 22 January 2018 10:59 AM
To: SAMANTHA TAN <sam@sngahtee.com>
Subject: RE: ACCIDENT INVOLVING OUR CLEINT'S VEHICLE SKP9655P & YOUR INSURED SJM1748H ON 18/01/2018

Hi Samantha,

Liability is down against our insured.

Regards,

Albert Hong
Senior Executive, Claims

T +65 6540 2182
F +65 6725 0853
E albert.hong@budgetdirect.com.sg

**Budget
Direct**
insurance

Customer Care: +65 6221 2111
Claims: +65 6221 2199
Claims (Int.): +65 6540 2199

190 Clemenceau Avenue
#03-01, Singapore Shopping Centre
Singapore 239924
budgetdirect.com.sg

Auto & General Insurance (Singapore) Pte. Limited (co. Reg. No. 201626103G) trading as Budget Direct Insurance.

From: SAMANTHA TAN [<mailto:sam@sngahtee.com>]
Sent: Monday, 22 January, 2018 9:55 AM
To: Claims <claims@budgetdirect.com.sg>
Cc: Albert Hong <albert.hong@budgetdirect.com.sg>
Subject: ACCIDENT INVOLVING OUR CLEINT'S VEHICLE SKP9655P & YOUR INSURED SJM1748H ON 18/01/2018

Hi All,

We refer to above and wish to check liability for this case.

Hope to hear from you soon.

Thank you.

Best Regards

Samantha Tan | sam@sngahtee.com

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD | BLK 3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457
TEL: 62686183 (4LINES) | FAX: 62681429 | Find us at <http://www.sngahtee.com>



Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 2284A

Vehicle Details

Vehicle No.: SKP9655L

Vehicle to be Exported: No

Intended De-registration Date: 31 Jan 2018

Vehicle Make: HONDA

Vehicle Model: CITY 1.5 SV CVT

Primary Colour: Brown

Manufacturing Year: 2014

Engine No.: L15Z11414239

Chassis No.: MRHGM6660EP000129

Maximum Power Output: 88.0 kW (118 bhp)

Open Market Value: \$16,539.00

Original Registration Date: 24 Oct 2014

First Registration Date: 24 Oct 2014

Transfer Count: 0

Actual ARF Paid: \$6,539.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 23 Oct 2024

PARF Rebate Amount: \$4,904.00

Intended COE Rebate Details

COE Expiry Date: 23 Oct 2024

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$64,841.00

COE Rebate Amount: \$43,628.00

Total Rebate Amount: \$48,532.00

The information contained herein is correct as at 22 Jan 2018

OK

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 3 July 2018 9:37 AM
To: Sharon Sng
Cc: Taufikh (LKKAUTO); SUR
Subject: RE: SKP9655L - FINALISE & AFTER PAINT

Dear Sharon,

Noted with thanks.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sharon Sng [mailto:sharon@sngahtee.com]
Sent: Tuesday, 3 July 2018 9:31 AM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Cc: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Subject: RE: SKP9655L - FINALISE & AFTER PAINT

Hi Veron

its the number frame that is damaged. Cannot clip straight.
However amount is the same, confirm lumpsum \$2500 then.

Best Regards

Sharon Sng

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD | BLK 3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457
TEL: 62686183 (4LINES) | FAX: 62681429 | Find us at <http://www.sngahtee.com>



From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: Tuesday, July 3, 2018 8:28 AM
To: Sharon Sng; Taufikh (LKKAUTO); SUR
Subject: RE: SKP9655L - FINALISE & AFTER PAINT

Dear Sharon,

WITHOUT PREJUDICE

-Rear number plate can't see any damaged.

Offer Lump Sum \$2500/- @ 5 working days.

Kindly confirmed.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sharon Sng [mailto:sharon@sngahtee.com]

Sent: Monday, 2 July 2018 5:30 PM

To: Taufikh (LKKAuto) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>

Subject: SKP9655L - FINALISE & AFTER PAINT

Best Regards

Sharon Sng

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD | BLK 3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457
TEL: 62686183 (4LINES) | FAX: 62681429 | Find us at <http://www.sngahtee.com>



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/01/2018 09:23
Date Of Accident	18/01/2018 07:30
Exact Location Of Accident	WOODLANDS AVE 12 TO SLE(BKE)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKP9655L
Insured/Policyholder	
Name Of Registered Owner	TAN WEE PING
NRIC No	S7662284A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91198963
Alternative Phone No	OTHERS-96550243

Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC-1.5 I-VTEC (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	HL ASSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MP301433
Cover Note Number	

Driver

Name of Driver	TAN WEE PING
NRIC No	S7662284A
Date Of Birth	22/07/1976
Occupation	INDOOR
Date Of Driving Pass	22/08/2009
Driving Experience	8 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91198963
Fax Number	
Contact Number	OTHERS-96550243
Email Address	NOEMAIL

Address	BLK 688B WOODLANDS DRIVE 75 #16-34
Postcode	732688
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : KIEW FUI SZE
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident


ON 18/01/2018 AT AROUND 0730HRS, I WAS TRAVELLING ALONG WOODLANDS AVE 12 AND I WAS ON EXTREME RIGHT 1ST LANE. ON THAT TIME I WAS STATIONARY ON MY LANE, SUDDENLY I FEEL AN IMPACT FROM MY REAR THEN I WENT DOWN TO SEE AND NOTICES THAT VEHICLE B HAD COLLIDED ONTO MY VEHICLE REAR PORTION.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJM1748H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TIANG TIAN SANG
NRIC/Passport Number	S1504243E
Contact Number	92729693
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	



No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

I AM AWARE THAT MY INSURER MAY HAVE A 14 DAYS TIMEFRAME FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY. I WILL CHECK MY POLICY FOR MORE DETAILS.

GIA/IRIC Sketch Plan Form_V3

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Accident Circumstances

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

☐ Claim own policy
☒ Claim third party
☐ Claim OD / TP at other workshop
☐ For record purpose
Policy No. IMP301433
Insurer HL Veh. No. SKP9655L

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3 Pioneer Road North #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Our Ref:

Date : 02/07/2018

ATTN:THE MOTOR CLAIMS DEPT

AUTO & GENERAL INSURANCE (S) PTE LTD

SUPPLEMENTARY ESTIMATE COST OF REPAIR

Vehicle Reg No. SKP9655L
Date of Accident 18-Jan-18
Type of Claim TP BUDGET
Survey By _____

Model / Year HONDA CITY
Policy No. _____
Prepared By SHARON
Chassis No. _____

S/NO	Description	Qty	List Price	Amount
1	REAR SPARE TYRE BOARD	1	\$ 120.00 LESS 20%	\$ 120.00 \$ 12.00 <u>\$ 108.00</u>

Sharon ✓

孫亞弟汽車燒焊私人有限公司

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB Reg / GST Reg. No: 200810440N

EST/QUOTE NO. SQ003508

AUTO & GENERAL INSURANCE(SINGAPORE)PTE LTD

MOTOR CLAIMS DEPT

190 CLEMENCEAU AVE

#03-01 S'PORE SHOPPING CENTRE

(S) 239924

ATTENTION :

CONTACT : -

FAX NO: 67250853

DATE : 22/1/2018
 ACCIDENT DATE : 18/1/2018
 VEHICLE NO : SKP9655L
 CHASSIS/ENG.NO : MRHGM6660EP000129
 VEHICLE MODEL : HONDA CITY
 CLAIM NO :
 POLICY NO : SURVEY BY LKK
 REMARK : 9655NTUC TP AGST
 SJM1748H

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
** LIST PRICE **							
1	1	PC	REAR BUMPER	463.70	20	370.96	de 370.96
2	10	PC	REAR BUMPER CLIPS	39 3.90	20	3.12	nel 31.20
3	2	PC	REAR BUMPER RETAINER	36 18.00	20	14.40	nel 28.80
4	1	PC	REAR BUMPER REFLECTOR(LH)	30.00	20	24.00	X 24.00
5	3	PC	REAR PARKING SENSOR (3 pcs)	300 150.00	20	120.00	✓ still 360.00
6	1	PC	REAR BOOT LID	475.00	20	380.00	bt 380.00
7	1	PC	REAR BOOT EMBLEM	24.00	20	19.20	nel 19.20
8	1	PC	REAR BOOT CITY STICKER	22.80	20	18.24	nel 18.24
9	2	PC	REAR BOOT HINGE	66.40	20	53.12	RX 106.24
10	1	PC	REAR BOOT IVTEC STICKER	21.60	20	17.28	nel 17.28
11	1	PC	REAR NUMBER PLATE CHROME	98.50	20	78.80	11 X 78.80
12	1	PC	REAR BOOT INSULATOR	28.90	20	23.12	11 X 23.12
13	1	PC	REAR BOOT LOCK	90.30	20	72.24	11 7x 72.24
14	12	PC	REAR BOOT INSULATOR CLIPS	3.50	20	2.80	11 7x 33.60
15	2	PC	REAR BOOT LAMP	110.00	20	88.00	11 7x 176.00
16	2	PC	REAR TAILLAMP	225.00	20	180.00	11 7x 360.00
17	2	PC	REAR TAILLAMP PANEL	68.80	20	55.04	RX 110.08
18	1	PC	REAR END PANEL	316.70	20	253.36	bt 253.36
19	1	PC	REAR END PANEL TOP GARNISH	88.60	20	70.88	de 70.88
20	1	PC	REAR END PANEL RUBBER	89.80	20	71.84	twi? 71.84
21	1	PC	REAR REMOTE SENSOR	90.00	20	72.00	an? X 72.00
						SUB-TOTAL:	2,677.84

SAM

PAGE: 1 of 2

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD

E & O E

孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ003508

AUTO & GENERAL INSURANCE(SINGAPORE) PTE LTD

MOTOR CLAIMS DEPT

190 CLEMENCEAU AVE

#03-01 S'PORE SHOPPING CENTRE

(S) 239924

ATTENTION:

CONTACT: -

FAX NO: 67250853

DATE : 22/1/2018
ACCIDENT DATE : 18/1/2018
VEHICLE NO : SKP9655L
CHASSIS/ENG.NO : MRHGM6660EP000129
VEHICLE MODEL : HONDA CITY
CLAIM NO :
POLICY NO : SURVEY BY LKK
REMARK : 9655NTUC TP AGST
SJM1748H

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	MISC/MARKUP	TOTAL AMT
------	-----	------	-------------	-------	--------	-------------	-----------

** SPECIAL NETT PRICE **							
1	1	PC	REAR NUMBER PLATE	35.00			35.00
						35.00	35.00
						SUB-TOTAL	35.00

** WORK LABOUR **							
TO KNOCK, WELD, REMOVE & FIX ON ABOVE PARTS				1000.00		700	1,000.00
TO REMOVE & REFIX REAR TRIMS				100.00		50	100.00
TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS				1100.00		700	1,100.00
TO CHECK WIRING				30.00		✓	30.00
TO APPLY ANTI RUST COATING				150.00		60	150.00
						SUB-TOTAL	2,380.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tan Jiah 97495749

23/1/18 R 1615

Lumpsum

Resurvey after repair

5 days

24/1/18

5188.84

5000.84

SAM

PAGE: 2 of 2

SUB-TOTAL : S\$ 5,092.84
ADD 7% GST. S\$ 356.50
GRAND TOTAL : S\$ 5,449.34

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD

E & O E

孫亞弟汽車燒焊私人有限公司

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB Reg./GST Reg. No: 200810440N

EST/QUOTE NO. SQ003508

AUTO & GENERAL INSURANCE(SINGAPORE) PTE LTD

MOTOR CLAIMS DEPT

190 CLEMENCEAU AVE

#03-01 S'PORE SHOPPING CENTRE

(S) 239924

ATTENTION :

CONTACT : -

FAX NO: 67250853

DATE 22/1/2018

ACCIDENT DATE : 18/1/2018

VEHICLE NO : SKP9655L

CHASSIS/ENG.NO : MRHGM6660EP000129

VEHICLE MODEL : HONDA CITY

CLAIM NO :

POLICY NO : SURVEY BY LKK

REMARK 9655NTUC TP AGST
SJM1748H

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
** LIST PRICE **							
✓ 1	1	PC	REAR BUMPER	463.70	20	370.96	de - 370.96 ✓
2	10	PC	REAR BUMPER CLIPS	3.90	20	3.12	net - 31.20 ✓
3	2	PC	REAR BUMPER RETAINER	18.00	20	14.40	net - 28.80 ✓
4	1	PC	REAR BUMPER REFLECTOR(LH)	30.00	20	24.00	X 24.00 X
5 * 2	✓ 3	PC	REAR PARKING SENSOR	150.00	20	120.00 (\$40) ✓	360.00
6	1	PC	REAR BOOT LID	475.00	20	380.00	bt - 380.00 ✓
7	1	PC	REAR BOOT EMBLEM	24.00	20	19.20	net - 19.20 ✓
8	1	PC	REAR BOOT CITY STICKER	22.80	20	18.24	net - 18.24 ✓
9	2	PC	REAR BOOT HINGE	66.40	20	53.12	Rx 106.24 X
10	1	PC	REAR BOOT IVTEC STICKER	21.60	20	17.28	net - 17.28 ✓
11	1	PC	REAR NUMBER PLATE CHROME	98.50	20	78.80	X 78.80 X
12	1	PC	REAR BOOT INSULATOR	28.90	20	23.12	X 23.12 X
13	1	PC	REAR BOOT LOCK	90.30	20	72.24	? 72.24 X
14	12	PC	REAR BOOT INSULATOR CLIPS	3.50	20	2.80	? 33.60 X
15	2	PC	REAR BOOT LAMP	110.00	20	88.00	? 176.00 X
16	2	PC	REAR TAILLAMP	225.00	20	180.00	? 360.00 X
17	2	PC	REAR TAILLAMP PANEL	68.80	20	55.04	Rx 110.08 X
18	1	PC	REAR END PANEL	316.70	20	253.36	bt - 253.36 ✓
✓ 19	1	PC	REAR END PANEL TOP GARNISH	88.60	20	70.88	de - 70.88 ✓
✓ 20	1	PC	REAR END PANEL RUBBER	89.80	20	71.84	twi - 71.84 ✓
21	1	PC	REAR REMOTE SENSOR	90.00	20	72.00	? 72.00 X

SUB-TOTAL: 2,677.84

\$1501.76

SAM

PAGE: 1 of 2

孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ003508

AUTO & GENERAL INSURANCE(SINGAPORE) PTE LTD

MOTOR CLAIMS DEPT

190 CLEMENCEAU AVE

#03-01 S'PORE SHOPPING CENTRE

(S) 239924

ATTENTION:

CONTACT: -

FAX NO: 67250853

DATE : 22/1/2018

ACCIDENT DATE : 18/1/2018

VEHICLE NO : SKP9655L

CHASSIS/ENG.NO : MRHGM6660EP000129

VEHICLE MODEL : HONDA CITY

CLAIM NO :

POLICY NO : SURVEY BY LKK

REMARK : 9655NTUC TP AGST
SJM1748H

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
------	-----	------	-------------	-------	--------	-------------	-----------

** SPECIAL NETT PRICE **

1	*	1	PC	REAR NUMBER PLATE	35.00		35.00 <i>phsp?</i> 35.00 ✓
							<hr/> SUB-TOTAL 35.00

** WORK LABOUR **

TO KNOCK,WELD,REMOVE & FIX ON ABOVE PARTS	1000.00	<i>700</i>	1,000.00
TO REMOVE & REFIX REAR TRIMS	100.00	<i>50</i>	100.00
TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS	1100.00	<i>700</i>	1,100.00
TO CHECK WIRING	30.00	✓	30.00
TO APPLY ANTI RUST COATING	150.00	<i>60</i>	150.00
			<hr/> SUB-TOTAL 2,380.00

Tan Kah 97495749
- wp'

23/1/18 @ 1615

Lumpsum

Resumy after repair

5 days

total \$3184.76
4497.80 = \$2547.80
\$7500
Shrim 2/2/18
Lumpsum ok? PLS REVIEW

SAM

PAGE: 2 of 2

SUB-TOTAL : S\$ 5,092.84

ADD 7% GST. S\$ 356.50

GRAND TOTAL : S\$ 5,449.34

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD

E & O E



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI18001347/T1vd3n2

(BUDGET DIRECT INSURANCE)
190 CLEMENCEAU AVENUE #03-01
SINGAPORE SHOPPING CENTRESINGAPORE
239924

Date : 05-07-2018



Code : AGI

Policy Particulars :- THIRD PARTY CLAIM

1.	Insured Veh.	SJM 1748H	Veh. Inspected	SKP 9655L
	Policy No.		Coverage (\$)	0.00
	Claim No.	C10001290	Excess (\$)	0.00
	Assign From	ALBERT HONG	Assign Date	22/01/2018

Vehicle Particulars & Condition

2.	Make & Model	HONDA CITY	c.c	1497
	Engine No.	HIDDEN	Year of Reg.	2014
	Chassis No.	MRHGM6660EP000129	Colour	BLACK
	Odometer	81646	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		

Conditions of Tyres

3.		Size	Make	Balance
	R/H Front Tyre	185/55 R16	MICHELIN	6 mm
	L/H Front Tyre	185/55 R16	MICHELIN	6 mm
	R/H Rear Tyre	185/55 R16	MICHELIN	6 mm
	L/H Rear Tyre	185/55 R16	MICHELIN	6 mm

Description of Damages

4.	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
----	--

General Information

5.	Accident Date	18/01/2018	Inspection Date	23/01/2018
	Survey held at	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD BLK 3, PIONEER ROAD NORTH, #01-18 SINGAPORE 628457.		

Remarks

5a.	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
-----	--

Estimate Days of Repair

5b.	ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-----	-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKP 9655L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	463.70	463.70
10	REAR BUMPER CLIPS @\$3.90	NECESSARY	39.00	39.00
2	REAR BUMPER RETAINER @\$18.00	NECESSARY	36.00	36.00
1	REAR BUMPER REFLECTOR (LH)	TO REPAIR SEE LABOUR	30.00	-
3	REAR PARKING SENSOR @\$150.00	SHORTED (2 PCS ONLY)	450.00	300.00
1	REAR BOOT LID	BENT	475.00	475.00
1	REAR BOOT EMBLEM	NECESSARY	24.00	24.00
1	REAR BOOT CITY STICKER	NECESSARY	22.80	22.80
2	REAR BOOT HINGE @\$66.40	TO REPAIR SEE LABOUR	132.80	-
1	REAR BOOT IVTEC STICKER	NECESSARY	21.60	21.60
1	REAR NUMBER PLATE CHROME	NOT NECESSARY	98.50	-
1	REAR BOOT INSULATOR	NOT NECESSARY	28.90	-
1	REAR BOOT LOCK	NOT NECESSARY	90.30	-
12	REAR BOOT INSULATOR CLIPS @\$3.50	NOT NECESSARY	42.00	-
2	REAR BOOT LAMP @\$110.00	NOT NECESSARY	220.00	-
2	REAR TAILLAMP @\$225.00	NOT NECESSARY	450.00	-
2	REAR TAILLAMP PANEL @\$68.80	TO REPAIR SEE LABOUR	137.60	-
1	REAR END PANEL	BENT	316.70	316.70
1	REAR END PANEL TOP GARNISH	DEFORMED	88.60	88.60
1	REAR END PANEL RUBBER	TWISTED	89.80	89.80
1	REAR REMOTE SENSOR	NOT NECESSARY	90.00	-
1	REAR SPARE TYRE BOARD (ADDITIONAL)	TORN	120.00	120.00
	LESS 20% DISCOUNT		-693.46	-399.44
			2,773.84	1,597.76
SPECIAL NETT ITEMS				
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	35.00	-
			35.00	-

Report Ref No. CS/AGI18001347/T1vd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO KNOCK,WELD,REMOVE & FIX ON ABOVE PARTS.INCLUSIVE OF THE REPAIR OF REAR BUMPER REFLECTOR (LH),REAR BOOT HINGE AND REAR TAILLAMP PANEL.		1,000.00	700.00
	TO REMOVE & REFIX REAR TRIMS.		100.00	50.00
	TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS.		1,100.00	700.00
	TO CHECK WIRING.		30.00	30.00
	TO APPLY ANTI RUST COATING.		150.00	60.00
			2,380.00	1,540.00
	GRAND TOTAL		5,188.84	3,137.76
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,500.00

Report Ref No. CS/AGI18001347/T1vd3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.