

REF: CS/MSG18001351/T1rd302

ASSIGNMENT NO.

Merimen Taufik
Kwok Woon Choo

MSG

22/01/18 @ 401pm

① OF PD/WS / TR RES / OD RES / EVAC / INV / MV

To: Bay of Vehicle SKP 1124E

to: Volkswagen 92361588

17 Tuas Ave 9

Ref: S27936551SMF 546931

Sum Insured: \$3,000.00

Make of Veh: 19/01/2018

CA: (REV) REF: REV 24 HRS

Date Time: 22/01/2018 Germaine

Date Time: Auto Approved: ☒ EPR

SKP 1124E-X

Sent poli thru merimen ; Pending offer

25/1/18 @ 1038am Woon Choo said pending for mv

25/1/18 Rate approved \$16000, vacuum & regas aircon net is \$237.50 from Siew Wei by merimen

Taufik

MS 167

MS 167

Date
Estimated Cost
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect vehicle No.

at Workshop No.

of

Insured

Policy No.

Claims No.

Sum Insured

Excess

\$3000

Client's Record

Make of veh

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

NS	OS

Bar or Market Value

\$67K

DAO Accident Report

Consistent? Yes or No

SLA / PP Seen

Consistent? Yes or No

Est. Repairs

days

Res: Yes or No

Sum Surp

%

3 val: Yes or No

OA / REV / REP. / 24 HRS

Vehicle IN / OUT

Date

Person Contacted

SKP1124E

2014 Aug

Type Motor Cycle Bus Van Lorry Taxi Prime Mover

Truck Trailer

Make

Volkswagen Jetta

1390

Colour

Blue

Insured Std N/A

St. Reading

61451

Insured Std N/A

Eng No

C No

WVWZ7Z16ZE M050976

Gen. Cond Good / Fair / Poor / Burnt

Steering Inorder / Jammed / Leaked / Burnt or

Brake Inorder / Jammed / Leaked / Burnt or

Mod. Nil / SRim / STD A/Rim or

Tyre Size

F:

225 / 40 R18

R:

7

BS / DUN / EXNOVA / GY / FS / LIZA / MITSUBISHI / SUMI

TOYO / YOKO or

Front

Rear

R. Bal

6

mm

R. Bal

6

mm

L. Bal

6

mm

L. Bal

6

mm

D.O.A.

D.O.A.

23/1/18 @ 1445

Survey held at

KW Tms

Des. of Damages

Front

Rear

OS

N.S

U/O

Roof top or

The U/O - Chassis frame Body Structure affected due to collision

Date Time Action Instruction

25/1/18 Email Germaine informed C/A not exceeding 1B1 \$16K ex \$3000

30/1/18 Supplementary approve

Confirm \$15,901.34, 10 days
Red: \$30,814.33, 66%.

RECEIVED 9 JUL 2018

Date Time File Pass No

☐

Prel. Report

typist

☒

Final Report

Date Time File Return No

Days Of Repair

10

Resurvey No. of Trial

1

Survey Fee

Add Fee:

☐

Site Fee

\$

☐

Test Fee

\$

☐

Test Fee

\$

☐

Test Fee

\$

Record Form No

00

Comp. Fee

15,901.34

490
10
460

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Jan 2018		22 Jan 2018 16:01 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:		WANG MAOLONG , ID: S2626092B, Tel: +6591126175, Email: ml_w@hotmail.com		[Created by insurer]
Vehicle Reg. No.:		SKP1124E	Date of Loss:	19/01/2018 08:00 - :59
Claim Type:		OD / 546931	Policy/Cover Note No.:	S27936551SMF (Comprehensive) Coverage: 14/08/2017 - 13/08/2018
		Excess:	S\$3,000.00	
Repairer:		Volkswagen Centre Singapore - Tuas (HQ) 17 TUAS AVE 9, 639197 Tuas - Tel:		
Handling Insurer:		MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Kwok Woon Choo - 6643 1330]		
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 23/01/2018]		
Driver/Custodian:		WANG MAOLONG (58 / Male), NRIC: S2626092B, Tel: +6591126175		
Adj Asg. Remarks:		TO REVERT - UNDER VW SCHEME		

ASSOCIATED MAIL RECEIVED

[View All](#) | [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[View All](#) | [Search Tasks](#) | [Create New Task](#) | [Complete](#)

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 25 January 2018 5:04 PM
To: Ong, Germaine (VWG Singapore); SUR
Cc: Foo, John (VWG Singapore); 'Cheong, Pearlyn (VWG Singapore)'; Charmaine.Kong@vw.com.sg; Tang, Shu Shi (VWG Singapore); Tan, Evelyn (VWG Singapore); Oh, Aik Seong (VWG Singapore)
Subject: SKP 1124E-DOA: 19/1/2018 (MSIG OD)

Dear Germaine,

As instructed by our client MSIG , please proceed to repair the insured vehicle **SKP 1124E not exceeding \$16K on part by part (Excess \$3000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Please note that vacuum & regas aircon net is \$237.50

Best Regards,

Veron Chen | Case Handler on behalf of Janice

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***SKP1124E (546931)**

OD

Jan 19 2018 8:00AM

[WANG MAOLONG]

Volkswagen Centre Singapore - Tuas

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 25/01/2018 14:15 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$16000.00) - SKP1124E - Claim Handler: Kwok Woon Choo

Approved:16000.00:a if c; please check with w/shop if they can repair at \$16000.00 before excess subject to finalisation please note that vacuum & regas aircon net is \$237.50

DOCUMENTS SUMMARY

There are no documents.

Woon Choo Kwok

From: Koh Lay Hoon
Sent: Monday, January 22, 2018 2:21 PM
To: Woon Choo Kwok
Subject: FW: OD CLAIM SKP1124E DOA: 19/01/2018
Attachments: MyDocument_2018_01_22_02_07_18.pdf

From: Ong, Germaine (VWG Singapore) [mailto:Germaine.ong@vw.com.sg]
Sent: Monday, January 22, 2018 2:11 PM
To: Claims <claims@sg.msig-asia.com>
Cc: Kong, Charmaine (VWG Singapore) <charmaine.kong@vw.com.sg>; Goh, Edmund (VWG Singapore) <edmund.goh@vw.com.sg>; Cheong, Pearlyn (VWG Singapore) <Pearlyn.cheong@vw.com.sg>; Wong, Meiy (VWG Singapore) <meiy.wong@vw.com.sg>
Subject: OD CLAIM SKP1124E DOA: 19/01/2018

Dear Claim


Please arrange survey at 17 TUAS AVE 9

Best Regards

Germaine Ong
Insurance Service Advisor
AfterSales

Volkswagen Centre Singapore
17 Tuas Ave 9
Singapore 639197

HP: +65 92361588
Germaine.ong@vw.com.sg
<http://www.vw.com.sg>



From: germaine.ong@vw.com.sg [mailto:germaine.ong@vw.com.sg]
Sent: Monday, 22 January, 2018 2:08 PM

To: Ong, Germaine (VWG Singapore)
Subject: Scan von MyMFP

Scan from MyMFP

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

Woon Choo Kwok

From: Koh Lay Hoon
Sent: Monday, January 22, 2018 2:21 PM
To: Woon Choo Kwok
Subject: FW: OD CLAIM SKP1124E DOA: 19/01/2018
Attachments: MyDocument_2018_01_22_02_07_18.pdf

From: Ong, Germaine (VWG Singapore) [mailto:Germaine.ong@vw.com.sg]
Sent: Monday, January 22, 2018 2:11 PM
To: Claims <claims@sg.msig-asia.com>
Cc: Kong, Charmaine (VWG Singapore) <charmaine.kong@vw.com.sg>; Goh, Edmund (VWG Singapore) <edmund.goh@vw.com.sg>; Cheong, Pearlyn (VWG Singapore) <Pearlyn.cheong@vw.com.sg>; Wong, Meiy (VWG Singapore) <meiy.wong@vw.com.sg>
Subject: OD CLAIM SKP1124E DOA: 19/01/2018

Dear Claim


Please arrange survey at 17 TUAS AVE 9

Best Regards

Germaine Ong
Insurance Service Advisor
AfterSales

Volkswagen Centre Singapore
17 Tuas Ave 9
Singapore 639197

HP: +65 92361588
Germaine.ong@vw.com.sg
<http://www.vw.com.sg>



From: germaine.ong@vw.com.sg [mailto:germaine.ong@vw.com.sg]
Sent: Monday, 22 January, 2018 2:08 PM

To: Ong, Germaine (VWG Singapore)
Subject: Scan von MyMFP

Scan from MyMFP

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18001351/T1rd3

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 23-01-2018



Code : MSG

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SKP 1124E
Policy No.	S27936551SMF	Coverage (\$)	0.00
Claim No.	546931	Excess (\$)	3,000.00
Assign From	MERIMEN (KWOK CHOON CHOO)	Assign Date	23/01/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Engine No.	HIDDEN	Accident Date	19/01/2018	Inspection Date	22/01/2018
Survey held at	VOLKSWAGEN GROUP SINGAPORE PTE LTD NO 17 TUAS AVE 9 SINGAPORE 639197				

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Kwok Woon Choo

Date: 24 Jan 2018

Preliminary Advice

Vehicle No	: SKP1124E	Accident Date	: 19/01/2018
Make	: VOLKSWAGEN JETTA	Policy No.	: S27936551SMF
Assignment Date	: 22/01/2018	Excess	: S\$3,000.00
Date of Inspection	: 23/01/2018	Est. Duration of Repair	: 10.00
Inspection At	: VOLKSWAGEN CENTRE SINGAPORE - TUAS (HQ) 17 TUAS AVE 9 SINGAPORE 639197		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	44,565.67
Revised Amount	:S\$	28,908.72
Check Items (Estimated)	:S\$	6,401.95
Total	:S\$	35,310.67

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	67,000.00
COE / PARF Rebate	:S\$	48,856.00
Salvage Value	:S\$	
Margin for Repair	:S\$	18,144.00

Remarks

(X) Kindly advice on offer repair cost to repairer. Please note the margin repair cost is \$18,144.00.

() The above survey was conducted on a 'without prejudice' basis.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Kwok Woon Choo

Date: 30 Jan 2018

Preliminary Advice

Vehicle No	: SKP1124E	Accident Date	: 19/01/2018
Make	: VOLKSWAGEN JETTA	Policy No.	: S27936551SMF
Assignment Date	: 22/01/2018	Excess	: S\$3,000.00
Date of Inspection	: 23/01/2018	Est. Duration of Repair	: 10.00
Inspection At	: VOLKSWAGEN CENTRE SINGAPORE - TUAS (HQ) 17 TUAS AVE 9 SINGAPORE 639197		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	46,715.67	(Include Supplementary \$2,150.00)
Revised Amount	:S\$	31,058.72	
Check Items (Estimated)	:S\$	6,401.95	
Total	:S\$	37,460.67	
Lump Sum Repair	:S\$	16,000.00	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	67,000.00
COE / PARF Rebate	:S\$	48,856.00
Salvage Value	:S\$	
Margin for Repair	:S\$	18,144.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/01/2018 11:27
Date Of Accident	19/01/2018 08:00
Exact Location Of Accident	WOODLANDS AVE 2
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKP1124E
Insured/Policyholder	
Name Of Registered Owner	WANG MAOLONG
NRIC No	S2626092B
Email Address	ML_W@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-91126175
Alternative Phone No	OFFICE-91126175
Vehicle Particulars	
Manufacturer	VOLKSWAGEN
Model	JETTA A6 1.4 TSI DSG 90KW TL
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	S 27936551 SMF
Cover Note Number	

Driver

Name of Driver	WANG MAOLONG
NRIC No	S2626092B
Date Of Birth	07/11/1959
Occupation	INDOOR
Date Of Driving Pass	15/07/2014
Driving Experience	3 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91126175
Fax Number	
Contact Number	OFFICE-91126175
Email Address	ML_W@HOTMAIL.COM

Address BLK212B PUNGGOL WALK #07-713

Postcode 822212

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General information of the Accident

Type Of Accident COLLISION - CROSS JUNCTION

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name ANG MO KIO NORTH NEIGHBOURHOOD POLICE CENTRE

Police Station Address ROAD: 51 ANG MO KIO AVE 9 , POSTCODE: 569784 , COUNTRY: SINGAPORE

Police Station Contact TEL NO: 1800-4849999 - FAX NO: 62181399

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SGH9552P

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver CHENG TOON NGEE

NRIC/Passport Number S7022234E

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving straight on Woodlands
 road, when the green light.
 Car SGH 9552P
 was right in front of me, when there
 was green light.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

\$KPH24E

AMH

S 27936551 SMF

NCD : 30%

EXCESS : \$3000

CONTACT
NUMBER : 91126175

EMAIL : m1_w@hotmail.com

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S2626092B



Name

WANG MAOLONG

王茂龙

Race

CHINESE

Date of birth

07-11-1959

Country of birth

CHINA

Sex

M

S2626092B

REPUBLIC OF SINGAPORE DRIVING LICENCE



WANG MAOLONG

Issue Date 07 Nov 1959

Valid Date 15 Jul 2014



002125988A



4441723

NRIC No. S2626092B



Date of issue

05-08-2008

APT BLK 212B PHONGON WALK #07-213

SINGAPORE 436175

Date: 11/05/2014

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3A Motor cars without clutch pedals (Auto) <= 2000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles without clutch pedals <= 2500kg

EFFECTIVE DATE
15 Jul 2014



Licence No. S2626092B

Addendum Sheet Pg. 1



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00 Singapore 048580
Tel (65) 6224 0010 Fax (65) 6224 0030
Operating Hours : Monday to Friday, 09:00 – 17:00
UEN: S665500206 / GST Reg. No.: M400017735

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MVGSI18009455 Vehicle Registration No: SKP1124E
Name (as shown in NRIC) : WAN MAO LON NRIC/FIN/Passport No : S2626092B
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
Address : BLK 212B PUNGGOL WALK #07-713 Singapore (822212)
Contact (Tel) : 91126175 Mobile No. : 91126175
Email Address : ML_W@hotmail.com
Date of Accident : 19/01/18 Time of Accident : _____
Place of Accident : WOODLANDS AVIS 2
Insurance Company: MJLG

(B) ADDITIONAL INFORMATION / AMENDMENTS:


I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

made correction for sketch plan.

Policyholder / Driver's Signature
Date: _____

Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____
Date: _____

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

At 2:00 am, SGP 1124E driving straight on Woodlands Ave 2, During the Green light. Car SGT 9552P turned right from Ave 2 to Ave 9, when there was ^{not} a green arrow.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Addendum Sheet Pg. 1



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00 Singapore 048580
Tel (65) 6224 0010 Fax (65) 6224 0030
Operating Hours: Monday to Friday, 09:00 – 17:00
UEN: S66550020G / GST Reg. No.: M400017735

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS

Original Report No. MVG8/8009455 ✓ Vehicle Registration No: SKP1124E
Name (as shown in NRIC): WANG MAOLONG NRIC/FIN/Passport No.: S2626092B
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
Address: 13LK 11213, #07-713, Punggol Walk Singapore (P2212)
Contact (Tel): _____ Mobile No.: 91126175
Email Address: ma-w@hotmail.com
Date of Accident: 19 Jan 2018 Time of Accident: 8:00am
Place of Accident: Junction of Woodlands Ave 2 and Ave 5.
Insurance Company: MSIG

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

During the conversation between the police officer and
the driver (SGH9552P), I heard that the driver
mentioned he turned right on normal Green-Light
(No right-turn green light). I was driving
straight on normal Green Light (Pis refer to Traffic Police Report
No: T/20180122/2040).

Policyholder / Driver's Signature

Date: 22 Jan '2018

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Date:

I will revert from Third Party claim to OD/recovery.



**SINGAPORE
POLICE FORCE**



T/20180122/2040

Police Station Of Origin:
Ang Mo Kio North N.P.C
51 Ang Mo Kio Avenue 9 SINGAPORE
569784
Tel No. 1800-4849999

1 of 3

Report No. T/20180122/2040

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 22/01/2018 11:16		Vide Report No.:	Station Diary No.: 29
Informant's Particulars			
Name of Informant: WANG MAOLONG		Address: APT BLK 212B PUNGGOL WALK #07-713 SINGAPORE 822212	
ID Type / ID No.: NRIC NO / S2626092B		Contact No.: Home/Office Mobile: 91126175	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 58	Date of Birth: 07/11/1959	Type of Informant: Driver
Race: Chinese		Language:	Institution / School Name:
Occupation: Analyst		Driving Licence Information: Class: 3A Date of Expiry:	

General Information of the Accident

Type of Accident: Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 19/01/2018 08:00	Type of Location: T-Junction
Location: Junction of Road 1 and Road 2 WOODLANDS AVENUE 2 WOODLANDS AVENUE 5			
Weather: Clear	Road Surface: Dry	Road Speed Limit:	
Traffic Flow:	Traffic Control:	Traffic Volume:	
Type of Collision: Between Moving Vehicles - Head To Side			Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passengers
SGH9552P	Car				Slightly Damaged	2
SKP1124E	Car				Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	Use of Pedestrian Crossing: NA
No. of Pedestrians Injured: NIL	



**SINGAPORE
POLICE FORCE**



T/20180122/2040

Police Station Of Origin:
Ang Mo Kio North N.P.C
51 Ang Mo Kio Avenue 9 SINGAPORE
569784
Tel No. 1800-4849999

2 of 3

Report No. T/20180122/2040

CONTINUATION OF REPORT

Name	Cheng Toon Ngee	ID No.	S7022234E
Related Vehicle	SGH9552P (Car)	Contact No.	81821056
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	WANG MAOLONG	ID No.	S2626092B
Related Vehicle	SKP1124E (Car)	Contact No.	91126175
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3A Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 19/01/2018 at about 0800hrs, I was driving my car SKP1124E travelling along Woodlands Avenue 2 towards Causeway Point. When I reach the junction of Woodlands Avenue 2 and Avenue 5, the traffic light is green, thus I proceeded to go straight. Suddenly, another car SGH9552P made a right turn from the opposite direction into Woodlands Avenue 9. I was unable to stop in time and collided into his vehicle. No one was injured. My vehicle suffered some damaged at the front portion. There were about 4 traffic police officers at scene. I am lodging this report for insurance claim purposes.



SINGAPORE
POLICE FORCE

Police Station Of Origin:
Ang Mo Kio North N.P.C
51 Ang Mo Kio Avenue 9 SINGAPORE
569784
Tel No: 1800-4849999



T/20180122/2040

3 of 3

Report No. T/20180122/2040

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

Sgt 2 JAYZ TAN ZHANG JIE

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
22/01/2018 11:16

Officer In Charge Of Case:
TP (GIT)

Sgt 3 RASHIDAH BINTE AZMAN
Contact No: 65476216

Classification Of Case:

Authentication Stamp
NP168



Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 6092B

Vehicle Details

Vehicle No.: SKP1124E

Vehicle to be Exported: No

Intended De-registration Date: 24 Jan 2018

Vehicle Make: VOLKSWAGEN

Vehicle Model: JETTA 1.4 TSI AT 1622G5

Primary Colour: Blue

Manufacturing Year: 2014

Engine No.: CAXE60102

Chassis No.: WVVZZZ16ZEM050976

Maximum Power Output: 90.0 kW (120 bhp)

Open Market Value: \$18,692.00

Original Registration Date: 14 Aug 2014

First Registration Date: 14 Aug 2014

Transfer Count: 0

Actual ARF Paid: \$8,692.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 13 Aug 2024



PARF Rebate Amount: \$6,519.00

Intended COE Rebate Details

COE Expiry Date: 13 Aug 2024

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

 .QP Paid:	\$64,600.00
 COE Rebate Amount:	\$42,337.00
Total Rebate Amount:	\$48,856.00

The information contained herein is correct as at 24 Jan 2018

OK



SGCARMART.COM

New Cars

Used Cars

Sell My Car

Directory

Products

Articles

Cheap Car Insurance Renewal

Is your car insurance expiring soon?

Receive best quotations from multiple insurers in as little as 2 hours.

VOLKSWAGEN JETTA 1.4

Price Range

Depreciation

2014

Vehicle Type

Home » Used Cars » In-Carz Credit Pte Ltd » Volkswagen Jetta 1.4A TSI

Tools & Tips

Car Buying


Car Selling

Car Aftermarket

Car Ownership

On The Move

Lifestyle



Volkswagen Jetta 1.4A TSI

Overview

Financial

Accessories

Similar

Research

Photos

Map

IN-CARZ CREDIT PTE LTD

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Car Details

Price	\$69,800	
Depreciation	\$9,940 /yr View models with similar depreciation	?
Reg Date	25-Aug-2014 (6yrs 7mths COE left)	
Manufactured	2014	?
Mileage	38,000 km (11.1k /yr)	
Transmission	Auto	
Engine Cap	1,390 cc	
Road Tax	\$620 /yr	?
Power	90.0 kW (120 bhp) View specs of the Volkswagen Jetta (2011-2017)	
Curb Weight	1,417 kg	?
Features	Powerful And Fuel Saving 1.4L TSI Engine (120 BHP), Smooth 7 Speed DSG Transmission, 6 x SRS Airbags.	
Accessories	Original Premium Leather Upholstery Seats, Factory Fitted CD/Audio System, Dual Zone Aircon System With Rear Aircon, Solar Films.	
Description	Up To 90% Loan Or 20% Down Payment Available. Well Kept By 1 Lady Owner, Special Edition Unit. Agent Maintain Unit/Warranty. Low Mileage Done At 38K Km. Original Paintwork Since Day 1. Almost New Condition. View To Believe. Call Now For More Details.	
COE	\$64,600	?



Seller Informat

Company

Compare



Service Order Confirmation

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SERVICE ORDER NO.: 18IP0190

CUSTOMER NO.: CV026570

CUSTOMER NAME: WANG MAOLONG

TELEPHONE NO.:

ADDRESS: 212B PUNGGOL WALK #07-713

Singapore

VEH No.: SKP1124E

Order Date: 19/01/18

Reg Date: 14/08/14

KM: 56,443

VIN NO.: VVVZZZ16ZEM050976

ENGINE NO:

SA: Goh Edmund

MODEL: JETTA A6 1.4 TSI DSG 90KW TL MODEL NO.: 1622G5

Taufik 9745747
* Remark: Not Authorized
Ex \$3000

Resurvey before paint

10 days.

23/1/18 E 1445

[Signature]
23/1/18

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
Labor						
1	B&P TOWING	156	TU	1.25		✓ 195
2	B&P SUNDRIES	48	TU	1.25		✓ 60.48
3	B&P MECH	1	TU	280		✓ 280 260 160
4	B&P DIAG	1	TU	480		✓ 480 360 288
5	B&P WHEEL ALIGNMENT	1	TU	360		? 360 240 ✓
6	B&P MECH	2	TU	840		? 2,520 950 760 x
7	B&P AIRCON	1	TU	420		✓ 420 190
8	EXT00037	1	UNIT	0		0
9	B&P ALEX LABOUR	1	UNIT	840		✓ 840 550 470
10	B&P ALEX LABOUR	5	UNIT	840		4200 6,720 2375 1900
11	B&P ALEX PAINT	5	UNIT	800		4000 5,600 2750 2200
12	B&P NUMBER PLATE	1	ST	80		bt ✓ 80 64
Item						
13	5C8857002D 6T6	1	PCS	2,306.63		de ✓ 2,306.63 x 100
14	1KM880201E 81U	1	PCS	2,595.17		act ✓ 2,595.17 1297.59
15	5C6880204H	1	PCS	2,802.24		act ✓ 2,802.24 1401.12
16	5K0953569AL	1	PCS	734.69		act ✓ 734.69 367.34
17	5C6857706B RAA	1	PCS	810.56		act ✓ 810.56 405.28
18	5C6857705A RAA	1	PCS	810.56		act ✓ 810.56 405.28
19	3C8857819	2	PCS	89.78		act ✓ 179.56 89.78
20	5C0959655C 02A	1	PCS	1,458.41		act ✓ 1,458.41 x 100
21	5C6845011 NVB	1	PCS	824.12		act ✓ 824.12 412.06
22	999999ERP	1	PCS	14.03		act ✓ 14.03 7.02
23	D 004660M2	1	PCS	183.87		act ✓ 183.87 91.94
24	D 00940104	1	PCS	113.84		act ✓ 113.84 56.92
25	D 00920002	1	PCS	32.19		act ✓ 32.19 16.10
26	D 181802M1	1	PCS	29.46		act ✓ 29.46 14.73
27	D 00950025	2	PCS	11.19		act ✓ 22.38 11.19
28	5C6823031E	1	PCS	1,020.84		bt ✓ 1,020.84 x 100

Service Order Confirmation

SERVICE ORDER NO: 18IP0190

CUSTOMER NO.: CV026570

CUSTOMER NAME: WANG MAOLONG

TELEPHONE NO.:

ADDRESS: 212B PUNGGOL WALK #07-713

Singapore

VEH No.: SKP1124E

Order Date: 19/01/18

Reg Date: 14/08/14

KM: 56,443

VIN NO.: WWWZZZ16ZEM050976

ENGINE NO:

SA: Goh Edmund

MODEL: JETTA A6 1.4 TSI DSG 90KW TL MODEL NO.: 1622G5

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
29	5C6823301 BONNET HINGE LHS	1	PCS	97.29	bt	97.29 x nn
30	5C6823302A BONNET HINGE RHS	1	PCS	135.41	bt	135.41 x nn
31	1K8823186D 9B9 BONNET LATCH	1	PCS	97.52	nn	97.52
32	5C8823509D BONNET LOCK	1	PCS	158.60	nn	158.60
33	5C6807217D GRU FRONT BUMPER	1	PCS	1,343.15	de	1,343.15 070.58
34	5C6807287 9B9 FRONT NUMBER PLATE HOLDER	1	PCS	107.49	mis	107.49 53.75
35	N 0385491 RIVET	6	PCS	0.80	rec	4.80 2.40
36	5C6807109C FRONT REINFORCEMENT	1	PCS	573.69	bt	573.69 Xnn
37	5C6807248A BUMPER FOAM LHS	1	PCS	104.61	de	104.61 52.31
38	5C6807248B BUMPER FOAM RHS	1	PCS	104.51	de	104.51 52.26
39	5C6805706D BUMPER CENTER BRACKET	1	PCS	107.79	cue	107.79 53.90
40	5C6807183 FRT LHS BUMPER SIDE BRACKET	1	PCS	33.50	rec	33.50 16.75
41	5C6807184 FRT RHS BUMPER SIDE BRACKET	1	PCS	33.50	rec	33.50 16.75
42	5C6805903 9B9 FRT LOWER SPOILER	1	PCS	511.01	de	511.01 Rnn
43	D 172090A2 1PK ADHES.	1	PCS	110.52	rec	110.52 nn
44	5C5071609 GRU FRONT SPOILER (BODY KIT)	1	PCS	1,460.73	de	1,460.73 730.37
45	5C6853651 QWA RADIATOR GRILLE	1	PCS	546.89	cue	546.89 273.45
46	5C6853677 9B9 CENTRE GRILLE	1	PCS	203.46	de	203.46 101.73
47	5C6853665 9B9 FRT LHS FOG LAMP GRILLE	1	PCS	89.00	mis	89.00 44.50
48	5C8941005 FRT LHS HEADLIGHT	1	PCS	766.68	cue	766.68 383.34
49	5C8941006 FRT RHS HEADLIGHT	1	PCS	1,061.66	aut	1,061.66 530.83
50	5C6805588D LOCK CARRIER	1	PCS	85.49	cue	85.49 } x
51	5C6805567 SUPPORT LOCK CARRIER	1	PCS	85.49	bt	85.49 } nn
52	1KD805965 9B9 SLIDE VAVLE	1	PCS	15.48	de	15.48
53	1KD805962 9B9 AIR DUCT INTAKE	1	PCS	19.53	de	19.53 9.77
54	1K0805971C 9B9 AIR CHANNEL	1	PCS	33.74	de	33.74 16.87
55	5C6805931 LHS HEADLIGHT TOP PANEL	1	PCS	37.79	bt	37.79
56	5C0820411F CONDENSER	1	PCS	844.19	nn	844.19
57	1K0121253AA RADIATOR INNER	1	PCS	909.47	nn	909.47
58	1K0121251BN RADIATOR OUTER	1	PCS	909.47	nn	909.47

Service Order Confirmation

SERVICE ORDER NO: 18IP0190

CUSTOMER NO.: CV026570

CUSTOMER NAME: WANG MAOLONG

TELEPHONE NO.:

ADDRESS: 212B PUNGGOL WALK #07-713
Singapore

VEH No.: SKP1124E

Order Date: 19/01/18

Reg Date: 14/08/14 KM: 56,443

VIN NO.: WWWZZZ16ZEM050976 ENGINE NO:

SA: Goh Edmund

MODEL: JETTA A6 1.4 TSI DSG 90KW TL MODEL NO.: 1622G5

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
59	5C6121283 AIR GUIDE (LHS)	1	PCS	33.27		de ✓ 33.27 16 64
60	5C6121284 AIR GUIDE (RHS)	1	PCS	33.27		de ✓ 33.27 16 64
61	1KM959455G ELECTR FAN (BIG)	1	PCS	657.99		7 ✓ 657.99 42 14
62	1KM959455E ELECTR FAN (SMALL)	1	PCS	865.92		8 ✓ 865.92 42 14
63	5C6821105A FRT FENDER LHS	1	PCS	691.67		bt ✓ 691.67 42 14
64	5C6821135 FENDER BRACKET	1	PCS	45.27		bt ✓ 45.27 42 14
65	5C6805911 FENDER WHEEL LINING	1	PCS	152.27		de ✓ 152.27 76 14

TOTAL	44,565.67
GST AMOUNT	3,119.60
TOTAL AMOUNT	47,685.27

On Behalf Of "COMPANY"

Certified Goods/Service received:

Authorized Signature

Customer

3671962

NOTE: THIS IS NOT AN OFFICIAL RECEIPT

Supplementary or Omitted List



VEHICLE NUMBER: **SKP1124E**
MODEL **JETTA**

CLAIMS DETAILS

	LABOUR DESCRIPTION	QUANTITY	UNIT PRICE	AMOUNT
1	R&R D/BOARD	1.5	475	570 \$712.50 all ✓
2	R&R SEAT BELT & AIRBAG CONTROL UNIT	0.5	475	190 \$237.50 all ✓
3	VEHICLE ON BENCH- CELETTE (NETT)	1	1200	960 \$1,200.00 ✓
Total				\$2,150.00

No.	Item No.	Description	Qty	Unit price	DISCOUNT	Amount
1						
2						
3						
4						
5						
6						
7						
8						
9						
10						
11						
12						
13						
14						
15						
16						
17						
18						
19						
20						
TOTAL:						\$0.00

Total Labour & Parts

\$2,150.00

Survey By

Service Order Confirmation

SERVICE ORDER NO.: 18IP0190

CUSTOMER NO.: CV026570

CUSTOMER NAME: WANG MAOLONG

TELEPHONE NO.:

ADDRESS: 212B PUNGGOL WALK #07-713

Singapore

VEH No.: SKP1124E

Order Date: 19/01/18

Reg Date: 14/08/14

KM: 61,451

SA: Goh Edmund

VIN NO.: WVVZZZ16ZEM050976

ENGINE NO.:

MODEL: JETTA A6 1.4 TSI DSG 90KW TL **MODEL NO.:** 1622G5

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
Labor						
1	B&P TOWING	156	TU	1.25		195
2	B&P SUNDRIES	48	TU	1.25	20	48
3	B&P MECH	1	TU	200	20	160
4	B&P DIAG	1	TU	360	20	288
5	B&P WHEEL ALIGNMENT	1	TU	300	20	240
6	B&P MECH	2	TU	475	20	760
7	B&P AIRCON	1	TU	237.5	20	190
8	B&P MECH	1.5	TU	475	20	570
9	B&P MECH	0.5	TU	475	20	190
10	B&P INSURANCE EXCESS	1	TU	-3,000		-3,000
11	EXT00037	1	UNIT	0		0
12	EXT00037	1	UNIT	0		0
13	B&P ALEX LABOUR	1	UNIT	550	20	440
14	B&P ALEX LABOUR	5	UNIT	475	20	1,900
15	B&P ALEX PAINT	5.5	UNIT	500	20	2,200
16	B&P NUMBER PLATE	1	ST	80	20	64
17	B&P CELETTE	1	G	1,200	20	960
Item						
18	1KM880201E 81U	1	PCS	2,595.17	50	1,297.59
19	5C6880204H	1	PCS	2,802.24	50	1,401.12
20	5K0953569AL	1	PCS	734.89	50	367.35
21	5C6857706B RAA	1	PCS	810.56	50	405.28
22	5C6857705A RAA	1	PCS	810.56	50	405.28
23	3C8857819	2	PCS	89.78	50	89.78
24	5C6845011 NVB	1	PCS	824.12	50	412.06
25	999999ERP	1	PCS	14.03	50	7.02
26	D 004660M2	1	PCS	183.87	50	91.94
27	D 00940104	1	PCS	113.84	50	56.92
28	D 00920002	1	PCS	32.19	50	16.10

Service Order Confirmation

SERVICE ORDER NO: 18IP0190

CUSTOMER NO.: CV026570

CUSTOMER NAME: WANG MAOLONG

TELEPHONE NO.:

ADDRESS: 212B PUNGGOL WALK #07-713

Singapore

VEH No.: SKP1124E

Order Date: 19/01/18

Reg Date: 14/08/14

KM: 61,451

SA: Goh Edmund

VIN NO.: WYVZZZ16ZEM050976

ENGINE NO:

MODEL: JETTA A6 1.4 TSI DSG 90KW TL MODEL NO.: 1622G5

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
29	D 181802M1 ACTIVATOR	1	PCS	29.46	50	14.73
30	D 00950025 APPLICATOR	2	PCS	11.19	50	11.19
31	5C6807217D GRU FRONT BUMPER	1	PCS	1,343.15	50	671.58
32	5C6807287 9B9 FRONT NUMBER PLATE HOLDER	1	PCS	107.49	50	53.75
33	N 0385491 RIVET	6	PCS	0.80	50	2.40
34	5C6807248A BUMPER FOAM LHS	1	PCS	104.81	50	52.31
35	5C6807248B BUMPER FOAM RHS	1	PCS	104.51	50	52.26
36	5C6805706D BUMPER CENTER BRACKET	1	PCS	107.79	50	53.90
37	5C6807183 FRT LHS BUMPER SIDE BRACKET	1	PCS	33.50	50	16.75
38	5C6807184 FRT RHS BUMPER SIDE BRACKET	1	PCS	33.50	50	16.75
39	5C5071609 GRU FRONT SPOILER (BODY KIT)	1	PCS	1,480.73	50	730.37
40	5C6853651 QWA RADIATOR GRILLE	1	PCS	546.89	50	273.45
41	5C6853677 9B9 CENTRE GRILLE	1	PCS	203.46	50	101.73
42	5C6853665 9B9 FRT LHS FOG LAMP GRILLE	1	PCS	89.00	50	44.50
43	5C8941005 FRT LHS HEADLIGHT	1	PCS	766.68	50	383.34
44	5C8941006 FRT RHS HEADLIGHT	1	PCS	1,061.66	50	530.83
45	1KD805962 9B9 AIR DUCT INTAKE	1	PCS	19.53	50	9.77
46	1K0805971C 9B9 AIR CHANNEL	1	PCS	33.74	50	16.87
47	5C6121283 AIR GUIDE (LHS)	1	PCS	33.27	50	16.64
48	5C6121284 AIR GUIDE (RHS)	1	PCS	33.27	50	16.64
49	5C6805911 FENDER WHEEL LINING	1	PCS	152.27	50	76.14

Remarks : OD CLAIM

DOA: 19/01/2018

SURVEY BY: TAUFIK

LIMIT REPAIR \$16K

INSURANCE EXCESS \$3000

Service Order Confirmation

SERVICE ORDER NO: 18IP0190

CUSTOMER NO.: CV028570

CUSTOMER NAME: WANG MAOLONG

TELEPHONE NO.:

ADDRESS: 212B PUNGGOL WALK #07-713

Singapore

VEH No.: SKP1124E

Order Date: 19/01/18

Reg Date: 14/08/14

KM: 81,451

SA: Goh Edmund

VIN NO.: WVVZZZ16ZEM050976

ENGINE NO:

MODEL: JETTA A6 1.4 TSI DSG 90KW TL MODEL NO.: 1622G5

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
-----	-------------	-----	-----	------------	--------	--------

TOTAL	12,901.26
GST AMOUNT	903.09
TOTAL AMOUNT	13,804.35

On Behalf Of "COMPANY"

Certified Goods/Service received:

Authorized Signature

Customer

NOTE: THIS IS NOT AN OFFICIAL RECEIPT

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Jan 2018		22 Jan 2018 16:01 Edit Adj Rpt	S\$15,901.34 Edit Estimates	S\$15,901.34 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	-----------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	WANG MAOLONG, ID: S2626092B, Tel: +6591126175, Email: ml_w@hotmail.com		
Vehicle Reg. No.:	SKP1124E	Date of Loss:	19/01/2018 08:00 - :59
Claim Type:	OD / 546931	Policy/Cover Note No.:	S27936551SMF (Comprehensive) Coverage: 14/08/2017 - 13/08/2018
		Excess:	S\$3,000.00
Repairer:	Volkswagen Centre Singapore - Tuas (HQ) 17 TUAS AVE 9, 639197 Tuas - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Kwok Woon Choo - 6643 1330]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 21/02/2018]		
Driver/Custodian:	WANG MAOLONG (58 / Male), NRIC: S2626092B, Tel: +6591126175		
Adj Asg. Remarks:	TO REVERT - UNDER VW SCHEME		

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
<ul style="list-style-type: none"> MSIG_SG (01/02/2018): Alert - Adj Mandate Approved (S\$16000.00) - SKP1124E - Claim Handler: Kwok Woon ... MSIG_SG (25/01/2018): Alert - Adj Mandate Approved (S\$16000.00) - SKP1124E - Claim Handler: Kwok Woon ... 		

ALL ASSOCIATED TASKS		View All	Search Tasks	Create New Task	Complete				
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKP1124E (546931)
OD
Jan 19 2018 8:00AM
[WANG MAOLONG]
Volkswagen Centre Singapore - Tuas

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Volkswagen Centre Singapore (HQ)		Thumbnail	Print
1	19/01/18 12:44	Accident Statement		Load HTM	
2	19/01/18 13:09	Addendum Sheet		Load TIF	
3	19/01/18 13:09	Accident Statement Addm. #1		Load HTM	
4	22/01/18 13:00	Addendum Sheet		Load TIF	
5	22/01/18 13:00	Accident Statement Addm. #2		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	24/01/18 18:26	Adjuster Immediate Advice		Load HTM	
2	30/01/18 17:48	Adjuster Immediate Advice		Load HTM	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Volkswagen Centre Singapore (HQ)		Thumbnail	Print
1	19/01/18 12:32	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
2	19/01/18 12:32	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
3	19/01/18 12:32	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
4	19/01/18 12:32	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
5	19/01/18 12:32	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
6	19/01/18 12:32	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
7	19/01/18 12:32	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
8	19/01/18 12:32	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
9	19/01/18 12:34	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
10	19/01/18 12:34	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
11	19/01/18 12:34	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
12	19/01/18 12:34	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
13	19/01/18 12:34	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
14	19/01/18 12:34	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	24/01/18 18:48	General View		Load JPG	<input checked="" type="checkbox"/>
2	24/01/18 18:48	General View		Load JPG	<input checked="" type="checkbox"/>
3	24/01/18 18:48	General View		Load JPG	<input checked="" type="checkbox"/>
4	24/01/18 18:48	General View		Load JPG	<input checked="" type="checkbox"/>
5	24/01/18 18:48	General View		Load JPG	<input checked="" type="checkbox"/>
6	24/01/18 18:48	General View		Load JPG	<input checked="" type="checkbox"/>
7	24/01/18 18:48	General View		Load JPG	<input checked="" type="checkbox"/>
8	24/01/18 18:48	General View		Load JPG	<input checked="" type="checkbox"/>

9	24/01/18 18:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
10	24/01/18 18:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
11	24/01/18 18:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
12	24/01/18 18:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
13	24/01/18 18:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
14	24/01/18 18:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
15	24/01/18 18:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
16	24/01/18 18:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
17	24/01/18 18:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
18	24/01/18 18:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
19	24/01/18 18:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
20	24/01/18 18:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
21	24/01/18 18:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
22	24/01/18 18:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
23	24/01/18 18:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
24	24/01/18 18:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
25	24/01/18 18:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
26	24/01/18 18:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
27	24/01/18 18:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
28	24/01/18 18:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
29	24/01/18 18:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
30	24/01/18 18:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
31	24/01/18 18:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
32	24/01/18 18:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
33	24/01/18 18:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
34	24/01/18 18:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
35	24/01/18 18:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
36	24/01/18 18:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
37	24/01/18 18:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
38	24/01/18 18:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
39	24/01/18 18:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
40	24/01/18 18:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
41	24/01/18 18:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
42	24/01/18 18:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
43	24/01/18 18:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
44	24/01/18 18:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
45	24/01/18 18:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
46	24/01/18 18:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
47	24/01/18 18:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
48	24/01/18 18:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
49	24/01/18 18:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
50	24/01/18 18:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
51	24/01/18 18:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
52	24/01/18 18:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
53	24/01/18 18:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
54	24/01/18 18:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
55	24/01/18 18:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
56	24/01/18 18:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
57	24/01/18 18:48	General View	1	Load JPG	<input checked="" type="checkbox"/>
58	24/01/18 18:48	General View	1	Load JPG	<input checked="" type="checkbox"/>

59	24/01/18 18:48	General View	1	Load JPG	✓
60	24/01/18 18:48	General View	1	Load JPG	✓
61	24/01/18 18:48	General View	1	Load JPG	✓
62	24/01/18 18:48	General View	1	Load JPG	✓
63	24/01/18 18:48	General View	1	Load JPG	✓
64	24/01/18 18:48	General View	1	Load JPG	✓
65	24/01/18 18:48	General View	1	Load JPG	✓
66	24/01/18 18:48	General View	1	Load JPG	✓
67	24/01/18 18:48	General View	1	Load JPG	✓
68	24/01/18 18:48	General View	1	Load JPG	✓
69	24/01/18 18:48	General View	1	Load JPG	✓
70	24/01/18 18:48	General View	1	Load JPG	✓
71	24/01/18 18:48	General View	1	Load JPG	✓
72	24/01/18 18:48	General View	1	Load JPG	✓
73	24/01/18 18:48	General View	1	Load JPG	✓
74	24/01/18 18:48	General View	1	Load JPG	✓
75	24/01/18 18:48	General View	1	Load JPG	✓
76	24/01/18 18:48	General View	1	Load JPG	✓
77	24/01/18 18:48	General View	1	Load JPG	✓
78	24/01/18 18:49	General View	1	Load JPG	✓
79	24/01/18 18:49	General View	1	Load JPG	✓
80	24/01/18 18:49	General View	1	Load JPG	✓
81	24/01/18 18:49	General View	1	Load JPG	✓
82	24/01/18 18:49	General View	1	Load JPG	✓
83	24/01/18 18:49	General View	1	Load JPG	✓
84	24/01/18 18:49	General View	1	Load JPG	✓
85	24/01/18 18:49	General View	1	Load JPG	✓
86	24/01/18 18:49	General View	1	Load JPG	✓
87	24/01/18 18:49	General View	1	Load JPG	✓
88	24/01/18 18:49	General View	1	Load JPG	✓
89	01/02/18 17:53	Reinspection Photo	1	Load JPG	✓
90	01/02/18 17:53	Reinspection Photo	1	Load JPG	✓
91	01/02/18 17:53	Reinspection Photo	1	Load JPG	✓
92	01/02/18 17:53	Reinspection Photo	1	Load JPG	✓
93	01/02/18 17:53	Reinspection Photo	1	Load JPG	✓
94	01/02/18 17:53	Reinspection Photo	1	Load JPG	✓
95	01/02/18 17:53	Reinspection Photo	1	Load JPG	✓
96	01/02/18 17:53	Reinspection Photo	1	Load JPG	✓
97	01/02/18 17:53	Reinspection Photo	1	Load JPG	✓
98	01/02/18 17:53	Reinspection Photo	1	Load JPG	✓
99	01/02/18 17:53	Reinspection Photo	1	Load JPG	✓
100	01/02/18 17:53	Reinspection Photo	1	Load JPG	✓
101	01/02/18 17:53	Reinspection Photo	1	Load JPG	✓
102	01/02/18 17:53	Reinspection Photo	1	Load JPG	✓
103	01/02/18 17:53	Reinspection Photo	1	Load JPG	✓
104	01/02/18 17:53	Reinspection Photo	1	Load JPG	✓
105	01/02/18 17:53	Reinspection Photo	1	Load JPG	✓
106	01/02/18 17:53	Reinspection Photo	1	Load JPG	✓
107	01/02/18 17:53	Reinspection Photo	1	Load JPG	✓
108	01/02/18 17:53	Reinspection Photo	1	Load JPG	✓

109	01/02/18 17:53	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
110	01/02/18 17:53	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
111	01/02/18 17:53	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
112	01/02/18 17:53	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
113	01/02/18 17:53	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
114	01/02/18 17:53	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
115	01/02/18 17:53	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
116	01/02/18 17:53	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
117	01/02/18 17:53	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
118	01/02/18 17:53	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
119	01/02/18 17:53	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
120	01/02/18 17:53	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
121	01/02/18 17:53	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
122	01/02/18 17:53	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
123	01/02/18 17:53	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
Documentation					
			1 per page	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	22/01/18 15:25	E-MAIL FR VOLKSWAGEN TO ARRANGE OD SURVEY	1	Load PDF	
2	22/01/18 15:29	OD ESTIMATE + GIA REPORT + POLICE REPORT + INSD NRIC + DL	1	Load PDF	
3	22/01/18 15:44	TP REPORT SGH9552P	1	Load PDF	
No	Finalized On	Volkswagen Centre Singapore (HQ)		Thumbnail	Print
1	19/01/18 12:36	Sketch Plan [Linked Accident Report Documents]	1	Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	24/01/18 18:48	SKP 1124E ESTIMATE	1	Load PDF	
2	30/01/18 17:51	SKP 1124E SUPPLEMENTARY ESTIMATE	1	Load PDF	

Linked Accident Report Documents

			View	View in Browser	<input checked="" type="checkbox"/>
Assessment Reports			1 per page	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
No	Finalized On	Volkswagen Centre Singapore (HQ)		Thumbnail	Print
1	19/01/18 12:44	Accident Statement	1	Load HTM	
2	19/01/18 13:09	Addendum Sheet	1	Load TIF	
3	19/01/18 13:09	Accident Statement Addm. #1	1	Load HTM	
4	22/01/18 13:00	Addendum Sheet	1	Load TIF	
5	22/01/18 13:00	Accident Statement Addm. #2	1	Load HTM	
Photos/Images					
			3 per page	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
No	Finalized On	Volkswagen Centre Singapore (HQ)		Thumbnail	Print
1	19/01/18 12:32	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
2	19/01/18 12:32	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
3	19/01/18 12:32	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
4	19/01/18 12:32	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
5	19/01/18 12:32	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
6	19/01/18 12:32	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
7	19/01/18 12:32	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
8	19/01/18 12:32	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
9	19/01/18 12:34	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
10	19/01/18 12:34	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
11	19/01/18 12:34	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
12	19/01/18 12:34	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
13	19/01/18 12:34	Accident Photo	1	Load JPG	

					<input checked="" type="checkbox"/>
14	19/01/18 12:34	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation					
			1 per page		<input checked="" type="checkbox"/>
No	Finalized On	Volkswagen Centre Singapore (HQ)		Thumbnail	Print
1	19/01/18 12:36	Sketch Plan		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST			Reset	Save	Print
There are no document checklists configured.					

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
<div style="border: 1px solid black; height: 40px; width: 100%;"></div> <div style="text-align: right;"> </div>	
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG18001351/T1RD3E2

Date: 12/02/2018

REFERENCE

Insured/Claimant:	WANG MAOLONG	Policy No:	S27936551SMF	
Date of Loss:	19/01/2018	Nature of Claim:	OD	Claim No: 546931

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKP1124E	Engine No:	CAXE60102
Make & Model:	VOLKSWAGEN JETTA, 1.4 TSI (A)	Chassis No:	WVWZZZ16ZEM050976
Reg. Date:	14/08/2014 (Man. Year: 2014)	Odometer:	61451 km
Colour:	Blue		
Engine Capacity:	1390 cc		
Market Value/New Car Price:	S\$67,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	27,090.67	7,760.34	19,330.33	71.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	19,625.00	8,141.00	11,484.00	58.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	46,715.67	15,901.34	30,814.33	65.96
- Excess (\$\$)	3,000.00	3,000.00	0.00	0.00
(\$\$)	43,715.67	12,901.34	30,814.33	70.49
+ GST 7.00/7.00% (\$\$)	3,060.10	903.09	2,157.01	70.49
Nett Amount (\$\$)	46,775.77	13,804.43	32,971.34	70.49

INSPECTION

Date of Assignment: 22/01/2018

Date Inspected: 23/01/2018 Inspected At:

Volkswagen Centre Singapore - Tuas (HQ)
17 TUAS AVE 9
Singapore 639197

Estimated Period of Repair: 10.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 12 Feb 2018)
Parts: 143 VOLKSWAGEN JETTA 1.4 TSI (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKP1124E)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*NUMBER PLATE	Bent	80.00 FS	*64.00 FS
2	1		*DASHBOARD	Not Necessary	2,306.63 FS	*- FS
3	1		*AIRBAG (S/WHEEL)	Cut	2,595.17 FS	*1,297.59 FS
4	1		*AIRBAG (PASSENGER)	Cut	2,802.24 FS	*1,401.12 FS
5	1		*SEAT BELT RH	Cut	810.56 FS	*405.28 FS
6	1		*SEAT BELT LH	Cut	810.56 FS	*405.28 FS
7	2		*SEAT BELT ADJUSTER	Cut	179.56 FS	*89.78 FS
8	1		*AIRBAG CONTROL UNIT	Not Necessary	1,458.41 FS	*- FS
9	1		*FRONT WINDSCREEN	Cracked	824.12 FS	*412.06 FS
10	1		*ERP STICKER	Necessary	14.03 FS	*7.02 FS
11	1		*2K GLUE	Necessary	183.87 FS	*91.94 FS
12	1		*CLEANER	Necessary	113.84 FS	*56.92 FS
13	1		*PRIMER	Necessary	32.19 FS	*16.10 FS
14	1		*ACTIVATOR	Necessary	29.46 FS	*14.73 FS
15	1		*APPLICATOR (2 PCS)	Necessary	22.38 FS	*11.19 FS
16	1		*FRT BONNET	Not Necessary	1,020.84 FS	*- FS
17	1		*BONNET HINGE LHS	Not Necessary	97.29 FS	*- FS
18	1		*BONNET HINGE RHS	Not Necessary	135.41 FS	*- FS
19	1		*BONNET LATCH	Not Necessary	97.52 FS	*- FS
20	1		*BONNET LOCK	Not Necessary	158.60 FS	*- FS
21	1		*FRONT BUMPER	Deformed	1,343.15 FS	*671.58 FS
22	1		*FRONT NUMBER PLATE HOLDER	Missing	107.49 FS	*53.75 FS
23	6		*RIVET	Necessary	4.80 FS	*2.40 FS
24	1		*FRONT REINFORCEMENT	Not Necessary	573.69 FS	*- FS
25	1		*BUMPER FOAM LHS	Deformed	104.61 FS	*52.31 FS
26	1		*BUMPER FOAM RHS	Deformed	104.51 FS	*52.26 FS
27	1		*BUMPER CENTER BRACKET	Cracked	107.79 FS	*53.90 FS
28	1		*FRT LHS BUMPER SIDE BRACKET	Necessary	33.50 FS	*16.75 FS
29	1		*FRT RHS BUMPER SIDE BRACKET	Necessary	33.50 FS	*16.75 FS
30	1		*FRT LOWER SPOILER	Not Necessary	511.01 FS	*- FS
31	1		*1PK ADHES	Not Necessary	110.52 FS	*- FS
32	1		*FRONT SPOILER (BODY KIT)	Deformed	1,460.73 FS	*730.37 FS
33	1		*RADIATOR GRILLE	Cracked	546.89 FS	*273.45 FS
34	1		*CENTRE GRILLE	Deformed	203.46 FS	*101.73 FS
35	1		*FRT LHS FOG LAMP GRILLE	Missing	89.00 FS	*44.50 FS
36	1		*FRT LHS HEADLIGHT	Cracked	766.68 FS	*383.34 FS
37	1		*FRT RHS HEADLIGHT	Cut	1,061.66 FS	*530.83 FS
38	1		*LOCK CARRIER	Not Necessary	85.49 FS	*- FS
39	1		*SUPPORT LOCK CARRIER	Not Necessary	85.49 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*SLIDE VALVE	Not Necessary	15.48 FS	*- FS
41	1		*AIR DUCT INTAKE	Deformed	19.53 FS	*9.77 FS
42	1		*AIR CHANNEL	Deformed	33.74 FS	*16.87 FS
43	1		*LHS HEADLIGHT TOP PANEL	Not Necessary	37.79 FS	*- FS
44	1		*CONDENSER	Not Necessary	844.19 FS	*- FS
45	1		*RADIATOR INNER	Not Necessary	909.47 FS	*- FS
46	1		*RADIATOR OUTER	Not Necessary	909.47 FS	*- FS
47	1		*AIR GUIDE (LHS)	Deformed	33.27 FS	*16.64 FS
48	1		*AIR GUIDE (RHS)	Deformed	33.27 FS	*16.64 FS
49	1		*ELECTR FAN (BIG)	Not Necessary	657.99 FS	*- FS
50	1		*ELECTR FAN (SMALL)	Not Necessary	865.92 FS	*- FS
51	1		*FRT FENDER LHS	Not Necessary	691.67 FS	*- FS
52	1		*FENDER BRACKET	Not Necessary	45.27 FS	*- FS
53	1		*FENDER WHEEL LINING	Deformed	152.27 FS	*76.14 FS
54	1		*S/WHEEL SPRING CLOCK	Cut	734.69 FS	*367.35 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					27,090.67	7,760.34

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	B&P TOWING CHARGES	New	195.00	195.00
2	AIR CON GAS	New	60.00	48.00
3	ELECT WIRING & MECH COMPONENT	New	280.00	160.00
4	PROGRAMMING & CALIBRATION	New	480.00	288.00
5	B&P WHEEL ALIGNMENT	New	360.00	240.00
6	R&R ENGINE	New	2,520.00	760.00
7	VACUUM & REGAS AIRCON	New	420.00	190.00
8	R&R WINDSCREEN	New	840.00	440.00
9	LABOUR	New	6,720.00	1,900.00
10	SPRAY PAINT	New	5,600.00	2,200.00
11	R&R D/BOARD	New	712.50	570.00
12	R&R SEAT BELT & AIRBAG CONTROL UNIT	New	237.50	190.00
13	VEHICLE BENCH - CELLETE	New	1,200.00	960.00
Gross Labour Cost (S\$)			19,625.00	8,141.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >