

REF: cs/Lpc18001362/Ktd35
ASS. MGR: Kenneth
From (Person): Ong Li Li
ASSIGNMENT (Office): Lpc
Date/Time: 23/1/18 @ 11:22am
Estimated Cost: Bill to:

OD/TP/WS/TP RES/OD RES/EVA/TSV/MV/CS
To Inspect Vehicle No: SLM 9571Z
at Workshop mt: Cheng Hoe Motor
of BIK 1019 # 01-374 / 382 Yishun Ind. Park A
Policy No: Z17VPO5016454
Sum Insured: Claim No: 17/18/18/VPO5/020349
Excess: \$500.00
Make of Veh: Date: 20/01/2018
(Client's Record)

CA / REV / REP. / REV 24 HRS
Date/Time: 11:25am @ 23/1/18
Person Contacted: Dorelyn
Vehicle: IN / OUT

Date/Time	Action/Instruction
	SLM 9571Z - X
24/1/18 @ 11:25am	revert to Gerald via Manimen.
	Market value: \$78,000
	UTA: 41,100/-
	NV: 36,900/-

ASS. REC. BY:

REF:

LPC /

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / ☒ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$ 78k

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLN 95717 Yr Regn: 09, 17

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer orMake: Subaru Swift GLCC 1372Colour: A. Blue A/C: ☒ Insured / Std / NI / NASp. Reading: _____ T/Radio: ☒ Insured / Std / NI / NA

Eng/No: _____

C/No: JSAFEC828.00336156Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModl: ☒ Nil / S/Rim / STD A/Rim orTyre Size: F: 185/55R16

R: _____

☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal: 6 mmL/Bal: 6 mmD.O.A: 20/1/18

Rear

R/Bal: 5 mmL/Bal: 5 mmD.O.I: 23/1/18

Survey held at _____

Des. of Damages: ☒ Frt / ☒ Rear / ☒ O/S / ☒ N/S / ☒ UIC / ☒ Rooftop or

The U/C / Chassis frame & Body Structure affected due to collision.

OPC

Date / Time Action / Instruction

24/1 File parts to Carhome
T/loss, engine & gearbox affected.

Based on our surveyor opinion, the vehicle front body chassis badly affected, engine

Submit uneconomical total loss repair.

RECEIVED 30 JAN 2018

Date/Time, File Pass to?

1) 30/1 Typist

Date/Time, File Return to?

2) _____

☐

Prel. Report

☐

Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format:

Lump Sum / I.B.I. (\$

OD-TL

380



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CS/LPC18001362/Ktd3

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 23-01-2018



Code : LPC2

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SLM 9571Z
Policy No.	z17vp05016454	Coverage (\$)	0.00
Claim No.	17/18/18/VP05/020349	Excess (\$)	500.00
Assign From	MERIMEN (ONG LI LI)	Assign Date	23/01/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	20/01/2018	Inspection Date	23/01/2018
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Jan 2018 Sendback Est	23 Jan 2018 11:17 S\$30.00	23 Jan 2018 11:22 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	RAMLAN BIN ABDUL MANAP, ID: S1240787D		
Vehicle Reg. No.:	SLM9571Z	Date of Loss:	20/01/2018 12:00 - :59
Claim Type:	OD / 17/18/18/VP05/020349	Policy/Cover Note No.:	Z17VP05016454 (Comprehensive)
		Excess:	S\$500.00
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142		
Handling Insurer:	Lonpac Insurance Bhd (HQ) - Tel: +65 62507388 ... [Handled by Ong Li Li - 62799254]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 01/02/2018]		
Driver/Custodian:	MOHAMMED AMIRULHAFIZ BIN RAMLAN (31 / Male), NRIC: S8619337Z, Tel: +6590627921		
Adj Asg. Remarks:	SURVEY & REVERT.		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Tuesday, 23 January 2018 10:25 AM
To: CHENG HOE MOTOR PTE LTD (AMK)
Cc: MT_Claim_SG; assignments@lkkauto.com
Subject: RE: ARRANGE OD SURVEY FOR SLM9571Z (DOA: 20/01/2018)

Our Ref : 17/18/18/VP05/020349

Dear Doryln,

Dear Dorlyn,

Kindly upload your request into Merimen.

In the meantime, we have appointed LKK Auto Consultants Pte Ltd to survey vehicle.

Aside to LKK – Ms Catherine,

Kindly proceed to survey and revert.

*11.25am
veh ✓
kenneth*

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: CHENG HOE MOTOR PTE LTD (AMK) [mailto:chmamk@singnet.com]

Sent: Tuesday, 23 January, 2018 10:18 AM

To: GERALD POH WEE BIN; CHENG HOE MOTOR PTE LTD (HQ)

Subject: ARRANGE OD SURVEY FOR SLM9571Z (DOA: 20/01/2018)

Hi,

Kindly help out to arrange for surveyor to survey your insured vehicle SLM 9571Z traffic accident on 20.01.2018.

Vehicle sustain severe damages, please assist to arrange survey at our ANG MO KIO BRANCH & discuss further.

Thank you.

Rgds,

Dorlyn Li (Ms)

CHENG HOE MOTOR PTE LTD (AMK)

No. 10 Ang Mo Kio Ind Park 2A

#01-04

Ang Mo Kio Autopoint

Singapore 568047

Tel : 6481 2001

Fax : 6482 1296

Email : chmamk@singnet.com

Nivitha (LKK Auto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Tuesday, 23 January 2018 10:29 AM
To: CHENG HOE MOTOR PTE LTD (AMK)
Cc: MT_Claim_SG; assignments@lkkauto.com
Subject: FW: ARRANGE OD SURVEY FOR SLM9571Z (DOA: 20/01/2018)

Dear Dorlyn,

Kindly upload your request into Merimen.

In the meantime, we have appointed LKK Auto Consultants Pte Ltd to survey vehicle. The excess applicable is \$500.00 (Section I)

Aside to LKK – Ms Catherine,

Kindly proceed to survey and revert.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: CHENG HOE MOTOR PTE LTD (AMK) [<mailto:chmamk@singnet.com>]
Sent: Tuesday, 23 January, 2018 10:18 AM
To: GERALD POH WEE BIN; CHENG HOE MOTOR PTE LTD (HQ)
Subject: ARRANGE OD SURVEY FOR SLM9571Z (DOA: 20/01/2018)

Hi,

Kindly help out to arrange for surveyor to survey your insured vehicle SLM 9571Z traffic accident on 20.01.2018.

Vehicle sustain severe damages, please assist to arrange survey at our ANG MO KIO BRANCH & discuss further.

Thank you.

Rgds,
Dorlyn Li (Ms)
CHENG HOE MOTOR PTE LTD (AMK)
No. 10 Ang Mo Kio Ind Park 2A
#01-04
Ang Mo Kio Autopoint
Singapore 568047
Tel : 6481 2001
Fax : 6482 1296
Email : chmamk@singnet.com

CHENG HOE MOTOR PTE LTD (AMK)

From: "GERALD POH WEE BIN" <geraldpoh@lonpac.com>
Date: Tuesday, January 23, 2018 10:28 AM
To: "CHENG HOE MOTOR PTE LTD (AMK)" <chmamk@singnet.com>
Cc: "MT_Claim_SG" <mt_claim@lonpac.com>; <assignments@lkkauto.com>
Subject: FW: ARRANGE OD SURVEY FOR SLM9571Z (DOA: 20/01/2018)

Dear Dorlyn,

Kindly upload your request into Merimen.

In the meantime, we have appointed LKK Auto Consultants Pte Ltd to survey vehicle. The excess applicable is \$500.00 (Section I)

Aside to LKK – Ms Catherine,

Kindly proceed to survey and revert.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: CHENG HOE MOTOR PTE LTD (AMK) [mailto:chmamk@singnet.com]

Sent: Tuesday, 23 January, 2018 10:18 AM

To: GERALD POH WEE BIN; CHENG HOE MOTOR PTE LTD (HQ)

Subject: ARRANGE OD SURVEY FOR SLM9571Z (DOA: 20/01/2018)

Hi,

Kindly help out to arrange for surveyor to survey your insured vehicle SLM 9571Z traffic accident on 20.01.2018.

Vehicle sustain severe damages, please assist to arrange survey at our ANG MO KIO BRANCH & discuss further.

Thank you.

Rgds,

Dorlyn Li (Ms)

CHENG HOE MOTOR PTE LTD (AMK)

No. 10 Ang Mo Kio Ind Park 2A

#01-04

Ang Mo Kio Autopoint

Singapore 568047

Tel : 6481 2001

Fax : 6482 1296

Email : chmamk@singnet.com

23/01/2018

Shiau Chan (LKKAUTO)

To: ONG LI LI; assignments
Cc: MT_Claim_SG; SUR
Subject: RE: ARRANGE OD SURVEY FOR SLM9571Z (DOA: 20/01/2018) 17/18/18/020349

Dear Ms Ong,

The vehicle is not economical to repair due to both front chassis engine block and gearbox are damaged.

Refer to the tele-conversation between you and our surveyor, Kenneth.

Based on our surveyor's opinion, the front both chassis badly affected, engine block and gear box also damages.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ONG LI LI [mailto:llong@lonpac.com]
Sent: Wednesday, 24 January 2018 12:18 PM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; assignments <assignments@lkkauto.com>
Cc: MT_Claim_SG <mt_claim@lonpac.com>; SUR <sur@lkkauto.com>
Subject: RE: ARRANGE OD SURVEY FOR SLM9571Z (DOA: 20/01/2018) 17/18/18/020349

Dear Shiau Chan

Is the vehicle not economical or not road worthy to repair?

X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Shiau Chan (LKKAUTO) [mailto:siewsc@lkkauto.com]
Sent: Wednesday, 24 January, 2018 11:45 AM
To: ONG LI LI; GERALD POH WEE BIN; assignments
Cc: MT_Claim_SG; SUR
Subject: RE: ARRANGE OD SURVEY FOR SLM9571Z (DOA: 20/01/2018) 17/18/18/020349

Dear Ms Ong,

Please be informed that we have submitted our preliminary advice via Merimen System.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ong Li Li

Date: 24 Jan 2018

Preliminary Advice

Vehicle No	: SLM9571Z	Accident Date	: 20/01/2018
Make	: SUZUKI SWIFT	Policy No.	: Z17VP05016454
Assignment Date	: 23/01/2018	Excess	: S\$500.00
Date of Inspection	: 23/01/2018	Est. Duration of Repair	: 0.00
Inspection At	: CHENG HOE MOTOR PTE LTD (YISHUN) BLK 1019 #01-374/382, YISHUN INDUSTRIAL PARK A SINGAPORE 768761		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident. The undercarriage and body structure affected due to collision.

Repairer's Estimate (Gross)	:S\$	TOTAL LOSS
Revised Amount	:S\$	TOTAL LOSS
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	78,000.00
COE / PARF Rebate	:S\$	41,100.00
Salvage Value	:S\$	
Margin for Repair	:S\$	36,900.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- (X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

張建福 (機件) 拖車服務
TEO KIAN HOCK (CHEE CHEN) TOWING SERVICES

Mailing Address: 40 Cactus Road, Singapore 809597

Tel: 6858 4067 Fax: 6854 0407

廿四小時服務 24 HOURS SERVICE

Reg. No. 413736/00L

CASH SALE / WORK ORDER

No. 18426

Date: 22.01.12

寶號

Messrs:

車號

Vehicle No:

由

From:

時間 (日/夜)

Time (day/night):

其他

Others:

車型

Model No:

到

To:

CASH \$:

CHEQUE:

經手人

Authorised by:

收貨人

Received by:

注意: 本公司對所拖之車輛, 在進行中如有任何損失或破壞, 一概由車主自行負責。

NOTE: Vehicle is towed at owner's risk. The Company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/01/2018 10:16
Date Of Accident	20/01/2018 12:30
Exact Location Of Accident	T/JUNCTION OF BRICKLAND RD & CHOA CHU KANG AVE 3
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLM9571Z
Insured/Policyholder	
Name Of Registered Owner	RAMLAN BIN ABDUL MANAP
NRIC No	S1240787D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91902152
Alternative Phone No	OTHERS-90627921

Vehicle Particulars

Manufacturer	SUZUKI
Model	SWIFT-1.4 GLX (A)
Exact Purpose for which vehicle was being used at time of accident	PTE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	LONPAC INSURANCE BHD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	Z17VP05016454
Cover Note Number	06/12/2017 - 05/12/2018

Driver

Name of Driver	MOHAMMED AMIRULHAFIZ BIN RAMLAN
NRIC No	S8619337Z
Date Of Birth	11/07/1986
Occupation	INDOOR
Date Of Driving Pass	21/09/2011
Driving Experience	6 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90627921
Fax Number	
Contact Number	
Email Address	MOHD_AMIRULHAFIZ_RAMLAN@SPF.GOV.SG

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

5

DETAILS OF INJURED PERSON 1

Name

MOHAMMED AMIRULHAFIZ BIN RAMLAN

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SLM9571Z

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

DETAILS OF INJURED PERSON 2

Name

SYARIFAH NAMEERA BINTE SYED HAMDAN ALFADAAK

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SLM9571Z

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

DETAILS OF INJURED PERSON 3

Name

FEMALE ADULT (DRIVER)

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SJM5540M

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

YES

Address

Postcode

DETAILS OF INJURED PERSON 4

Name

FEMALE GIRL

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SJM5540M

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

YES

Address

Postcode

SKETCH PLAN

VEHICLE NO.: SLM9571Z
INSURER : Lumpac
DATE & TIME: 20/01/18 @ 1230

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 22/01/18

Driver's Signature

(If driver is not the policyholder)

Date & Time: 22.01.2018 / 1230 HRS

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.: Dorlyn (AMK) 22/01/18



SINGAPORE POLICE FORCE



T/20180121/7005

1 of 4

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20180121/7005

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 21/01/2018 13:19		Vide Report No.: J/20180120/0142		Station Diary No.:	
Informant's Particulars					
Name of Informant: MOHAMMED AMIRULHAFIZ BIN RAMLAN			Address: APT BLK 723 JURONG WEST AVENUE 5 #09-152 SINGAPORE 640723		
ID Type / ID No.: NRIC NO / S8619337Z			Contact No.: Home/Office: Mobile: 90627921		
Nationality: SINGAPORE CITIZEN			Email: Mohd_Amirulhafiz_RAMLAN@spf.gov.sg		
Sex: Male	Age: 31	Date of Birth: 11/07/1986	Type of Informant: Driver		
Race: Malay			Language: English		Institution / School Name:
Occupation: Police officer			Driving Licence Information: Class: 3		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 20/01/2018 12:30	Type of Location: T-Junction
Location: BRICKLAND ROAD T-junction of Brickland Road and Choa Chu kang Avenue 3 Lamp Post Number: 15				
Weather: Sunny		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Dual Carriage Way		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head On				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJM5540M	Car	TOYOTA	PICNIC	Blue	Seriously Damaged	4
SLM9571Z	Car	SUZUKI	SWIFT	Blue	Totally Damaged	1

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SLM9571Z	LONPAC INSURANCE BHD.	Z17VP05016454	06/12/2017	05/12/2018



**SINGAPORE
POLICE FORCE**



T/20180121/7005

2 of 4

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20180121/7005

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Passenger			
Name	SYARIFAH NAMEERA BINTE SYED HAMDAN ALFADAAK	ID No.	S9322464G
Related Vehicle	SLM9571Z (Car)	Contact No.	81897095
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	20/01/2018	Date Discharge	20/01/2018
No. of Days granted Medical Leave	04	Degree of Injury	Slight
Driver			
Name	MOHAMMED AMIRULHAFIZ BIN RAMLAN	ID No.	S8619337Z
Related Vehicle	SLM9571Z (Car)	Contact No.	90627921
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	20/01/2018	Date Discharge	20/01/2018
No. of Days granted Medical Leave	03	Degree of Injury	Slight

Brief Details.

On 20.01.2018 at about 1230hrs, I was driving my personal car, SLM9571Z along Brickland Road towards the direction of KJE. Upon reaching the T-junction of Brickland Road and Choa Chu kang Ave 3, I saw the traffic light was green and the right turn green arrow had appeared. As my eyes were on the traffic light I did not make a check on the oncoming traffic from Brickland Rd. When I executed the right turn, another vehicle, SJM5540M collided head onto the front left side of my vehicle.

The airbags to my vehicle were deployed and the next thing I knew my vehicle was slowly moving to the side of the road. I got out of my vehicle and attended to my passenger and brought her out from my car. I then proceeded to make a check on the other party of the vehicle. They had 5 person in their vehicle, 2 female adult, 2 male teenager and 1 female girl. I noticed that the female girl had a cut on her right leg.

Witnesses assisted in calling for the ambulance and Traffic Police. The driver of SJM5540M and her injured daughter were conveyed to hospital by ambulance. My passenger and I sustained multiple muscles contusions.

The traffic police attended to the scene and advised me to lodge a NP168 under IO Norhidayu T120068.

My vehicle was towed away from the scene. I wished to state that the incident happened very fast and there were no other vehicles involved.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0787D
Vehicle Details	
Vehicle No.:	SLM9571Z
Vehicle to be Exported:	No
Intended De-registration Date:	24 Jan 2018
Vehicle Make:	SUZUKI
Vehicle Model:	SWIFT GLX 1.4 AT
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	K14B1140476
Chassis No.:	JSAFZC82S00336156
Maximum Power Output:	70.0 kW (93 bhp)
Open Market Value:	\$11,702.00
Original Registration Date:	19 Apr 2017
First Registration Date:	19 Apr 2017
Transfer Count:	1
Actual ARF Paid:	\$11,702.00
OPC Cash Rebate Details	
OPC Cash Rebate Eligibility:	No
OPC Cash Rebate Eligibility Expiry Date:	-
OPC Cash Rebate Amount:	-
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Apr 2027
PARF Rebate Amount:	\$8,776.00
Intended COE Rebate Details	
COE Expiry Date:	18 Apr 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$35,000.00
COE Rebate Amount:	\$32,324.00
Total Rebate Amount:	\$41,100.00

The information contained herein is correct as at 24 Jan 2018

OK

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0787D
Vehicle Details	
Vehicle No.:	SLM9571Z
Vehicle to be Exported:	Yes
Intended De-registration Date:	22 Jan 2018
Vehicle Make:	SUZUKI
Vehicle Model:	SWIFT GLX 1.4 AT
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	K14B1140476
Chassis No.:	JSAFZC82S00336156
Maximum Power Output:	70.0 kW (93 bhp)
Open Market Value:	\$11,702.00
Original Registration Date:	19 Apr 2017
First Registration Date:	19 Apr 2017
Transfer Count:	1
Actual ARF Paid:	\$11,702.00
OPC Cash Rebate Details	
OPC Cash Rebate Eligibility:	No
OPC Cash Rebate Eligibility Expiry Date:	-
OPC Cash Rebate Amount:	-
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Apr 2027
PARF Rebate Amount:	\$8,776.00
Intended COE Rebate Details	
COE Expiry Date:	18 Apr 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$35,000.00
COE Rebate Amount:	\$28,000.00
Total Rebate Amount:	\$36,776.00

The information contained herein is correct as at 22 Jan 2018

Need Items for Your Car?

We have thousands of car parts & accessories to explore.

The best online platform to sell and buy car parts & accessories - Marketplace

☒ Past Models
 ☐ Current Models

Home » New Cars » Past Cars » Suzuki Past Cars » Suzuki Swift

Tools & Tips

Car Buying

Car Selling

Car Aftermarket

Car Ownership

On The Move

Lifestyle

Vehicle Number Plates

BUY & SELL
Your AUSPICIOUS
& UNIQUE Vehicle No.

Do you know? We are Singapore's
BIGGEST PLAYER
with the most vehicle plate numbers for sale!

[Click here to see all Auspicious Numbers!](#)

Related Articles



Suzuki gets new Swift brand ambassador



Suzuki releases new Swift Sport teaser video



sgCarMart's very own choice of Pokercars

CAT A \$36,890 ▼

CAT B \$42,661 ▼

CAT E \$44,000 ▼

COE premiums fall across the board

» View More

Past Car

Models no longer being sold by local distributors.

Model unavailable since Jun 2017

Suzuki Swift

Overview

Pricing

Photos

Research

Reviews

Specs

Features

Similar

Accessories

Promo

Submit a Review

Report Error

Share

Like 91k



USER RATINGS:

(11 reviews)

Details

Distributor

Champion Motors

Hotline

66311118

Built in

Japan (launched 2011, facelifted Oct-2013)

Successor

Suzuki Swift (2018)

Predecessor

Suzuki Swift (2004-2011)

Pricelist

17-Jan Pricelist

Select Another Date ▼

» View All Available Suzuki Models

» View All Past Suzuki Models

Submodel

Last Recorded Price

Fuel Economy

Power

Transmission

Detailed Info

1.4 GLX Plus (A)

-

16.1km/L

94bhp

4-speed (A)

Specs | Features

1.4 GLX Premium (A)

-

16.1km/L

94bhp

4-speed (A)

Specs | Features

1.4 GLX Special Edition Plus (A)

\$85,900 (May 2017)

16.1km/L

94bhp

4-speed (A)

Specs | Features

- Read facelift article

1.4 GLX Special Edition Premium (A)

\$88,900 (May 2017)

16.1km/L

94bhp

4-speed (A)

Specs | Features

1.4 GLX (M)

\$98,900 (Mar 2015)

18.2km/L

94bhp

5-speed (M)

Specs | Features

1.4 GLX (M)

\$104,900 (Dec 2013)

18.1km/L

94bhp

5-speed (M)

Specs | Features

1.4 GL (A)

\$108,500 (Sep 2012)

16.1km/L

94bhp

4-speed (A)

Specs | Features

1.4 GL (M)

\$108,500 (Sep 2012)

18.1km/L

94bhp

5-speed (M)

Specs | Features

1.4 GLX (A)

\$109,900 (Dec 2013)

16.1km/L

94bhp

4-speed (A)

Specs | Features

Suzuki Swift Review

Car Review - Suzuki Swift 2011 1.4 GLX (A)

10 May 2011 | Suzuki Reviews

The latest model from Champion Motors raises the bar for the pleasing-personality Swift, but how well does it compare to its segment peers? We take the loveboy out for a long weekend drive.



The Good

- Exterior styling is still as attractive as ever
- Comfortable benches all-round
- Provides an enthusiastic drive



The Bad

- Limited headroom for rear occupants
- It holds a mere 1.4-litre engine under the hood

FACELIFT The Suzuki Swift was facelifted on Jan 2016. Read more

Comparison Tests:

Nissan Note 1.2 DIG-S (A) vs Suzuki Swift 1.4 (A) vs Toyota Yaris 1.33 (A)



VS



VS



CONSUMER REVIEWS

Reliable, affordable, good handling car ...

Previous ride was 1.3 swift bought second hand, drive till eol no major breakdown, therefore purchase 1.4GLX swift due to it's reliability and low cost of maintenance. Overall quite happy with the performance. ...

Read More »

Love at first sight

Went to test drive the lancer/k3/city/mazda2 as I was looking for a replacement car for my 8 year old manual avante. None of them really caught my eye due to the pricing. I was pretty tempted by the lancer init...

Read More »

Submit a review

Receive 3 MCF points when you submit a review

» View All 11 Consumer Reviews

Items for Suzuki Swift



Advance Design Sport Seat



LED Scuff Plate



Shadow E-Drive Advance 4 E Throttle Cont...

Compare



Prices and information are effective from 13 April to 26 April 2017, 12 noon.

NORMAL CAR REGISTRATION PRICE LIST


CATEGORY A MODELS	LIST PRICE INCLUDING COE	6 MONTHS ROAD TAX	IN-HOUSE FINANCE AND INSURANCE REBATE	CEVS REBATE	40TH ANNIVERSARY DISCOUNT	SAVER NON-GUARANTEED COE COE REBATE \$48K	CLASSIC GUARANTEED COE 8 BIDS COE REBATE \$48K
SWIFT 1.4 AT 5-DR PLUS PREMIUM Combined Fuel Consumption 5.2 l/100km CO2 Emission 147g/km	\$94,483 \$98,483	\$305 \$305	(\$2,000) (\$2,000)		(\$8,888) (\$8,888)	\$83,900 \$87,900	\$86,900 \$90,900
SWIFT 1.4 AT 5-DR SPECIAL EDITION							
PLUS PREMIUM Combined Fuel Consumption 5.2 l/100km CO2 Emission 147g/km	\$96,483 \$99,483	\$305 \$305	(\$2,000) (\$2,000)		(\$8,888) (\$8,888)	\$85,900 \$88,900	\$88,900 \$91,900
GAZ 1.4 AT SEDAN							
PLUS PREMIUM Combined Fuel Consumption 5.4 l/100km CO2 Emission 128g/km	\$108,483 \$110,483	\$305 \$305	(\$2,000) (\$2,000)	(\$5,000) (\$5,000)	(\$8,888) (\$8,888)	\$92,900 \$94,900	\$95,900 \$97,900
S-CROSS 1.6 CVT							
2WD - PLUS Combined Fuel Consumption 5.8 l/100km CO2 Emission 137g/km	\$107,420 \$111,420	\$368 \$368	(\$2,000) (\$2,000)		(\$8,888) (\$8,888)	\$96,900 \$100,900	\$99,900 \$103,900
2WD - PREMIUM							
4WD, Panoramic Roof - PLUS Combined Fuel Consumption 5.8 l/100km CO2 Emission 137g/km	\$111,420 \$114,420	\$368 \$368	(\$2,000) (\$2,000)		(\$8,888) (\$8,888)	\$100,900 \$103,900	\$103,900 \$106,900
4WD, Panoramic Roof - PREMIUM							
VITARA 1.6 6-SPEED AT							
2WD - PLUS Combined Fuel Consumption 5.5 l/100km CO2 Emission 127g/km	\$118,420 \$121,420	\$368 \$368	(\$2,000) (\$2,000)	(\$5,000) (\$5,000)	(\$8,888) (\$8,888)	\$102,900 \$105,900	\$105,900 \$108,900
2WD - PREMIUM							
4WD, Panoramic Roof - PLUS Combined Fuel Consumption 5.7 l/100km CO2 Emission 133g/km	\$124,420 \$127,420	\$368 \$368	(\$2,000) (\$2,000)	(\$5,000) (\$5,000)	(\$8,888) (\$8,888)	\$108,900 \$111,900	\$111,900 \$114,900
4WD, Panoramic Roof - PREMIUM							
CATEGORY B MODELS							
SWIFT SPORT 1.6 CVT - PLUS Combined Fuel Consumption 6.1 l/100km CO2 Emission 154g/km	\$110,420 \$114,420	\$368 \$368	(\$2,000) (\$2,000)		(\$8,888) (\$8,888)	\$99,900 \$103,900	\$102,900 \$106,900
CVT - PREMIUM							

- Prices and specifications are subject to change without prior notice.
 - A fee of \$1,000 will be charged for any change of body colour or \$2,000 for change of model.
 - Champion Motors (1975) Pte Ltd reserves the rights to use Open CAT COE (CAT E) to register any car.
 - Prices quoted are without insurance.
 - In-house finance rebate of \$1,500 and insurance rebate of \$500 applies where applicable (Minimum loan \$40,000 for 5 years).
- TERMS & CONDITIONS APPLY.

DON'T MISS OUT ON THIS INCREDIBLE DEAL!

40th Anniversary Discount worth \$8,888 - 2.38% Special Interest Rate
Free 3M Solar Film - 5-year Unlimited Mileage Warranty

www.suzukicar.com.sg



Suzukicarsg

237 ALEXANDRA ROAD #01-08 THE ALEXCER SINGAPORE 159929.
MON TO FRI 9.00AM - 6.00PM, SAT 9.00AM - 7.00PM, SUN & PUBLIC HOLIDAYS 10.00AM - 6.00PM.
ENQUIRY: 6631 1118

Suzuki Service Centres are conveniently located at Pandan and Bukit Batok.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Status
Main	23 Jan 2018	23 Jan 2018 11:17 S\$30.00	23 Jan 2018 11:22 Edit Adj Rpt	S\$30.00 Edit Estimates	S\$30.00 View Rpt	Pending for Survey Report

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	RAMLAN BIN ABDUL MANAP , ID: S1240787D								
Vehicle Reg. No.:	SLM9571Z	Date of Loss:	20/01/2018 12:00 - :59						
Claim Type:	OD / 17/18/18/VP05/020349	Policy/Cover Note No.:	Z17VP05016454 (Comprehensive)						
		Excess:	S\$500.00						
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142								
Handling Insurer:	Lonpac Insurance Bhd (HQ) - Tel: +65 62507388 ... [Handled by Ong Li Li - 62799254]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 01/02/2018]								
Driver/Custodian:	MOHAMMED AMIRULHAFIZ BIN RAMLAN (31 / Male), NRIC: S8619337Z, Tel: +6590627921								
Adj Asg. Remarks:	SURVEY & REVERT.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> LONPAC_HQ (30/01/2018): Alert - Adj Mandate Revoked - SLM9571Z - Claim Handler: Ong Li Li 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SLM9571Z (17/18/18/VP05/020349)

OD

Jan 20 2018 12:00PM

[RAMLAN BIN ABDUL MANAP]

Cheng Hoe Motor Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View <div>View in Browser</div>		
Assessment Reports									1 per page		<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)							Thumbnail	Print	
1	23/01/18 11:17	Repairer Estimates							Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	24/01/18 11:25	Adjuster Immediate Advice							Load HTM		
									3 per page		<input checked="" type="checkbox"/>
Photos/Images									Thumbnail	Print	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Load JPG	<input checked="" type="checkbox"/>	
1	24/01/18 11:19	General View							Load JPG	<input checked="" type="checkbox"/>	
2	24/01/18 11:19	General View							Load JPG	<input checked="" type="checkbox"/>	
3	24/01/18 11:19	General View							Load JPG	<input checked="" type="checkbox"/>	
4	24/01/18 11:19	General View							Load JPG	<input checked="" type="checkbox"/>	
5	24/01/18 11:19	General View							Load JPG	<input checked="" type="checkbox"/>	
6	24/01/18 11:19	General View							Load JPG	<input checked="" type="checkbox"/>	
7	24/01/18 11:19	General View							Load JPG	<input checked="" type="checkbox"/>	
8	24/01/18 11:19	General View							Load JPG	<input checked="" type="checkbox"/>	
9	24/01/18 11:19	General View							Load JPG	<input checked="" type="checkbox"/>	
10	24/01/18 11:19	General View							Load JPG	<input checked="" type="checkbox"/>	
11	24/01/18 11:19	General View							Load JPG	<input checked="" type="checkbox"/>	
12	24/01/18 11:19	General View							Load JPG	<input checked="" type="checkbox"/>	
13	24/01/18 11:19	General View							Load JPG	<input checked="" type="checkbox"/>	
14	24/01/18 11:19	General View							Load JPG	<input checked="" type="checkbox"/>	
15	24/01/18 11:19	General View							Load JPG	<input checked="" type="checkbox"/>	
16	24/01/18 11:19	General View							Load JPG	<input checked="" type="checkbox"/>	
17	24/01/18 11:19	General View							Load JPG	<input checked="" type="checkbox"/>	
18	24/01/18 11:19	General View							Load JPG	<input checked="" type="checkbox"/>	
19	24/01/18 11:19	General View							Load JPG	<input checked="" type="checkbox"/>	
20	24/01/18 11:19	General View							Load JPG	<input checked="" type="checkbox"/>	
21	24/01/18 11:19	General View							Load JPG	<input checked="" type="checkbox"/>	
22	24/01/18 11:19	General View							Load JPG	<input checked="" type="checkbox"/>	
23	24/01/18 11:19	General View							Load JPG	<input checked="" type="checkbox"/>	
24	24/01/18 11:19	General View							Load JPG	<input checked="" type="checkbox"/>	
25	24/01/18 11:19	General View							Load JPG	<input checked="" type="checkbox"/>	
26	24/01/18 11:19	General View							Load JPG	<input checked="" type="checkbox"/>	
27	24/01/18 11:19	Chassis Number							Load JPG	<input checked="" type="checkbox"/>	
28	24/01/18 11:19	General View							Load JPG	<input checked="" type="checkbox"/>	
29	24/01/18 11:19	General View							Load JPG	<input checked="" type="checkbox"/>	
30	24/01/18 11:19	General View							Load JPG	<input checked="" type="checkbox"/>	
31	24/01/18 11:19	General View							Load JPG	<input checked="" type="checkbox"/>	
32	24/01/18 11:19	General View							Load JPG		

					<input checked="" type="checkbox"/>
33	24/01/18 11:19	General View		Load JPG	<input checked="" type="checkbox"/>
34	24/01/18 11:19	General View		Load JPG	<input checked="" type="checkbox"/>
35	24/01/18 11:19	General View		Load JPG	<input checked="" type="checkbox"/>
36	24/01/18 11:19	General View		Load JPG	<input checked="" type="checkbox"/>
37	24/01/18 11:19	General View		Load JPG	<input checked="" type="checkbox"/>
Documentation					1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		Thumbnail	Print
1	23/01/18 11:21	TOWING BILL		Load JPG	<input checked="" type="checkbox"/>
2	30/01/18 11:59	TOWING INV		Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	24/01/18 11:19	Log card (if available)		Load PDF	

Linked Accident Report Documents

					View <input type="button" value="View in Browser"/>
Assessment Reports					1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		Thumbnail	Print
1	22/01/18 16:46	Accident Statement		Load HTM	
Photos/Images					3 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		Thumbnail	Print
1	22/01/18 16:46	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
2	22/01/18 16:46	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
3	22/01/18 16:46	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
4	22/01/18 16:46	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
5	22/01/18 16:46	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
6	22/01/18 16:46	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
7	22/01/18 16:46	SCENE PHOTO		Load JPG	<input checked="" type="checkbox"/>
8	22/01/18 16:46	SCENE PHOTO		Load JPG	<input checked="" type="checkbox"/>
9	22/01/18 16:46	SCENE PHOTO		Load JPG	<input checked="" type="checkbox"/>
10	22/01/18 16:46	SCENE PHOTO		Load JPG	<input checked="" type="checkbox"/>
Documentation					1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)		Thumbnail	Print
1	22/01/18 16:45	Sketch Plan		Load JPG	<input checked="" type="checkbox"/>
2	22/01/18 16:45	Sketch Plan #2		Load JPG	<input checked="" type="checkbox"/>
3	22/01/18 16:45	Sketch Plan #3		Load JPG	<input checked="" type="checkbox"/>
4	22/01/18 16:45	Sketch Plan #4		Load JPG	<input checked="" type="checkbox"/>
5	22/01/18 16:45	Sketch Plan #5		Load JPG	<input checked="" type="checkbox"/>
6	22/01/18 16:45	Sketch Plan #6		Load JPG	<input checked="" type="checkbox"/>
7	22/01/18 16:45	IC & DL		Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse
Singapore 199555

Our File No: CS/LPC18001362/KTD3S2

Date: 30/01/2018

REFERENCE

Insured/Claimant: RAMLAN BIN ABDUL MANAP Policy No: Z17VP05016454
Date of Loss: 20/01/2018 Nature of Claim: OD Claim No: 17/18/18/VP05/020349

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLM9571Z**
Make & Model: SUZUKI SWIFT, 1.4 GLX (A) Engine No: K14B1140476
Reg. Date: 19/04/2017 (Man. Year: 2016) Chassis No: JSAFZC82S00336156
Colour: Metallic Blue Odometer: 0 km
Engine Capacity: 1372 cc
Market Value/New Car Price: S\$78,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 185/55 R16 Rear Tyre Size: 185/55 R16
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 5 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	30.00	30.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	30.00	30.00	0.00	0.00
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	-470.00	-470.00	0.00	0.00
+ GST 7.00/0.00% (S\$)	-32.90	0.00	-32.90	100.00
Nett Amount (S\$)	-502.90	-470.00	-32.90	6.54

INSPECTION

Date of Assignment: 23/01/2018 Present Location:
Date Inspected: 23/01/2018 Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)
Cheng Hoe Motor Pte Ltd (Yishun)
Blk 1019 #01-374/382, Yishun Industrial
Park A
Singapore 768761

Estimated Period of Repair: 0.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value :	\$78,000.00
OMV :	\$11,702.00
PARF Rebate (1) :	\$ 8,776.00
Quota Premium Paid :	\$35,000.00
COE Rebate (2) :	\$32,324.00
Total Rebate (1) + (2) = :	\$41,100.00

The total amount incurred will be Market Value \$78,000.00 minus Total Rebate \$41,100.00 = \$36,900.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Jan 2018)
Parts:	144	SUZUKI SWIFT 1.4 GLX (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLM9571Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING (FROM AMK AUTOPOINT #02-12 TO #01-04)	New	30.00	30.00
Gross Labour Cost (\$\$)			30.00	30.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >