

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No: 199607198R GST Reg. No. 19-9607198-R				
Affiliated to Federation Internationale Des Experts En Automobile					
AUTO & GENERAL INSURANCE (S) PL Ref : CS/AG				Avd3n2	
(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Date: 06-04-2018		
			Code: AGI		
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SJL 6078E	Veh. Inspected	SKN 8335C	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10001301	Excess (\$)	0.00	
	Assign From	ALBERT HONG	Assign Date	23/01/2018	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA WISH	c.c	1794	
	Engine No.	HIDDEN	Year of Reg.	2007	
	Chassis No.	ZNE100332184	Colour	SILVER	
	Odometer	220791	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	205/55 R16	HIFLY	6 mm	
	L/H Front Tyre	205/55 R16	HIFLY	6 mm	
	R/H Rear Tyre	205/55 R16	HIFLY	6 mm	
	L/H Rear Tyre	205/55 R16	HIFLY	6 mm	
4.	4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.				
	DAMAGES SEE DETAILS.				
5.	. General Information				
	Accident Date	21/01/2018	Inspection Date	25/01/2018	
	Survey held at TORQUE 5 PTE LTD				
		8 KAKI BUKIT AVENUE 4 #01-50 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a.	5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.		Estimate Days of Repair			

4 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: