

Surveyor: Muhammad
REF: CS3 / ALH 18001365 / Algd3er
From (Person): Shawn Wui of ALH Date/Time: 27032018
Estimated Cost: _____ Bill to: _____

Special Instruction:
1/8: # 8800-00

Third Parties:

Claimant:

Surveyor: Treasure Appraisal

Workshop: Hendon Automotive

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: SEIN 8446M Insured: SLK 7930U
at Workshop m/s Hendon Automotive Tel: _____
of 280 Woodlands Ind Park E5 #01-19
Policy No: _____ Claim No: 964874951036
Sum Insured: _____ Excess: _____
Make of Veh: _____ D.O.A. 21.01.2018
(Client's Record)

Date/Time: 10-04-2018 (Tuesday) @ 4pm H.O.D. Enforcement/Date: _____
Person Contacted: 02-04-2018 (Monday) @ 4pm Vehicle IN / OUT
Date/Time: _____ Confirmed with _____ Final Fig _____ days (Red \$ _____ / _____ %; Original 7 days)
Date/Time: 05/7/18 Submit Final Fig 5650, 6 days (Red \$ 3150 / 36 %; Original 7 days)

Date/Time	Action/Instruction
	<u>67 Home Avenue # 03-03 (S) 598744 (Ms Lynn - 94593885)</u>
<u>03042018</u>	<u>Owner forget got appointment (by Rasul)</u>
	<u>Billing RS + RI</u>

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

RECEIVED 05 JUL 2018

Para(3) : Nett Value

Market Value : _____
Salvage Value : _____
Nett Value : _____

Inspected/
Evaluated by:

Fee Charged:

Date:

Basic & Add
Transport
Photos
Others
Total

200

20

220

1) Date/Time 05/7/18 File Pass to [Signature]

2) Date/Time _____ File Return to _____

3) Date/Time _____ File Pass to _____

4) Date/Time _____ File Return to _____

5) Date/Time _____ File Pass to _____

6) Date/Time _____ File Return to _____

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

N/S	O/S

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SN 8446M Yr Regn: 2006 / NOV
 Type: M/Cat / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: HAWA STREAM 1.8A C.C. 1799
 Colour: BLACK A/C: Insured / Std / NI / NA
 Sp. Reading: 175986 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: RN61015175
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / 5/Rim / STD A/Rim or
 Tyre Size: F: 225/40R18
 R: _____

33 / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front Rear
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 21/01/18 D.O.I. 10/04/18
 Survey held at: 67, Hume Ave

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

[Signature]
 5/7/2018

Date / Time Action / Instruction

Date/Time, File Pass to? ☐ : Prel. Report

ij ☐ : Final Report

Date/Time, File Return to?

25

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

1. 50.00

1. Phone

1. Others

1.

TOTAL:

Add Fee: ☐ Site Insp \$

☐ Interview \$

☐ Tech Insp \$

☐ Weekend \$

Report Format :

Lump Sum / I.B.I: (\$)

Catherine Chong (LKK Auto)

From: Kelly Cheng <kelly.cheng@ksteoptr.com>
Sent: Thursday, 5 April, 2018 4:14 PM
To: Wui, Shawnkaijye
Cc: Md Noor, Norsiah
Subject: Re: Request for Re-inspection Our Claim No: 9648749510SG (003) Your Ref: TKS/H600-ACC-39904.18/kc

WITHOUT PREJUDICE

Dear Sirs/Mdm,

We refer to your email dated 4 March 2018.

Kindly note that re-arrangements have been made for you to re-inspect our client's vehicle SGN 8446 M. The details of the re-inspection are as follows:-

Date/Time:	10 April 2018 (Monday) @ 4:00PM
Venue/Location:	67 HUME AVENUE, #08-03, (S) 598744
Person In-Charge:	Ms Lynn
Contact:	9459 2885
Remarks:	Please call our client upon reaching

Kindly confirm the same and arrange for your In-House-Surveyor to attend punctually.

Please let us have your proposed offer within 14 days from the date of re-inspection.

Thank you!

On Wed, Apr 4, 2018 at 10:07 AM, Wui, Shawnkaijye <Shawnkaijye.Wui@aig.com> wrote:

WITHOUT PREJUDICE

Dear Kelly,

Please be informed that your client did not turn up for the re-inspection.

Thanks and Regards,

Shawn Wui
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd.

Catherine Chong (LKK Auto)

From: Wui, Shawnkaijye <Shawnkaijye.Wui@aig.com>
Sent: Tuesday, 27 March, 2018 3:35 PM
To: Catherine Chong (LKK Auto); sur@lkkauto.com
Subject: FW: Request for Re-inspection Our Claim No: 9648749510SG (003) Your Ref: TKS/H600-ACC-39904.18/kc
Attachments: SLK7930U GIA report (OI).PDF; TP GIA and Survey Report.pdf

Dear Catherine,

New assignment to conduct physical RI. Previously arranged by my colleague, Norsiah.

Please assist to confirm with TP repairer and solicitor.

Enclosed herewith,

- 1) Both parties GIA report,
- 2) TP survey report

Kindly acknowledge this assignment.

Thanks and Regards,
Shawn Wui
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way, #08-16, Singapore 079120

Tel +(65) 6419 1959 | Fax +(65) 6835 7416

Shawnkaijye.Wui@aig.com | www.aig.com.sg

IMPORTANT NOTICE

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use

From: Kelly Cheng [mailto:kelly.cheng@ksteoptr.com]
Sent: Thursday, March 22, 2018 5:19 PM
To: Wui, Shawnkaijye; Md Noor, Norsiah
Subject: Re: Request for Re-inspection Our Claim No: 9648749510SG (003) Your Ref: TKS/H600-ACC-39904.18/kc

WITHOUT PREJUDICE

Dear Sirs/Mdm,

We refer to your email dated 5 March 2018.

Kindly note that arrangements have been made for you to re-inspect our client's vehicle SGN 8446 M. The details of the re-inspection are as follows:-

Date/Time:	2 April 2018 (Monday) @ 4:00PM
Venue/Location:	67 HUME AVENUE, #08-03, (S) 598744
Person In-Charge:	Ms Lynn
Contact:	9459 2885
Remarks:	Please call our client upon reaching

Kindly confirm the same and arrange for your In-House-Surveyor to attend punctually.

Please let us have your proposed offer within 14 days from the date of re-inspection.

Thank you!

On Thu, Mar 22, 2018 at 2:15 PM, Wui, Shawnkaijye <Shawnkaijye.Wui@aig.com> wrote:

WITHOUT PREJUDICE

Dear Kelly,

Please advise whether your client has arranged the re-inspection?

Thanks and Regards,

Shawn Wui
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way, #08-16, Singapore 079120

Tel +(65) 6419 1959 | Fax +(65) 6835 7416

Shawnkaijye.Wui@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Md Noor, Norsiah
Sent: Monday, March 05, 2018 10:07 AM
To: 'Kelly Cheng'
Cc: 'SUR'; 'Catherine Chong (LKK Auto)'
Subject: Request for Re-inspection Our Claim No: 9648749510SG (003) Your Ref: TKS/H600-ACC-39904.18/kc

WITHOUT PREJUDICE

Dear Kelly,

We refer to the above.

We wish to conduct physical re-inspection on your client's vehicle.

Please advise date, time and location 5 days in advance.

Thank you

Norsiah Md Noor

AIG

Complex Claims Examiner

Claims | AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419-1606 | Fax +(65) 6835-7417

Norsiah.MdNoor@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any

copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

--
Best Regards,
Kelly Cheng
Tel: 6333 4222 ext 72
Fax: 6333 5675

Teo Keng Siang LLC
111 North Bridge Road
Peninsula Plaza, #29-07/08
Singapore 179098

ASSIGNMENT (Office)

Insured

From Person:

Chin Lee Ying

at

AIG

Date/Time:

23/1/18 @ 10:09am

Estimated Cost:

Bill to:

OD/HI/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGN8446M

Insured:

SLK 79304

at Workshop no:

Hendon Automotive

Tel:

9459 2885

at 280 Woodlands Ind. Park ES # 01-19

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

DOA

21/01/2018

CA / REV / REP. / REV 24 HRS

'wp'

W.S. Information

Date/Time:

10:20am @ 23/1/18

Period Covered:

Lin

Vehicle ID:

OUT

Date/Time:

Active/Inactive


X

Engine

SGN8446M - X

SLK 79304 - X

**- FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED
VEHICLE SLK7930U AND SGN8446M ON 21/01/2018**

From: Chin, Lee-Ying
To: 'assignments', Admin A
Cc: Fong, Andy-SY
Sent: 23/1/2018 10:09:33 AM
Attachments:  SLK7930U.TIF

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947 | Fax +(65) 6835 7416

Lee-Ying.Chin@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

HENDON AUTOMOTIVE PTE LTD

280 Woodlands Industrial Park E5 #01-19, Harvest@Woodlands S(757322)
TEL : 94592885 FAX : 63345178

Date :

Pre-repair Inspection

M/s AIG Asia Pacific Insurance Pte. Ltd
AIG Building
78 Shenton Way
#08-16
Singapore 079120

By FAX 6415 3727 Only

Dear Sir,

ACCIDENT INVOLVING S6N 8446M AND SLK 7930 U ON 21/01/8 @ 10:30

We refer to the above matter.

We are the appointed repair workshop of vehicle no. S6N 8446MWe understand that you are the insurer of vehicle no. SLK 7930 U

The owner of vehicle no. S6N 8446M has authorised us to carry out the repairs to his vehicle which was damaged by your insured's vehicle. The owner intends to make a claim against you insured and/or insured's authorised driver for the accident which is caused wholly and/or contributed by your insured and/or your insured's authorised driver's negligence.

We hereby give you notice of the accident and an opportunity to inspect the damaged to the vehicle prior to the commencement of the repairs.

Kindly take note that we hereby give you 2 days' notice to conduct a pre-repair inspection of vehicle no. S6N 8446M at my premises.



Yours faithfully

Taufelbe

ALG

Q.E 2021 Nov

SGN8446M 2006 Nov

Type: ☐ Car ☐ Motorcycle ☐ Bus ☐ Van ☐ Lorry ☐ Taxi ☐ Prime Mover

Tevfik Tezcaner

Handy Stream 1797

Colour: Black Size: 40 Insured: Std / N / NA

172709

Figure 1

CIN: 82524 RN6/0/5/75

Gen. Cond. Good / Fair / Poor / Burnt

Sleeping Inorder / Jammed / Leaked / Burnt or

Brake: ☒ Indicia / ☐ Jammed / ☐ Leaked / ☐ Burnt off

Mod NII / ~~S/Rim~~ / STD A/Rim 0

Type Size: 265 40418.

ES / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO /

Front

6

6

DOA 24/1/18 D. Zuma

Survey held at Hendon Park on 15/10/1952

Vehicle IN / OUT

The UIC Chassis frame Body Structure affects due to collision

The UIC Chassis frame Body Structure affects due to collision

Days Of Repair:

Resurvey No. of Trip

2002年 7月

Add Fee: \$

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Anywillful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIARecords Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/01/2018 11:43
Date Of Accident	21/01/2018 10:35
Exact Location Of Accident	BUKIT PAMJANG RING RDOPPOSITE SENJA LRT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLK7930U
Insured/Policyholder	
Name Of Registered Owner	LEONG MUN HENG
NRIC No	S0869179G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98360576
Alternative Phone No	Others-98360576

Vehicle Particulars

Manufacturer	KIA
Model	FORTE K3-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	SENDING CHILDREN TO SWIMMING POOL
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100499528
Cover Note Number	

Driver

Name of Driver	LEONG KIT YIN
NRIC No	S8413973D
Date Of Birth	24/04/1984
Occupation	INDOOR
Date Of Driving Pass	13/11/2009
Driving Experience	8 YEARS AND 2 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-98360576
Fax Number	
Contact Number	
Email Address	LEONG_KIT_YIN@HOTMAIL.COM

Address	BLK 487 SEGAR ROAD #15-548
Postcode	670487
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	Name: : ETHAN CHIA Gender: : Male

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGN8446M
Vehicle Make/Model/Colour	HONDA STREAM/BLACK
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	WEE CHEE KEONG
NRIC/Passport Number	S7814712A
Contact Number	91257595
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	BUMPER & CAR BOOT DOOR DAMAGE
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:




Driver's Signature
(If driver is not the policyholder)
Date & Time: 22/1/16 5:58/4PM



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


I was driving along Bukit Panyang Road, going towards Bukit Panyang Plaza. As I was approaching the traffic light which was green, a black Honda stream in front of me braked as the green light turned to amber. I applied my brake immediately but still unable to put the car to a full stop, hence knocking into the back of the Honda stream.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature

Date & Time:


Driver's Signature

(If driver is not the policyholder)

Date & Time: 22/1/18 8:50 AM


Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

1) Number of Passengers in Vehicle A (Including driver)?

2

Passenger 1

Name : Leong Kit Yin (Driver)

Gender : M ☒ F

Passenger 2

Name : Ethan (him)

Gender : ☒ M / F

Passenger 3

Name : _____

Gender : M / F

Passenger 4

Name : _____

Gender : M / F

Passenger 5

Name : _____

Gender : M / F

Passenger 6

Name : _____

Gender : M / F

Passenger 7

Name : _____

Gender : M / F

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/01/2018 12:55
Date Of Accident	21/01/2018 10:20
Exact Location Of Accident	BUKIT PANJANG RING ROAD TOWARDS CITY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGN8446M
Insured/Policyholder	
Name Of Registered Owner	WEE CHEE KEONG (HUANG ZHIQIANG)
NRIC No	S7814712A
Email Address	CHEEKEONG@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-91257595
Alternative Phone No	OFFICE-91257595

Vehicle Particulars

Manufacturer	HONDA
Model	STREAM 1.8 A

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA140896/1
Cover Note Number	

Driver

Name of Driver	WEE CHEE KEONG (HUANG ZHIQIANG)
NRIC No	S7814712A
Date Of Birth	27/05/1978
Occupation	INDOOR
Date Of Driving Pass	01/10/2001
Driving Experience	16 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91257595
Fax Number	
Contact Number	
Email Address	CHEEKEONG@HOTMAIL.COM

Address 67 HUME AVENUE
#08-03
Postcode 598744
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OWNER
Vehicle Registration Number of Driver's Own Vehicle -
-
Insurance Company of Driver's Own Vehicle -
-

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 2
Passenger 1
NAME: : WEE JIN JAN
GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO THE ATTACHMENT

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLK7930U
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver LEONG KIT YIN
NRIC/Passport Number S8413973D
Contact Number 91692995/98360576
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims
- (e) the information so collected under (d) above may be shared / disclosed
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

21/1/2018


Driver's Signature
(if driver is not the policyholder)
Date & Time:


21/1/2018

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

SKETCH PLAN

Veh A: SHN 8046 M
B: SLK 7930 U



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT Bukit Panjang Ring Rd

I was travelling on the 2nd lane of Bukit Panjang Ring Rd towards ^{city} ~~the town~~
I stopped at the traffic light at the junction with Senja Road.

Vehicle B - plate number SLK 79304 hit my rear after stopping.


There were no injuries.

DECLARATION

I/We declare the foregoing particulars are true in every respect


Police Officer's Signature
Date & Time:

21/1/2018


Driver's Signature
(If driver is not the policyholder)
Date & Time: 21/1/2018

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:

Treasure Appraisal Services

9 Joo Chiat Place Singapore 427743
HP: (65) 9833 1618 Fax: (65) 6747 1017
Email: treasureappraisal@gmail.com
Reg No: 53218791A



VEHICLE ASSESSMENT REPORT

Report No : T-HD-180123/8446M
Date : 29-Jan-18

REFERENCE

Assigned By : Wee Chee Keong
Name of Workshop : Hendon Automotive Pte Ltd
Place of Inspection : 280 Woodlands Industrial Park E5 #01-19 Harvest @ Woodlands Singapore 757322
Date of Assignment : 23-Jan-18
Date of Accident : 21-Jan-18
Date of Inspection : 23-Jan-18

PARTICULARS OF DAMAGED VEHICLE

Vehicle Reg No	: SGN 8446 M	Chassis No	: RN61015175
Year of Reg	: Nov-06	Odometer/km	: 172709
Make/Model	: Honda Stream	Engine No	: R18A1717179
Vehicle Colour	: Black	Engine Capacity	: 1799 cc
Vehicle Type	: MPV	Transmission Type	: Auto

PRE-ACCIDENT CONDITION OF VEHICLE (STATIC TESTS ONLY)

General Condition	: Good		
Body Paint Work	: Good	Footbrake	: Serviceable
Steering	: Serviceable	Handbrake	: Serviceable
Front Undercarriage	: Serviceable	Rear Undercarriage	: Serviceable

TIRES CONDITION	Tire Brand	Size	Tread Balance
Front RH	: Bridgestone	: 225/40 R18	: 80%
Rear RH	: Bridgestone	: 225/40 R18	: 80%
Front LH	: Bridgestone	: 225/40 R18	: 80%
Rear LH	: Bridgestone	: 225/40 R18	: 80%

Road Wheels Type : Sport Rim

Note: The above percentages represent the estimated remaining balance of the tire treads in mm.

* Denotes damaged components.

SYNOPSIS OF DAMAGES

At the time of survey, we noted that the vehicle has sustained an impact damages on the rear portions.

For further detail of the damages, please refer to our schedule and 122 pcs of surveyed photograph attached.

Treasure Appraisal Services

9 Joo Chiat Place Singapore 427743
HP: (65) 9833 1818 Fax: (65) 6747 1017
Email: treasureappraisal@gmail.com
Reg No: 53218791A



RECOMMENDATIONS

We referred to your instruction to appraise the above vehicle SGN 8446 M on 23-Jan-18 and in the accordance, we have carried out a physical assessment at your appointed workshop.

A static inspection was carried out and report is enclosed for your reference. The estimated repair cost submitted by the repairer for SGD 13,251.92 as per attached schedule has been scrutinised and revised by us against the actual damages found on the vehicle and we recommended the replacements and rectifications accordingly.

The repair cost has been revised to SGD 10,972.00 and therefore in the consideration of the repairer giving a further 20% even discount, it was agreed that the repairs to be carried out at a contractual lump sum of SGD 8,800.00 nett.

In such event, the repairer shall has the prerogative to either use new, OEM, re-conditioned parts and/or repair any damaged body parts that the repairer is confident and capable of repairing as long as the vehicle is put on the road in its pre-accident and road worthy condition and to the entire satisfaction of the owner.

Under normal circumstances, the estimated period of repairs is **Seven (7)** working days.

Pursuant to your instructions, we have NOT AUTHORISED to carry out the repairs on your behalf and we are submitting this report for your consideration.

This survey and/or appraisalment was carried out to the best of our knowledge, ability and on a "STRICTLY WITHOUT PREJUDICE" basis to any party concern.

We are reverting the matter to you for your discretion.

Yours Truly,
Treasure Appraisal Services



Dixon Yee T W
Automobile Appraiser

The revised estimate was made from a visual inspection. Any discrepancies or unseen damage/s should be notified to the company within Fourteen (14) days from the date thereof. Otherwise, the revised amount should deem to be valid.

This report is strictly confidential and is given for the use of client and their authorised assigned agent and any disclosure or publication of it or part or whole shall be the responsibility of such person and no liability shall be attached to TREASURE APPRAISAL SERVICES thereof.

Treasure Appraisal Services

9 Joo Chiat Place Singapore 427743
HP: (65) 9833 1818 Fax: (65) 6747 1017
Email: treasureappraisal@gmail.com
Reg No: 53218791A



APPRAISEMENT SCHEDULE

Vehicle Registration No: SGN 8446 M

Report No: T-HD-180123/8446M

S/N	Descriptions	Condition	Qty	Repairer's Estimate	Our Assessment
LIST ITEMS					
1	Tailgate glass moulding	Necessary	1 pc	\$ 118.50	\$ 118.50
2	Tailgate panel	Damaged	1 pc	\$ 1,285.00	\$ 1,285.00
3	Tailgate RH damper	Damaged	1 pc	\$ 149.00	\$ 149.00 X
4	Tailgate LH damper	Damaged	1 pc	\$ 149.00	\$ 149.00 X
5	Tailgate RH hinge	Damaged	1 pc	\$ 65.00	\$ 65.00 X
6	Tailgate LH hinge	Damaged	1 pc	\$ 65.00	\$ 65.00 X
7	Tailgate outer garnish	Reusable	1 pc	\$ 189.00	\$ -
8	Tailgate outer handle	Reusable	1 pc	\$ 153.40	\$ -
9	Tailgate "H" emblem	Necessary	1 pc	\$ 42.50	\$ 42.50
10	Tailgate number plate lamp	Reusable	2 pcs	\$ 45.00	\$ -
11	Tailgate "STREAM" emblem	Necessary	1 pc	\$ 68.50	\$ 68.50
12	Tailgate lock assy	Damaged	1 pc	\$ 303.20	\$ 303.20
13	Tailgate lock striker	Damaged	1 pc	\$ 65.00	\$ 65.00 X NN
14	Tailgate trim board	Damaged	1 pc	\$ 489.50	\$ 489.50
15	Tailgate pull pocket	Missing	1 pc	\$ 82.60	\$ 82.60 X NN
16	Tailgate weather strip	Damaged	1 pc	\$ 186.60	\$ 186.60
17	LH tail lamp assy	Damaged	1 pc	\$ 585.90	\$ 585.90
18	LH tail lamp bolt cover	Necessary	1 pc	\$ 12.50	\$ 12.50
19	LH tail lamp panel	Repaired	1 pc	\$ 325.00	\$ -
20	RH tail lamp assy	Damaged	1 pc	\$ 585.90	\$ 585.90
21	RH tail lamp bolt cover	Necessary	1 pc	\$ 12.50	\$ 12.50
22	RH tail lamp panel	Repaired	1 pc	\$ 325.00	\$ -
23	Rear bumper towing cover	Damaged	1 pc	\$ 42.50	\$ 42.50
24	Rear RH bumper side retainer	Damaged	1 pc	\$ 48.50	\$ 48.50 X NN
25	Rear LH bumper side retainer	Damaged	1 pc	\$ 48.50	\$ 48.50
26	Rear bumper lower support bracket	Damaged	2 pcs	\$ 111.80	\$ 111.80
27	Rear end outer panel	Damaged	1 pc	\$ 685.00	\$ 685.00
28	Rear end panel inner member	Damaged	1 pc	\$ 559.00	\$ 559.00 repair
29	Rear end panel garnish	Damaged	1 pc	\$ 189.50	\$ 189.50
30	Rear spare tire carrier	Damaged	1 pc	\$ 326.50	\$ 326.50 repair
				\$ 7,314.90	\$ 6,277.50
Less Discount : 20%				\$ 1,462.98	\$ 1,255.50
List Parts Sub-Total :				\$ 5,851.92	\$ 5,022.00
SPECIAL NETT ITEMS					
1	Rear fibre bumper sport cover	Damaged	1 pc	\$ 1,500.00	\$ 1,500.00 700
2	Reverse sensor assy	Damaged	1 set	\$ 350.00	\$ 280.00 220
3	Reverse camera assy	Damaged	1 set	\$ 450.00	\$ 350.00 X NN
4	Tailgate glass sealant	Necessary	1 pc	\$ 150.00	\$ 120.00 60
5	Tailgate glass inner foam tape	Necessary	1 pc	\$ 120.00	\$ 100.00 60
6	Spare wheel tire and rim	Reusable	1 pc	\$ 250.00	\$ -
Special Nett Parts Total :				\$ 2,820.00	\$ 2,350.00 1040

Treasure Appraisal Services

9 Joo Chiat Place Singapore 427743

HP: (65) 9833 1818 Fax: (65) 6747 1017

Email: treasureappraisal@gmail.com

Reg No: 53218791A



Parts Total :

\$ 8,671.92

\$ 7,372.00

S/N	Labour Descriptions	Repairer's Estimate	Our Assessment
1	To furnish towing service to workshop.	\$ 150.00	\$ 60.00 X MN
2	Diagnose, replace and/or repair to rectify rear electrical system for proper functioning.	\$ 60.00	\$ 40.00 /
3	Transfer boot lid / tailgate mechanism and wiring assy to facilitate body repairs.	\$ 150.00	\$ 80.00 60
4	Dismantle, replace and/or re-install reverse sensor assy and rectify for proper functioning.	\$ 150.00	\$ 80.00 60
5	Dismantle, replace and/or re-install reverse camera assy and rectify for proper functioning.	\$ 150.00	\$ 120.00 60
6	Dismantle replace and/or re-install rear windscreen / tailgate glass assy to facilitate body repairs.	\$ 150.00	\$ 120.00 /
7	Dismantle and re-install rear interior upholstery; trimming and garnish/es to facilitate body repairs.	\$ 200.00	\$ 180.00 80
8	To carry out accident body repairs; dismantle vehicle body part/s, dismember affected damaged body panel/s, replace and/or repair, re-construction, weld to re-join and re-align vehicle body structures to pre-accident condition.	\$ 1,500.00	\$ 1,300.00 800
9	Dismantle, replace, repair and/or re-install boot lid or tailgate spoiler assy including sealant.	\$ 150.00	\$ 120.00 60
10	To furnish, putty, sanding, masking, prepare paint mixture & toning, complete cleaning, spray paint, polishing and waxing on affected areas.	\$ 1,500.00	\$ 1,200.00 800
11	To furnish and apply under-sealing & rust proofing coats on accident affected area.	\$ 300.00	\$ 240.00 100
12	Conduct water leakage tests to ensure proper air and water sealing.	\$ 120.00	\$ 60.00 30
Labour Total :		\$ 4,580.00	\$ 3,600.00 2210
Parts & Labour Total :		\$ 13,251.92	\$ 10,972.00

Note: The repairer has agreed to undertake the repairs at our adjusted amount of SGD 8,800.00 on a *Contractual Lump Sum Basis corresponding to supply of all parts, labour and spray painting charges.

Treasure Appraisal Services

9 Joo Chiat Place Singapore 427743

HP: (65) 9833 1618 Fax: (65) 6747 1017

Email: treasureappraisal@gmail.com

Reg No: 53218791A



N.B: *Under Contractual Lump Sum Basis, the repairer shall has the prerogative to either use new, OEM, re-conditioned parts and/or repair any damaged body parts that the repairer is confident and capable of repairing as long as the vehicle is put on the road in its pre-accident and road worthy condition and to the entire satisfaction of the owner.

Under normal circumstances, the estimated period of repairs is **Seven (7)** working days. Pursuant to your instruction, we have NOT AUTHORISED the repairs on your behalf.

Treasure Appraisal Services



Automobile Appraiser

3814.32

1040.00

2210.00

7064.32

20%

5,651.45

45-5,650

6 days

...CLAIM SUBFOLDER...(Pending for Survey Report)






































PRI






































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	29 Mar 2018 Edit Reg		27 Mar 2018 00:00 Edit Adj Rpt	\$5,650.00 Edit Estimates	\$5,650.00 View Rpt		Pending for Survey Report Cancel Case




































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	Leong Mun Heng , ID: S0869179G								
Main Claimant:	WEE CHEE KEONG (HUANG ZHIQIANG) , ID: S7614712A								
Vehicle Reg. No.:	SGN8446M	Date of Loss:	21/01/2018 10:00 - :59 [133 Months and 23 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 9648749510SG	Policy/Cover Note No.:	(Comprehensive) Coverage: 31/01/2017 - 30/01/2018						
Vehicle Reg. No. (Insured):	SLK7930U	Policy No. (Claimant):							
		Excess:							
Repairer:	Hendon Automotive (HQ) 280 WOODLANDS INDUSTRIAL PARK ES, #01-19 HARVEST @ WOODLANDS, 757322 Woodlands - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Wui, Shawn-KJ] Shawnkaijye.Wui@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 09/04/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (29/03/2018): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGN8446M (9648749510SG)
[SLK7930U]
TP
WEE CHEE KEONG (HUANG ZHIQIANG)
Jan 21 2018 10:00AM
[Leong Mun Heng]
Hendon Automotive

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Photos/Images															3 per page		<input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print	
1	28/03/18 19:40	Odometer Reading														Load JPG	<input checked="" type="checkbox"/>	
2	28/03/18 19:40	Chassis Number														Load JPG	<input checked="" type="checkbox"/>	
3	28/03/18 19:40	General View														Load JPG	<input checked="" type="checkbox"/>	
4	28/03/18 19:40	General View														Load JPG	<input checked="" type="checkbox"/>	
5	28/03/18 19:40	General View														Load JPG	<input checked="" type="checkbox"/>	
6	28/03/18 19:40	General View														Load JPG	<input checked="" type="checkbox"/>	
7	28/03/18 19:40	General View														Load JPG	<input checked="" type="checkbox"/>	
8	28/03/18 19:40	General View														Load JPG	<input checked="" type="checkbox"/>	
9	28/03/18 19:40	General View														Load JPG	<input checked="" type="checkbox"/>	
10	28/03/18 19:40	General View														Load JPG	<input checked="" type="checkbox"/>	
11	28/03/18 19:40	General View														Load JPG	<input checked="" type="checkbox"/>	
12	28/03/18 19:40	General View														Load JPG	<input checked="" type="checkbox"/>	
13	28/03/18 19:40	General View														Load JPG	<input checked="" type="checkbox"/>	
14	28/03/18 19:40	General View														Load JPG	<input checked="" type="checkbox"/>	
15	28/03/18 19:40	General View														Load JPG	<input checked="" type="checkbox"/>	
16	28/03/18 19:40	General View														Load JPG	<input checked="" type="checkbox"/>	
17	28/03/18 19:40	General View														Load JPG	<input checked="" type="checkbox"/>	
18	28/03/18 19:40	General View														Load JPG	<input checked="" type="checkbox"/>	
19	28/03/18 19:40	General View														Load JPG	<input checked="" type="checkbox"/>	
20	28/03/18 19:40	General View														Load JPG	<input checked="" type="checkbox"/>	
21	28/03/18 19:40	General View														Load JPG	<input checked="" type="checkbox"/>	
22	28/03/18 19:40	General View														Load JPG	<input checked="" type="checkbox"/>	
23	28/03/18 19:40	General View														Load JPG	<input checked="" type="checkbox"/>	
24	28/03/18 19:40	General View														Load JPG	<input checked="" type="checkbox"/>	
25	28/03/18 19:40	General View														Load JPG	<input checked="" type="checkbox"/>	
26	28/03/18 19:40	General View														Load JPG	<input checked="" type="checkbox"/>	
27	28/03/18 19:40	General View														Load JPG	<input checked="" type="checkbox"/>	
28	28/03/18 19:40	General View														Load JPG	<input checked="" type="checkbox"/>	
29	28/03/18 19:40	General View														Load JPG	<input checked="" type="checkbox"/>	
30	28/03/18 19:40	General View														Load JPG	<input checked="" type="checkbox"/>	
31	28/03/18 19:40	General View														Load JPG	<input checked="" type="checkbox"/>	
32	28/03/18 19:40	General View														Load JPG	<input checked="" type="checkbox"/>	
33	28/03/18 19:40	General View														Load JPG	<input checked="" type="checkbox"/>	
34	28/03/18 19:40	General View														Load JPG	<input checked="" type="checkbox"/>	
35	28/03/18 19:40	General View														Load JPG	<input checked="" type="checkbox"/>	
36	28/03/18 19:40	General View														Load JPG	<input checked="" type="checkbox"/>	
37	28/03/18 19:40	General View														Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	28/03/18 19:40	General View	 Load JPG	<input checked="" type="checkbox"/>
39	28/03/18 19:40	General View	 Load JPG	<input checked="" type="checkbox"/>
40	28/03/18 19:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	28/03/18 19:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	28/03/18 19:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	28/03/18 19:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	28/03/18 19:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	28/03/18 19:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	28/03/18 19:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	28/03/18 19:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	28/03/18 19:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	28/03/18 19:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	28/03/18 19:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	28/03/18 19:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	28/03/18 19:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	28/03/18 19:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	28/03/18 19:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	28/03/18 19:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	28/03/18 19:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	28/03/18 19:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	28/03/18 19:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	28/03/18 19:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	28/03/18 19:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	28/03/18 19:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	28/03/18 19:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	28/03/18 19:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	28/03/18 19:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	28/03/18 19:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	28/03/18 19:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	28/03/18 19:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	28/03/18 19:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	28/03/18 19:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	28/03/18 19:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	28/03/18 19:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	28/03/18 19:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	28/03/18 19:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	28/03/18 19:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	28/03/18 19:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	28/03/18 19:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	28/03/18 19:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	28/03/18 19:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	28/03/18 19:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	28/03/18 19:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	28/03/18 19:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	28/03/18 19:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	28/03/18 19:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	28/03/18 19:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	28/03/18 19:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	28/03/18 19:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	28/03/18 19:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	28/03/18 19:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	28/03/18 19:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	28/03/18 19:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
91	28/03/18 19:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
92	28/03/18 19:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
93	28/03/18 19:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
94	28/03/18 19:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
95	28/03/18 19:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
96	28/03/18 19:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
97	28/03/18 19:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
98	28/03/18 19:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
99	28/03/18 19:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
100	28/03/18 19:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
101	28/03/18 19:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
102	28/03/18 19:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
103	28/03/18 19:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
104	28/03/18 19:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
105	28/03/18 19:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
106	28/03/18 19:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
107	28/03/18 19:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
108	28/03/18 19:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
109	28/03/18 19:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
110	28/03/18 19:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
111	28/03/18 19:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
112	28/03/18 19:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
113	28/03/18 19:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
114	28/03/18 19:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
115	28/03/18 19:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
116	28/03/18 19:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
117	28/03/18 19:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
118	28/03/18 19:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
119	28/03/18 19:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
120	28/03/18 19:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
121	28/03/18 19:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/07/18 10:09	PHOTO	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	29/03/18 11:02	OI GIA Report	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg No. 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18001365/T1QD3E2

Date: 06/07/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SGN8446M

Insured Vehicle No : SLK7930U

Date of Loss: 21/01/2018

Nature of Claim: TP

Claim No: 9648749510SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGN8446M

Make & Model: HONDA STREAM, 1.8 (A)

Engine No: R18A1717179

Reg. Date: 29/11/2006 (Man. Year: 2006)

Chassis No: RN61015175

Colour: Black

Odometer: 175986 km

Engine Capacity: 1799 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40 R18

Rear Tyre Size:

225/40 R18

Front Left Side: Bridgestone 6 mm

Rear Left Side:

Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side:

Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,671.92	4,854.32	3,817.60	44.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,580.00	2,210.00	2,370.00	51.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,251.92	7,064.32	6,187.60	46.69
Approved Total (Overridden) (S\$)		5,650.00		
Nett Amount (S\$)	13,251.92	5,650.00	7,601.92	57.36

INSPECTION

Date of Assignment: 27/03/2018

Date Inspected: 10/04/2018 Inspected At:

67 Home Avenue #08-03 (S) 598744

Repairer : Hendon Automotive (HQ)

Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE GLASS MOULDING	Replaced	118.50 FL	*118.50 FL
2	1		*TAILGATE PANEL	Replaced	1,285.00 FL	*1,285.00 FL
3	1		*TAILGATE RH DAMPER	Not Necessary	149.00 FL	*- FL
4	1		*TAILGATE LH DAMPER	Not Necessary	149.00 FL	*- FL
5	1		*TAILGATE RH HINGE	Not Necessary	65.00 FL	*- FL
6	1		*TAILGATE LH HINGE	Not Necessary	65.00 FL	*- FL
7	1		*TAILGATE OUTER GARNISH	Reusable	189.00 FL	*- FL
8	1		*TAILGATE OUTER HANDLE	Reusable	153.40 FL	*- FL
9	1		*TAILGATE H EMBLEM	Replaced	42.50 FL	*42.50 FL
10	2		*TAILGATE NUMBER PLATE LAMP	Reusable	45.00 FL	*- FL
11	1		*TAILGATE STREAM EMBLEM	Replaced	68.50 FL	*68.50 FL
12	1		*TAILGATE LOCK ASSY	Replaced	303.20 FL	*303.20 FL
13	1		*TAILGATE LOCK STRIKER	Not Necessary	65.00 FL	*- FL
14	1		*TAILGATE TRIM BOARD	Replaced	489.50 FL	*489.50 FL
15	1		*TAILGATE PULL POCKET	Not Necessary	82.60 FL	*- FL
16	1		*TAILGATE WEATHER STRIP	Replaced	186.60 FL	*186.60 FL
17	1		*LH TAIL LAMP ASSY	Replaced	585.90 FL	*585.90 FL
18	1		*LH TAIL LAMP BOLT COVER	Replaced	12.50 FL	*12.50 FL
19	1		*LH TAIL LAMP PANEL	Repaired	325.00 FL	*- FL
20	1		*RH TAIL LAMP ASSY	Replaced	585.90 FL	*585.90 FL
21	1		*RH TAIL LAMP BOLT COVER	Replaced	12.50 FL	*12.50 FL
22	1		*RH TAIL LAMP PANEL	Repaired	325.00 FL	*- FL
23	1		*REAR BUMPER TOWING COVER	Replaced	42.50 FL	*42.50 FL
24	1		*REAR RH BUMPER SIDE RETAINER	Not Necessary	48.50 FL	*- FL
25	1		*REAR LH BUMPER SIDE RETAINER	Replaced	48.50 FL	*48.50 FL
26	2		*REAR BUMPER LOWER SUPPORT BRACKET	Replaced	111.80 FL	*111.80 FL
27	1		*REAR END OUTER PANEL	Replaced	685.00 FL	*685.00 FL
28	1		*REAR END PANEL INNER MEMBER	Repaired	559.00 FL	*- FL
29	1		*REAR END PANEL GARNISH	Replaced	189.50 FL	*189.50 FL
30	1		*REAR SPARE TIRE CARRIER	Repaired	326.50 FL	*- FL
31	1		*REAR FIBRE BUMPER SPORT COVER	Replaced	1,500.00 FS	*700.00 FS
32	1		*SET REVERSE SENSOR ASSY	Replaced	350.00 FS	*220.00 FS
33	1		*SET REVERSE CAMERA ASSY	Not Necessary	450.00 FS	*- FS
34	1		*TAILGATE GLASS SEALANT	Replaced	150.00 FS	*60.00 FS
35	1		*TAILGATE GLASS INNER FOAM TAPE	Replaced	120.00 FS	*60.00 FS
36	1		*SPARE WHEEL TIRE AND RIM	Reusable	250.00 FS	*- FS

F=Franchise part. S=SpcNett L=ListItemDisc

Sub Total (\$\$)	10,134.90	5,807.90
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,462.98	953.58

Total Parts (\$\$)	8,671.92	4,854.32
--------------------	----------	----------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO FURNISH TOWING SERVICE TO WORKSHOP	New	150.00	0.00
2	DIAGNOSE, REPLACE AND / OR REPAIR TO RECTIFY REAR ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	60.00	40.00
3	TRANSFER BOOT LID / TAILGATE MECHANISM AND WIRING ASSY TO FACILITATE BODY REPAIRS	New	150.00	60.00
4	DISMANTLE, REPLACE AND / OR RE-INSTALL REVERSE SENSOR ASSY AND RECTIFY FOR PROPER FUNCTIONING	New	150.00	60.00
5	DISMANTLE, REPLACE AND / OR RE-INSTALL REVERSE CAMERA ASSY AND RECTIFY FOR PROPER FUNCTIONING	New	150.00	60.00
6	DISMANTLE AND RE-INSTALL REAR INTERIOR UPHOLSTERY; TRIMMING AND GARNISH / ES TO FACILITATE BODY REPAIRS	New	200.00	80.00
7	TO CARRY OUT ACCIDENT BODY REPAIRS; DISMANTLE VEHICLE BODY PART/S, DISMEMBER AFFECTED DAMAGED BODY PANEL/S, REPLACE AND / OR REPAIR, RE-CONSTRUCTION, WELD TO RE-JOIN AND RE-ALIGN VEHICLE BODY STRUCTURES TO PRE-ACCIDENT CONDITION	New	1,500.00	800.00
8	DISMANTLE, REPLACE, REPAIR AND / OR RE-INSTALL BOOT LID OR TAILGATE SPOILER ASSY INCLUDING SEALANT	New	150.00	60.00
9	TO FURNISH, PUTTY, SANDING, MASKING, PREPARE PAINT MIXTURE & TONING, COMPLETE CLEANING, SPRAY PAINT, POLISHING AND WAXING ON AFFECTED AREAS	New	1,500.00	800.00
10	TO FURNISH AND APPLY UNDER-SEALING & RUST PROOFING COATS ON ACCIDENT AFFECTED AREA	New	300.00	100.00
11	CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND WATER SEALING	New	120.00	30.00
12	DISMANTLE REPLACE AND / OR RE-INSTALL REAR WINDSCREEN / TAILGATE GLASS ASSY TO FACILITATE BODY REPAIRS	New	150.00	120.00
Gross Labour Cost (S\$)			4,580.00	2,210.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >