







# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC3/AIG18001371/K1hs3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 23-01-2018	
		Code : AIG	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SKS 6934K	Veh. Inspected	SHA 2986S
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	23/01/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer		Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	21/01/2018	Inspection Date	22/01/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

# COMFORTDELGRO ENGINEERING

member of COMFORTDELGRO

Date/Time: 22.01.2018 14:26 Page : 1

am: ARC Repair TP(CLSO)1

**JOB CARD** Sales Order:

JC NO.305109204

OMER  
S COMFORT TRANSPORTATION PTE LTD  
OMER NO 7010045  
ESS 383 SIN MING DRIVE  
Singapore SINGAPORE 575717  
65508755

REGN NO SHA2986S	MILEAGE
MAKE HYUNDAI	FUEL E 1/2 F
MODEL I-40	DATE/TIME IN 22.01.2018 09:15
YR OF MANU 29.03.2014	TARGET DATE
CHASSIS CODE KMHLB41UMEU052352	COMPLETION DATE/TIME

UNT CARD NO.

## JOB DESCRIPTION

ccident Date: 21.01.2018  
ATURE: 3P 21.01.18/C

/NO LABOR CODE DESCRIPTION

CKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

No.: SHA2986S LIMITS

Vehicle No.: SHA2986S

f Service Advisor

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

To be kept by Security Guard

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO : SHA 2986S

DATE 22/1/2018

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Wheel Hup-Cap (RH) ✓			\$ 150.70 ✓
	Rear Fender (RH) x 2986S			
	SUB TOTAL			\$ 150.70
	LESS 20%			\$ 30.14
	DISCOUNTED TOTAL			\$ 120.56
	Rear Bumper Advertisement Logo ✓			\$ 50.00 Nett ✓
	Rear Fender Advertisement Logo (LH/RH) LHx RH ✓	\$	100.00	\$ 200.00 Nett
	Rear Door Advertisement Logo (RH) ✓			\$ 100.00 Nett ✓
	Rear Door Comfortdelgro & Apps Sticker (RH) ✓			\$ 80.00 Nett ✓
	Front Door Coloured Comfort Logo (RH) x			\$ 75.00 Nett
	Front Door Advertisement Logo (RH) x			\$ 100.00 Nett
	Front Fender Advertisement Logo (RH) x			\$ 100.00 Nett
				\$ 705.00
	<b>Labour Charge</b>			
	Panel Beating			\$ <del>350.00</del> <sup>200</sup>
	Spray Painting Charge			\$ <del>1,000.00</del> <sup>180</sup>
	Tuff Kote			\$ <del>50.00</del> x
	Rear Wheel Alignment			\$ <del>120.00</del> x
	TOTAL LABOUR			\$ 1,520.00
	ESTIMATE TOTAL			\$ 2,345.56

Kalin 16/1/18  
 22/1/18 1500hrs  
 2 Days  
 4/5  
 After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without prejudice" basis
- No legal liability is accepted
- Survey must be resurveyed and is subject to approval from Insurance Company

Acc: \_\_\_\_\_  
 S: \_\_\_\_\_  
 De: \_\_\_\_\_

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

# COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

Our Job Ref No : 305109204

Date : 25/01/18

## FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN ANG

Vehicle Reg No. : SHA2986S

Date of Accident : 21-Jan-18

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: AIG ASIA --- SKS6934K

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

**Total for Part-By-Part Repair Cost**

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20% \$650.00

**Final Lumpsum Repair cost \$650.00**

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : LIM T S

Signature : KALVIN

Name : LIM T S

Name : KALVIN

Tel : 62148398

Date : 25/1/18

Fax : 65468156

## For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees	-----			
4. LTA Search Fee				
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO : SHA 2986S

DATE 22/1/2018

MAKE :

MODEL : HYUNDAI i40

LKK - Kalvin

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Wheel Hup-Cap (RH) <i>X rep</i>			\$ 150.70	
	<i>Rear Fender (RH) X rep</i>			\$ 150.70	
	<i>Door Bump (RH) X rep</i>			\$ 30.14	
	SUB TOTAL			\$ 120.56	
	LESS 20%				
	DISCOUNTED TOTAL				
	Rear Bumper Advertisement Logo <i>X</i>			\$ 50.00	Nett
	Rear Fender Advertisement Logo (LH/RH) <i>LHX RHV</i>		\$ 100.00	\$ 200.00	Nett
	Rear Door Advertisement Logo (RH) <i>/</i>			\$ 100.00	Nett
	Rear Door Comfortdelgro & Apps Sticker (RH) <i>/</i>			\$ 80.00	Nett
	Front Door Coloured Comfort Logo (RH) <i>X</i>			\$ 75.00	Nett
	Front Door Advertisement Logo (RH) <i>X</i>			\$ 100.00	Nett
	Front Fender Advertisement Logo (RH) <i>X</i>			\$ 100.00	Nett
				\$ 705.00	
	Labour Charge				
	Panel Beating			\$ 350.00	<i>360</i>
	Spray Painting Charge			\$ 1,000.00	<i>1000</i>
	Tuff Kote			\$ 50.00	<i>X</i>
	Rear Wheel Alignment			\$ 120.00	<i>X</i>
	TOTAL LABOUR			\$ 1,520.00	
	ESTIMATE TOTAL			\$ 2,345.56	

Kalvin 16/1/18  
 22/1/18 1500hrs  
 2 Days  
 L/S  
 After Repair photo

LKK Auto Consultants hereby notify the Repairer of the following:

- To reserve & restore after spray painting
- To display damaged part during survey
- Parts prices are subject to confirmation
- Third party liability on a "without prejudice" basis
- No other work to be carried out
- Survey must be surveyed and removed from Insurance Company

Acc: \_\_\_\_\_  
 Sig: \_\_\_\_\_  
 Date: \_\_\_\_\_

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Our Ref : T 0118 / SHA2986S /CL(st)  
Your Ref:  
Date : 12-Feb-18

**AIG ASIA PACIFIC INSURANCE PTE LTD**  
**CHARTIS Buliding**  
**78 Shenton Way**  
**#07-16**  
**Singapore 079120**

**Attn : Motor Claims Department WITHOUT PREJUDICE**

Dear Sir

**ACCIDENT INVOLVING OUR TAXI SHA2986S YOUR INSURED SKS6934K**  
**AND OTHER ON 21.01.18**

We are the authorised repair workshop for Comfort Transportation Pte Ltd, the owner of motor Vehicle No : **SHA2986S** which was involved in the captioned accident with your insured vehicle. The vehicle owner and the taxi driver concerned have requested and authorized us to assist them in presenting their claims against the party responsible for all applicable matters arising from the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving **SKS6934K** we are submitting these claim for your consideration on behalf of the claimants.

#### TAXI OWNER'S CLAIM

1	Cost of Repair	\$ 695.50
2	3 days Loss of Rental @ \$ 129.28 per day	\$ 387.84
3	Survey Report Fees (Surveyed by M/s LKK)	\$ -
4	GIA / LTA Search Fees	\$ 7.49
5	GIA / Police Report Fees	\$ -
6	Towing / Medical / Transportation	\$ -
<b>Sub Total :</b>		<b>\$ 1,090.83</b>

#### HIRER'S CLAIM

7	3 days Loss of Income @ \$ 80.00 per days	\$ 240.00
<b>Total Claims :</b>		<b>\$ 1,330.83</b>

We enclosed herewith the following documents to support the claims: -

- a) Original repair bill and photocopies of photographs : 10 pcs.  
b) LTA search slip/s of : SKS6934K  
c) GIA / Police report/s of : SHA2986S  
d) Letter of authority from owner / hirer / operator  
( X ) Photograph/s of Accident Scene ( ) Certificate of Insurance  
( ) Witness statement/s ( x ) Downtime/Mileage record

Kindly look into the matter and let us hear from you on the settlement of the said claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours faithfully

Cecilia Lee

Executive

CDGE Claims Department

Tel : 6214 8354 Fax: 6214 1843 Email : cecilialee@sparkcarcare.com

This is a computer generated letter. No signature is required.

CDGE Taxi Claims Dept  
59 Loyang Drive 4th Floor  
Singapore 508969

ComfortDelGro Engineering Pte Ltd  
205 Braddell Road Singapore 579701

Mainline +65 6383 6280  
Facsimile +65 6280 9755

www.cdge.com.sg

Company Registration No: 199506548W

#### Workshops

**Braddell**  
205 Braddell Road  
Singapore 579701

**Loyang**  
59 Loyang Drive  
Singapore 508969

**Sin Ming**  
383 Sin Ming Drive  
Singapore 575717

**Pandan**  
45 Pandan Road  
Singapore 608285

**Ubi**  
320 Ubi Road 3  
Singapore 408649

**Senoko**  
24 Senoko Loop  
Singapore 758156

**Sungei Kadut**  
7 Sungei Kadut Way  
Singapore 725791

**Yishun**  
501 Yishun Industrial Park A  
Singapore 768732





Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

**Our Ref: CC3/AIG18001371/K1hs3**

29 JANUARY 2018

**ANG AIK KOON**  
BLK 55 CHAI CHEE DRIVE  
#02-212  
SINGAPORE 460055

Dear Sir/Madam,

**ACCIDENT INVOLVING SKS 6934K / SHA 2986S / OTHERS ON 21.01.2018**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

You are aware that your No-Claim Discount (NCD – if applicable) will be with held for the time being. Pending for final allocation of liability in settlement by our principal AIG Asia Pacific Insurance Pte Ltd.

Please call us if you have further queries.

Yours faithfully,

Siti Jaafar  
Case Handler  
DID: 6256 3561  
FAX: 6741 4108  
Email: [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com)

c.c. AIG Asia Pacific Insurance Pte Ltd  
(Motor Claims Dept)

## LETTER OF AUTHORISATION

(NAE / PAF)

ACCIDENT INVOLVING i 40 SHA2986S , SK56934K , UNKNOWN ON 21-Jan-18 14:35  
ALONG ECP TWDS AIRPORT B4 MARINE VISTA EXIT

I / We **TAN PHUAY HONG** (Hirer) NRIC No.: **S0279910C**

and/or (Relief) NRIC No.:

Taxi Number **SHA2986S**

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
3. To sign Discharge Voucher on my/our behalf.
4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of **"ComfortDelGro Engineering Pte Ltd"**.

Date **22-Jan-2018**

Name of Hirer **TAN PHUAY HONG**  
Hirer NRIC **S0279910C**

Signature :



Address **210 SERANGOON CENTRAL #02-262**  
**550210**

Contact No. **96375371**

**RELEASE VOUCHER**  
**(AIG Asia Pacific - Express Third Party Claim)**

"We/I, **COMFORTDELGRO ENGINEERING PTE LTD** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$1,150.00** (Global Sum) for vehicle no. **SHA 2986S** that was damaged pursuant to the accident which occurred on **21/01/2018** (date) along **ECP > CHANGI AIRPORT B4 MARINE VISTA EXIT** (location) involving vehicle no/s **SKS 6934K**.

This is pursuant to the inspection conducted on **22/01/2018** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **COMFORT TRANSPORTATION PTE LTD** ("the third party claimant") of vehicle no. **SHA 2986S** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SHA 2986S** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 12 (day) of March (month) 2019 (year)



**AWK**

Signed by appointed surveyor

  
AILEEN TAN  
Manager, Claims

Signed by "the workshop" (with chop)

CLAIMS DEPARTMENT  
COMFORTDELGRO ENGINEERING PTE LTD  
55 LOYANG DRIVE  
SINGAPORE 639955

"The contents of this document apply to vehicle damages only.  
All personal injuries and damages arising therefrom are excluded  
from the ambit and application of this document"

Please forward your cheque made payable to:  
**COMFORTDELGRO ENGINEERING PTE LTD**

## TAX INVOICE

8010004

AIG ASIA PACIFIC INSURANCE PTE LTD

#08-16 78 SHENTON WAY, CHARTIS BUILD  
SINGAPORE 079120

CONTACT NO: 64193000 3225094

VEHICLE NO  
SHA2986S

MAKE  
HYUNDAI

MODEL  
I-40

DATE OF REG  
29.03.2014

CHASSIS CODE  
KMHLB41UMEU052352

INV. NO/DATE  
91354516 30.01.2018

JOB NO.  
305109204

ODOMETER READING

JOB TYPE

Description : 3P 21.01.18

### Invoice for Lump Sum Repair

Total Lump Sum Repair Amt	650.00
Add GST @ 7.000 %	45.50
<b>Total Invoice amount</b>	<b>695.50</b>

Issued by : CHEWBEELING 30.01.2018 11:50:53  
Repair Type : CLSO/57/57  
Payment Type/Term : /Credit 30 days

ComfortDelGro Engineering Pte Ltd  
A member of COMFORTDELGRO

Head Office:  
205 Braddell Road  
Singapore 579701

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.

Our Ref: CT18010625

Date: 29 January 2018



**TO WHOM IT MAY CONCERN**

Dear Sir/Madam

ACCIDENT ON	21/01/2018 @ 14:35 hrs
ALONG	ECP > CHANGHI AIRPORT B4 MARINE VISTA EXIT
INVOLVING	SKS6934K, UNKNOWN

We refer to the above-mentioned accident and wish to inform that **Comfort Transportation Pte Ltd** is the registered owner of the taxi bearing vehicle registration number **SHA2986S** (the "Taxi"). The Taxi was hired to **TAN PHUAY HONG IC NO S0279910C** a registered hirer-operator of **Comfort Transportation Pte Ltd** at the time of occurrence of the aforementioned accident at a rental rate **\$129.28** per day (inclusive of GST).

Please be advised that the Taxi was insured with **First Capital Insurance Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay  
Executive, Fleet Safety

This is a computer generated letter. No signature is required.

DATE	NAME OF DRIVER	MILEAGE READING	MILEAGE TRAVELLED (KM)	HOURS OPERATED (TIME)		DATE	NAME OF DRIVER
				FROM	TO		
16-01-18	P-H Tan	40785-9	268	07.00	17.30		
17-01-18	P-H Tan	408177	318	07.15	18.15		
18-01-18	P-H Tan	408427	250	07.00	18.00		
19-01-18	P-H Tan	408677	250	07.00	20.00		
20-01-18	P-H Tan	408937	260	03.45	18.15		
21-01-18	P-H Tan	409197	260	07.00	18.30		
22-01-18	P-H Tan	409317	120	07.00	09.30		
22/1	Accident			0915	/		
24/1	repair	121		/	1245		

Erasmus

SIA 25865

## Enquire Vehicle Insurer

Vehicle No.	Incident Date/Time	Search Status	Insurance Company Code	Insurance Company Name
SKS6934K	21 Jan 2018 / 14:35:00	Successful	A04	AIG ASIA PACIFIC INSURANCE PTE. LTD.

Previous

OK

# Thank you



Goh Cheng Chuan Andrew Cornelius has successfully logged out.

Your last login date and time was 22 Jan 2018, 12:01:27.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

## Session Transaction History

<u>S/No.</u>	<u>Asset Type</u>	<u>Asset ID</u>	<u>Asset Owner ID</u>	<u>Transaction Type</u>	<u>Transaction Amount(S\$)</u>	<u>Log Date/Time</u>
1	Vehicle	SK56934K	-	18.32 Insurance Enquiry (GIRO Payment)	7.49	22 Jan 2018 / 12:02:04



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

## CLAIM SUBFOLDER TRACKING



Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Jan 2018 <a href="#">Edit Reg</a>		22 Jan 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$650.00</b> <a href="#">Edit Estimates</a>	<b>S\$650.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span>[Created by adjuster]</span>									
Insured:	<b>Ang Aik Koon (Hong YiKun)</b> , ID: S7324354H								
Main Claimant:	<b>COMFORT TRANSPORTATION PTE LTD</b> , Co. Reg. No.: 199303821R								
Vehicle Reg. No.:	<b>SHA2986S</b>	Date of Loss:	21/01/2018 00:00 - :59 [45 Months and 23 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 3004001928SG</b>	Policy/Cover Note No.:	2100410644 (Comprehensive) Coverage: 30/04/2017 - 29/04/2018						
Vehicle Reg. No. (Insured):	<b>SKS6934K</b>	Policy No. (Claimant):	D-18088936MFSH						
		Excess:							
Repairer:	<b>ComfortDelGro Engineering Pte Ltd (Loyang)</b> 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300								
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Lee, Ming-Yao</b> ] MingYao.Lee@aig.com								
Claimant's Insurer:	<b>MS First Capital Insurance Ltd (HQ)</b> - Tel: 62222311								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>KALVIN ANG WEI KUN</b> ] ... [Final Rpt due 01/02/2018]								
<b>ASSOCIATED MAIL RECEIVED</b> <span><a href="#">View All</a></span> <span><a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span><a href="#">View All</a></span> <span><a href="#">Search Tasks</a></span> <span><a href="#">Create New Task</a></span> <span><a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SHA2986S (3004001928SG)  
[SKS6934K]  
TP  
COMFORT TRANSPORTATION PTE LTD  
Jan 21 2018 12:00AM  
[Ang Aik Koon (Hong YiKun)]  
ComfortDelGro Engineering Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Video															1 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>		
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)												Thumbnail		Print				
1	27/02/18 09:34	Video - Accident <small>From:OO - Reg. No: SKS6934K, Claimant: ANG AIK KOON</small>													Load AVI					
2	27/02/18 09:42	Singapore - Video - Accident													Load AVI					
Letters/Correspondences															1 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print				
1	(Draft)	Third Party Express Settlement - Payment Breakdown													Edit					
Assessment Reports															1 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>		
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)												Thumbnail		Print				
1	24/01/18 12:15	Accident Statement <small>From:OO - Reg. No: SKS6934K, Claimant: ANG AIK KOON</small>													Load HTM					
Photos/Images															3 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print				
1	23/01/18 17:47	General View													Load JPG		<input checked="" type="checkbox"/>			
2	23/01/18 17:47	General View													Load JPG		<input checked="" type="checkbox"/>			
3	23/01/18 17:47	General View													Load JPG		<input checked="" type="checkbox"/>			
4	23/01/18 17:47	General View													Load JPG		<input checked="" type="checkbox"/>			
5	23/01/18 17:47	General View													Load JPG		<input checked="" type="checkbox"/>			
6	23/01/18 17:47	General View													Load JPG		<input checked="" type="checkbox"/>			
7	23/01/18 17:47	General View													Load JPG		<input checked="" type="checkbox"/>			
8	23/01/18 17:47	General View													Load JPG		<input checked="" type="checkbox"/>			
9	23/01/18 17:47	General View													Load JPG		<input checked="" type="checkbox"/>			
10	23/01/18 17:47	General View													Load JPG		<input checked="" type="checkbox"/>			
11	23/01/18 17:47	General View													Load JPG		<input checked="" type="checkbox"/>			
12	23/01/18 17:47	General View													Load JPG		<input checked="" type="checkbox"/>			
13	23/01/18 17:47	General View													Load JPG		<input checked="" type="checkbox"/>			
14	23/01/18 17:47	General View													Load JPG		<input checked="" type="checkbox"/>			
15	23/01/18 17:47	General View													Load JPG		<input checked="" type="checkbox"/>			
16	23/01/18 17:47	General View													Load JPG		<input checked="" type="checkbox"/>			
17	23/01/18 17:47	General View													Load JPG		<input checked="" type="checkbox"/>			
18	23/01/18 17:47	General View													Load JPG		<input checked="" type="checkbox"/>			
19	23/01/18 17:47	General View													Load JPG		<input checked="" type="checkbox"/>			
20	23/01/18 17:47	General View													Load JPG		<input checked="" type="checkbox"/>			
21	23/01/18 17:47	General View													Load JPG		<input checked="" type="checkbox"/>			
22	23/01/18 17:47	General View													Load JPG		<input checked="" type="checkbox"/>			
23	23/01/18 17:47	General View													Load JPG		<input checked="" type="checkbox"/>			
24	25/01/18 17:41	Reinspection Photo													Load JPG		<input checked="" type="checkbox"/>			
25	25/01/18 17:41	Reinspection Photo													Load JPG		<input checked="" type="checkbox"/>			

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
26	25/01/18 17:41	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/01/18 15:34	TP GIA REPORT	 Load PDF	
2	23/01/18 15:34	TP ESTIMATE- MARKED	 Load PDF	
3	29/01/18 08:50	LETTER TO OI	 Load PDF	
4	15/03/19 12:29	WORKSHOP INVOICE	 Load PDF	
5	15/03/19 12:29	AUTHORISATION TO ACT FORM	 Load PDF	
6	15/03/19 12:29	Release Voucher	 Load PDF	
7	15/03/19 12:29	RENTAL MILEAGE	 Load PDF	
8	15/03/19 12:29	RENTAL RECEIPT	 Load PDF	
9	15/03/19 12:29	LTA SEARCH	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	25/01/18 10:48	TP GIA From: TP - Reg. No: SLL5783K, Claimant: Blue Star Concierge Pte Ltd	 Load PDF	
2	25/01/18 10:48	SKU5073R - 1st Vehicle From: TP - Reg. No: SLL5783K, Claimant: Blue Star Concierge Pte Ltd	 Load PDF	
3	25/01/18 10:48	SGN5323D - 2nd Vehicle From: TP - Reg. No: SLL5783K, Claimant: Blue Star Concierge Pte Ltd	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKS6934K (Insd veh)	Model:	HYUNDAI I40 1.7 D CRDI F/L
	SHA2986S (TP veh)		AT ABS AIRBAG 4DR (M)
Date of Accident:	21/01/2018		

Global Sum Settlement	: <input checked="" type="checkbox"/> [ X ] Yes	<input type="checkbox"/> [ ] No
Repair Estimate	: \$	2,509.75
Final Repair Cost	: \$	1,150.00
Loss of Use	: \$	2.50 days at \$50.00 per day
Rental (if any)	: \$	2.50 days
LTA / GIA Search Fee	: \$	
Others:	: \$	
	: \$	
Final Settlement Sum (Global Sum)	: \$	1,150.00

**Is Third Party Workshop GIA Registered?** ☒ [ X ] YES ☐ [ ] NO (Kindly indicate below)

**A) For Non GIA Registered Workshop:** Agreed Liability \_\_\_\_\_ (%)

**B) For GIA Registered Workshop:** BOLA Applicable: ~~Yes~~/ No BOLA Scenario No: \_\_\_\_\_

NIL

BOLA Liability: \_\_\_\_\_ 100 \_\_\_\_\_ (%) Assessed Liability (\*): \_\_\_\_\_ (%)

\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks \_\_\_\_\_

Payment Instruction: Payee's Breakdown			
1)	ComfortDelGro Engineering Pte Ltd	: \$	1,150.00
2)		: \$	
3)		: \$	
4)		: \$	
5)		: \$	

JOANNE LEE KHANG MIN

15 Mar  
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

# LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18001371/K1HB3Q2

Date: 15/03/2019

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 2100410644

Claimant Vehicle No: SHA2986S

Insured Vehicle No: SKS6934K

Date of Loss: 21/01/2018

Nature of Claim: TP

Claim No: 3004001928SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHA2986S

Make &amp; Model: HYUNDAI I40, 1.7 D CRDI F/L AT ABS AIRBAG 4DR (M)

Engine No: D4FDEU410036

Reg. Date: 29/03/2014 (Man. Year: 2014)

Chassis No: KMHLB41UMEU052352

Colour: Blue

Odometer: 409405 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: West Lake 7 mm

Rear Left Side: West Lake 7 mm

Front Right Side: West Lake 7 mm

Rear Right Side: West Lake 7 mm

The above values represent the remaining tyre treads depth

### COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	825.56	280.00	545.56	66.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,520.00	560.00	960.00	63.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>2,345.56</b>	<b>840.00</b>	<b>1,505.56</b>	<b>64.19</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>650.00</b>		
(S\$)	2,345.56	650.00	1,695.56	72.29
<b>+ GST 7.00/7.00% (S\$)</b>	164.19	45.50	118.69	72.29
<b>Nett Amount (S\$)</b>	<b>2,509.75</b>	<b>695.50</b>	<b>1,814.25</b>	<b>72.29</b>
<b>+ Loss of Use (2.5 x S\$50.00/day) (S\$)</b>		125.00		
<b>+ Car Rental (2.5 x S\$129.28/day) (S\$)</b>		323.20		
<b>+ Doc/Search Fee (S\$)</b>		7.49		
<b>Nett Liability (S\$)</b>		<b>1,151.19</b>		
<b>Global Sum Settlement (S\$)</b>		<b>1,150.00</b>		

### INSPECTION

Date of Assignment: 22/01/2018  
Date Inspected: 22/01/2018 Inspected At: ComfortDelGro Engineering Pte Ltd  
(Loyang)  
59 Loyang Drive  
Singapore 508969  
Estimated Period of Repair: 2.0 days

---

**Adjuster:** KALVIN ANG WEI KUN

**Manager:** VIC ALPEH

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WHEEL HUP-CAP (RH)	Repair	150.70 FL	*- FL
2	1		*REAR FENDER (RH) (NPA)	Repair	0.00 FL	*- FL
3	1		*DOOR REAR (RH) (NPA)	Repair	0.00 FL	*- FL
4	1		*REAR BUMPER ADVERTISEMENT LOGO	Not Necessary	50.00 FS	*- FS
5	1		*REAR FENDER ADVERTISEMENT LOGO (LH/RH)	N/S Not Necessary/O/SNecessary	200.00 FS	*100.00 FS
6	1		*REAR DOOR ADVERTISEMENT LOGO (RH)	Necessary	100.00 FS	*100.00 FS
7	1		*REAR DOOR COMFORTDELGRO & APPS STICKER (RH)	Necessary	80.00 FS	*80.00 FS
8	1		*FRONT DOOR COLOURED COMFORT LOGO (RH)	Not Necessary	75.00 FS	*- FS
9	1		*FRONT DOOR ADVERTISEMENT LOGO (RH)	Not Necessary	100.00 FS	*- FS
10	1		*FRONT FENDER ADVERTISEMENT LOGO (RH)	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>855.70</b>	<b>280.00</b>
<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	<b>30.14</b>	<b>0.00</b>
<b>Total Parts (S\$)</b>	<b>825.56</b>	<b>280.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	350.00	200.00
2	SPRAY PAINTING CHARGE	New	1,000.00	360.00
3	TUFF KOTE	New	50.00	0.00
4	REAR WHEEL ALIGNMENT	New	120.00	0.00
Gross Labour Cost (S\$)			1,520.00	560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >