

EDIT	SIR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT
<input type="checkbox"/>	1		PANEL BEATING	200	0	0	Reviewing	
<input type="checkbox"/>	2		SPRAY PAINTING CHARGE	180	0	0	Reviewing	

Yes No

Save

Detailed Assessment

Inspection Date *

01/22/2018



Total Loss

Yes No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Fair

Steering (Serviceable)

Yes No

Footbrake (Serviceable)

Yes No

Handbrake (Serviceable)

Yes No

Engine Modification

Yes No

Pre-accident condition

Good

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

205/60R16

Rear Tyre Size

205/60R16

FNOL INFORMATI... BLK 441 CHOA CHU KANG, 680441,
Singapore

POST SURVEY INF...

CATEGORY Address type

FNOL INFORMATI... Personal Correspondence

POST SURVEY INF...

CATEGORY Gender

FNOL INFORMATI... Male

POST SURVEY INF...

CATEGORY Marital status

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Identification #

FNOL INFORMATI... S1463528I

CATEGORY Make

POLICY INFORMAT... AUDI

CATEGORY Date of Birth

ASSESSMENT INFO... HYUNDAI

FNOL INFORMATI... June 3, 1961

CATEGORY Model

POST SURVEY INF... 

POLICY INFORMAT... A6 AVANT 3.0 TFSI

CATEGORY Age

ASSESSMENT INFO... I40 1.7 CRDI F/L AT ABS AIRBAG 4DR

FNOL INFORMATI... 56

CATEGORY Type

POST SURVEY INF...

POLICY INFORMAT...

CATEGORY Occupation

ASSESSMENT INFO...

FNOL INFORMATI... Unknown

CATEGORY Type of Paint

POST SURVEY INF...

POLICY INFORMAT...

CATEGORY Education Qualification

ASSESSMENT INFO...

FNOL INFORMATI... Other

CATEGORY Chassis No

POST SURVEY INF...

POLICY INFORMAT... WAUZZZ4G5CN082501

CATEGORY Driving Experience

Pending verification -
Direct Settlement

Claim Handler

NG Stacey
6568804351
stacey.ng@axa.com.sg

Messages Invoices History Documents

Assessment Metrics Notes

Additional Instructions

CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE
NG Stacey	1/23/18 3:40 PM	1619	1619	Open	<input type="button" value="Share"/>	<input type="button" value="Clone"/>

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
EMAIL FROM CDGE TO AXA.pdf	Letters and Correspondence	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	January 24, 2018
EMAIL RECEIVED FROM WORKSHOP INCLUDING ESTIAMTE & SH6693T TP GIA.msg	Letters and Correspondence	Workshop	NIKAM Santosh Pandurang	January 22, 2018
NEW EMAIL.msg	Letters and Correspondence	Others	PATIL Amol	January 22, 2018
SH6693T TP GIA.PDF	Forms / Claim Documents	Claim Form	PATIL Amol	January 18, 2018
SBY358M INSD GIA.PDF	Forms / Claim Documents	Claim Form	PATIL Amol	January 18, 2018

Pending verification -
Direct Settlement

Claim Handler

NG Stacey
6568804351
stacey.ng@axa.com.sg

Messages Invoices History Documents

Assessment Metrics Notes

Document Type

Document SubType

Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
------	------	----------	--------	---------------

Accident Statement	Reports & Statement		Merimen	
--------------------	---------------------	--	---------	--

LTA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	May 7, 2018
----------------	-------------------------	--------	-----------------------------------	-------------

RENTAL RECEIPT.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	May 7, 2018
--------------------	-------------------------	--------	-----------------------------------	-------------