

SINGAPORE

Tanjong

REF:

AZH

ASSIGNMENT

From: _____ Date: 25-01-2018

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SKW 1965H

at Workshop mis

Cham's Customcraft

of

Bike 1010 Bukit Merah Lane 3 #01-105

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

230 pm - 430 pm

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____

Person Contacted: _____

Date / Time

Action / Instruction

Veh No:

SKW 1965H

Yr Regn:

2015 Oct

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Subaru Forester

CC

1995

Colour:

white

A/C

Insured / Std / NI / NA

Sp. Reading

42007

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JF/SJSKCSF9050417.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 225/60R17

R: ~ ~

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

25/1/18 @ 1525

Survey held at

Cham's Customcraft

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time File Pass to?

☐

: Preli. Report

1:

Date/Time File Return to?

☐

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

Add Fee:

☐

: Site Insp

\$

☐

: Interview

\$

☐

: Tech Insp

\$

☐

: Weekend

\$

Report Format:

Lump Sum / I.B.I. / S

Photos

Diagrams

TOTAL