

CWS Adrian ASSIGNMENT (Office)
 From (Person) Lurene Jaw of FCI Date/Time 24/1/18 @ 11:17 am
 Estimated Cost: _____ Bill to: _____
 OD: TP WS/TP RES / OD RES / EVA / INV / MV / CS
 To Inspect Vehicle No: SKG165S Insured: SHB 2437E
 at Workshop no: 96 Motorsports Tel: 90211096
 of 62764 Kaki Bkt Ave 6, 417893
 Policy No: _____ Claim No: D18000699MFSH
 Sum Insured: _____ Excess: _____
 Make of Veh: _____ D.O.A. 22/01/2018
 (Client's Record) _____
 CA / REV / REP. / REV 24 HRS lwp 25/01/2018
 Date/Time 12:17pm @ 24/1/18 Person Connected Alwyn Vehicle OUT
 Date/Time 24/01/18 Action/Inspection + SKG165S-X
SHB 2437E-NA/AIG/18001333/r3 D.O.A. 22/01/18
 30/1/18 Informed FCI pending est from repairer
 16/3/18 Adrian confirmed LS \$6500 (Red 7661.99, 54/10)
 19/3/18 Email preli revised to FCI

Adrian

REF:

FCI

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s 96 Motorsports
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

N/S	
O/S	

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$85k
 IDAC Accident Rpt.: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: 66K 1655 Yr Regn: 20 Feb 2016
 Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Toyota Altis cc 1598
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp. Reading: 59619 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: MR053 REH 104548084
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 205 / 55 R16
 R: 11
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: _____ Rear: _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 25-01-18
 Survey held at WS 12:30pm
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 9 FEB 2018

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time, File Return to?

2) 19/2 - typist

Report Format: CWS

Lump Sum / I.B.I: (\$) 6500k

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$) ☐ : Interview (\$) ☐ : Tech. Invs (\$) ☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Photos 050

Date 19/2/18

TOTAL

4x15 60

170+60

50

50

88

418

Survey Department Check List (Case Handler)

Reference No.: CS/F01/1800/427/Av03
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No				
C	Insurance Authorisation (CA /REV/REP)	✓			
C	Report Type				
C	Weekend Charges	✓			
N	Survey held at/Repairer				
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)	✓			
C	Days of repair	✓			
C	Finalised Amount				
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By:

VERON

19/3/18

Case Handler

Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18001427/Avd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 24-01-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 2437E	Veh. Inspected	SGK 165S
Policy No.		Coverage (\$)	0.00
Claim No.	D18000699MFSH	Excess (\$)	0.00
Assign From	CWS (LURENE JAW)	Assign Date	24/01/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	22/01/2018	Inspection Date	
Survey held at	96 MOTORSPORTS PTE LTD 62/64 KAKI BUKIT AVENUE 6 SINGAPORE 417893 ARK @ KB		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	23-01-2018	Our Ref No. D18000699MFSH
Accident Date	22-01-2018	Claim Type. Third Party
Insured Vehicle	SHB2437E	Third Party Vehicle. SGK165S
Survey Location	62 & 64 Kaki Bukit Avenue 6 ARK@KB Singapore 417893	
Contact Person.	ALWYN	
Contact No.	90211096/ 90211096	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	96 MOTORSPORTS PTE LTD	Attention. NIL
Cc : TP Solicitor	KURU & CO	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/234196)



PRI Documents



Close



PRI Header Details

Claim No	D18000699MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & KURU & C
Workshop Name	96 MOTORSPORTS PTE LTD (Contact Person : ALWYN)	Survey Location & Contact Details	62 & 64 Kaki Bukit Avenue 6 ARK@KB Singapore 41789: Mobile: 90211096 , Phone: 90211096 , Fax: 0 EmailId: KURULEGAL@YAHOO.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHB2437E	TP Vehicle No	SGK165S
PRI Recieved Date	23-01-2018 04:47:05 PM	Surveyor Appointed Date	24-01-2018 11:16:12 AM	Surveyor Accept Date	24-01-2018 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	24-01-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 19 March 2018 11:55 AM
To: 'Claim Workflow System'
Cc: 'LURENEJAW@MSFIRSTCAPITAL.COM.SG'; SUR
Subject: RE: SURVEY ASSESSMENT - D18000699MFSH/1, SGK 165S
Attachments: SGK 165S PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SGK 165S
Date of survey: 25/1/2018
Number of days:5 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 30 January 2018 8:44 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18000699MFSH/1, SGK 165S

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SGK 165S on 25/1/2018

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler




LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 24 January 2018 12:19 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18000699MFSH/1

Dear Sir/Mdm,



Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]

Sent: Wednesday, 24 January 2018 11:17 AM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG

Subject: PRI: SURVEY ASSESSMENT - D18000699MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System




Motor Claims Department

First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.





Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18000699MFSH
Our ref: CS/FCI18001427/Avd3

Date : 19/3/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SGK 165S


We thank you for your instruction on 24/1/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 25/1/2018 at the premises of M/s 96 MOTORSPORTS PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$14,161.99
Revised Estimate Amount	: S\$8,137.12
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:




The vehicle sustained damages at the front portion.



Comments/Present Status:
Damages Consistent

Yours faithfully,

ADRIAN LING WAI PING
B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI
Licensed Appraiser



Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 30 January 2018 8:44 AM
To: 'Claim Workflow System'
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18000699MFSH/1, SGK 165S

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SGK 165S on 25/1/2018

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 24 January 2018 12:19 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18000699MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 24 January 2018 11:17 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18000699MFSH/1



Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.


Kindly submit your report via CWS within the next 14 days.

Best Regards,



Admin Team
Claim Workflow System
Motor Claims Department
First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	9360I

Vehicle Details

Vehicle No.:	SGK1655
Vehicle to be Exported:	No
Intended De-registration Date:	29 Jan 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS CLASSIC 1.6 CVT
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	1ZRX559993
Chassis No.:	MR053REH104548084
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$17,982.00
Original Registration Date:	24 Feb 2016
First Registration Date:	24 Feb 2016
Transfer Count:	0
Actual ARF Paid:	\$17,982.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Feb 2026
PARF Rebate Amount:	\$13,486.00

Intended COE Rebate Details

COE Expiry Date:	23 Feb 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,651.00
COE Rebate Amount:	\$37,665.00
Total Rebate Amount:	\$51,151.00

The information contained herein is correct as at 29 Jan 2018

OK

▶ altis Used Vehicle List (20 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availability
Toyota Corolla Altis 1.6A Elegance	\$85,800	\$9,500 /yr	27-Jan-2016	1,598 cc	34,015 km	The Car Enthusiast Pte Ltd	Available
1 Owner! Only! Guarantee Not Grab/Uber Unit! Borneo Servicing And 5 Years Warranty! Low Mileage Done, Elegance Model! Keyless Entry, Push Start System! Minimum Down Payment With Bank Or In House Loan A...							
Office No. - 66848470 Pan - 91010990 Sebastian Ng - 96828212							
Toyota Corolla Altis 1.6A	\$85,800	\$9,550 /yr	15-Feb-2016	1,598 cc	31,700 km	Republic Auto	Available
Complimentary 1 Year Republic Auto Maintenance Package, Fully Serviced & Maintained By Borneo Motors, 5 Years Warranty By Borneo Motors, COE Value \$51,301, Loan Interest Rate At 2.78%, Call/ SMS Cleme...							
Office No. - 65672000 Clement Fok - 81683206							
Toyota Corolla Altis 1.6A Elegance	\$85,100	\$9,300 /yr	04-Mar-2016	1,598 cc	27,464 km	New Way Leasing Pte Ltd	Available
5 Years Agent Warranty, Full Agent Service Record. Owner Consignment, Please Call To Arrange For Appointment Before Coming.							
Office No. - 62622030 Hao - 98279436 Vincent - 98295005							
Toyota Corolla Altis 1.6A Elegance	\$91,800	\$10,090 /yr	15-Mar-2016	1,598 cc	41,800 km	Mandal Motor Trading	Available
Tip Top Condition, 5 Years Warranty By Borneo Motors, Fuel Efficient And Easy Handling, Loan Available, Trade In Welcome. Price Negotiable, Call Or Visit Our Showroom Now For Viewing Now!							
Office No. - 67775585 David - 93860705 Kelvin - 93874964 Ms Li Jin - 97548093 Mr Liu - 97855422							
Toyota Corolla Altis 1.6A Elegance	\$83,500	\$8,960 /yr	19-Apr-2016	1,598 cc	27,000 km		Available
Bought In June 17 From My Friend. Full Agent Service. 5 Years Warranty. Park Under Shelter, Ceramic Paintwork Coating. Selling Due To Upgrade. Membership And Extra Credits With Agent That Can Offset A...							
Office No. - - Cw - 96554047							
Toyota Corolla Altis 1.6A Elegance	\$89,360	\$9,650 /yr	27-Apr-2016	1,598 cc	30,000 km	Excel Motoring	Available
Warranty And Serviced By Borneo! High OMV Value! One Owner! One Of The Most Reliable Fuel Efficiency Japanese Made Sedan Model To Own In Town! Genuine Low Mileage Done! Good As Brand New! Low Deprecia...							
Office No. - 67626693 James - 97995575 Dan - 98975978 Eric - 91811549							
Toyota Corolla Altis 1.6A Elegance	\$86,800	\$9,320 /yr	04-May-2016	1,598 cc	40,000 km	Auto Nexus Pte Ltd	Available
Pristine Pearl White Beauty. Elegant Cream Interior, Elegance Model With Smart Key Functions, DVD Player With Built-In GPS, Driver Power Seats And More! Full Original Condition And Warranty From Borneo...							
Office No. - 67433722 Kelvin - 90707779							
Toyota Corolla Altis 1.6A Elegance	\$91,800	\$9,920 /yr	05-May-2016	1,598 cc	25,000 km	Platinum Auto	Available
1 Ownership, 100% Accident Free, Fully Serviced At Borneo Motors With 5 Years Warranty, Like Brand New Car, High PARF Value Of \$9,795. High Loan Available, Please Call For Viewing.							
Office No. - 63864184 Richard - 98173682 Shawn - 90494620 Jackson - 97735487 Vincent C - 84821530							
Toyota Corolla Altis 1.6A	\$90,000	\$9,690 /yr	09-May-2016	1,598 cc	29,800 km	Carro	Available
Accident Free, New Battery. Changed Tires And Rims.							
Office No. - 67146652 Jace - 81394200							
Toyota Corolla Altis 1.6A Elegance	\$91,700	\$9,800 /yr	30-May-2016	1,598 cc	31,000 km	Seng Lee Hong Vehicle Trading	Available
Elegant And Sporty Grey Elegance Model With Day Running Light! Only 1 Owner With Very Low Mileage Done! Under Warranty! Full Service History With Borneo Motors! High PARF Value At \$10000. Buy With A P...							
Office No. - 64672802 Kevin Soo - 97976757 Neo Lam Lee - 96202802							
Toyota Corolla Altis 1.6A	\$90,800	\$9,690 /yr	08-Jun-2016	1,598 cc	20,106 km	Ace Automobile	Available

96 motorsports PTE LTD

62 & 64 Kaki Bukit Ave 6, (S) 417893, Ark@KB

Tel: 6702 6996

Fax: 6384 6996

Email: admin@96motorsports.com

MROS3REH104548084

Vehicle number: SGK165S

Vehicle Made & Model: TOYOTA ALTIS

TP 1st Cap Versa

Qty	List Items	Amount \$
1	Front bonnet <i>Distorted.</i>	1,028.10 ✓
1	Front bonnet seal <i>new</i>	62.60 +
1	Front bonnet insulator <i>new</i>	189.90 +
8	Front bonnet insulator clips @ 5.50 <i>new</i>	44.00 +
2	Front bonnet hinges @ 58.50 <i>new</i>	117.00 +
1	Front bonnet lock <i>new</i>	128.90 +
1	Front bonnet lock cable <i>Not new</i>	89.60 +
1	Front bumper <i>Distorted</i>	510.60 ✓
1	Front bumper CTR grille <i>separated</i>	142.60 ✓
2	Front bumper fog lamps - L/R @ 289.80 <i>2 new</i>	579.60 +
2	Front bumper fog lamp cover - L/R @ 88.95 <i>new</i>	177.90 +
1	Front bumper sponge <i>2hd</i>	187.30 ✓
1	Front bumper reinforcement <i>Best</i>	497.60 <i>386.60</i>
2	Front bumper side retainers - L/R @ 81.76 <i>new</i>	163.52 ✓
10	Front bumper clips @ 4.50 <i>new</i>	45.00 <i>30</i>
1	Front bumper undercover <i>new</i>	146.60 +
2	Front fenders - L/R @ 621.20 <i>Repair</i>	1,242.40 +
2	Front fender emblem "VVT-I" @ 32.20 <i>new</i>	64.40 ✓
2	Front fender inner shields - L/R @ 169.30 <i>2 new</i>	338.60 +
30	Front fender inner shield clips @ 4.50 <i>new</i>	135.00 +
1	Front grille assy <i>Cracked</i>	599.60 <i>537.80</i>
1	Front grille top garnish <i>new</i>	82.20 +
5	Front grille top garnish clips @ 4.50 <i>new</i>	22.50 +
2	Front headlamps - L/R @ 1026.50 <i>Cracked</i>	2,053.00 ✓
2	Front headlamp lower brackets - L/R @ 48.20 <i>new</i>	96.40 +
2	Front headlamp top mouldings - L/R @ 141.20 <i>new</i>	282.40 +
1	Front support panel assy <i>Repair</i>	872.30 +
1	Air con condenser <i>Best</i>	1,474.50 ✓
1	Radiator assy <i>Dented</i>	1,764.40 ✓
1	Radiator top support garnish <i>new</i>	89.90 +
1	Radiator top hose <i>2 new</i>	48.60 +
1	Radiator bottom hose	59.20 +

Vehicle number: SGK165S

Vehicle Make & Model: TOYOTA ALTIS

1	Radiator fan cowl	8342.82	214.73*
1	Radiator fan blade	6257.11	176.42*
1	Radiator fan motor		481.95*
Sub-total			14,209.32
Less 25%			3,552.33
Total List			10,656.99

Special Nett Items

1 set	Front no. plate	60.00-50
1 bot	Air con oil	65.00-40
1 bot	Radiator coolant	60.00-40
Total Special Nett		185.00

Labour charges

Towing charges	100.00 *
To remove, refix A/C condenser & refill A/C gas	150.00-120
To check front electrical wiring	50.00-30
To respray undercoating	120.00 *
To respray painting and etc	1,400.00-800
Panel beating, cut, weld remove & replacing above parts	1,500.00-800
Total Labour	3,320.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$

14,161.99

LKK Auto Consultants hence notify the Repairs of the following:

- To remove and replace spray painting
- To remove and replace during resurvey
- To remove and replace to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Signature: _____
Date: _____

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18001427/Avd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 19-03-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 2437E	Veh. Inspected	SGK 165S	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18000699MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	24/01/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ALTIS	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	MR053REH104548084	Colour	SILVER	
Odometer	59619	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	PIRELLI	6 mm	
L/H Front Tyre	205/55 R16	PIRELLI	6 mm	
R/H Rear Tyre	205/55 R16	PIRELLI	6 mm	
L/H Rear Tyre	205/55 R16	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/01/2018	Inspection Date	25/01/2018	
Survey held at	96 MOTORSPORTS PTE LTD 62/64 KAKI BUKIT AVENUE 6 SINGAPORE 417893 ARK @ KB			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGK 165S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BONNET	DISTORTED	1,028.10	1,028.10
1	FRONT BONNET SEAL	NOT NECESSARY	62.60	-
1	FRONT BONNET INSULATOR	NOT NECESSARY	189.90	-
8	FRONT BONNET INSULATOR CLIPS @\$5.50	NOT NECESSARY	44.00	-
2	FRONT BONNET HINGES @\$58.50	NOT NECESSARY	117.00	-
1	FRONT BONNET LOCK	NOT NECESSARY	128.90	-
1	FRONT BONNET LOCK CABLE	NOT NECESSARY	89.60	-
1	FRONT BUMPER	DISTORTED	510.60	510.60
1	FRONT BUMPER CTR GRILLE	DEFORMED	142.60	142.60
2	FRONT BUMPER FOG LAMPS-L/R @\$289.80	NOT NECESSARY	579.60	-
2	FRONT BUMPER FOG LAMP COVER-L/R @\$88.95	NOT NECESSARY	177.90	-
1	FRONT BUMPER SPONGE	DEFORMED	187.30	187.30
1	FRONT BUMPER REINFORCEMENT	BENT	497.60	386.60
2	FRONT BUMPER SIDE RETAINERS-L/R @\$81.76	NECESSARY	163.52	163.52
10	FRONT BUMPER CLIPS @\$4.50	NECESSARY	45.00	30.00
1	FRONT BUMPER UNDERCOVER	NOT NECESSARY	146.60	-
2	FRONT FENDERS-L/R @\$621.20	TO REPAIR SEE LABOUR	1,242.40	-
2	FRONT FENDER EMBLEM "VVT-I" @\$32.20	NECESSARY	64.40	64.40
2	FRONT FENDER INNER SHIELDS-L/R @\$169.30	NOT NECESSARY	338.60	-
30	FRONT FENDER INNER SHIELD CLIPS @\$4.50	NOT NECESSARY	135.00	-
1	FRONT GRILLE ASSY	CRACKED	599.60	537.80
1	FRONT GRILLE TOP GARNISH	NOT NECESSARY	82.20	-
5	FRONT GRILLE TOP GARNISH CLIPS @\$4.50	NOT NECESSARY	22.50	-
2	FRONT HEADLAMPS-L/R @\$1026.50	CRACKED	2,053.00	2,053.00
2	FRONT HEADLAMP LOWER BRACKETS-L/R @\$48.20	NOT NECESSARY	96.40	-
2	FRONT HEADLAMP TOP MOULDINGS-L/R @\$141.20	NOT NECESSARY	282.40	-
1	FRONT SUPPORT PANEL ASSY	TO REPAIR SEE LABOUR	872.30	-
1	AIR CON CONDENSER	BENT	1,474.50	1,474.50
1	RADIATOR ASSY	DENTED	1,764.40	1,764.40

Report Ref No. CS/FCI18001427/Avd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RADIATOR TOP SUPPORT GARNISH	NOT NECESSARY	89.90	-
1	RADIATOR TOP HOSE	NOT NECESSARY	48.60	-
1	RADIATOR BOTTOM HOSE	NOT NECESSARY	59.20	-
1	RADIATOR FAN COWLING	NOT NECESSARY	214.73	-
1	RADIATOR FAN BLADE	NOT NECESSARY	176.42	-
1	RADIATOR FAN MOTOR	NOT NECESSARY	481.95	-
	LESS 25% DISCOUNT		-3,552.33	-2,085.70
			10,656.99	6,257.12
	SPECIAL NETT ITEMS			
1	SET FRONT NO PLATE (SN)	BENT	60.00	50.00
1	BOT AIR CON OIL (SN)	NECESSARY	65.00	40.00
1	BOT RADIATOR COOLANT (SN)	NECESSARY	60.00	40.00
			185.00	130.00
	LABOUR			
	TOWING CHARGES.	NOT NECESSARY	100.00	-
	TO REMOVE,REFIX A/C CONDENSER & REFILL A/C GAS.		150.00	120.00
	TO CHECK FRONT ELECTRICAL WIRING.		50.00	30.00
	TO RESPRAY UNDERCOATING.	NOT NECESSARY	120.00	-
	TO RESPRAY PAINTING AND ETC.		1,400.00	800.00
	PANEL BEATING,CUT,WELD REMOVE & REPLACING ABOVE PARTS.INCLUSIVE OF THE REPAIR OF FRONT FENDERS-L/R AND FRONT SUPPORT PANEL ASSY.		1,500.00	800.00
			3,320.00	1,750.00
	GRAND TOTAL		14,161.99	8,137.12
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,500.00

Report Ref No. CS/FCI18001427/Avd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

