

ASSIGNMENT (Office)

Merimen

From/Person:

Muhamd Ashid

MSIG

Date/Time:

19/01/18 @ 4:52pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / EVV / MV / CS

To Inspect Vehicle No:

SJA 7308 L

Insured:

FBF 68492

at Workshop no:

Autobest Motor

Ref:

67456932

of Blk 3006, Ubi Rd 1 # 01-362

Policy No:

MSD LVMS / 17 / 369628

Claim No:

MSC/V / 18-006111

Sum Insured:

Excess:

Make of Veh:

D.O.A:

18/01/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

1wp

25/01/2018

MOD Estimated:

Date/Time:

9:35am @ 24/1/18

Person Conducted:

Mr. Lee

Vehicle IN/OUT

Date/Time	Action/Instructions (X) Estimate
	SJA 7308 L - X
	FBF 68492 -
	Dismantle Qud : 25.01.2018
	After repair : 31.01.2018

B.10.10.10

MURMEN

ASSIGNMENT

From

Date:

25/01/2018

Estimated Cost:

OD / ☒ WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SJA 7308L

at Workshop mis

Auto Best

of

3006 Ubi Rd 1 # 01-362

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S
X	

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SJA 7308L

Yr Regn:

25/5/2009.

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Altis

cc:

1598.

Colour:

Greenish Silver

A/C:

Insured / Std / NI / NA

Sp. Reading:

128314

T. Radio: Insured / Std / NI / NA

Eng. No:

C/No:

MR53ZEE106145744

Gen. Cond: Good ☒ Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / ☒ STD A/Rim or

Tyre Size:

F:

195/65 R15

R:

195/65 R15

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MITSUBISHI / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

3

mm

R/Bal.

4

mm

L/Bal.

3

mm

L/Bal.

4

mm

D.O.A.

18/1/2018

D.O.I.

25/1/2018

Survey held at

As Above

Des. of Damages: Frt ☒ Rear ☒ O/S / N/S / U/C / Rooftop or

Left Rear


The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Range \$3900 - \$4900

5 Days Repair

RECEIVED 09 APR 2018



9/4/2018

Date/Time File Pass to?

09/04/2018

☐

Preli. Report

☐

Final Report

Date/Time File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transportation

1 - 95 - 5

Photo

Chart

TOTAL

120

50

10

180

Report Format:

PRs.

Lump Sum / I.B. / I.S.

Add Fee:

☐

Site Insp. IS

☐

Interview IS

☐

Tech. Insp. IS

☐

Weekend IS

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Jan 2018		19 Jan 2018 16:52 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	LIM SIN MING, ID: S6980699F		
Main Claimant:	YEE GEOK ENG, ID: S1504826C		
Vehicle Reg. No.:	SJQ7308J	Date of Loss:	18/01/2018 08:00 - :59
Claim Type:	TP / MSC/V/18-000111	Policy/Cover Note No.:	MSD/VMS/17/369628-CA (TP, Fire & Theft) Coverage: 18/10/2017 - 17/10/2018
Vehicle Reg. No. (Insured):	FBF6849Z	Policy No. (Claimant):	
		Excess:	
Repairer:	Auto Best Motor Services (HQ) BLK 3006 UBI ROAD 1, #01-362, 408700 Ubi - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 20/01/2018]		
Driver/Custodian (Insured):	LOW KOK LENG (), NRIC: G8075754P, Tel: +6598826299		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/01/2018 11:11
Date Of Accident	18/01/2018 08:30
Exact Location Of Accident	PIE (CHANGI) BF JLN EUNOS EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJQ7308J
Insured/Policyholder	
Name Of Registered Owner	YEE GEOK ENG
NRIC No	S1504826C
Email Address	CORINE.YEE@JETSTATASIA.COM
Mobile Phone No	(LOCAL) +65-97483038
Alternative Phone No	OFFICE-97483038

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA 1.6 ALTIS
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	10502039
Cover Note Number	

Driver

Name of Driver	YEE GEOK ENG
NRIC No	S1504826C
Date Of Birth	11/01/1961
Occupation	INDOOR
Date Of Driving Pass	02/06/1989
Driving Experience	28 YEARS AND 7 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97483038
Fax Number	
Contact Number	OFFICE-97483038
Email Address	CORINE.YEE@JETSTATASIA.COM

Address	NA
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I slow down and stop due to the heavy traffic along pie toward changi, before eunos exit. Seconds later, Veh b hit against my left rear portion. My car was badly damage and no injury involved on my side.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBF6849Z
Vehicle Make/Model/Colour	HONDA/ANF125CR M
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	LOW KOK LENG
NRIC/Passport Number	G8075754P
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

Sketch Plan

IMPORTANT NOTICE

SKETCH PLAN

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
 - (a) I understand, acknowledge, agree and consent that:
 - (i) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 - (ii) collectively the "Purposes";
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


VERIFIED BY AJAX MARS
REPORTING OFFICER
MOHAMED SHARIL
B/N SATAR

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



ACCIDENT STATEMENT (2000 characters)

I slow down and stop due to the heavy traffic along pie toward changi, before eunos exit. Seconds later, Veh b hit against my left rear portion. My car was badly damage and no injury involved on my side.

Taxi Voucher No.:

Are you claiming your own insurance policy for the repair of your vehicle?

No, Claim 3rd party

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
MOHAMED SHARIL BIN SATAR

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

18 January, 2018 10:38 am

Date/Time:

18 January, 2018 10:38 am



































...CLAIM SUBFOLDER...(Pending for Survey Report)









































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Jan 2018		19 Jan 2018 16:52 Edit Adj Rpt	\$0.00 Edit Estimates	\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	LIM SIN MING , ID: S6980699F								
Main Claimant:	YEE GEOK ENG , ID: S1504826C								
Vehicle Reg. No.:	SJQ7308J	Date of Loss:	18/01/2018 08:00 - :59 [103 Months and 24 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MSC/V/18-000111	Policy/Cover Note No.:	MSD/VMS/17/369628-CA (TP, Fire & Theft) Coverage: 18/10/2017 - 17/10/2018						
Vehicle Reg. No. (Insured):	FBF6849Z	Policy No. (Claimant):							
		Excess:							
Repairer:	Auto Best Motor Services (HQ) BLK 3006 UBI ROAD 1, #01-362, 408700 Ubi - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Teo Cheng Ming Wilson] ... [Imm.Advice due 20/01/2018]								
Driver/Custodian (Insured):	LOW KOK LENG (), NRIC: G8075754P, Tel: +6598826299								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJQ7308J (MSC/V/18-000111)
 [FBF6849Z]
 TP
 YEE GEOK ENG
 Jan 18 2018 8:00AM
 [LIM SIN MING]
 Auto Best Motor Services

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No.	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	19/01/18 16:17	Accident Statement From: SC - Reg. No: FBF6849Z, Claimant: LIM SIN MING	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No.	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/04/18 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
2	09/04/18 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
3	09/04/18 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
4	09/04/18 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
5	09/04/18 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
6	09/04/18 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
7	09/04/18 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
8	09/04/18 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
9	09/04/18 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
10	09/04/18 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
11	09/04/18 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
12	09/04/18 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
13	09/04/18 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
14	09/04/18 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
15	09/04/18 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
16	09/04/18 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
17	09/04/18 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
18	09/04/18 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
19	09/04/18 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
20	09/04/18 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
21	09/04/18 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
22	09/04/18 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
23	09/04/18 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
24	09/04/18 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
25	09/04/18 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
26	09/04/18 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
27	09/04/18 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
28	09/04/18 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
29	09/04/18 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
30	09/04/18 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
31	09/04/18 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
32	09/04/18 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
33	09/04/18 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	09/04/18 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
35	09/04/18 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
36	09/04/18 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
37	09/04/18 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
38	09/04/18 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
39	09/04/18 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
40	09/04/18 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
41	09/04/18 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
42	09/04/18 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
43	09/04/18 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
44	09/04/18 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
45	09/04/18 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
46	09/04/18 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
47	09/04/18 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
48	09/04/18 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
49	09/04/18 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
50	09/04/18 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
51	09/04/18 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
52	09/04/18 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
53	09/04/18 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
54	09/04/18 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
55	09/04/18 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
56	09/04/18 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
57	09/04/18 16:32	General View	 Load JPG	<input checked="" type="checkbox"/>
58	09/04/18 16:33	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
59	09/04/18 16:33	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
60	09/04/18 16:33	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
61	09/04/18 16:33	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
62	09/04/18 16:33	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
63	09/04/18 16:33	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
64	09/04/18 16:33	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
65	09/04/18 16:33	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
66	09/04/18 16:33	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
67	09/04/18 16:33	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
68	09/04/18 16:33	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
69	09/04/18 16:33	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
70	09/04/18 16:33	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	19/01/18 16:17	SJQ7308J E-FILE REPORT From: SC - Reg. No: FBF6849Z, Claimant: LIM SIN MING	 Load PDF	
2	19/01/18 16:24	PRI from G S Lim & Partners	 Load PDF	
3	19/01/18 16:53	Survey Disagree on SJE - LKK	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18001429/WD3E2

Date: 10/04/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMS/17/369628-CA
Claimant Vehicle No :	SJQ7308J	Insured Vehicle No :	FBF6849Z
Date of Loss:	18/01/2018	Nature of Claim:	TP
		Claim No:	MSC/V/18-000111

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJQ7308J	Engine No:	3ZZ4890322
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053ZEE106145744
Reg. Date:	25/05/2009 (Man. Year: 2009)	Odometer:	128314 km
Colour:	Silver		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Michelin 3 mm	Rear Left Side:	Michelin 4 mm
Front Right Side:	Michelin 3 mm	Rear Right Side:	Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	19/01/2018		
Date Inspected:	25/01/2018	Inspected At:	Auto Best Motor Services (HQ) BLK 3006 UBI ROAD 1, #01-362 Singapore 408700
Estimated Period of Repair:	0.0 days		

Adjuster: Teo Cheng Ming Wilson

Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,900.00 - \$4,900.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Apr 2018)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJQ7308J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >