assum to Charles	446 U Db39 14KK
INS. CASE OWNER Shawi CC T/III18 Surveyor: Marcus Doi:	ASSIGNMENT Date / Tithe:
Pre-assign / CCU / FTE SHP 378 VQ Insured Vehicle No. CTPV	Claim No. : WOMOO 5
Insured Tel No. : HP: Excess Sec II :S\$ D.O.A : UY	Policy No. : Make / Model : Hyllword : Hyllword : Hyllword : Hyllword : Wes :
If NO, Driver Name / Age (V/LAYES/) Driver Tel No.: (V/LAYES/)	OI GIA REPORT YBS / NO : TP GIA REPORT: (YES) NO
INSRS: FOH WATER TEL: Liability: RMKS: WSP: Tel: Liability: RMKS: RMKS:	INSRS: WSP: Tel: Liability: RMKS: INSRS: WSP: Tel: Liability: RMKS:
Date/Time	STAGE DATE/PIC
WILLIS SIN MITTER	Non-Reporting lir (1st): Non-Reporting lir (Znd): Non-Reporting lir (Final): Notification lir (if non-pickup):
25/1/8 - Seek 1WY- habity	Call Of: After call for to Of:
25/11/8 - TO agreed love	Documentation Check List: Handler Typist Notification Itr (if non-pickup)
	After call its to Of:
report of the property.	Authorisation To Act Release Voucher:
29/1/18 - File pass to Macus to lin	Final Repair Bill:
23/418 - Flejorsto typeman	Car Rental Invoice:
1 1	LTA / GIA
3 1/18 - DV SUL RECEIVED 2 3	FEB 2018 Medical Bill:
8/3/18 - Filepass to shu po: to	Mand he/Reject Instruction: LOD Payment Breakdown Forms
PRELIMINARY ADVICE Date/Time: Sent By:	Post-Repair Photos:
	Others:
FINALIZATION Date/Time: Confirms Repair Cost: SS (days) Reduction	TOTAL
FINAL SETTLEMENT Date/Time: 13 Configur with FW	Email Call
Final Liability: (Agreed / Astocked) BOLA S/I Repair Cost: W 111 SS 1254 23 Loss of Rental (LOR): SS (days)	N No.:) If NO or B 28, Ass. Lin.
Loss of Use (LOU): S\$ \ \\$\mu \cdot \(\text{U} \cdot \(\text{U} \) \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	
Loss of income (LOI)	ck only one]
GIA/LTA Search SS — Medical: SS —	1) Claim status: Norte /Reject/Private Settle
Disbursement: SS	/ Independent) 2) Report Format:
Legal Cost SS Total: SS 2 ¥37 - 23 Global Sum SS:	3) Survey fee: # 350.00
	Email Call
	Motor Co. Sdn. Phol.
Payee 2: (Strike if N.A.) SS Name 2:	
Payee 3: (Strike if N.A.) SS Name 3:	

(BR11/13) Wef	REF:	11.10	15
ASS. REC. BY: MOVELS		////	
		ASSIGNMENT	
From:	Date	Veh No. S6K Y18	3K Yr Regn 3 15
Estimated Cost	H-CM SHET	Type M.Car / M.Cycle / Bus /	Van / Lorry / Taxi / Prime Mover /
OD THIWS ITP RESIDE	RES/EVA/INV/MV	Truck / Trailer or (A)	/
To Inspect Vehicle No:	SAK YIFOX	Make Honle	civic == 15.91
at Workshop m/s	Koh miss	Day Colour Trey	Insured / Std / NI / NA
of .	1.	Sp.Reading 7//57	T/Radio: Insured / Std / NI / NA
insured		Eng/No:	/
Policy No.		CINO: MRH	FB1630FP000086
Claims No.		Gen. Cond. Good / Fair / Poor	
Sum Insured	Excess	Steering: Invider / Jammed / L	.eaked / Burnt or
(Client's Record)		Brake: Interder / Jammed / L	eaked / Burnt or
Make of Veh		Modi: Nil / S/Run / STD A	Rim or
		Tyre Size: F:	
(Policy Condition)		R: 2	05/55-16
Remark: The veh had comme	50.55 F.165	O/S BS DUN LEXMOVA GY FS	/
repair at the time of	f inspection.	TOYO / COKO Or	
Bal. or Market Value.		Erent	Rear
DAC Accident Rport	Consistent? : Yes or No	R/Bal. Comm	R/Bal mm
GIA / PR Seen:	Consistent? : Yes or No	L/Bal d mm	LiBal. P pm
Est. Repairs: 3	days Res: Yes or No	D.O.A. 14/1/18	D.O.I. 25/1/49
Lum Sum: /3/	% 3 Val.: Yes or No	Survey held at	7 110
CA / REV / REP. / 24	HRS		/ O/S / N/S / U/C / Rooftop ar
	Vehicle: IN	OUT Re	0/
	Contacted		Body Structure affected due to collision.
VIS Confi	1 1 7 1 6	950 # 2/09.58 W	L. 1
11.2	in a vinar of		
		(1	Ciel # 1264 37/1
			1 1 1
	Lauren		
Oute/Time, File Pass to?	: Preli. Report	Days Of Repair:	
DistarTime: File Return to?	: Final Report	Resurvey No. of Trip:	Survey Fee:
Date the rie Return to	Add	Fee: Site Insp (\$	Transportation:
	Add	Interview (\$) _S+RSS
Report Format :		Tech Invs (\$) Photos
ump Sum / I.B.I: (\$) Others
ANTHU QUILLI LD L. 13		Weekend (\$	y



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Amiliated to Federation Interi	nationale Des Experts En Autor	nobile		
IND	IA INTERNATIONA	AL INSURANCE PL	Ref : CC4/III180014	46/pb3		
	CECIL STREET -02 IOB BUILDING	SINGAPORE 049711	Date: 24-01-2018 Code: III2			
1.		Policy Particul	ars :- THIRD PARTY CLA	IM		
	Insured Veh.	SHA 3782G	Veh. Inspected	SGK 4180X		
	Policy No.		Coverage (\$)	0.00		
	Claim No.		Excess (\$)	0.00		
	Assign From		Assign Date	24/01/2018		
2.		Vehicle P	articulars & Condition			
	Make & Model		c.c	0		
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer		Steering			
	Brakes		Modification			
	General					
3.		Cor	nditions of Tyres			
		Size	Make	Balance		
	R/H Front Tyre			mm .		
	L/H Front Tyre			mm		
	R/H Rear Tyre			mm		
	L/H Rear Tyre			mm		
4.		Descr	ription of Damages			
5.		Gen	neral Information			
	Accident Date	14/01/2018	Inspection Date			
	Survey held at	KAH MOTOR CO SDN BER	HAD			
		15 UBI ROAD 4 SINGAPORE 408610				
5a.			Remarks			



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Customer

Registration No

Chassis No

Website: www.honda.com.sg

: INDIA INTERNATIONAL INSURANCE

049711

#04-00 & #05-00 IOB BUILDING

64 CECIL STREET

: MRHFB1630FP000086

SINGAPORE

: SGK4180X

For 24-hours Roadside Assistance, Call 98203838

Surveyor to Survey this vehicle thanks

QUOTATION

GST Reg No.: M200050223 Company Ref. No.: S60FC1380G

Date | Time : 23. Jan 2018 7:18:39 PM Surveyor Name :

			100 miles				
Model	; 2015 CIVIC 1.6L AUTO (EURO 4)	Surv	eyor Nam	e :			
Owner's Name	; CHNG HAK PENG (ZHUANG	Surv	ey Date	:			
Ins Policy No.	:	Auth	orisation	Date :			
Date of Accident	: 14/1/2018						
						GST	Amount
Item	Description	Qty	Unit Pric	e Disc %	Amount	Amt	incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER: CHNG HAK PENG (ZHUANG XUEPENG)						
	OWNER INSURER: NTUC INCOME INS CO-OPERATIVE LTD						
	ACC DATE: 14/1/2018						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: INDIA INTERNATIONAL INSURANCE PTE						
	TP VEH: SHA3782G						
	2.1.					1124771111	
04715-TR0-G10ZZ	FACERR BUMPER DU/BE	1	700.70	25	525.52	36.79	562.31
71593-TR0-A02	SPACERR.RR.BUMPER SIDE Sen +	1	18.30 .	25	13.72	0.96	14.68
71598-TR0-A02	SPACERL RR BUMPER SIDE	1	18.30 /	25	13.72	0.96	14.68
91505-TM8-003	CLIPBUMPER New	2	2.00	25	3.00	0.21	3.21
91506-S9A-003	CLIP BBUMPER NO.	2	2.40	25	3.60	0.25	3.85
	. •			Sum Item	559.56	39.17	598.73
BOSUN	SUNDRIES	1	30.00	nei	30.00 /	0 2 10	32.10
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	80.00		80.00	5.60	85.60
BKBU02R	REPLACE RR BUMPER, REPAIR RR BUMPER LOWER SPOILER.	1	1200.00	560	1200.00	84.00	1284.00
BP03R	SPRAY PAINTING ON RR BUMPER, RR BUMPER LOWER	R1	1500.00	900	1500.00	105.00	1605.00
	450 XZ			Sum Labor	2810.00	196.70	3,006,70

Survey By

Date & Time

25/1/18

Excess

Total (In

Total (Inclusive of GST) 3.605.43

3,369.56

235.87

3,605.43

Total Amount

Signature Telpie shots kelve ja, z

3 Ly



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Customer

: INDIA INTERNATIONAL INSURANCE

64 CECIL STREET

#04-00 & #05-00 IOB BUILDING

SINGAPORE

049711

Registration No

: SGK4180X

Chassis No

: MRHFB1630FP000086

Model Owner's Name

: 2015 CIVIC 1.6L AUTO (EURO 4) : CHNG HAK PENG (ZHUANG

Ins Policy No.

Date of Accident

: 14/1/2018

Description

Document No.

: SQT18000356

: 23. Jan 2018

: WZI007

Customer No. Svc Advisor

: LIM CHOU SIONG

Engine No

Date

: R16B25100177

Date | Time

: 23. Jan 2018 7:18:39 PM

Amount

Surveyor Name

.

Qty Unit Price Disc %

Survey Date

Authorisation Date

GST

QUOTATION

Company Ref. No.: \$60FC1380G

GST Reg No.: M200050223

Amount

Amt

incld GST

2

Page

C S Lim 81006303 (He)

LKK Auto Consultants nence notify the Repairer of the following:

- To requirely before after spray painting
- To display damaged partial during resurvey
- Points prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- · No diese monitorionis) is attract
- . Supplementary denics must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

This is a computer generated invoice. No signature is required

Part prices are subjected to change without notice

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

Atta: Marcus (LK.K.)

GST Reg No.: M200050223 Company Ref. No.: \$60FC1380G

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408851. Tel: +65 6841 3883 Fax: +65 6741 5022

3 days

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5480

Customer:

WZI007 / INDIA INTERNATIONAL

Chassis No:

MRHFB1630FP000086

License No:

Mileage:

35106

Engine No:

SGK4180X

R16B25100177

Document No:

SVO18007365

Printed By:

CSLIM

Order Date:

5. February 2018 9:32:43 AM

Order Time: Service Advisor:

LIM CHOU SIONG

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Am	ount incld GST
	TP DIRECT SETTLEMENT (J/NO: 69939)						
	OWNER: CHNG HAK PENG (ZHUANG XUI	EPENG)					
	OWNER INSURER: NTUC INCOME INSIC		TIVE LTD				
	ACC DATE: 14/1/2018	70-70-00	AD CHESTON				
	SURVEYED BY: MARCUS (L. K. K.)						
	DATE: 25/01/2018 @ 14:00PM						
	REF NO:						
	TP INSURER: INDIA INTERNATIONAL INS	URANCE	PTE LTD				
	TP VEH: SHA3782G		NAMES AND				
04715-TR0-G10ZZ	FACERR BUMPER	- 4	700.70	25	525.52	36.79	562.31
71693-TR0-A02	SPACERR RR BUMPER SIDE	- 1	18.30	25	13.72	0.95	14.68
71598-TR0-A02	SPACERL.RR.BUMPER SIDE	1	18.30	25	13.72	0.96	14.88
91505-TMB-003	CLIPBUMPER	2	2.00	25	3.00	0.21	3.2
91506-89A-003	CLIP BBUMPER	2	2.40	25	3.60	0.25	3.8
91000-030-003	our boom en		SUN	PARTS:	559.56	39.17	598.7
BOSUN	0672	1	10.00		10.00	0.70	10.7
000011	SUNDRIES		00000		DOM: NO		
BML02I	EXT-YJ	4	80.00		80.00	5.60	85.6
DIRECT	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER		1.000000				
	TEST.(N)						
BKBU02R	EXT-YJ	1	560.00		580.00	39.20	599.2
	REPLACE RR BUMPER, REPAIR RR BUMPER LOWER SPOILER,						
	RR PANEL & OTHER DAMAGE PARTS.				TO SWAW		
BP03R	EXT-YBH	1	900.00		900.00	63.00	963.0
	SPRAY PAINTING ON RR BUMPER, RR BUMPER LOWER						
	SPOILER & RR PANEL		SUM	LABOUR:	1,650.00	108.50	1,658.6
			TO	TAL SGD	2,109.58	147.67	2,257.2
			APS 00 PO-LL 10 70 P	212 (122-224)			0.057.4
			Total Paya	ble (SGD)			2,257.2

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particular	5	
Owner ID Type:	Singapore NRIC	
Owner ID:	2687C	
Vehicle Details		
Vehicle No.:	SGK4180X	
Vehicle to be Exported:	No	
Intended De-registration Date:	25 Jan 2018	
Vehicle Make:	HONDA	
Vehicle Model:	CIVIC 1.6 VTIS A/T ABS D/AIRBAG 2WD	
Primary Colour:	Grey	
Manufacturing Year:	2015	
Engine No.:	R16B25100177	
Chassis No.:	MRHFB1630FP000086	
Maximum Power Output:	92.0 kW (123 bhp)	
Open Market Value:	\$21,031.00	
Original Registration Date:	20 Mar 2015	
First Registration Date:	20 Mar 2015	
Transfer Count:	0	
Actual ARF Paid:	\$21,444.00	
Intended PARF Rebate De	etails	
PARF Eligibility:	Yes	
PARF Eligibility Expiry Date:	19 Mar 2025	
PARF Rebate Amount:	\$16,083.00	
Intended COE Rebate De	ails	
COE Expiry Date:	19 Mar 2025	
COE Category:	A - Car up to 1600cc & 97kW (130bhp)	
COE Period(Years):	10	
QP Paid:	\$61,410.00	
COE Rebate Amount:	\$43,867,00	
Total Rebate Amount:	\$59,950.00	

The information contained herein is correct as at 25 Jan 2018

Hsiao Tong (LKKAuto)

From:

Hsiao Tong (LKKAuto)

Sent:

Thursday, 25 January 2018 4:12 PM

To:

'Lim Chou Siong'

Cc:

Admin A: Zaini (LKK Auto)

Subject:

Your Ref: SGK 4180X *Our Ref: CC4/III18001446/Upb3 [ACCIDENT INVOLVING SHA

3782G(III) & SGK 4180X ON 14/01/2018]

Your Ref: SGK 4180X

Without Prejudice

Our Ref: CC4/III18001446/Upb3

Dear Sirs/Madam,

ACCIDENT INVOLVING SHA 3782G(III) & SGK 4180X ON 14/01/2018

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Claim Audit

- 1	AUDIT TRAIL			
60.	On	Audit	Remarks	By
				[A]
	24 Jan 2018	POUNDED SERVICE DE 111 PER 111 PER 111 PER	19 to a thousand a state of the contract of the section of the sec	Lau
1	15:24	Clm Veh Model Changed	(204464) HONDA CIVIC 1.6 VTI-5 (A).	Shu
	13.24			Pe
				[A]
	24 1 2010		Reg No: SGK4180X. Acct Date: 2018/01/14. Claim Type: TP. Insurer: India Internati	Lau
2	24 Jan 2018	Clm Created	onal Insurance Pte Ltd (HQ), TP Insurer: NTUC Income Insurance Co-operative Ltd	Shi
	15:24		(HQ). Workshop: Kah Motor Co Sdn Bhd (Ubi)	Pe
				(A)
3	24 Jan 2018	Adi Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	Sh
	15:24			pe
				1.57
				[A
4	24 Jan 2018	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/02/02	La
	15:24	and training and		Sh
				Pe
				[A
5	24 Jan 2018	Adj Mandate Set	Approved:0,00.Reinsp:Adj decides.	La
÷.	15:24	may riamante ser	CONTROL OF CONTROL OF A CONTROL OF THE PROPERTY OF THE PROPERT	Sh
				Po
				[A
	24 Jan 2018	A SECURIOR STATE OF	(2065) White Not In (2055) Direct Settlement	La
6	15:24	Label Added	(30651): Vehicle Not In,(30653): Direct Settlement.	Sh
				Pe
				(A
	24 Jan 2018	Participation of the American	MATERIA NA PROPERTINA MATERIA PER ATERIA.	La
7	15:24	Adj Adjuster Assigned	[None] -> MARCUS CHUA	Sh
	20.61			pe
				[A]
	3E 3nn 3019		Claimant's Name: -> COMFORT TRANSPORTATION PTE LTD. Claimaint's ID: -> 1993	Lat
8	25 Jan 2018 10:16	Clm Dtl Modified	03821R.	Sh
	10.10		DJULIN.	Pe
				[A]
	25 100 2010			CHE
9	25 Jan 2018	Adj Mandate Request	Cur.Reg:0.00:PODS Liability:100% Remarks: Insured driver rear-ended third party.	HSI
	12:29			TON
	25 Jan 2018			[1]
10	14:32	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/02/02	Sher
				Pill
	25 Jan 2018	PER PER SECURIOR SON DESCRIPTION	The POSSERING PROGRAM PROGRAM IN THE	[1]
11	14:32	Adj Mandate Set	Approved:0.00.	Sher
				Pilli
				[A
12	26 Jan 2018	Label Removed	(30651): Vehicle Not In.	La
1.6	13:19	Lubei Nemoveu	Lancase of Caretings (121)	Sh
				Pe
				[A
	26 Jan 2018	Add not validated		La
13	13:21	Adj Rpt Initiated		Sh
				Pe
				(A
21	26 Jan 2018			La
14	13:21	Clm Details Notified		Sh
				Pe
				1.5
	24 546 2010		Cur.Req:2437.23:PODS Liability: 100% (BOLA 27) Quantum:(a)CORw/GST:\$2,257.2	CHE
15	24 Feb 2018	Adj Mandate Request	3 + (b) LOU(3days X\$60.00): \$180.00 = Total:\$2,437.23 Vehicle Model: Honda Crvi	HSI
	10:27		c (1598cc) For your approval pls.	TON
				1101

ACTIVITY

No record

Merimen Billin	g for this case -	Transaction	History			
			Add Humin			
1706472	26/01/2018 13:21	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SGK4180X	10.70

Print Received Message

This mail is associated with:

*SGK4180X (MCT18010467) [SHA3782G] TP CHNG HAK PENG Jan 14 2018 4:00PM [COMFORT TRANSPORTATION PTE LTD] Kah Motor Co Sdn Bhd

From

India International Insurance Pte Ltd (HQ) (III_SG), sent on 26/02/2018 10:17 AM.

To

Subject

Alert - Adj Mandate Approved (S\$2437.23) - SGK4180X - Claim Handler: Sherini Pillai

Approved:2437.23.

Hsiao Tong (LKKAuto)

From:

Hsiao Tong (LKKAuto)

Sent:

Monday, 5 March 2018 11:14 AM

To:

'Emillin Liew'

Cc:

Zaini (LKK Auto); Faeaz; Admin A

Subject:

RE: LKK C/O INDIA- Submission of Third Party Direct Settlement, Y/R:

CC4/III18001446/Upb3 : O/R: SGK4180X

Attachments:

DV_SGK 4180X.pdf

Without Prejudice

Hi Emilin.

We refer to your below email.

We confirm settlement as follows: -

Cost of Repair(w/GST)

\$ 2.257.23

2. Loss of Use (3days x \$60.00)

\$ 180.00

TOTAL \$ 2,437.23

Please duly sign the DV enclosed and return the original copy tom us (LKK) for our necessary action.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: <u>chewht@lkkauto.com</u> | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Emillin Liew [mailto:emillinliew@honda.com.sg]

Sent: Tuesday, 20 February 2018 9:07 AM

To: Admin A <admin-a@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Cc: Zaini (LKK Auto) <Zaini@lkkauto.com>; SUR <sur@lkkauto.com>; Faeaz <faeaz@honda.com.sg>

Subject: LKK C/O INDIA- Submission of Third Party Direct Settlement, Y/R: CC4/III18001446/Upb3 : O/R: SGK4180X

Dear Hsiao Tong,

RE: ACCIDENT INVOLVING SGK4180X AND SHA3782G ON 14.01.18

Attached please find our Original repair invoice, DV and other relevant documents for the direct settlement claim. Hard copies have mail to you on 20.02.18.

We would appreciate if you could process payment for this claim soonest possible.


Kindly contact us if you need any clarifications.

Warmest Regards,

Emillin Liew DID: +65 6514 5684

Email: emillinliew@honda.com.sg

KAH MOTOR CO. SDN. BHD. (A member of Oriental Holdings Berhad) 15 Ubi Road 4 Singapore 408610 Tel: +65 6743 4333 Fax: +65 6748 0770



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.



Kah Motor Co. Sdn. Bhd.

(A Member of Oriental Holdings Berhad) 15 Ubi Road 4

Singapore 408610 Tel: +65 6841 3838 Fax: +65 6748 0770

www.honda.com.sg

5 March 2018

Your ref

MCT18010467

Our ref

SGK4180X

LKK Auto Consultants Pte Ltd

Blk 51 Paya Ubi Industrial Park Ubi Ave 1

#02-25

Singapore 408933

Attn: Motor Claims Dept / Chew Hsiao Tong

Dear Sir / Madam.

ACCIDENT INVOLVING SGK4180X AND SHA3782G ON 14.01.18

We herewith enclosed the original Express Settlement discharge voucher duly signed for your necessary action.

Kindly let us have your cheque payment of S\$2,437.23 (nett) in favour of Kah Motor Co. Sdn. Bhd.as soon as possible.

Your prompt settlement would be much appreciated.

Thank you.

Yours sincerely,

Emillin

DID: 6514 5684

emillinliew@honda.com.sg



Kah Motor Co. Sdn. Bhd.

(A Member of Oriental Holdings Berhad)

15 Ubi Road 4 Singapore 408610

Tel: +65 6841 3838 Fax: +65 6748 0770 www.honda.com.se

M/s India International Insurance Pte Ltd

64 Cecil Street

#04-00 & #05-00 IOB Building

Singapore 049711

Date: >c 2 1 5

RECEIVED 2 3 FEB 2018

Your ref: CC4/III18001446/Upb3

Our ref: SGK4180X

Attn: Motor Claims Department

Dear Sir / Madam,

THIRD PARTY DIRECT SETTLEMENT

ACCIDENT INVOLVING SGK4180X AND SHA3782G ON 14.01.18

We refer to the items(s) marked (✓) below:

(✓) We refer to LKK- Hsiao Tong's email dated 25.01.18

(✓) We enclosed herewith the repair invoice / Third Party Direct Settlement Agreement.

(✓) Kindly forward the discharge voucher for our client's signature within <u>2 weeks</u> via email to emillinliew@honda.com.sg or faeaz@honda.com.sg

() We return your discharge voucher duly completed.

(✓) Kindly expedite settlement the following:-

Repair Cost

S\$2,257.23 payable to Kah Motor Co Sdn Bhd

Loss of Use

\$\$60.00 x 3 Days = \$\$180.00 payable to

Chng Hak Peng

Rental

NIL

Third Party Insurer Search

NIL

LTA Search

NIL

- (✓) Kindly let us have your cheque made in favour of the above mentioned names(s) for our transmission as soon as possible.
- (✓) Letter of Authority

Thank you.

Yours faithfully,

Lim Chou Siong

LETTER OF AUTHORITY

TO WHOM IT MAY CONCERN

ACCIDENT INVOLVING (OWNER'S VEHICLE NO.)	K4180×
% (THIRD PARTY'S VEHICLE NO.)	82 G
ON 14/01/2018 ALONG June Com	nonwealth Ave wand Clementi Ave 3
 I hereby authorize Kah Motor Co Sdn Bho person authorized by Kah Motor to do all or a To submit, resolve and make any claims(s) v the 3rd party insurers. 	l and its agents or any ny of the following.
To execute, sign discharge voucher / in necessary documents in connection with and claim	
Any payment should be made in favour of my na Bhd	me / Kah Motor Co Sdn
Oleva	
Owner Signature	
(Co stamp & authorized signature if it's Co. register	ed vehicle)
Name : Chry Hat Peng	
Name : Chry Hat Peng NRIC No : S7302687C	
Vehicle No : SEK 4180X	



INDIA INTERNATIONAL INSURANCE PTE LTD

Co. Reg. No. 198703792k | GST. Reg. No. M2-0078806-X 64 | Cecil Street | #04 | #05 | #06-02 | 108 Building | Singapore 049711

Office (65) 63476100 Email insure@ii.com.eg Fax (65) 62244174 Website www.lli.com.sg

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III-Direct Settlement (PODS)

WITHOUT PREJUDICE to:

India Ref: MCT18010467 Claimant Ref : SGK4180X

Any Personal Injury Claims

This is a second of the second	op") hereby confirm that we/l have reached an agreement
with the appointed Surveyor of India International Insurance Pte L	
of Surveyor) with respect to the amount claimed for S\$ 2, use/sental), S\$ (search fee), vehicle no. SGK 4180X the	
on 14/01/2018 (date) at Junction Commonwealth Ave W & Clem	
vehicle). This is pursuant to the inspection conducted on25/01/2018	
We/l confirm that we/l are/am authorized by the owner	CHNG HAK PENG ("the third party
claimant") of vehicle no.SGK 4180Xo make the claim as set out	
the matter on his/her behalf in a manner that we/l deem fit. We	
party claimant*.	The second of th
We/l further confirm that we/l will indemnify India International In	surance Pte Ltd for all damages, loss and/or expense that
they will or have already incurred in the event that "the third ;	party claimant" after the above said agreement lodges a
further claim against the former for any loss and expenses suffer of use pursuant to the damage to SGK 4180X (vehicle no.) as a	
We/I confirm that the agreement reached above is in full and pursuant to the accident and that further this settlement is reach basis.	[19] (TELEPHONE) [2] (1) (1) [2] (1) (1) (1) [2] (1) (1) (1) (1) (1) (1) (1) (1) (1) (1)
This agreement is subject to the application of Singapore law and dispute arising out of the same.	
We/l authorize you to pay the total amount of S\$_2,437.23_to	Kah Motor Co. Sdn. Bhd.
Dated this 5th day of MEVIL 2018	
CLAIMANT:	WITNESS: ((LKK))
Signature:	Signature: CKS.
Signed by "the workshop" (with chap)	Signed by appointed Surveyor
Name: Lin Class Sions	Name: LKK Auto Consultants Pte Ltd
NRIC: 56930967/Z	NRIC: 199607198R
Address: KAH MOTOR CO. SDN. BHD.	Address: 51 Ubi Avenue 1
SINGAPORE 408610	#01-25 Paya Ubi Ind. Park S(408933)
TEL: 6841 3833 FAX: 6748 0770 Nationality:	Nationality:
Occupation: Service Advisor	Occupation:



(ah Motor Co. Sdn. Bhd.

ORIGINAL

Service Tax Invoice

GST Reg No. M200050223 Company Ref. No. S60FC1380G

A Member of Oriental Holdings Berhad)

5 Ubi Road 4, 408610 SINGAPORE

Jhi Parts Centre

hone No.: +65 6841 3838 Fax No.:

NDIA INTERNATIONAL INSURANCE PTE LTD *VIOTOR CLAIMS DEPT* 34 CECIL STREET #04-00 & #05-00 IOB BUILDING SINGAPORE, 049711

Customer No. :

WZ1007

SINV-BS18000275 Invoice No. 15/02/18 Invoice Date SVO18007365 Order No. Reference 69939 Job Card No. 23/01/18 / 7:18:39 PM Date/Time Received SGK4180X Licence No. 2015 CIVIC 1.6L AUTO (EURO Model MRHFB1630FP000086 Car Chassis No. R16B25100177 : Car Engine No. 35106 Mileage LIM CHOU SIONG 0427A Service Advisor CSLIM Served By

7% GST Amount incld Amount Amount U. PriceDisc % Qty. UoM TP DIRECT SETTLEMENT (J/NO: 69939) No OWNER: CHNG HAK PENG (ZHUANG XUEPENG) OWNER INSURER: NTUC INCOME INS CO-OPERATIVE LTD ACC DATE: 14/1/2018 SURVEYED BY: MARCUS (L. K. K.) DATE: 25/01/2018 @ 14:00PM REF NO: TP INSURER: INDIA INTERNATIONAL INSURANCE PTE LTD TP VEH: SHA3782G 10.70 0.70 10.00 10:00 Hours 85.60 SUNDRIES 5.60 80.00 BOSUN 80.00 INSPECT RR LIGHTING MECHANISMS. Hours EXT-BML02I PERFORM WATER 599.20 TEST.(N) 39.20 560.00 560.00 REPLACE RR BUMPER, REPAIR RR BUMPER Hours EXT-BKBU02R LOWER SPOILER. RR PANEL & OTHER DAMAGE PARTS. 963.00 900.00 63.00 900.00 SPRAY PAINTING ON RR BUMPER, RR Hours EXT-BP03R BUMPER LOWER VAH SPOILER & RR PANEL 562.31 36.79 525.52 25 700.70 Each FACERR.BUMPER 14 68 0.95 04715-TR0-G10ZZ 13.72 25 Each 18.30 SPACERR RR BUMPER SIDE 14.68 0.96 13.72 25 71593-TR0-A02 18.30 Each SPACERL RR BUMPER SIDE 3.21 0.21 3.00 25 71598-TR0-A02 2 00 Each 2 CLIPBUMPER 3.85 0.25 91505-TMB-003 3.60 25 2.40 Each 2 CLIP BBUMPER 91506-S9A-003 1,658.50 108.50 1,550.00 Sum Labor 39.17 598.73 559.56 Sum Item 2,257.23 147.67 2,109.56 Total SGD 2,257.23

Page

Total Payable (SGD)

...CLAIM SUBFOLDER...(Pending for Survey Report) Direct Settlement

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	25 Jan 2018 Edit Reg		24 Jan 2018 00:00 Edit Adj Rpt	5\$2,109.56 Edit Estimates	\$\$2,109.56 View Rpt		Pending for Survey Report Cancel Case
	Main	Refere	ence	Claim Details		ocuments	Show All
CLAIM S	UBFOLDER DET	AILS				[Created by ac	fjuster]
Insured:		COMFORT TO	RANSPORTATION	PTE LTD, Co. Re	g. No.: 199303821F	1	
Main Clain	nant:	CHNG HAK P	ENG, ID: 57302				
Vehicle Re	g. No.;	SGK4180X		Date of Loss	S;	14/01/2018 16:0	00 - :59
Claim Typ	e:	TP / MCT18	3010467	Policy/Cove	Note No.:		
Vehicle Re	eg. No. (Insured):	SHA3782G	A3782G Policy No. (Claimant):		5070624739-02		
				Excess:	-water-with the		
Repairer:	Marian Cara II	The second second second second	The second secon	15 Ubi Road 4, 4086			
Handling I				e Pte Ltd (HQ) - Te		andled by Sherini	Pillai]
Claimant's	Insurer:			perative Ltd (HQ)		MARCHE COM	[Eleal Det
Adjuster:		due 02/02/		(HQ) - Tel: 6256-	3561 [Handled b	y MARCUS CHUA	[Final Kpt
ASSOCIA	TED MAIL RECE	EIVED				View All	Compose Case Mail
				437.23) - SGK418 .00) - SGK4180X -			
ALL ASS	OCIATED TASK	s⊟		٧	iew All Search T	asks Create Ne	w Task Complete
Due Dat	The resonant of the	Type Task Gro	oup Subject	Handler Assig	ned By Com	pleted On Co	reated On Done

Claim Documents

*SGK4180X (MCT18010467)

[SHA3782G]

TP

CHNG HAK PENG

Jan 14 2018 4:00PM

[COMFORT TRANSPORTATION PTE LTD]

Kah Motor Co Sdn Bhd

Pho	otos/Images		3 pe	r page 🔍	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
ī	25/01/18 15:51	Odometer Reading	0	Load JPG	3
2	25/01/18 15:51	General View	0	Load JPG	V
3	25/01/18 15:51	Chassis Number	0	Load JPG	\mathbf{Z}
4	25/01/18 15:51	General View	0	Load JPG	V
5	25/01/18 15:51	General View	0	Load JPG	\square
5	25/01/18 15:51	General View	0	Load JPG	\mathbf{Z}
7	25/01/18 15:51	General View	0	Load JPG	$\overline{\mathbf{A}}$
В	25/01/18 15:51	General View	0	Load JPG	$\overline{\mathbf{A}}$
9	25/01/18 15:51	General View	0	Load JPG	Z
10	25/01/18 15:51	General View	0	Load JPG	\mathbf{Z}
11	25/01/18 15:51	General View	0	Load JPG	S
12	25/01/18 15:51	General View	0	Load JPG	$\overline{\mathbf{A}}$
13	25/01/18 15:51	General View	0	Load JPG	Z
14	25/01/18 15:51	General View	0	Load JPG	V
15	25/01/18 15:51	General View	0	Load JPG	V
16	25/01/18 15:51	General View	0	Load 3PG	\mathbf{Z}
17	25/01/18 15:51	General View	0	Load JPG	V
18	25/01/18 15:51	General View	0	Load 3PG	V
19	25/01/18 15:51	General View	0	Load JPG	V
20	25/01/18 15:51	General View	0	Load JPG	$\overline{\mathbf{A}}$
21	25/01/18 15:51	General View	0	Load JPG	\mathbf{Z}
22	25/01/18 15:51	General View	0	Load JPG	120
23	25/01/18 15:51	General View	0	Load JPG	\mathbf{Z}
24	25/01/18 15:51	General View	0	Load JPG	Ø
25	25/01/18 15:51	General View	0	Load JPG	✓
26	25/01/18 15:51	General View	0	Load JPG	Z
27	25/01/18 15:51	General View	0	Load JPG	$\overline{\mathbf{A}}$
28	25/01/18 15:51	General View	0	Load JPG	V
29	08/02/18 17:47	Reinspection Photo	0	Load JPG	\mathbf{Z}
30	08/02/18 17:47	Reinspection Photo	0	Load JPG	Z
31	08/02/18 17:47	Reinspection Photo	0	Load JPG	\mathbf{Z}
32	08/02/18 17:47	Reinspection Photo	0	Load JPG	\mathbf{Z}
Doc	cumentation		1 pe	rpage 🗸	\mathbf{Z}
No I	Relabel/Reorder 24/01/18 15:24	LKK Auto Consultants Pte Ltd (HQ) EMAIL FROM III DD 24012018	0	Thumbnail Load PDF	Prin

2	24/01/18 15:24	TP EST & GIA REPORT	0	Load PDF	
3	26/01/18 15:10	TP ESTIMATE- MARKED	0	Load PDF	
4	23/02/18 14:34	WORKSHOP INVOICE	0	Load PDF	
5	23/02/18 14:34	LOD	0	Load PDF	
6	08/03/18 16:16	AUTHORISATION TO ACT FORM	0	Load PDF	
7	08/03/18 16:16	DISCHARGE VOUCHER	0	Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
1	25/01/18 08:53	Singapore Accident Statement	0	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
	^			
	~			
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co.Reg. No. 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC4/III18001446/UPB3Q2

Date:

08/03/2018

REFERENCE

Date of Loss:

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant Vehicle

SHA3782G

No:

SGK4180X 14/01/2018

Nature of Claim:

Insured Vehicle No:

TP

Claim No: MCT18010467

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SGK4180X

Make & Model:

HONDA CIVIC, 1.6 VTI-S (A)

Engine No:

R16B25100177

34777 km

Reg. Date:

20/03/2015 (Man. Year: 2015)

Chassis No: Odometer.

MRHFB1630FP000086

Colour:

Grey

Engine Capacity: Market Value/New Car Price:

1598 cc N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Footbrake (Serviceable):

Pre-accident Condition:

Yes

Handbrake (Serviceable):

CONDITION OF TYRES Front Tyre Size:

205/55 R16

Rear Tyre Size:

205/55 R16

Front Left Side:

Yokohama 8 mm

Rear Left Side: Rear Right Side: Yokohama 8 mm Yokohama 8 mm

Front Right Side: Yokohama 8 mm

the above values represent the	e remaining tyre treads depth
COST OF CLAIMS	R

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		589.56	569.56	20.00	3.39
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,780.00	1,540.00	1,240.00	44.60
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	3,369.56	2,109.56	1,260.00	37.39
	+ GST 7.00/7.00% (S\$)	235.87	147.67	88.20	37.39
	Nett Amount (S\$)	3,605.43	2,257.23	1,348.20	37.39
	+ Loss of Use (3.0 x S	S\$60.00/day) (S\$)	180.00		

+ Loss of Use (3.0 x S\$60.00/day) (S\$)

Nett Liability (S\$) 2,437.23

INSPECTION

Date Inspected:

Date of Assignment:

24/01/2018

25/01/2018

Inspected At:

Kah Motor Co Sdn Bhd (Ubi)

15 Ubi Road 4 Singapore 408610

Estimated Period of Repair:

3.0 days

Adjuster Report Page 2 of 4

Adjuster: MARCUS CHUA Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Referen	ce	
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Feb 2018)
Parts:	143	HONDA CIVIC 1.6 VTI-S (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted,	no print-code for SGK4180X)
Validity:		es are valid only if they contain the print code (above) on all estimate pages, running page the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values n	ot in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	30.00 FS	*10.00 FS
2	1		*FACERR.BUMPER	Dented / Deformed	525.52 FS	*525.52 FS
3	1		*SPACERR.RR.BUMPER SIDE	Bent	13.72 FS	*13.72 FS
4	1		*SPACERL.RR.BUMPER SIDE	Bent	13.72 FS	*13.72 FS
5	2		*CLIPBUMPER	Necessary	3.00 FS	*3.00 FS
6	2		*CLIP BUMPER	Necessary	3.60 FS	*3.60 FS
F≃Fra	nchise	part. S=SpcN	ett			
				Total Parts (S\$)	589.56	569.56
_						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	INSPECT RR LIGHTING MECHANISMS .PERFORM WATER	New	80.00	80.00
2	REPLACE RR BUMPER ,REPAIR RR BUMPER LOWER SPOILER	New	1,200.00	560.00
3	SPRAY PAINTING ON RR BUMPER ,RR BUMPER LOWER	New	1,500.00	900.00
	Gross Labo	ur Cost (S\$)	2,780.00	1,540.00
	Report was unsubmitted durin	a this print-out.		

< END OF ESTIMATES >