

# Accident Sketch Plan Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20180122/2183

Police Station Of Origin:  
Ang Mo Kio North N.P.C  
51 Ang Mo Kio Avenue 9 SINGAPORE  
569784  
Tel No: 1800-4849999

1 of 4

Report No. T/20180122/2183

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 22/01/2018 19:16		Vide Report No.: A/20180122/0023		Station Diary No.: 100	
<b>Informant's Particulars</b>					
Name of Informant: CANDY MCDONALD			Address: APT BLK 601 CLEMENTI WEST STREET 1 #12-06 SINGAPORE 120601		
ID Type / ID No.: NRIC NO / S7137287A			Contact No.: Home/Office:                      Mobile:		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Female	Age: 46	Date of Birth: 13/10/1971	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Uber Driver			Driving Licence Information: Class: 3                      Date of Expiry:		

## General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 22/01/2018 03:00	Type of Location: Straight Road
Location: Junction of Road 1 and Road 2 SERANGOON ROAD BEATTY ROAD Along Serangoon Road				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Light	
Type of Collision: Chain Collision			Anyone conveyed by ambulance: No	

## Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHC8624L	TAXI	HYUNDAI	I40 1.7 CRDI F/L AT ABS AIRBAG 4DR	Blue	Slightly Damaged	0
SHD9706Y	TAXI	CHEVROLET	EPICA 2.0DSL AT ABS D/AB 2WD 4DR	Red	Slightly Damaged	0

# Accident Sketch Plan Pg. 2



**SINGAPORE  
POLICE FORCE**



T/20180122/2183

Police Station Of Origin:  
Ang Mo Kio North N.P.C  
51 Ang Mo Kio Avenue 9 SINGAPORE  
569784  
Tel No: 1800-4849999

2 of 4

Report No. T/20180122/2183

## CONTINUATION OF REPORT

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SLG9621U	Car	HONDA	GRACE 1.5 HYBRID DX CVT ABS D/AIRBAG 2WD	White	Seriously Damaged	1

Details of Person Involved					
Any Pedestrian Involved: No					
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA		
Driver					
Name	TANG CHAI HING		ID No.	S1415124I	
Related Vehicle	SHC8624L (TAXI)		Contact No.		
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3,4,5 Date of Expiry: NIL	
Date Treatment	NIL		Date Discharge	NIL	
No. of Days granted Medical Leave		NIL	Degree of Injury		NIL
Driver					
Name	CHUA KIM YEOW		ID No.	S1370585B	
Related Vehicle	SHD9706Y (TAXI)		Contact No.		
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL	
Date Treatment	NIL		Date Discharge	NIL	
No. of Days granted Medical Leave		NIL	Degree of Injury		NIL
Driver					
Name	CANDY MCDONALD		ID No.	S7137287A	
Related Vehicle	SLG9621U (Car)		Contact No.		
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL	
Date Treatment	NIL		Date Discharge	NIL	
No. of Days granted Medical Leave		NIL	Degree of Injury		NIL





**SINGAPORE  
POLICE FORCE**



T/20180122/2183

Police Station Of Origin:  
Ang Mo Kio North N.P.C  
51 Ang Mo Kio Avenue 9 SINGAPORE  
569784  
Tel No: 1800-4849999

3 of 4

Report No. T/20180122/2183

CONTINUATION OF REPORT

Lane 3 5

**Brief Details.**

On 22/01/2018 at about 3am, I was driving my car along Serangoon road with 3 lanes and with a passenger. When I was driving along the right most lane, suddenly I saw something dark like a shadow running across the lane in front of my car. I thought I was going to hit onto someone or something, thus I instantly checked on my left side and made a quick swerve to the left center lane. When I swerved onto the center lane on my left, my car was heading towards a red colored taxi. The red colored taxi was parked on the left most lane but was not properly parked as a third of the taxi's right side was overlapping into the center lane. I immediately applied emergency breaking but could not stop in time. My car collided onto the right rear side of the taxi.

My car's front left side was seriously damaged. I then got off the vehicle immediately to make a check. The red taxi was damaged at the right rear tyre and the right rear fender area. The red taxi driver then went to the blue taxi which was in front of his taxi and informed him that there was a slight knock at the rear bumper of his car.

After taking photos of the scene, I immediately checked on my passenger. My passenger who was a elderly aunty, informed me that she felt pain and thus I called 995 for ambulance. Shortly after, ambulance and police arrived at the scene. The ambulance assessed my passenger and was conveyed to hospital from the scene. The Traffic Police officer assessed the scene and subsequently informed all parties to lodge a traffic accident report.

My car had in-car camera and TP seized it for evidence. I left the scene after police concluded their investigation. I am lodging this report as instructed by the Traffic police. My case in-charge is TP IO Jamie tel: 65476397.



**SINGAPORE  
POLICE FORCE**



T/20180122/2183

Police Station Of Origin:  
Ang Mo Kio North N.P.C  
51 Ang Mo Kio Avenue 9 SINGAPORE  
569784  
Tel No: 1800-4849999

4 of 4




Report No. T/20180122/2183

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: F / Staff Sgt TERRENCE FELIX 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 22/01/2018 19:16
Officer In Charge Of Case: TP / GIT / SI NG CHWEE THENG Contact No.: 65476397 	Classification Of Case:
Authentication Stamp NP168	