

INFORM

INS CASE OWNER:

Ming Yao

CC6 / AIG18001473 / B/KS3

LKK:

IDAC:

Surveyor:

MTH

DOI:

ASSIGNMENT

21/1/18

Date / Time:

24/01/18

Registered in Merimen:

24/01/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

GSD 7681T

Claim No.:

61799770955G

Name of Insured:

DAIMLER FLEET MANAGEMENT

Policy No.:

Insured Tel No.:

HP: 6211 9722

Make / Model:

Excess Sec II :SS

D.O.A: 13/1/17

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

Final ? Yes / No

XE 2806T



INSRS:

WSP: VAX Auto

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OE:

After call ltr to OE:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OE:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By: -

FINALIZATION

Date/Time: 18/1/18

Confirm with: BONE

Confirm by: MTH

Repair Cost:

PIP

S\$ 500

(2 days) Reduction:

74 %

Email

Call

FINAL SETTLEMENT

Date/Time: 01-01-18

Confirm with: BONE

Email

Call

Final Liability:

100

%

50

(Agreed / Assessed)

BOLA S/N No.:

Nil

If NO or B 28, Ass. Lia:

Repair Cost:

S\$ 500

S\$ 261.50

Loss of Rental (LOR):

-

S\$ -

(days)

Loss of Use (LOU):

S\$ 150.00

S\$ 150.00

(S150 x 2 days)

Loss of Income (LOI):

-

S\$ -

(S x 2 days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

S\$ 1.45

Medical:

-

S\$ -

Disbursement:

-

S\$ -

(e.g. Tow/ Independent)

Legal Cost:

-

S\$ -

Total:

S\$ 430.95

S\$ 430.95

Global Sum S\$ 430

FINAL PAYMENT

Date/Time: 01-01-18

Confirm with: BONE

Email

Call

Payee 1:

S\$ 430.00

Name 1:

VAX Auto Service Pte Ltd

Payee 2 (Strike if N.A.):

S\$

Name 2:

Payee 3 (Strike if N.A.):

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: + \$20 + \$20

Email

Call

Email

Call

Email

Call

Signature: Tanpin

REF:

III A2G

Ref: 18001473/T/K/S 2

ASSIGNMENT

From: _____ Date: 31.01.2018

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: XE 2806T

at Workshop via Vfix

of No. 2 Buruh Crescent #04-08

Insured: ACE @ Buruh S'pore 627546

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Van: Kent - 9021 1212.

(Policy Condition)

Remark: The vsh had commenced its repair at the time of inspection.

12pm
Owner waiting

N/S	O/S

Bel. or Market Value: _____

ICAC Accident Report: _____ Consistent? : Yes or No

GIA / PR. Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res: Yes or No

Lum. Surt: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

Plp. +500 (Res: +1,445.20 74%)

Van No: XE 2806T.

1st Regn: 2017 April.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover

Truck / Trailer or

Make: Volvo FM420

CS: 12777

Colour: white

A/C Insured / Std / NI / NA

Sp Reading: 47510

T/Radio: Insured / Std / NI / NA

Eng No: _____

C/Vo: yV2x610A8H3806576

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil S/Rim / STD A/Rim or

Tyre Size: F: 315/80R22.5

R: " (D)

BS / DUN / EXNOVA (GY) FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R.Bel: 8 mm

R.Bel: S/S mm

L.Bel: 8 mm

L.Bel: S/S mm

D.O.A. _____

D.O.I. 3/1/18

Survey held at: 2 Buruh Crescent

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Fnt N/S

The U/C / Chassis frame / Body Structure affected due to collision

Date/Time File Pass to:

☐

: Prel. Report

Days Of Repair: _____

Date/Time File Return to:

☐

: Final Report

Resurvey No. of Trip: _____

Survey Fee

Date/Time File Return to:

Add Fee:

☐

Site Insp

\$

☐

Interview

\$

☐

Tech. Insp

\$

☐

Witness

\$

Transporter

_____ \$ + RD _____

Printed

Checked

TOTAL

Report Format:

Lump Sum / I.B.M. /



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC6/AIG18001473/T1ks3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 24-01-2018



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBD 7681T	Veh. Inspected	XE 2806T
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	24/01/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	13/11/2017	Inspection Date	31/01/2018
Survey held at	VFIX AUTO SERVICE PTE LTD 60 KAKI BUKIT AVE 6, ARK@KB, 417892 KAKI BUKIT SINGAPORE 417892		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

M/S AIG ASIA PACIFIC INS PTE LTD
CHARTIS BUILDING
78 SHENTON WAY #08-16
SINGAPORE 079120

ESTIMATE

DATE : 24/1 /2018
ACC DATE : 13/11/2017
REF NO. : VFIX-TP20170393
POLICY NO :

Attention: Motor Claim Department

RE : VEHICLE NO XE2806T VOLVO FM

DESCRIPTION	AMOUNT S\$
1 1 FRONT BUMPER LH	Rp 485.00
2 1 SIDE LAMP LH	411 X 128.00
3 1 STEP BOARD GARNISH LH	Rp 215.00
	828.00
LESS 10%	82.80
	<u>S 745.20</u>

LABOUR & MISCELLANEOUS :	AMOUNT S\$
1 To remove damaged parts with all necessary components/attachments apply hot-works where necessary straighten step board bracket replace new parts refit align into position with all necessary components attachments	200 600.00
2 To spray paint replaced/repainted body panels inclusive of preparatory works and painting materials	300 600.00
	<u>S 1,200.00</u>

GRAND TOTAL : S 1,945.20

SINGAPORE DOLLARS : ONE THOUSAND NINE HUNDRED FORTY FIVE
& TWENTY ONLY

Vfix Auto Service Pte Ltd



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tanpin 97495749
'wp'
31/1/18 @ 1225
02 days
Repairing after repair
Sur @ Mkantho wa



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/AIG18001473/ks3

29th January 2018

Daimler Fleet Management

1 Gateway Drive

#15-08

Westgate Tower

Singapore 608531

Dear Sirs,

**ACCIDENT INVOLVING GBD 768IT AND XE 2806T ON 11/12/2017 ALONG/ AT
PIONEER ROAD TOWARDS JALAN BUROH**

We, LKK Auto Consultants Pte Ltd has been appointed to act on the behalf of your insurer, AIG Asia Pacific Insurance Pte Ltd (AIG) to settle a THIRD PARTY claim against you for an accident which happened on the above-mentioned date and location.

Kindly proceed to lodge your GIA report within five (05) working days of receipt of this letter, giving the version of the accident amongst other things related to the accident. The GIA report can be lodged at any of AIG reporting centres. You may refer to your Certificate of Insurance for the list of the reporting centres.

If you have any information to add or any amendments to make, please contact the undersigned within five days from the date of this letter.

Please note that the standing of your insurance policy such as NCD, premium & etc would be affected.

Yours faithfully,

Zaini

Claims

Tel : 6841 2132

Fax: 6741 4108

Email : Zaini@lkkauto.com

c.c. *Claims Manager*
AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

19 APRIL 2018

Our Ref. No. : VFIX-TP20170393

MOTOR CLAIMS DEPT
AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

vfix
Vfix Auto Service Pte Ltd
60 Kaki Bukit Ave 6
Ark@KB Singapore 417892
Email: vfixauto@gmail.com
Tel: 64489266 Fax: 64452368
Co Reg. No: 201602964H
GST Reg No: 201602964H

WITHOUT PREJUDICE

Dear Sir / Madam

PROPERTY CLAIM ONLY

**ACCIDENT INVOLVING XE2806T AND GBD7681T ON 13 NOV 2017
ALONG PIONEER ROAD TOWARDS JALAN BUROH**

We refer to the above-mentioned accident.

We are writing on behalf of **M/S CA TRANSPORTATION & WAREHOUSING PTE LTD** the registered owner of motor vehicle number **XE2806T** which was involved in the above accident.

We are instructed that the above accident was caused by the negligence and management of your insured's vehicle number **GBD7681T**. As a result of the above accident, our client's vehicle was damaged and our client's has been put to loss and expense, particulars of which are as follows :-

1	Cost of Repair	:S\$	535.00
2	Loss of Use (2 days X \$ 150.00)	:S\$	300.00
3	LTA Fees	:S\$	7.45
TOTAL AMOUNTS		:S\$	842.45

We enclosed a list of the supporting documents :-

- (a) Original Final Repair Bill
- (b) LTA Tax Invoice
- (c) GLA / Police Report lodged by Our Client
- (d) Letter of Authority

Kindly acknowledge receipt of the above said documents and your favourable reply is greatly appreciated.

Any settlement reached is strictly without prejudice to and shall not affect any other claims arising from this accident. Settlement is solely for the items claimed only.

Yours Faithfully,
VFIX AUTO SERVICE PTE LTD




Kelvin Poh



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC6/AIG18001473/ks3

09 FEBRUARY 2018

DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD
1 GATEWAY DRIVE
#15-08 WESTGATE
SINGAPORE 608531
ATTN: HR / MANAGEMENT

Dear Sir/Madam,

ACCIDENT INVOLVING GBD 7681T AND XE 2806T ON 13.11.2017

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

If you have evidence/information to prove that we should not settle the third party claim, kindly let us have them in writing within the next 10 days i.e. by 19/02/2018, after we shall proceed with negotiation with Third Party claimant on the **without prejudice basis** and any settlement should not bind any claims whatsoever by you/your driver against the other party's insurer arising from this particular accident.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Zaini
Case Handler
DID: 6841 2132
FAX: 6741 4108
Email: Zaini@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

To: AIG ASIA PACIFIC INS PTE LTD
78 SHENTON WAY
#07-16 AIG BLDG
SINGAPORE 079120

Dear Sir / Madam,

Claimant:

ACCIDENT INVOLVING XE2806T AND GBD7681T ON 13/11/2017 AT
PIONEER ROAD TOWARDS JALAN BUROH

I/We, CA TRANSPORTATION & WAREHOUSING PTE LTD, am/are the registered owner of
motor car no. XE2806T

Please be informed that I have assigned all compensation monies due to me/us in the above
accident to VFIX AUTO SERVICE PTE LTD.

I/We hereby authorized you to release all monies pertaining to the above mentioned accident
to VFIX AUTO SERVICE PTE LTD and forward the settlement cheque to VFIX AUTO SERVICE PTE
LTD whom I/we have authorized to collect the said compensation monies.

Thank you,



Signature of Claimant &
Company Stamp if applicable
IC no.: 199200740D
Date: 19/04/18

90171918
CHUA LEN HO
12156941E

Signature of Witness

IC no.: S1527552I
Date: 19/04/18

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, VFIX AUTO SERVICE PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$430.00 (Global Sum) for vehicle no. XE 2806T that was damaged pursuant to the accident which occurred on 13/11/2017 (date) along PIONEER ROAD TOWARDS JALAN BUROH involving vehicle no/s GBD 7681T.

This is pursuant to the inspection conducted on 31/01/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner CA TRANSPORTATION & WAREHOUSING PTE LTD ("the third party claimant") of vehicle no. XE 2806T make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to XE 2806T (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 08 (day) of JAN (month) 20 19 (year)



MTH

Signed by appointed surveyor



[Signature]

Signed by "the workshop" (with chop)

***** This Discharge Voucher applies only to the claimant's claim for his property damage and will not affect his personal injuries claim and/or uninsured losses claim on a later date.**

*** Further, the settlement sums herein shall not be used as evidence to prejudice the claimant's personal injuries claim and/or other uninsured losses claim arising out of the subject matter in this action.**



Vfix Auto Service Pte Ltd
60 Kaki Bukit Ave 6
Ark@KB Singapore 417892
Email: vfixauto@gmail.com
Tel: 64489268 Fax: 64452368
Co Reg. No: 201602964H
GST Reg No: 201602964H

FINAL REPAIR BILL

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

DATE : 19/04/2018
VEHICLE NO : XE2806T
MAKE/MODEL : VOLVO FM420
ACC DATE : 13/11/2017
CLAIM NO : VFIX-TP20170393
POLICY NO :

AMOUNT S\$

LUMP SUM REPAIR COST

Repair Amount	500.00
7% GST	35.00
Total	<u>535.00</u>

SINGAPORE DOLLARS: FIVE HUNDRED & THIRTY FIVE
ONLY

VFIX AUTO SERVICE PTE LTD



Kelvin Poh

Land Transport Authority
10 Sin Ming Drive
Singapore 575701

GST Registration No. : M4-0006529-2

XE2806T

Print Date/Time : 27 Dec 2017 / 15:52:48

Receipt Date/Time : 27 Dec 2017 / 15:52:41

Tax Invoice/Receipt

Receipt No. : ITNET-00000-171227-001703

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - GBD7681T				
As at 13 Dec 2017/09:30:00				
Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.				
1	Insurance Enquiry - GBD7681T Enquiry Fee 20171227155150224462	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	XXXXXXXXXXXX8539		Credit Card: Visa /MasterCard	7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Jan 2018 Edit Reg		24 Jan 2018 00:00 Edit Adj Rpt	S\$500.00 Edit Estimates	S\$500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	DAIMLER FLEET MANAGEMENT SINGAPORE PTE LTD, Co. Reg. No.: 57029518J		
Main Claimant:	CA TRANSPORTATION & WAREHOUSING PTE LTD, Co. Reg. No.: 199200740D		
Vehicle Reg. No.:	XE2806T	Date of Loss:	13/11/2017 09:00 - :59 [7 Months and 1 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 8679637925SG	Policy/Cover Note No.:	0999994842 (Comprehensive)
Vehicle Reg. No. (Insured):	GBD7681T	Policy No. (Claimant):	D17MTHCVE001155
		Excess:	
Repairer:	Vfix Auto Service Pte Ltd (HQ) 60 Kaki Bukit Ave 6, ARK@KB, 417892 Kaki Bukit - Tel: 64552957		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com		
Claimant's Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIXH BIN HAMID] ... [Final Rpt due 02/02/2018]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (25/01/2018): Request To Upload TP GIA Report
- AIG_SG (25/01/2018): No OI GIA Report

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*XE2806T (8679637925SG)
[GBD7681T]

TP

CA TRANSPORTATION & WAREHOUSING PTE LTD
Nov 13 2017 9:00AM
[DAIMLER FLEET MANAGEMENT SINGAPORE PTE LTD]
Vfix Auto Service Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

Upload Video

Upload Audio

View

View in Browser

Letters/Correspondences

1 per page

No

Finalized On

LKK Auto Consultants Pte Ltd (HQ)

Thumbnail

Print

1

(Draft)

Third Party Express Settlement – Payment Breakdown

1

Edit

Assessment Reports

1 per page

No

Finalized On

AIG Asia Pacific Insurance Pte. Ltd. (SG)

Thumbnail

Print

1

31/01/18 16:01

Accident Statement

From: SC - Reg. No: GBD7681T, Claimant: DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD

1

Load HTM

Photos/Images

3 per page

No

Relabel/Reorder

LKK Auto Consultants Pte Ltd (HQ)

Thumbnail

Print

1

10/01/19 12:35

LKK INSPECTION PHOTOS

1

Load PDF

Documentation

1 per page

No

Relabel/Reorder

LKK Auto Consultants Pte Ltd (HQ)

Thumbnail

Print

1

24/01/18 18:36

NOTIFICATION FROM WORKSHOP

1

Load PDF

2

26/01/18 14:50

TP GIA REPORT

1

Load PDF

3

29/01/18 12:27

GBD 7681T - NON REPORTING LETTER

1

Load PDF

4

02/02/18 12:09

TP ESTIMATE- MARKED

1

Load PDF

5

14/01/19 08:11

WORKSHOP INVOICE

1

Load PDF

6

14/01/19 08:11

AUTHORISATION TO ACT FORM

1

Load PDF

7

14/01/19 08:11

Release Voucher

1

Load PDF

8

14/01/19 08:11

LTA SEARCH

1

Load PDF

9

14/01/19 08:11

LETTER TO OI

1

Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>	
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>	

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	GBD7681T (Insd veh)	Model:	VOLVO FM420 42T RSS SC
	XE2806T (TP veh)		12.8 D (M)
Date of Accident:	13/11/2017		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:	\$	2,081.36
Final Repair Cost	:	\$	430.00
Loss of Use	:	\$	2.00 days at \$150.00 per day
Rental (if any)	:	\$	days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	430.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 50 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Vfix Auto Service Pte Ltd	:	\$ 430.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

14 Jan
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18001473/T1EB3Q2

Date: 14/01/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

0999994842

Claimant Vehicle
No : XE2806T

Insured Vehicle No : GBD7681T

Date of Loss: 13/11/2017

Nature of Claim:

TP

Claim No: 8679637925SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: XE2806T

Make & Model: VOLVO FM420 42T RSS SC, 12.8 D (M)

Engine No: D13665371

Reg. Date: 12/04/2017 (Man. Year: 2016)

Chassis No:

YV2XG10A8HB806876

Colour: White

Odometer:

47510 km

Engine Capacity: 12777 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 315/80 R22.5

Rear Tyre Size:

315/80 R22.5 (D)

Front Left Side: Goodyear 8 mm

Rear Left Side:

Goodyear 8/8 mm

Front Right Side: Goodyear 8 mm

Rear Right Side:

Goodyear 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	745.20	0.00	745.20	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,200.00	500.00	700.00	58.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,945.20	500.00	1,445.20	74.30
+ GST 7.00/7.00% (S\$)	136.16	35.00	101.16	74.29
Nett Amount (S\$)	2,081.36	535.00	1,546.36	74.30
+ Loss of Use (2.0 x S\$150.00/day) (S\$)		300.00		
		(S\$) 835.00		
Liabile Amount (50.00%) (S\$)		417.50		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		424.95		
Global Sum Settlement (S\$)		430.00		

INSPECTION

Date of Assignment: 24/01/2018

Date Inspected: 31/01/2018 Inspected At:

2 BUROH CRESCENT #04-08 ACE @
BUROH
SINGAPORE 627546
Repairer: Vfix Auto Service Pte Ltd (HQ)

Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER LH	Repair	485.00 FL	*- FL
2	1		*SIDE LAMP LH	Not Necessary	128.00 FL	*- FL
3	1		*STEP BOARD GARNISH LH	Repair	215.00 FL	*- FL
					Sub Total (S\$)	828.00
					- List Item Discount on L Items 10.00/10.00% (S\$)	0.00
					Total Parts (S\$)	0.00

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE DAMAGED PARTS WITH ALL NECESSARY COMPONENTS/ ATTACHMENTS APPLY HOT-WORKS WHERE NECESSARY STRAIGHTEN STEP BOARD BRACKET REPLACE NEW PARTS REFIT ALIGN INTO POSITION WITH ALL NECESSARY COMPONENTS ATTACHMENTS	New	600.00	200.00
2	TO SPRAY PAINT REPLACED/ REPAIRED BODY PANELS INCLUSIVE OF PREPARATORY WORKS AND PAINTING MATERIALS	New	600.00	300.00
Gross Labour Cost (S\$)			1,200.00	500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >