REF: ABM (AXA)

Surveyor

Smart claim

# ASSIGNMENT

From: Date: 26012018

Estimated Cost:

OD / (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGS 131Y

at Workshop m/s Trans Eurokars

of 12 Sungei Kadut Ave

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: Jobi

(Policy Condition) 11am

Remark: The veh had commenced its repair at the time of inspection.

| N/S | O/S |
|---|---|
| | |

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No. SGS 131Y Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Mini Cooper F55. c.c

Colour Green A/C: Insured / Std / NI / NA

Sp.Reading 13230 T/Radio: Insured / Std / NI / NA

Eng/No: ~~205/45R17~~

C/No: WMWXS720302E45870

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/45R17

R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Continental

| Front | | Rear | |
|---|---|---|---|
| R/Bal. | 7 mm | R/Bal. | 7 mm |
| L/Bal. | 7 mm | L/Bal. | 7 mm |
| D.O.A. | 23/1/18 | D.O.I. | 26/1/18 |

Survey held at Trans Eurokars

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction |
|---|---|
| | |

Date/Time. File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time. File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp ($ ) S + RS S

☐ Interview ($ ) Photos

☐ Tech. Invs ($ ) Others

☐ Weekend ($ )

TOTAL

Report Format :

Lump Sum / I.B.I: ($ )