

81172105

From: christian@openbsd.org Date: [Sat, 10 Nov 2006 14:00:00 -0500](#)

Veh No: SM 131321C Yr Regn: 26/2/2013

Type: M.Car / M.Cycle / ~~Bus~~ / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Man NL320F C.C. 10518

Colour Multi Colour A/C: Insured / Std / NI / NA

Sp. Reading 554112 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: Wm AA 22 EE 0107001757

Gen. Cond: **Good** / **Fair** / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 275/70R22.5

N/S	O/S

R: " "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO/YOKO or Fire, 79

Front Rear

R/Bal. 1 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 15/11/12 D.O.I. 26/1/18

Survey held at SMRT

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

Est. n/s

The U/C / Chassis frame / Body Structure affected due to collision.

Copyright 2012 Pearson Education, Inc. or its affiliate(s). All rights reserved. Printed in the United States of America. This publication is protected by copyright. Any unauthorized distribution, reproduction, or use of this work is illegal. All other rights reserved. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, recording, or by any information storage or retrieval system, without prior written permission from the copyright owner. This work is published under the Creative Commons Attribution-NonCommercial-ShareAlike license. For more information, see <http://creativecommons.org/licenses/by-nc-sa/4.0/>.

☐: Preli. Report

□: Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: : Site Insp (\$

Lump Sum / I.B.I: (\$

1	Site Insp (\$
---	---------------

☐: Interview (\$

 : Tech. Invs (\$

☐ Weekend (\$)
$$) \quad \dots S + RS, \dots SI$$

Photos

) Others

TOTAL