

Signature:

REF:

CC3 / ALH18001487 / Agbnz

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No: 7106309992

Claims No: 071651950856

Sum Insured: \_\_\_\_\_ Excess: of

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

/	
N/S	O/S

Bal. or Market Value: 88K

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 01 8 1/2 days Res.: Yes or No

Lump Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SKH183H- Yr Regn: Aug 2012

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A6 Yr: 1984

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 85267 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WAU 2224G 7DN . 009292

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim or

Tyre Size: F: 255/35R20

R: 255/35R20

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. \_\_\_\_\_ D.O.I. 23/01/18

Survey held at: Premium

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

OD ALG.

SKH 183 H - CC3 / ALH13003966 / Hcdl

DOI: 150513

29/1/18 @ 3:09pm Informed Jeffrey ex: of - by email.

22/2/18 @ 12:08pm confirmed with Mr Bob final fig \$3052.40, 1 day.

(Cred \$ 840.60, 22%)

RECEIVED 26 APR 2018

Date/Time, File Pass to?

: Prel. Report

11/2/14 Initial

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee:

Transportation:

Add Fee:  Site Insp (\$ \_\_\_\_\_)

Interview (\$ \_\_\_\_\_)

Tech. Invs (\$ \_\_\_\_\_)

Weekend (\$ \_\_\_\_\_)

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

TOTAL

200

10

210

Report Format: Mer-09

Lump Sum / I.B.I: (\$) 3052.40



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/AIG18001487/Aqb

78 SHENTON WAY #08-16  
CHARTIS BUILDING  
SINGAPORE 079120

Date : 25-01-2018



Code : AIG

## 1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SKH 183H
Policy No.	2100309992	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	23/01/2018

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--	--

## 5. General Information

Accident Date	22/01/2018	Inspection Date	23/01/2018
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 SINGAPORE 408699		

## 5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Tuesday, 27 March 2018 12:08 PM  
**To:** 'Boo seng yak'; SUR; Carrine Leong; Nora Khai  
**Subject:** RE: FINAL REVISION SKH183H - OD AIG - SURVEYED 25 JAN 18

Dear Mr Boo,

Confirm final fig \$3,052.40 before GST and 1 repair day.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Boo seng yak [mailto:boojohnny@gmail.com]  
**Sent:** Saturday, 17 March 2018 4:14 PM  
**To:** Adrian Ling (LKKAuto) <[adrianling@lkkauto.com](mailto:adrianling@lkkauto.com)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>; Carrine Leong <[carrine.leong@premiumauto.com.sg](mailto:carrine.leong@premiumauto.com.sg)>; Nora Khai <[nora.khai@premiumauto.com.sg](mailto:nora.khai@premiumauto.com.sg)>  
**Subject:** FINAL REVISION SKH183H - OD AIG - SURVEYED 25 JAN 18

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$3052.00 @ 1 day of repair.

Photos attached.

Your early closure is appreciated.

Best regards - jb

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Monday, 29 January 2018 3:09 PM  
**To:** Claims Dept; SUR  
**Subject:** RE: SKH 183 H Own Damage Claim

Dear Jeffrey,

Please be informed that the excess of above vehicle is \$0/-.

Best Regards,

**Shiau Chan (Ms) | Case Handler**  
**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Thursday, 25 January 2018 2:14 PM  
**To:** Claims Dept <[claims@premiumauto.com.sg](mailto:claims@premiumauto.com.sg)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: SKH 183 H Own Damage Claim

Dear Jeffrey,

Please refer to the attached of marking estimate.

Best Regards,

**Shiau Chan (Ms) | Case Handler**  
**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Claims Dept [<mailto:claims@premiumauto.com.sg>]  
**Sent:** Wednesday, 24 January 2018 5:40 PM  
**To:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Cc:** [claims@premiumauto.com.sg](mailto:claims@premiumauto.com.sg)  
**Subject:** SKH 183 H Own Damage Claim

Dear all,

Attached the GIA, IC, DL, CI and estimate for your kind reference

Survey was carried out by Adrian yesterday.

Please let us have your marked estimate once ready.

Many thanks!

Best regards,  
**Jeffery Tan**

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6742F
Vehicle Details	
Vehicle No.:	SKH183H
Vehicle to be Exported:	No
Intended De-registration Date:	25 Jan 2018
Vehicle Make:	AUDI
Vehicle Model:	A6 2.0 TFSI MU
Primary Colour:	Grey
Manufacturing Year:	2012
Engine No.:	CDN279613
Chassis No.:	WAUZZZ4G7DN009292
Maximum Power Output:	132.0 kW (177 bhp)
Open Market Value:	\$44,541.00
Original Registration Date:	23 Aug 2012
First Registration Date:	23 Aug 2012
Transfer Count:	0
Actual ARF Paid:	\$44,541.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Aug 2022
PARF Rebate Amount:	\$31,178.00
Intended COE Rebate Details	
COE Expiry Date:	22 Aug 2022
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$94,502.00
COE Rebate Amount:	\$43,237.00
<b>Total Rebate Amount:</b>	<b>\$74,415.00</b>

The information contained herein is correct as at 25 Jan 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	23/01/2018 11:41
Date Of Accident	22/01/2018 09:30
Exact Location Of Accident	CEYLON RD -ABOUT 50M FROM EAST COAST ROAD JUNCTION
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKH183H
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LING YEW JIN, KELVIN
NRIC No	S7316742F
Email Address	TYCG18@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91282979
Alternative Phone No	OFFICE-91282979

### Vehicle Particulars

Manufacturer	AUDI
Model	A6 C7 2.0 TFSI MU
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100309992-05
Cover Note Number	

### Driver

Name of Driver	LING YEW JIN, KELVIN
NRIC No	S7316742F
Date Of Birth	08/05/1973
Occupation	INDOOR
Date Of Driving Pass	10/02/1992
Driving Experience	25 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91282979
Fax Number	
Contact Number	OFFICE-91282979
Email Address	TYCG18@GMAIL.COM

Address	BLK 66 MARINE PARADE ROAD #13-13
Postcode	449300
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

#### General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO SKETCH PLAN & POLICE REPORT NO: T/20180123/7008

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	
Vehicle Make/Model/Colour	UNKNOWN
Details Of Properties	
Vehicle Category	NA/UNKNOWN
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 23/01/2018  
10:00 hr

Driver's Signature  
(if driver is not the policyholder)

Date & Time: 23/01/2018  
10:00 hr


Reporting Centre Personnel's Signature

Name: TAN ENG SU  
NRIC/FIN No.: 95334909P



Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the morning of 22/01/2018, I parked my car along Ceylon Road, in the parallel parking lot found along said road, at about 8 a.m.

Upon my return at around to my car at 09:30 hrs I noticed the damage to my Left Side Wing Mirror. There had been no signs for me to be able to identify the cause of the damage, as I was away from my car.

(Please Refer to Similar Police Report on this incident)

DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
 Policyholder's Signature  
 Date & Time: 23/1/2018  
 10:00

  
 Driver's Signature  
 (if driver is not the policyholder)  
 Date & Time: 23/1/2018  
 10:00

   
 Reporting Centre Personnel's Signature  
 Name: TAN ENG SU  
 NRIC/FIN No.: G5334109P

Police Report



**SINGAPORE  
POLICE FORCE**



1201801237008

1 of 3

Police Station Of Origin:  
Traffic Police Division HQ  
10 Ubi Avenue 3 SINGAPORE 408655  
Tel No: 55170000

Report No. T201801237008

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 22/01/2018 15:11	Video Report No.	Station Diary No.
--	------------------	-------------------

Informant's Particulars		
Name of Informant: LING YEW JIN, KELVIN		Address: APT BLK 56 MARINE PARADE ROAD #13-13 SINGAPORE 449302
ID Type / ID No.: NRIC NO / S7316742F		Contact No.: Home/Office: Mobile: 91202979
Nationality: SINGAPORE CITIZEN		E-Mail: tjgg15@gmail.com
Sex: Male	Age: 44	Date of Birth: 08/05/1973
Type of Informant: Driver		Institution / School Name:
Race: Chinese		Language: English
Occupation: Management executive		Driving Licence Information: Class: J Date of Expiry:

General information of the Accident				
Type of Accident: Non Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 22/01/2018 09:30	Type of Location: Straight Road	
Location: CEYLON ROAD Parallel Parking lots along Ceylon Road, near address 3, Ceylon Road.				
Weather: Clear		Road Surface: Dry	Road Speed Limit	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: No Traffic	
Type of Collision: Please Refer to below Description			Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No. SKH183H	Type Car	Make Audi	Model A8	Color Grey	Condition: Slightly Damaged	No of Passenger: 0

Details of Vehicle Insurance				
Vehicle No. SKH183H	Insurance Company AIC ASIA PACIFIC INSURANCE PTE. LTD.	Insurance No.	Effective	Expiry Date:

Police Report



**SINGAPORE  
POLICE FORCE**



1201007237000

2 of 3

Police Station Of Origin:  
Traffic Police Division HQ  
10 Ubi Avenue 3 SINGAPORE 409035  
Tel No: 65470000

Report No: 1201007237000

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	LING YEW JIN, KELVIN	ID No.	S7316742F
Related Vehicle	SKH183H (Car)	Contact No.	912829179
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details:**

On the morning of 22/1/2018, I parked my car along the parallel parking lots found along Ceylon Road, beside House No. 3 Ceylon Road.

Upon return to my car, I discovered my Left Side Wing mirror, which was expose to the flow of traffic (as Ceylon Road is a One Way road, and the parking lot found on the right hand side of the road) badly damaged. Unfortunately I was unable to know, or had the ability to witness, who were the parties to have caused the damage as I was away from my car, and not sure when the actual impact to the mirror happened.

I am also unable to confirm for sure whether the damage was done by another vehicle, and if so, what type of vehicle, or even by a human powered vehicle such as bicycle or e-scooter etc

Police Report



**SINGAPORE  
POLICE FORCE**

Police Station Of Origin:  
Traffic Police Division HQ  
10 Ubi Avenue 3 SINGAPORE 408666  
Tel No: 65470000



1025 001204006

3 of 3

Report No: 1101001204006

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report  
Not applicable

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:  
TP / TP/D /  
TAN LEE HWANG (DAWN)  
Contact No: 65476216

Authentication Stamp  
R-161

Signature Of Informant:  
The identity of the person making this report has  
been authenticated by SingPass. No signature is  
required.

Date/Time:  
23/01/2018 15:11

Classification Of Case:

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: S7316742F

Name: LING YEW JIN, KELVIN  
(LING YAOREN, KELVIN)

Birth Date: 08 May 1973  
Issue Date: 20 Feb 2003



REPUBLIC OF SINGAPORE  
IDENTITY CARD NO. S7316742F



Name: LING YEW JIN, KELVIN  
(LING YAOREN, KELVIN)


凌耀仁  
Race

CHINESE  
Date of Birth: 08-05-1973  
Country of Birth: SINGAPORE  
Sex: M

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE  
10 Feb 1992



NP 428A



2663071

NRIC No: S7316742F



Blood Group: B+  
Date of Issue: 14-07-1995

APT BLK 66 MARINE PARADE ROAD #13-13  
SINGAPORE 449300

NRIC No: S7316742F Date: 08-08-2005 No: 5187816



# CERTIFICATE OF INSURANCE

## AUDI AUTO PROTECTOR PRIVATE VEHICLE

**Name of Policyholder** : LING YEW JIN, KELVIN (LING YAOREN, KELVIN)  
**Period of Insurance** : 23 Aug 2017 To 22 Aug 2018  
**Engine No.** : CDN279613  
**Chassis No.** : WAUZZZ4G7DN009292

**Vehicle No.** : SKH183H  
**Policy No.** : 2100309992-05  
**Endorsement No.** :  
**Issued Date** : 28 Jul 2017

### ABOUT THE COVER

**Make/Model** : AUDI A6 C7 2.0 TFSI MU  
**Engine Capacity/Tonnage** : 1,984.00 CC  
**Driver Restriction** : NA  
**Sum Insured** : Market Value  
**Off Peak Car** : No  
**First Year of Registration** : 2012  
**Insuring with COE/PARF** : Yes

#### Person or Classes of Persons Entitled to Drive\*

a) The Policyholder  
 b) Any other person who is driving on the Policyholder's order or with his/her permission.  
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.  
 You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

**Age Condition** : All Age Condition

#### Limitation as to use\*

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

#### Loss of Use (15 days)

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

### EXCESS

**Section 1**  
 Fire - \$0 Own Damage - \$800 Theft - \$0 Flood Cover - \$0

**Section 2**  
 Property Damage - \$0

**Windscreen** : \$100

#### Named Driver and Excess (where applicable)

LING YEW JIN, KELVIN (LING YAOREN, KELVIN) - \$800 (Own Damage)

### APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website [www.aig.com.sg](http://www.aig.com.sg) or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

### IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: MayBank

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125200

PREMIUM LEASING - AP  
 281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE  
 SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

**AIG Asia Pacific Insurance Pte. Ltd.**  
 AUTHORISED REPRESENTATIVE

ESSCFY

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/OD/0098/2018/JT  
**Date** : 24-Jan-18

Vehicle NOT IN workshop. Kindly arrange for survey.

## AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

**Attn: Mr. Adrian Ling - Motor Claims Dept**

**Tel: 6841 0055 - Fax: 6256 4315**

**Owner's Name** : Mr Ling Yew Jin, Kelvin  
**Address** : Blk 66 Marine Parade Road  
#13-13  
Singapore 449300  
**Telephone** : HP +65 9128 2979  
**Type of Claim** : Own Damage Claims  
**Policy No.** : 2100309992-05  
**Vehicle No** : **SKH 183 H**  
**Model Code** : Audi A6 C7 2.0 TFSI Mu  
**Model / Year** : Aug-12  
**Engine No** : CDN 279613  
**Chassis No** : WAUZZZ4G7DN009292  
**Mileage** :  
**Date In** :  
**Liability** : -  
**Excess Cost** : -  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 22-Jan-17  
**Place of Accident** : Ceylon Road

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

Telefax

## Estimated Labour Charges for Accident Vehicle SKH 183 H

<u>S/n</u>	<u>Nature of Jobs</u>		<u>Estimated Charges</u>	<u>Surveyor's Recommendation</u>
1	To remove LHS front door panel trims, renew LHS wing mirror assy. Reinstall all parts removed.	S/N	\$ 600.00 //	
2	To respray LHS wing mirror cap.		\$ 400.00 <sup>180</sup> 100+50	
3	To carry out diagnostic check.	S/N	\$ 192.00 //	
<b>TOTAL LABOUR CHARGES</b>		:	<u>\$ 1,192.00</u>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SKH 183 H.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	WING MIRROR MOUNTING ASSY - LHS <i>Dgd</i>	\$ 1,237.00	✓ 989.60
2	WING MIRROR CAP - LHS <i>cracked</i>	\$ 159.00	✓ 126.50
3	TURN SIGNAL INDICATOR - LHS <i>cracked.</i>	\$ 111.00	✓ 88.80 ✓
4	SIDE MIRROR GLASS (CONVEX) - LHS <i>cracked</i>	\$ 1,094.00	✓ 875.20
5	SUNDRIES <i>Nett</i>	\$ 100.00	? X
<b>TOTAL SPARE PARTS</b>		<b>\$ 2,701.00</b>	
<b>TOTAL LABOUR CHARGES</b>		<b>\$ 1,192.00</b>	
<b>GRAND TOTAL</b>		<b>\$ 3,893.00</b>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name : *Adrian Lj*  
Surveyed Date : *23/01/18*  
Authorised Date :  
Excess Cost :  
Liability :  
Remarks : *Authorised by car, 02 days.*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

## Please Note

: This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/OD/0098/2018/JT  
**Date** : 24-Jan-18

Vehicle NOT IN workshop. Kindly arrange for survey.

### AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way  
#07-16 AIG Building  
Singapore 079120

Hi Adrian

1 day - ok - jb - 17 Mar 18

**Attn: Mr. Adrian Ling - Motor Claims Dept**  
**Tel: 6841 0055 - Fax: 6256 4315**

**Owner's Name** : Mr Ling Yew Jin, Kelvin  
**Address** : Blk 66 Marine Parade Road  
#13-13  
Singapore 449300  
**Telephone** : HP +65 9128 2979  
**Type of Claim** : Own Damage Claims  
**Policy No.** : 2100309992-05  
**Vehicle No** : **SKH 183 H**  
**Model Code** : Audi A6 C7 2.0 TFSI Mu  
**Model / Year** : Aug-12  
**Engine No** : CDN 279613  
**Chassis No** : WAUZZZ4G7DN009292  
**Mileage** :  
**Date In** :  
**Liability** : -  
**Excess Cost** : -  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 22-Jan-17  
**Place of Accident** : Ceylon Road-about 50m from East Coast Road Junction

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SKH 183 H

<u>S/n</u>	<u>Nature of Jobs</u>		<u>Estimated Charges</u>	<u>Surveyor's Recommendation</u>
1	To remove LHS front door panel trims, renew LHS wing mirror assy. Reinstall all parts removed.	S/N	\$ 600.00	\$ 600.00
2	To respray LHS wing mirror cap. <i>(Our internal charge is already \$180.00) Adrian P/N</i>		\$ 400.00	\$ 180.00
3	To carry out diagnostic check.	S/N	\$ 192.00	\$ 192.00
<b>TOTAL LABOUR CHARGES</b>		<b>:</b>	<b>\$ 1,192.00</b>	<b>\$ 972.00</b>

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SKH 183 H.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT WING MIRROR MOUNTING ASSY - LHS	\$ 1,237.00	\$ 989.60
2	FRONT WING MIRROR CAP - LHS	\$ 159.00	\$ 126.80
3	WING MIRROR TURN SIGNAL INDICATOR - LHS	\$ 111.00	\$ 88.80
4	SIDE MIRROR GLASS (CONVEX) - LHS	\$ 1,094.00	\$ 875.20
5	SUNDRIES	\$ 200.00	
<b>TOTAL SPARE PARTS</b>		<b>\$ 2,801.00</b>	<b>\$ 2,080.40</b>
<b>TOTAL LABOUR CHARGES</b>		<b>\$ 1,192.00</b>	<b>\$ 972.00</b>
<b>GRAND TOTAL</b>		<b>\$ 3,993.00</b>	<b>\$ 3,052.40</b>

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name :  
Surveyed Date :  
Authorised Date :  
Excess Cost :  
Liability :  
Remarks :

**Please Note** : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the  
progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant

# Premium Automobiles

**AIG Asia Pacific Insurance Pte Ltd**  
78 Shenton Way  
#07-16 AIG Building  
Singapore 079120  
**Attn: Motor Claims Dept**  
**Yr Ref: SKH 183 H**

Norah Khai  
6768 9911  
6841 1183  
Nora.khai@premiumauto.com.sg  
Body & Paint Dept  
PA/OD/0098/2018/MAS

26 Apr 2018

from  
Telephone +65-  
Telefax +65-  
EMail  
Our department  
Our Ref  
Your Ref  
Date

total pages

Dear Sir,

**RE: INSURANCE CLAIM FOR SKH 183 H, Audi A6 C7 2.0 TFSI MU**

With reference to the above-mentioned vehicle, no **SKH 183 H**, claimant, **Mr. Ling Yew Jin, Kelvin**, please find the related document per attached.

1. A copy of the Original invoice no. 85012359 – S\$3,266.07
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai  
Claims Dept

Encls

AIG – SKH 183 H

Premium Automobiles Pte Ltd  
Showroom  
9 Leng Kee Road  
Singapore 159090  
Telephone (65) 6566 1111  
Telefax (65) 6471 3733

Service & Parts Centres  
55 Ubi Rd 1  
Singapore 408699  
Telephone (65) 6336 2323  
Telefax (65) 684 11183

**...CLAIM SUBFOLDER...(Pending for Survey Report)**

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 Jan 2018		25 Jan 2018 11:59 <a href="#">Edit Adj Rpt</a>	<b>S\$3,052.40</b> <a href="#">Edit Estimates</a>	<b>S\$3,052.40</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]																				
Insured:	LING YEW JIN, KELVIN, ID: S7316742F, Tel: +6591282979, Email: TYCG18@GMAIL.COM																					
Vehicle Reg. No.:	SKH183H	Date of Loss: 22/01/2018 09:00 - :59 [64 Months and 30 Days From LTA Reg Date (Man Yr)]																				
Claim Type:	OD / 0216519508SG	Policy/Cover Note No.: 2100309992-05 (Comprehensive) Excess: S\$0.00																				
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911																					
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Mohd Zawaye, Norsazani] Norsazani.Zawaye@aig.com																					
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 05/02/2018]																					
Driver/Custodian:	LING YEW JIN, KELVIN (44 / Male), NRIC: S7316742F, Tel: +6591282979																					
		<a href="#">View All</a> <a href="#">Compose Case Mail</a>																				
<b>ASSOCIATED MAIL RECEIVED</b>																						
<ul style="list-style-type: none"> <li>AIG_SG (29/01/2018): SKH183H / OD / 22/01/2018 / Coverage &amp; Excess update</li> </ul>																						
<input type="checkbox"/> <b>ALL ASSOCIATED TASKS</b>																						
<table border="1"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table>			Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?													
No results.																						
<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>																						

## Claim Documents

\*SKH183H (0216519508SG)  
OD  
Jan 22 2018 9:30AM  
[LING YEW JIN, KELVIN]  
Premium Automobiles Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View	Use Viewer	
<b>Photos/Images</b>										3 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print			
1	19/03/18 15:13	General View							Load JPG	<input checked="" type="checkbox"/>		
2	19/03/18 15:13	Chassis Number							Load JPG	<input checked="" type="checkbox"/>		
3	19/03/18 15:13	General View							Load JPG	<input checked="" type="checkbox"/>		
4	19/03/18 15:13	General View							Load JPG	<input checked="" type="checkbox"/>		
5	19/03/18 15:13	General View							Load JPG	<input checked="" type="checkbox"/>		
6	19/03/18 15:13	General View							Load JPG	<input checked="" type="checkbox"/>		
7	19/03/18 15:13	General View							Load JPG	<input checked="" type="checkbox"/>		
8	19/03/18 15:13	General View							Load JPG	<input checked="" type="checkbox"/>		
9	19/03/18 15:13	General View							Load JPG	<input checked="" type="checkbox"/>		
10	19/03/18 15:13	General View							Load JPG	<input checked="" type="checkbox"/>		
11	19/03/18 15:13	General View							Load JPG	<input checked="" type="checkbox"/>		
<b>Documentation</b>										1 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print			
1	25/01/18 14:12	Singapore Accident Statement							Load PDF			
2	25/01/18 14:12	Certificate of Insurance							Load PDF			
3	25/01/18 14:12	Driver's Driving License							Load PDF			
4	25/01/18 14:12	WORKSHOP ESTIMATE							Load PDF			
5	27/04/18 12:26	WORKSHOP INVOICE							Load PDF			
6	27/04/18 12:26	DISCHARGE VOUCHER							Load PDF			

## Linked Accident Report Documents

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View	Use Viewer	
<b>Assessment Reports</b>										1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)						Thumbnail	Print			
1	23/01/18 16:02	Accident Statement							Load HTM			
<b>Photos/Images</b>										3 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)						Thumbnail	Print			
1	23/01/18 15:46	Police Report							Load JPG	<input checked="" type="checkbox"/>		
2	23/01/18 15:46	Police Report							Load JPG	<input checked="" type="checkbox"/>		
3	23/01/18 15:46	Police Report							Load JPG	<input checked="" type="checkbox"/>		
4	23/01/18 15:57	Accident Photo							Load JPG	<input checked="" type="checkbox"/>		
5	23/01/18 15:57	Accident Photo							Load JPG	<input checked="" type="checkbox"/>		
6	23/01/18 15:57	Accident Photo							Load JPG	<input checked="" type="checkbox"/>		
7	23/01/18 15:57	Accident Photo							Load JPG	<input checked="" type="checkbox"/>		
8	23/01/18 15:57	Accident Photo							Load JPG	<input checked="" type="checkbox"/>		
9	23/01/18 15:57	Accident Photo							Load JPG	<input checked="" type="checkbox"/>		
10	23/01/18 15:57	Accident Photo							Load JPG	<input checked="" type="checkbox"/>		
11	23/01/18 15:57	Accident Photo							Load JPG	<input checked="" type="checkbox"/>		
<b>Documentation</b>										1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)						Thumbnail	Print			
1	23/01/18 15:53	Sketch Plan							Load JPG	<input checked="" type="checkbox"/>		
2	23/01/18 15:53	Sketch Plan #2							Load JPG	<input checked="" type="checkbox"/>		

### Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	<a href="#">Reset</a>	<a href="#">Save</a>	<a href="#">Print</a>
There are no document checklists configured.			

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>
<div style="border: 1px solid gray; height: 100px; width: 100%;"></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer
<small>Note: Remarks are private unless you show it to other parties.</small>

## LKK Auto Consultants Pte Ltd (Co Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way #07-16  
Singapore 079120

Our File No: CC3/AIG18001487/AQBN2

Date: 27/04/2018

#### REFERENCE

Insured/Claimant: LING YEOW JIN, KELVIN      Policy No: 2100309992-05  
Date of Loss: 22/01/2018      Nature of Claim: OD      Claim No: 0216519508SG

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKH183H	Engine No:	CDN279613
Make & Model:	AUDI A6, 2.0 TFSI MU (A)	Chassis No:	WAUZZZ4G7DN009292
Reg. Date:	23/08/2012 (Man. Year: 2012)	Odometer:	85267 km
Colour:	Grey		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$88,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	255/35R20	Rear Tyre Size:	255/35R20
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,701.00	2,080.40	620.60	22.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,192.00	972.00	220.00	18.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>3,893.00</b>	<b>3,052.40</b>	<b>840.60</b>	<b>21.59</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>272.51</b>	<b>213.67</b>	<b>58.84</b>	<b>21.59</b>
<b>Nett Amount (S\$)</b>	<b>4,165.51</b>	<b>3,266.07</b>	<b>899.44</b>	<b>21.59</b>

#### INSPECTION

Date of Assignment:	25/01/2018	Inspected At:	Premium Automobiles Pte Ltd (UBI)
Date Inspected:	23/01/2018		55 Ubi Road 1
			Singapore 408699

Estimated Period of Repair: 1.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*WING MIRROR MOUNTING ASSY-LHS	Damaged	1,237.00 FS	*989.60 FS	
2	1		*WING MIRROR CAP-LHS	Cracked	159.00 FS	*126.80 FS	
3	1		*TURN SIGNAL INDICATOR-LHS	Cracked	111.00 FS	*88.80 FS	
4	1		*SIDE MIRROR GLASS (CONVEX)-LHS	Cracked	1,094.00 FS	*875.20 FS	
5	1		*SUNDRIES	Not Necessary	100.00 FS	*- FS	
					<b>Total Parts (S\$)</b>	<b>2,701.00</b>	<b>2,080.40</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE LHS FRONT DOOR PANEL TRIMS,RENEW LHS WING MIRROR ASSY.REINSTALL ALL PARTS REMOVED	New	600.00	600.00
2	TO RESPRAY LHS WING MIRROR CAP	New	400.00	180.00
3	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (S\$)</b>			<b>1,192.00</b>	<b>972.00</b>

Report was unsubmitted during this print-out.
---

&lt; END OF ESTIMATES &gt;