

ASS. REC. BY:

REF: CS3 / CT18001507 / WBS21

Special Instruction:

Range & days

Supervisor:

Wilson

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CT1

Date/Time: 24/01/2018 3.24pm

Estimated Cost:

Bill to:

OD / ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SIN 2145K

Insured:

YP 4616S

at Workshop m/s

Precise Auto

Tel:

6705 7367

of

B1k 1 Kaki Bukit Ave 6 #02-34

Policy No:

DMCVSN1761301700

Claim No:

SNM180 00406 CD.

Sum Insured:

Excess:

Make of Veh:

D.O.A.

19012018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'WP'

H.O.D. Endorsement:

Date/Time:

24/01/2018 4.22pm

Person Contacted:

Anne

Vehicle IN OUT

Date/Time

Action/Instruction (X) Estimate

SIN 2145K - X

YP 4616S - X

Dismantle: 26/1/2018

After repair: 1/2/2018

PRS

REF: CT2

Growth W: 1507

Mentmen

ASSIGNMENT

From: Date: 25012018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: SJN 2145K

at Workshop mis: Precise

of Blk 1 Kaki Bukit Ave 6 #02-31

Insured

Policy No.

Claims No.

Sum Insured

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Date / Time Action / Instruction

Range \$4900 - \$5900

5 Day Repair

RECEIVED 10 APR 2018



4/4/2018

Date/Time File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 2

Survey Fee:

Transportation

1.5 - 3.5

Photo

Sketch

Add Fee:

☐

Site Insp \$

☐

Interview \$

☐

Tech. Insp \$

☐

Vehicle \$

Report Format: PRE

Lump Sum / I.B.I. / S

Veh No: SJN 2145K Yr Regn: 912/2009

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Wdh. CC: 1794

Colour: Dark Gray A/C: Insured / Std / NI / NA

So. Reading: 163899 T/Radio: Insured / Std / NI / NA

Eng No:

C.No: JTDER12W103001806

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size F: 195/65/R15

R: 195/65/R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Pirelli:

Front

Rear

R/Bal: 3 mm

R/Bal: 3 mm

L/Bal: 3 mm

L/Bal: 3 mm

D.O.A.

D.O.I: 25/1/2018

Survey held at: As Above

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Jan 2018		24 Jan 2018 15:24 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	KIM BOCK CONTRACTOR PTE LTD, Co. Reg. No.: 197800646E		
Main Claimant:	SM GROUP (1988) PTE LTD, Co. Reg. No.: 198804312K		
Vehicle Reg. No.:	SJN2145K	Date of Loss:	19/01/2018 19:00 - :59
Claim Type:	TP / SNM18D00406C02	Policy/Cover Note No.:	DMCVSN1761301700 (Comprehensive)
Vehicle Reg. No. (Insured):	YP4616S	Policy No. (Claimant):	17-MI001228-R00
		Excess:	S\$0.00
Repairer:	Precise Auto Service (HQ) No 1 Kaki Bukit Ave 6, #02-34/36, 417883 Kaki Bukit - Tel: 67457367		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Claimant's Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 02/02/2018]		
Driver/Custodian (Insured):	SEVUGARETHINAM PANDIYARAJAN (29 / Male), NRIC: G6535399M, Tel: +6586958650		
Adj Asg. Remarks:	NO EST, CASE W/O SJE		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

4.22pm
 veh. ✓
 Yun Hong
 25/1/18

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/01/2018 13:33
Date Of Accident	19/01/2018 19:15
Exact Location Of Accident	ALONG UPPER THOMSON ROAD TOWARDS YISHUN
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJN2145K
Insured/Policyholder	
Name Of Registered Owner	SM GROUP (1988) PTE LTD
Co Reg No	198804312K
Email Address	DARRENCE76@GMAIL.COM
Mobile Phone No	
Alternative Phone No	OFFICE-63489909

Vehicle Particulars

Manufacturer	TOYOTA
Model	WISH-1.8 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

PRIVATE HIRE

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	17-MI001228-R00
Cover Note Number	

Driver

Name of Driver	CHEOW YUE SENG
NRIC No	S7608735J
Date Of Birth	28/03/1976
Occupation	OUTDOOR
Date Of Driving Pass	18/05/2001
Driving Experience	16 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90013349
Fax Number	
Contact Number	
Email Address	NOEMAIL


Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan #2 Pg. 1

SKETCH PLAN

- ① SJN 2145K
 - ② YP 4616S
- Along Upper Thomson Road Towards Yishun.



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 19-01-2018 @ about 1915hrs, I was driving my car (SJN 2145K) stationary along Upper Thomson Road in middle lane with 3 uber passengers, waiting the queuing in my lane due to the traffic jam in front of me. When vehicles ahead of me start to moving slowly and I follow slowly wave on, suddenly, I felt an impact from behind. When I come out inspect my car I realized that Vehicle B (YP4616S) did not stop in time and then collided onto rear portion of my car. Hence I hereto lodge this report to claim against Vehicle B (YP4616S)'s Insurance for my accident damage. I wish to state that I will go to see doctor after this if I feel any uncomfortable after this.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 20/1/18

12pm

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Jan 2018		24 Jan 2018 15:24 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	KIM BOCK CONTRACTOR PTE LTD, Co. Reg. No.: 197800646E		
Main Claimant:	SM GROUP (1988) PTE LTD, Co. Reg. No.: 198804312K		
Vehicle Reg. No.:	SJN2145K	Date of Loss:	19/01/2018 19:00 - :59 [107 Months and 10 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D00406C02	Policy/Cover Note No.:	DMCVSN1761301700 (Comprehensive)
Vehicle Reg. No. (Insured):	YP4616S	Policy No. (Claimant):	17-MI001228-R00
		Excess:	S\$0.00
Repairer:	Precise Auto Service (HQ) No 1 Kaki Bukit Ave 6, #02-34/36, 417883 Kaki Bukit - Tel: 67457367		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Claimant's Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Teo Cheng Ming Wilson] ... [Final Rpt due 02/02/2018]		
Driver/Custodian (Insured):	SEVUGARETHINAM PANDIYARAJAN (29 / Male), NRIC: G6535399M, Tel: +6586958650		
Adj Asg. Remarks:	NO EST, CASE W/O SJE		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJN2145K (SNM18D00406C02)**
[YP4616S]

TP

SM GROUP (1988) PTE LTD
Jan 19 2018 7:00PM
[KIM BOCK CONTRACTOR PTE LTD]
Precise Auto Service

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Assessment Reports			1 per page ▼	✓
No	Finalized On	Auto N Cars Services Pte Ltd (HQ)	Thumbnail	Print
1	22/01/18 13:41	Accident Statement	Load HTM	
Photos/Images			3 per page ▼	✓
No	Finalized On	Auto N Cars Services Pte Ltd (HQ)	Thumbnail	Print
1	22/01/18 13:41	Accident Photo [Linked Accident Report Documents]	Load JPG	✓
2	22/01/18 13:41	Accident Photo [Linked Accident Report Documents]	Load JPG	✓
3	22/01/18 13:41	Accident Photo [Linked Accident Report Documents]	Load JPG	✓
4	22/01/18 13:41	ac [Linked Accident Report Documents]	Load JPG	✓
5	22/01/18 13:41	Accident Photo [Linked Accident Report Documents]	Load JPG	✓
6	22/01/18 13:41	Accident Photo [Linked Accident Report Documents]	Load JPG	✓
7	22/01/18 13:41	Accident Photo [Linked Accident Report Documents]	Load JPG	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/04/18 10:39	LKK SURVEYOR PHOTO 1	Load PDF	
2	10/04/18 13:57	LKK SURVEYOR PHOTO 2	Load PDF	
3	10/04/18 13:57	LKK SURVEYOR PHOTO 3	Load PDF	
Documentation			1 per page ▼	✓
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	24/01/18 15:23	OI GIA REPORT	Load PDF	
No	Finalized On	Auto N Cars Services Pte Ltd (HQ)	Thumbnail	Print
1	22/01/18 13:40	Sketch Plan [Linked Accident Report Documents]	Load TIF	
2	22/01/18 13:40	Sketch Plan #2 [Linked Accident Report Documents]	Load TIF	
3	22/01/18 13:41	IC & DL [Linked Accident Report Documents]	Load TIF	
4	22/01/18 13:41	INS CERT [Linked Accident Report Documents]	Load TIF	

Linked Accident Report Documents

Assessment Reports			1 per page ▼	✓
No	Finalized On	Auto N Cars Services Pte Ltd (HQ)	Thumbnail	Print
1	22/01/18 13:41	Accident Statement	Load HTM	
Photos/Images			3 per page ▼	✓
No	Finalized On	Auto N Cars Services Pte Ltd (HQ)	Thumbnail	Print
1	22/01/18 13:41	Accident Photo	Load JPG	✓

Assessment Reports			1 per page ▼	✓
No	Finalized On	Auto N Cars Services Pte Ltd (HQ)	Thumbnail	Print
2	22/01/18 13:41	Accident Photo	 Load JPG	✓
3	22/01/18 13:41	Accident Photo	 Load JPG	✓
4	22/01/18 13:41	ac	 Load JPG	✓
5	22/01/18 13:41	Accident Photo	 Load JPG	✓
6	22/01/18 13:41	Accident Photo	 Load JPG	✓
7	22/01/18 13:41	Accident Photo	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	Auto N Cars Services Pte Ltd (HQ)	Thumbnail	Print
1	22/01/18 13:40	Sketch Plan	 Load TIF	
2	22/01/18 13:40	Sketch Plan #2	 Load TIF	
3	22/01/18 13:41	IC & DL	 Load TIF	
4	22/01/18 13:41	INS CERT	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI18001507/WBS2
Date: 13/04/2018

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN1761301700
Claimant Vehicle No: SJN2145K Insured Vehicle No: YP4616S
Date of Loss: 19/01/2018 Nature of Claim: TP Claim No: SNM18D00406C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJN2145K** Engine No: 1ZZ3226106
Make & Model: TOYOTA WISH, 1.8 (A) Chassis No: JTDER12W103001806
Reg. Date: 09/02/2009 (Man. Year: 2009) Odometer: 163899 km
Colour: Dark Grey
Engine Capacity: 1794 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15
Front Left Side: Pirelli 3 mm Rear Left Side: Pirelli 3 mm
Front Right Side: Pirelli 3 mm Rear Right Side: Pirelli 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 24/01/2018
Date Inspected: 25/01/2018 Inspected At: Precise Auto Service (HQ)
Singapore 417883
Estimated Period of Repair: 5.0 days

Adjuster: Teo Cheng Ming Wilson

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

4/13/2018

Adjuster Report

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,900.00 - \$5,900.00

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Apr 2018)
Parts:	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJN2145K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >