

22/03/2002

ASS. RFC. BY:

REF:

CS/msh18001509/Wqb sm

Special Instruction:

Survivor:

Wilson

ASSIGNMENT (Office)

From (Person):

Trene Tan

of

MEL

Date/Time: 24/01/2018 320pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FD 1532P

Insured:

SKV 1145M

at Workshop m/s

First Motor

Tel:

of

Blk 3006 ubi Rd #01-398

Policy No:

MSD/VPCP/17-001781

Claim No:

MSC/V/18/000004

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

08/02/2017

CA / REV / REP. / REV 24 HRS WPI

H.O.D. Endorsement:

Date/Time:

24/01/2018 423pm

Person Contacted:

Mr. Lim

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	FD 1532P - X
	SKV 1145M - X
31/1/18	Submit Uneconomical Total Loss Report. (LS \$5300)
	UV: \$1500 (em)
	UTR: \$135
	NV: \$1365

PHS
SIR/MS/LS/MS

REF: msh

Melmen

ASSIGNMENT

From: Date: 25012018

Estimated Cost:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No: FQ 1532P

at Workshop m/s: First Motor

of Blk 3006 Ubi Rd 1 # 01-398

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bel. or Market Value:

1500 p (est)

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: FQ 1532P

Yr Regn: 8/5/1998

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda

cc 399

Colour: Black

A/C Insured / Std / NI / NA

Sp. Reading: 29430

T.Radio: Insured / Std / NI / NA

Eng/No:

C/No: NC 311555 208

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 120/60 2R17

R: 160/60 2R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

DIABLO (F)

Front

Rear

R.Bal.

2 mm

R.Bal.

2

mm

L.Bal.

mm

L.Bal.

mm

D.O.A.

8/12/2017

D.O.I.

25/1/2018

Survey held at

As Above

Des. of Damages

Frt

Rear

O/S

N/S

U/C

Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

* M.J → \$ 1500

— Recommend Total Lost (Extensive Repair) —

Signature

RECEIVED 5 JAN 2018

29/1/2018

Date/Time File Pass to?

☐

: Preli. Report

29/1/2018

☐

: Final Report

Date/Time File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transportation

\$ 400

Photo

Draw

Add Fee:

☐

Site Insp \$

☐

Interview \$

☐

Tech Invs \$

☐

Weekend \$

200

10

Report Format: MER-7L-4

Lump Sum / I.B.I: \$

Survey Department Check List (Case Handler)

Reference No.: CG/MSG/18001509/WQB
Policy Type: OD / TP / TP RES / TL / EVA

FB/1532P

Case Handler

Typist

Admin (Cgtr): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
☒	☒		
☒	☒		
☒	☒		
☒	☒		
☒	☒		
☒	☒		
☒	☒		
☒	☒		
☒	☒		
☒	☒		
☒	☒		
☒	☒		
☒	☒		
☒	☒		

Surveyor (Wilson): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

☒	☒		
☒	☒		
☒	☒		
☒	☒		
☒	☒		
☒	☒		
☒	☒		
☒	☒		
☒	☒		
☒	☒		
☒	☒		
☒	☒		
☒	☒		
☒	☒		
☒	☒		
☒	☒		
☒	☒		

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

☒	☐	☐
-------------------------------------	--------------------------	--------------------------

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

☒	☐	☐
☐	☐	☐
☐	☐	☐
☐	☐	☐
☐	☐	☐
☐	☐	☐

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

☐	☐	☐
--------------------------	--------------------------	--------------------------

Check By:

Chn 31/1/18
Case Handler Date



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18001509/Wqb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 25-01-2018	
		Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKV 1145M	Veh. Inspected	FQ 1532P
Policy No.	MSD/VPCP/17-001781	Coverage (\$)	0.00
Claim No.	MSC/V/18/000004	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAN)	Assign Date	24/01/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	08/12/2017	Inspection Date	25/01/2018
Survey held at	FIRST MOTOR BLK 3006 UBI RD 1 #01-398 SINGAPORE 408700		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Jan 2018		24 Jan 2018 15:20 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	TOKYO CENTURY LEASING (SINGAPORE PTE LTD), Co. Reg. No.: 197901535G		
Main Claimant:	IMRAN BIN KARIM, ID: S7237977B		
Vehicle Reg. No.:	FQ1532P	Date of Loss:	08/12/2017 18:00 - :59
Claim Type:	TP / MSC/V/18/000004	Policy/Cover Note No.:	MSD/VPCP/17-001781 (Comprehensive) Coverage: 01/09/2017 - 31/08/2018
Vehicle Reg. No. (Insured):	SKV1145M	Policy No. (Claimant):	
		Excess:	
Repairer:	M/s First Motor (HQ) Blk 3006 Ubi Road 1, #01-398, 408700 Ubi - Tel: 67431911		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 25/01/2018]		
Driver/Custodian (Insured):	SANDY SOH POH LI (/ Female), NRIC: S7604471F, Tel: +6581007822		
Adj Asg. Remarks:	Please survey, car is in. Thank You. Please assign Mr Marcus Chua to survey. Thank You.		

ASSOCIATED MAIL RECEIVED
[View All](#) [Compose Case Mail](#)

- MSIG_SG (23/01/2018): Cancellation of Assignment: FQ1532P

ALL ASSOCIATED TASKS
[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

4.23pm
 est: X
 veh: ✓
 Lim
 28/11/2018
 call by go

**COSMAS LLC**

A LIMITED LIABILITY LAW CORPORATION

Your Ref: Please Advise

Our Ref: CG/CH/ns/4472.18.Imran

22nd January 2018REG/CS/PAY/FA
22 JAN 2018

TH

**IMMEDIATE
ATTENTION****MSIG Insurance (Singapore) Pte Ltd**4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807**BY FAX & POST**
Fax No: 6225 7402

Dear Sir,

**CLAIMANT: IMRAN BIN KARIM (NRIC NO.S7237977B)
ACCIDENT INVOLVING FQ 1532P & SKV 1145M ALONG CTE TOWARDS CITY ON 8TH
DECEMBER 2017 AT ABOUT 1855 HOURS (PROPERTY DAMAGE CLAIM)**

1. We refer to the above matter in which we act for Imran Bin Karim, the owner and rider of motor vehicle No. FQ 1532P.
2. Our client's motor vehicle No. FQ 1532P was involved in an accident with motor vehicle No. SKV 1145M on 8th December 2017 which we understand was insured by your company. Estimated repair of the said vehicle is enclosed herewith for your kind reference.
3. We hereby give you two **(2) days (i.e 24th and 25th January 2018)** notice for your surveyor to arrange for an inspection on our client's motor vehicle No. FQ 1532P at our client's workshop with the address and time as follows:-

Place: **M/s First Motor**
Blk 3006 Ubi Road 1, #01-398
Singapore 408700

Contact No: **6743 1911 - Mr. Lim**
9639 1004 - Mr. Lim

Time: **Between 11am to 6pm**



**SINGAPORE
POLICE FORCE**



T/20171213/2179

Police Station Of Origin:
Yishun South N.P.C
32 Yishun Street 81 SINGAPORE 768456
Tel No: 1800-8522999

1 of 3

Report No. T/20171213/2179

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 13/12/2017 22:12		Vide Report No.:		Station Diary No.: 83	
Informant's Particulars					
Name of Informant: IMRAN BIN KARIM			Address: APT BLK 510A YISHUN STREET 51 #08-551 SINGAPORE 761510		
ID Type / ID No.: NRIC NO / S7237977B			Contact No.: Home/Office: Mobile: 82793772		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 45	Date of Birth: 16/10/1972	Type of Informant: Rider		
Race: Malay			Language:		Institution / School Name:
Occupation: Private security officer			Driving Licence Information: Class: 2B,2A,2 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 08/12/2017 18:55	Type of Location: Straight Road
Location: Along Road 1 CENTRAL EXPRESSWAY CTE towards Moulmein road				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FQ1532P	Motorcycle	HONDA	CB 400 F3VJ	Black	Seriously Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FQ1532P	NTUC Income Insurance Co-Operative Limited	5068111334-02	02/02/2017	01/02/2018

* D.O.A → 8/12/2017



Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		29	04 ¹²	2018 ⁷
Owner ID Type:	Singapore NRIC	8	12	2017
Owner ID:	7977B	21	4	
Vehicle Details		(Bal = 0.7 Month)		
Vehicle No.:	FQ1532P			
Vehicle to be Exported:	No	* Balance 4.7 Month		
Intended De-registration Date:	26 Jan 2018			
Vehicle Make:	HONDA			
Vehicle Model:	CB 400 F3VJ			
Primary Colour:	Red			
Manufacturing Year:	1998			
Engine No.:	NC23E1855217			
Chassis No.:	NC311555208			
Maximum Power Output:	-			
Open Market Value:	\$7,548.00			
Original Registration Date:	08 May 1998			
First Registration Date:	08 May 1998			
Transfer Count:	7			
Actual ARF Paid:	\$1,133.00			
Intended PARF Rebate Details				
PARF Eligibility:	No			
PARF Eligibility Expiry Date:	-			
PARF Rebate Amount:	\$0.00			
Intended COE Rebate Details				
COE Expiry Date:	30 Apr 2018			
COE Category:	D - Motorcycle			
COE Period(Years):	10			
PQP Paid:	\$988.00			
COE Rebate Amount:	\$135.00			
Total Rebate Amount:	\$135.00			

The information contained herein is correct as at 26 Jan 2018

OK

* M.V → \$ 1500.

Enquire Transfer Fee

Vehicle Details

Vehicle No.:	FQ1532P
Vehicle Type:	P00 - Passenger Motorcycle/Autocycle/Moped
Vehicle Attachment 1:	No Attachment
Vehicle Scheme:	Normal
Vehicle Make:	HONDA
Vehicle Model:	CB 400 F3VJ
Chassis No.:	NC311555208
Propellant:	Petrol
Engine No.:	NC23E1855217
Engine Capacity:	399 cc
Maximum Power Output:	-
Maximum Laden Weight:	-
Unladen Weight:	-
Year Of Manufacture:	1998
Original Registration Date:	08 May 1998
Lifespan Expiry Date:	-
COE Category:	D - Motorcycle
PQP Paid:	\$988.00
COE Expiry Date:	30 Apr 2018
Lay Up Expiry Date:	30 Apr 2018
Inspection Due Date:	01 Feb 2018
Intended Transfer Date:	26 Jan 2018
CO2 Emission:	-
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use [Enquire Road Tax Payable](#) for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable

	Amount Before GST (\$)	GST Amount (\$)	Amount After GST (\$)
Transfer Fee:	25.00	-	25.00
Total Amount Payable:			25.00

You may print this page for reference.

OK Print



income

made different

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number : 5068111334-02

Cover : Third Party-

- | | |
|---|-------------------|
| 1. Index mark and Registration Number of Vehicle | : FQ1532P |
| Chassis Number | : NC311555208 |
| 2. Name of Policyholder | : IMRAN BIN KARIM |
| 3. Effective Date of Insurance | : 02 Feb 2017 |
| 4. Expiry Date of Insurance | : 01 Feb 2018 |
| 5. Persons or Classes of Persons entitled to drive# | |

(a) Named Driver(s) Only.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to Use#

(a) Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession.

This Policy does not cover

- (a) Use for hire or reward.
- (b) Use for racing, pace-making, reliability trial or speed-testing.
- (c) Use for the carriage of goods (other than samples) in connection with any trade or business.
- (d) Use for any purpose in connection with the Motor Trade.

Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: N/A
EXCESS (SECTION 2)	: N/A
INSURE WITH COE	: N/A
NAMED DRIVER (1)	: IMRAN BIN KARIM
NAMED DRIVER (2)	: KARIM BIN NARDIM
HIRE PURCHASE COMPANY	: N/A
SUM INSURED	: N/A

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : A S PHOON PTE LTD (00000571911)
Date of Issue : 27 Jan 2017 10:39 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Countersigned By:

Authorised Officer

Chief Executive

FIRST MOTOR

BLK 3006 UBI ROAD 1 #01-398 SINGAPORE 408700

TEL: 6743 1911 / 6744 8333 FAX NO: 6745 8131

RCB REG NO: 289644/OOC

E-mail: lionell@singnet.com.sg

E-mail: first_motor_sg@yahoo.com

DATE : 19/1/2018

REF NO :

VEH NO : FQ1532P

HONDA CB400VS

ATTN : CLAIM DEPT

RE : ESTIMATION FOR ACCIDENT INVOLVING VEH NO. FQ1532P/ ON 17/01/2018

ITEM	QTY	DESCRIPTION	PRICE(SS)
1	1	HANDLE BAR ✓ BT	110.00 ✓
2	2	MIRROR (LH)&(RH)@\$65.00 BR/ BT	130.00 ✓
3	1	CLUTCH LEVER ✓ SCR/ BT	18.00 ✓
4	1	BRAKE LEVER ✓ SCR/ BT	36.00 ✓
5	1	HANDLE GRIP ✓ NEC	28.00 ✓
6	1	BALANCE ✓ SCR	20.00 ✓
7	1	METER ASSY ✓ BR	850.00 ✓
8	1	HEADLAMP ASSY ✓ DD	275.00 ✓
9	2	FORK ASSY (LH)&(RH)@\$880.00 ✓ BT	1,760.00 ✓ 1550
10	1	FRONT FENDER ✓ SCR	230.00 ✓
11	1	FRONT WHEEL ✓ WP	780.00 ✓
12	2	FRONT DISC (LH)&(RH)@\$395.00 ✓ DIS	790.00 ✓
13	1	RADIATOR UNIT ASSY ✓ SCR	680.00 ✓ 550
14	1	ENGINE GUARD ✓ DD	200.00
15	1	MUFFLE ✓ SCR	680.00
16	1	EXHAUST PIPE X R	780.00 X
17	2	FRONT SIGNALLAMP (RH)&(LH) @\$58.00 ✓ BR	116.00 ✓
18	1	REAR BOX GIVI ✓ SCR	180.00 ✓
19	1	BOX BRACKET ✓ BT	90.00 ✓
20	1	REAR SUSPENSION X NN	580.00 X

TOTAL PARTS	8,333.00	6633
LESS 10%	833.30	663.3
TOTAL	7,499.70	5969.9
ERP IU UNIT (NETT)/ BR	156.00	156.00
TOTAL	7,655.70	6125.9

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LABOUR & MISC

CHASSIS REPAIR	480.00	20
FUEL TANK PAINTING FEE X NN	350.00	X
TRANSPORT FEE	50.00	35
LABOUR CHARGE	350.00	✓

GRAND TOTAL : 8,885.70 505

Gtd # 6630.97

Dilett # 1326.19

Chump Sum # 5304.78

AUTHORISED SIGNATURE

15 APR

Wolam, Wate

25/1/2018

96404128

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Jan 2018		24 Jan 2018 15:20 Edit Adj Rpt	S\$5,300.00 Edit Estimates	S\$5,300.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	TOKYO CENTURY LEASING (SINGAPORE PTE LTD), Co. Reg. No.: 197901535G		
Main Claimant:	IMRAN BIN KARIM, ID: S7237977B		
Vehicle Reg. No.:	FQ1532P	Date of Loss:	08/12/2017 18:00 - :59
Claim Type:	TP / MSC/V/18/000004	Policy/Cover Note No.:	MSD/VPCP/17-001781 (Comprehensive) Coverage: 01/09/2017 - 31/08/2018
Vehicle Reg. No. (Insured):	SKV1145M	Policy No. (Claimant):	
		Excess:	
Repairer:	M/s First Motor (HQ) Blk 3006 Ubi Road 1, #01-398, 408700 Ubi - Tel: 67431911		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Teo Cheng Ming Wilson] ... [Imm.Advice due 25/01/2018]		
Driver/Custodian (Insured):	SANDY SOH POH LI (/ Female), NRIC: S7604471F, Tel: +6581007822		
Adj Asg. Remarks:	Please survey, car is in. Thank You. Please assign Mr Marcus Chua to survey. Thank You.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- MSIG_SG (23/01/2018): Cancellation of Assignment: FQ1532P

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FQ1532P (MSC/V/18/000004)

[SKV1145M]

TP

IMRAN BIN KARIM

Dec 8 2017 6:00PM

[TOKYO CENTURY LEASING (SINGAPORE PTE LTD)]

M/s First Motor

Upload Documents Upload Photos Compose New Letter

View View in Browser

Video			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	23/01/18 09:08	Video - Accident From:SC - Reg. No: SKV1145M, Claimant: TOKYO CENTURY LEASING (SINGAPORE PTE LTD)	Load MP4	☐
2	23/01/18 09:08	Video - Accident From:SC - Reg. No: SKV1145M, Claimant: TOKYO CENTURY LEASING (SINGAPORE PTE LTD)	Load MP4	☐
Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	23/01/18 09:08	Accident Statement From:SC - Reg. No: SKV1145M, Claimant: TOKYO CENTURY LEASING (SINGAPORE PTE LTD)	Load HTM	☐
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	31/01/18 11:16	General View	Load JPG	☒
2	31/01/18 11:16	General View	Load JPG	☒
3	31/01/18 11:16	General View	Load JPG	☒
4	31/01/18 11:16	General View	Load JPG	☒
5	31/01/18 11:16	General View	Load JPG	☒
6	31/01/18 11:16	General View	Load JPG	☒
7	31/01/18 11:16	General View	Load JPG	☒
8	31/01/18 11:16	General View	Load JPG	☒
9	31/01/18 11:16	General View	Load JPG	☒
10	31/01/18 11:16	General View	Load JPG	☒
11	31/01/18 11:16	General View	Load JPG	☒
12	31/01/18 11:16	General View	Load JPG	☒
13	31/01/18 11:16	General View	Load JPG	☒
14	31/01/18 11:16	General View	Load JPG	☒
15	31/01/18 11:16	General View	Load JPG	☒
16	31/01/18 11:16	General View	Load JPG	☒
17	31/01/18 11:16	General View	Load JPG	☒
18	31/01/18 11:16	General View	Load JPG	☒
19	31/01/18 11:16	General View	Load JPG	☒
20	31/01/18 11:16	General View	Load JPG	☒
21	31/01/18 11:16	General View	Load JPG	☒
22	31/01/18 11:16	General View	Load JPG	☒
23	31/01/18 11:16	General View	Load JPG	☒
24	31/01/18 11:16	General View	Load JPG	☒
25	31/01/18 11:16	General View	Load JPG	☒

					☒
26	31/01/18 11:16	General View		Load JPG	☒
27	31/01/18 11:16	General View		Load JPG	☒
28	31/01/18 11:16	General View		Load JPG	☒
29	31/01/18 11:16	General View		Load JPG	☒
30	31/01/18 11:16	General View		Load JPG	☒
31	31/01/18 11:16	General View		Load JPG	☒
32	31/01/18 11:16	General View		Load JPG	☒
33	31/01/18 11:16	General View		Load JPG	☒
34	31/01/18 11:16	General View		Load JPG	☒
35	31/01/18 11:16	General View		Load JPG	☒
36	31/01/18 11:16	General View		Load JPG	☒
37	31/01/18 11:16	General View		Load JPG	☒
38	31/01/18 11:16	General View		Load JPG	☒
39	31/01/18 11:16	General View		Load JPG	☒
40	31/01/18 11:16	General View		Load JPG	☒
41	31/01/18 11:16	General View		Load JPG	☒
42	31/01/18 11:16	General View		Load JPG	☒
43	31/01/18 11:16	General View		Load JPG	☒
44	31/01/18 11:16	General View		Load JPG	☒
45	31/01/18 11:16	General View		Load JPG	☒
46	31/01/18 11:16	General View		Load JPG	☒
47	31/01/18 11:16	General View		Load JPG	☒
48	31/01/18 11:16	General View		Load JPG	☒
49	31/01/18 11:16	General View		Load JPG	☒
50	31/01/18 11:16	General View		Load JPG	☒
51	31/01/18 11:16	General View		Load JPG	☒
52	31/01/18 11:16	General View		Load JPG	☒
53	31/01/18 11:16	General View		Load JPG	☒
54	31/01/18 11:16	General View		Load JPG	☒
55	31/01/18 11:16	General View		Load JPG	☒
56	31/01/18 11:16	General View		Load JPG	☒
57	31/01/18 11:16	General View		Load JPG	☒
58	31/01/18 11:16	General View		Load JPG	☒
59	31/01/18 11:16	General View		Load JPG	☒
60	31/01/18 11:16	General View		Load JPG	☒
61	31/01/18 11:16	General View		Load JPG	☒
62	31/01/18 11:16	General View		Load JPG	☒
63	31/01/18 11:16	General View		Load JPG	☒
64	31/01/18 11:16	General View		Load JPG	☒
65	31/01/18 11:16	General View		Load JPG	☒
66	31/01/18 11:16	General View		Load JPG	☒
67	31/01/18 11:16	General View		Load JPG	☒
68	31/01/18 11:16	General View		Load JPG	☒
69	31/01/18 11:16	General View		Load JPG	☒
70	31/01/18 11:16	General View		Load JPG	☒
71	31/01/18 11:16	General View		Load JPG	☒
72	31/01/18 11:16	General View		Load JPG	☒

73	31/01/18 11:16	General View	1	Load JPG	✓
74	31/01/18 11:16	General View	i	Load JPG	✓
75	31/01/18 11:16	General View	i	Load JPG	✓
76	31/01/18 11:16	General View	i	Load JPG	✓
77	31/01/18 11:16	General View	i	Load JPG	✓
78	31/01/18 11:16	General View	i	Load JPG	✓
79	31/01/18 11:16	General View	i	Load JPG	✓
80	31/01/18 11:16	General View	i	Load JPG	✓
81	31/01/18 11:16	General View	i	Load JPG	✓
82	31/01/18 11:16	General View	i	Load JPG	✓
83	31/01/18 11:16	General View	i	Load JPG	✓
84	31/01/18 11:16	General View	i	Load JPG	✓
85	31/01/18 11:16	General View	i	Load JPG	✓
86	31/01/18 11:16	General View	i	Load JPG	✓
87	31/01/18 11:17	General View	i	Load JPG	✓
				1 per page	✓
Documentation					
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	23/01/18 09:09	TP PRI with estimates	i	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	07/02/18 12:02	LTA REBATE	i	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18001509/WQBS2
Date: 07/02/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: MSD/VPCP/17-001781
Claimant Vehicle No: FQ1532P Insured Vehicle No: SKV1145M
Date of Loss: 08/12/2017 Nature of Claim: TP Claim No: MSCV/18/000004

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FQ1532P
Make & Model: HONDA CB 400 F3WYB, 399cc (M)
Reg. Date: 08/05/1998 (Man. Year: 1998)
Colour: Black
Engine Capacity: 399 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

Engine No: NC23E1855217
Chassis No: NC311555208
Odometer: 29430 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/60ZR17 Rear Tyre Size: 160/60ZR17
Front Left Side: DIABLO 2 mm Rear Left Side: Battlax 2 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,655.70	6,125.70	1,530.00	19.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,230.00	505.00	725.00	58.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,885.70	6,630.70	2,255.00	25.38
Approved Total (Overridden) (S\$)		5,300.00		
Nett Amount (S\$)	8,885.70	5,300.00	3,585.70	40.35

INSPECTION

Date of Assignment: 24/01/2018
Date Inspected: 25/01/2018 Inspected At: M/s First Motor (HQ)
Singapore 408700
Estimated Period of Repair: 0.0 days

Adjuster: Teo Cheng Ming Wilson

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

2/7/2018

Adjuster Report

MARKET VALUE: \$1,500.00 (est)

LTA REBATE :\$135.00

NETT VALUE :\$1,365.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 07 Feb 2018)

Parts: N/A HONDA CB 400 F3WYB 399cc (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for FQ1532P)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HANDLE BAR	Bent	110.00 FL	*110.00 FL
2	2		*MIRROR (LH)&(RH)	Broken / Bent	130.00 FL	*130.00 FL
3	1		*CLUTCH LEVER	Scratched / Bent	18.00 FL	*18.00 FL
4	1		*BRAKE LEVER	Scratched / Bent	36.00 FL	*36.00 FL
5	1		*HANDLE GRIP	Necessary	28.00 FL	*28.00 FL
6	1		*BALANCE	Scratched	20.00 FL	*20.00 FL
7	1		*METER ASSY	Broken	850.00 FL	*850.00 FL
8	1		*HEADLAMP ASSY	Dented	275.00 FL	*275.00 FL
9	2		*FORK ASSY (LH)&(RH)	Bent	1,760.00 FL	*1,550.00 FL
10	1		*FRONT FENDER	Scratched	230.00 FL	*230.00 FL
11	1		*FRONT WHEEL	Warped	780.00 FL	*780.00 FL
12	2		*FRONT DISC (LH)&(RH)	Distorted	790.00 FL	*790.00 FL
13	1		*RADIATOR UNIT ASSY	Scratched	680.00 FL	*550.00 FL
14	1		*ENGINE GUARD	Dented	200.00 FL	*200.00 FL
15	1		*MUFFLE	Scratched	680.00 FL	*680.00 FL
16	1		*EXHAUST PIPE	Repair	780.00 FL	*- FL
17	2		*FRONT SIGNALLAMP (RH)&(LH)	Broken	116.00 FL	*116.00 FL
18	1		*REAR BOX GIVI	Scratched	180.00 FL	*180.00 FL
19	1		*BOX BRACKET	Bent	90.00 FL	*90.00 FL
20	1		*REAR SUSPENSION	Not Necessary	580.00 FL	*- FL
21	1		*ERP IU UNIT	Broken	156.00 FS	*156.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,489.00	6,789.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	833.30	663.30
Total Parts (\$\$)	7,655.70	6,125.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHASSIS REPAIR.	New	480.00	120.00
2	FUEL TANK PAINTING FEE.	New	350.00	0.00
3	TRANSPORT FEE.	New	50.00	35.00
4	LABOUR CHARGE.	New	350.00	350.00
Gross Labour Cost (S\$)			1,230.00	505.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >