

22/03/2002

ASS. REC. BY:

REF:

CS3 / CT118001531 / Wb02

Special Instruction:

TAMPA X-00007

SUNALOK  
MUMUKH

W/SON

**ASSIGNMENT (Office)**

From (Person):

Irene Tay

of

CT1

Date/Time:

24012018 456pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SFT 970Z

Insured:

ABB 6507G

at Workshop m/s

Global Machinna

Tel:

of

25 Kaki Bukit Road 4 #01-62

Policy No:

DMCVSV 3078171700

Claim No:

SNM18D00433C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

200(2018)

CA / REV / REP. / REV 24 HRS WPI

H.O.D. Endorsement:

Date/Time:

25012018 1033am

Person Contacted:

MR. NEO

Vehicle **IN** / OUT

| Date/Time | Action/Instruction ( X ) Estimate |
|-----------|-----------------------------------|
|           | SFT 970Z - X                      |
|           | ABB 6507G - NA / TR112010352 / W1 |
|           | Dismantle Part: 26.01.2018        |
|           | After Repair: 30.01.2018          |
|           |                                   |
|           |                                   |
|           |                                   |
|           |                                   |
|           |                                   |

DCA: 23/5/12

PRS  
S. Wilson  
Machina

REF: CTL

# ASSIGNMENT

From: Date: 15/01/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SFT 970Z  
at Workshop in: Global Machina  
of: 25 Kaki Bukit Rd 4 #01-62  
Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

|     |     |
|-----|-----|
| X   |     |
| N/S | O/S |
|     |     |

Est. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Ref No: SFT 970Z Page: 2008 Dec 23

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Airwave

Colour: Black A/C Insured / Std / NI / NA

Sp. Reading: 23626 T. Radio: Insured / Std / NI / NA

Eng No:

C No: GJ1-1301337

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/65 R14

R: 185/65 R14

BS / DUN / EXNOVA / GY / FS / LIZA / NIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R.Bal: 3 mm R.Bal: 3 mm

L.Bal: 3 mm L.Bal: 3 mm

D.O.A. D.O.A. 25/1/2018

Survey held at: At Above @ 1.45pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Left Frt

The U/C / Chassis frame / Body Structure affected due to collision

Date Time Action / Instruction

Estimated repair range \$3,000 - \$4,000.

13/3/2018

Date Time File Pass to: ☐ : Preli. Report

13.03.2018 ☐ : Final Report

Date Time File Return to:

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transportation

Report Format: PRS

Lump Sum / L.Bal: \$

Add Fee: ☐ Site Insp: \$

☐ Interview: \$

☐ Test: \$

☐ Clean up: \$

☐ B-P: \$

Prints

Other

Total

150

## ...CLAIM SUBFOLDER...(New Assignment)

| CLAIM SUBFOLDER TRACKING |             |               |                                |         |               |            |                               |
|--------------------------|-------------|---------------|--------------------------------|---------|---------------|------------|-------------------------------|
| Case                     | Notified    | Est Submitted | Adj Assigned                   | Adj Rpt | Adj Submitted | Ins Auth'd | Status                        |
| Main                     | 23 Jan 2018 |               | 24 Jan 2018<br>16:56<br>Assign |         |               |            | New Assignment<br>Cancel Case |

|      |           |               |           |          |
|------|-----------|---------------|-----------|----------|
| Main | Reference | Claim Details | Documents | Show All |
|------|-----------|---------------|-----------|----------|

**CLAIM SUBFOLDER DETAILS**

[Created by insurer]

|                             |   |                        |                        |
|-----------------------------|---|------------------------|------------------------|
| Insured:                    |   |                        |                        |
| Main Claimant:              | PRESTIGE LEASING PTE LTD, Co. Reg. No.: NA  |                        |                        |
| Vehicle Reg. No.:           | SFT970Z   | Date of Loss:          | 20/01/2018 00:00 - :59 |
| Claim Type:                 | TP / SNM18D00433C02   | Policy/Cover Note No.: | DMCVSN3078171700       |
| Vehicle Reg. No. (Insured): | GBB6507G  | Policy No. (Claimant): |                        |
|                             |   | Excess:                | S\$0.00                |
| Repairer:                   | Global Machinna Pte Ltd (HQ) 25 Kaki Bukit Road 4, Synergy @ KB #01-62, 417800 Kaki Bukit - Tel:                    |                        |                        |
| Handling Insurer:           | China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192] |                        |                        |
| Adjuster:                   | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 02/02/2018]                                   |                        |                        |
| Adj Asg. Remarks:           | NO EST, CASE W/O SJE.   |                        |                        |

**ASSOCIATED MAIL RECEIVED**

View All Compose Case Mail

There are no mail for this case.

☐ **ALL ASSOCIATED TASKS**

View All Search Tasks Create New Task Complete

| Due Date    | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. |          |      |            |         |         |             |              |            |       |

25012018 @ 1035am

NR NRO veh in

MSME18010860 / SME Motor Pte Ltd - Kaki Bukit  
 ENTRY DATE & TIME: 22/01/2018 16:47  
 SUBMITTED BY: Chia Pei Ying

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report 22/01/2018 16:47  
 Date Of Accident 20/01/2018 13:00  
 Exact Location Of Accident 25 SYNERGY @ KB  
 Country/State of Loss SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number SFT970Z  
**Insured/Policyholder**  
 Name Of Registered Owner PRESTIGE LEASING PTE LTD  
 Co Reg No 199907072C  
 Email Address NOEMAIL  
 Mobile Phone No  
 Alternative Phone No OFFICE-97984296

### Vehicle Particulars

Manufacturer HONDA  
 Model AIRWAVE

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

### Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD  
 Type Of Coverage THIRD PARTY FIRE AND/OR THEFT  
 Fleet Policy NO  
 Policy Number 5094838100  
 Cover Note Number

### Driver

Name of Driver NEO BENG POH  
 NRIC No S1211732I  
 Date Of Birth 19/12/1956  
 Occupation INDOOR  
 Date Of Driving Pass 05/08/1975  
 Driving Experience 42 YEARS AND 5 MONTHS  
 Gender MALE  
 Mobile Number (LOCAL) +65-91095745  
 Fax Number  
 Contact Number  
 EMail Address NOEMAIL

Address BLK 31 EUNOS CRESCENT #17-204  
 Postcode 400031  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OTHER --  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

### General Information of the Accident

Type Of Accident SIDE SWIPE  
 Weather Conditions CLEAR  
 Road Surface DRY

### Other Information

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

### Details of Police Action

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

### Circumstances of Accident

WHEN I WAS DRIVING ALONG BLK 25 SYNERGY KB, SUDDENLY TOYOTA LORRY (GBB6507G) CAME OUT FROM PARKING LOT AND KNOCK ONTO MY LEFT SIDE FRONT.

### Attachment(s)

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO


### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBB6507G  
 Vehicle Make/Model/Colour  
 Details Of Properties VEHICLE B  
 Vehicle Category COMMERCIAL VEHICLE  
 Name of Driver  
 NRIC/Passport Number  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)

# Sketch Plan #2 Pg. 1

## SKETCH PLAN

KB  
Synergy  
Blk 25



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

When I Was Driving Along Blk 25 Synergy  
KB Suddenly Toyota Lorry GBB 650TG Come  
Out From Parking lot and knock My left Side Front

## DECLARATION

I/We declare that the following particulars are true in every respect

Policyholder's Signature  
Date & Time:



Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

*[Handwritten Signature]*

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

| CLAIM SUBFOLDER TRACKING |             |               |  |  |  |            |   |
|--------------------------|-------------|---------------|--|--|--|------------|---|
| Case                     | Notified    | Est Submitted | Adj Assigned   | Adj Rpt  | Adj Submitted                              | Ins Auth'd | Status  |
| Main                     | 23 Jan 2018 |               | 24 Jan 2018<br>16:56<br><a href="#">Edit Adj Rpt</a> | <b>S\$0.00</b><br><a href="#">Edit Estimates</a> | <b>S\$0.00</b><br><a href="#">View Rpt</a> |            | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

| Main | Reference | Claim Details | Documents | <a href="#">Show All</a> |
|------|-----------|---------------|-----------|--------------------------|
|------|-----------|---------------|-----------|--------------------------|

| CLAIM SUBFOLDER DETAILS     |  | [Created by insurer]                    |
|-----------------------------|--|---|
| Insured:                    | -, Co. Reg. No.: -   |   |
| Main Claimant:              | PRESTIGE LEASING PTE LTD, Co. Reg. No.: NA   |   |
| Vehicle Reg. No.:           | SFT970Z  | Date of Loss: 20/01/2018 00:00 - :59    |
| Claim Type:                 | TP / SNM18D00433C02  | Policy/Cover Note No.: DMCVSN3078171700 |
| Vehicle Reg. No. (Insured): | GBB6507G   | Policy No. (Claimant):                  |
|                             |  | Excess: S\$0.00                         |
| Repairer:                   | Global Machinna Pte Ltd (HQ) 25 Kaki Bukit Road 4, Synergy @ KB #01-62, 417800 Kaki Bukit - Tel:                         |   |
| Handling Insurer:           | China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]      |   |
| Adjuster:                   | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Teo Cheng Ming Wilson] ... [Final Rpt due 02/02/2018] |   |
| Adj Asg. Remarks:           | NO EST, CASE W/O SJE.  |   |

| ASSOCIATED MAIL RECEIVED         | <a href="#">View All</a> <a href="#">Compose Case Mail</a> |
|----------------------------------|--|
| There are no mail for this case. |  |

| ALL ASSOCIATED TASKS |              | <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a> |
|----------------------|--------------|--|
| Due Date             | Priority     | Type   |
| Task Group           | Subject      | Handler  |
| Assigned By          | Completed On | Created On   |
| Done?                |              |  |
| No results.          |              |  |



Claim Documents

\*SFT970Z (SNM18D00433C02)  
[GBB6507G]  
TP  
PRESTIGE LEASING PTE LTD  
Jan 20 2018 12:00AM  
[-]  
Global Machinna Pte Ltd

Upload Documents | Upload Photos | Compose New Letter

View View in Browser ▾

| Documentation |                 |  | 1 per page ▾ | <input checked="" type="checkbox"/> |
|---------------|-----------------|--|--------------|-------------------------------------|
| No            | Finalized On    | China Taiping Insurance (Singapore) Pte. Ltd. (HQ) |              | Thumbnail Print                     |
| 1             | 24/01/18 16:54  | PRS  |              | Load PDF                            |
| 2             | 25/01/18 10:20  | PRS LOCATION                                       |              | Load PDF                            |
| No            | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)                  |              | Thumbnail Print                     |
| 1             | 13/03/18 16:42  | LKKPhotosIn6-1                                     |              | Load PDF                            |
| 2             | 13/03/18 16:42  | LKKPhotosIn6-2                                     |              | Load PDF                            |
| 3             | 13/03/18 16:42  | LKKPhotosIn6-3                                     |              | Load PDF                            |

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.



# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT118001531/WBE2

Date: 13/03/2018

### REFERENCE

|                       |   |                      |                  |
|-----------------------|---|----------------------|------------------|
| Handling Insurer:     | China Taiping Insurance (Singapore) Pte. Ltd. | Policy No:           | DMCVSN3078171700 |
| Claimant Vehicle No : | SFT970Z                                       | Insured Vehicle No : | GBB6507G         |
| Date of Loss:         | 20/01/2018                                    | Nature of Claim:     | TP               |
|                       |   | Claim No:            | SNM18D00433C02   |

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                              |             |            |
|-----------------------------|------------------------------|-------------|------------|
| Reg No:                     | SFT970Z                      | Engine No:  | HIDDEN     |
| Make & Model:               | HONDA AIRWAVE, 1.5 (A)       | Chassis No: | GJ11301337 |
| Reg. Date:                  | 23/12/2008 (Man. Year: 2008) | Odometer:   | 236126 km  |
| Colour:                     | Black                        |             |            |
| Engine Capacity:            | 0 cc                         |             |            |
| Market Value/New Car Price: | N/A                          |             |            |
| Sum Insured (S\$):          | Market Value/New Car Price   |             |            |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

### CONDITION OF TYRES

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 185/65 R14    | Rear Tyre Size:  | 185/65 R14    |
| Front Left Side:  | Michelin 3 mm | Rear Left Side:  | Michelin 3 mm |
| Front Right Side: | Michelin 3 mm | Rear Right Side: | Michelin 3 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS           | Repairer's  | Adjuster's  | Difference  | Diff % |
|--------------------------|-------------|-------------|-------------|--------|
| Parts                    | 0.00        | 0.00        | 0.00        |        |
| Miscellaneous Items      | 0.00        | 0.00        | 0.00        |        |
| Labour                   | 0.00        | 0.00        | 0.00        |        |
| Paintwork Labour         | 0.00        | 0.00        | 0.00        |        |
| Towing                   | 0.00        | 0.00        | 0.00        |        |
| <b>Nett Amount (S\$)</b> | <b>0.00</b> | <b>0.00</b> | <b>0.00</b> |        |

### INSPECTION

|                             |            |   |
|-----------------------------|------------|---|
| Date of Assignment:         | 24/01/2018 |   |
| Date Inspected:             | 25/01/2018 | Inspected At: Global Machinna Pte Ltd (HQ)<br>25 Kaki Bukit Road 4, Synergy @ KB #01-62<br>Singapore 417800 |
| Estimated Period of Repair: | 3.0 days   |   |

Adjuster: Teo Cheng Ming Wilson

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 -\$4,000.00

REPAIR DETAILS

Reference

|               |  |   |
|---------------|--|---|
| Part Source:  | MRM-SG   | Version: 1.0 (Last Synchronised: 13 Mar 2018)           |
| Parts:        | M1-MPV   | HONDA AIRWAVE 1.5 (A) (Catalogue:Merimen Singapore 1.0) |
| Labour:       | Repairer's   | (Price-denominated Standard List)                       |
| Print Code:   | (Unsubmitted, no print-code for SFT970Z)   |   |
| Validity:     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |   |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *.   |   |

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >