


SMRT Accident Vehicle Repair Estimates

FIG

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4424Z
 Ref. No : TAX/01/18/2136
 Reg. Date : 13/01/2014
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : ALVIN CHEN ZUO SHENG
 Type of Accident : SIDE SWIPE
 Date / Time of Accident : 20/01/2018 05:10:00 PM
 Accident Reported Date / Time : 22/01/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : Yes
 Towed Back Date/Time : 20/01/2018
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024094225
 Special Instruction to ARC,if any :
 TOWED \$40 / SKU5223A
 Prepared Date : 22/01/2018 02:59:22 PM



5/2/18
 25/1/18
 Repair Shop Repair
 - Please Affix Point
 1005612
 20/01/2018 05:10:00 PM

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36UX0-5721872

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 507.00	0.00
Total Spray Painting Charges	: 756.00	0.00
Total Material Charges	: 1,064.25	1,064.25
Other Charges	: 420.00	0.00
TOTAL	: 2,747.25	0.00
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 3.00	0.00
Prepared / Adjusted By	:	2 days
Arc / Surveyor Sing Off Date	: 23/01/2018 10:04:16 AM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 23/01/2018 10:04:16 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH FRONT PORTION	507.00	0.00 300
Total Labour	507.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT FENDER RH	378.00	0.00 200
TO REPSRAY FRONT BUMPER	378.00	0.00 200
Total Spray Painting & Panel Beating	756.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	80.00	0.00 /
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 X
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 30
TO REPLACE SUNDRY PARTS	100.00	0.00 X
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	420.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
53801-47050		6505557	FENDER FRT/RH	1	723.40	25.00	542.55	Replace	Replace <i>R</i>	No
75442-47030			NAME PLATE (PRIUS)	1	60.80	25.00	45.60	Replace	Replace <i>✓ N</i>	No <i>RC</i>
52119-47930		6505517	BUMPER FRT	1	482.00	25.00	361.50	Replace	Replace <i>✓</i>	No <i>✓ TN</i>
52115-47040		6505515	BUMPER SUPPORT F/RH	1	76.40	25.00	57.30	Replace	Replace <i>7</i>	No
TOTAL MATERIALS								1,006.95	1,006.95	
TOTAL MATERIALS(Discounted)								1,064.25	1,064.25	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									