	Rasul	ASSIGNM	ENT (Office)				
From (Person	i): Rauhel Ton	of	GAL	Date/	Time:	74012018	10.4500
Estimated Co			Bill to:				
	S/TP RES/OD RES/ chicle No:	414F MCC	В	Insured:	>	SUSFC BY	
	m/s	Midpoint &	કેપાર્ક	Tel:	6861	9731	
of		5 Tuas Ave	- 11				
Policy No:_		- 22 - 2 - 3 111 - 2 112	Claim No:			100	
Sum Insured			Excess:				
Make of Vel (Client's Recei	(b)			D.O.A		8105-10.	
(Client's Recon	(b)						
(Client's Recon		5 (WP) 33	Faber Walk S	Pore 1 28967	@ 10at	M ement:	
(Client's Recon	1 REP. / REV 24 HR 25012018 14544	S (WP) 33 MPerson Contacted:	Fabor Walk s	Pore 1 28967	@ 10at	M ement:	
(Client's Recon CA / REV Date/Time:	/ REP. / REV 24 HR	MPerson Contacted: X) Estimat	Fabor Walk s	Pore 1 28967	@ 10at	M ement:	
(Client's Recon CA / REV Date/Time:	/ REP. / REV 24 HRS 2501208 \\+5\LG	MPerson Contacted: X) Estimat	Faber Walk s Connic	Vehicle	C IVal	M ement:	211
(Client's Recon CA / REV Date/Time:	Action/Instruction (MPerson Contacted: X) Estimat	Faber Walk s Connic	Vehicle	C IVal	m ement:	21

REF:

Catherine Chong (LKK Auto)

From:

Janice Lee (LKKAuto) <JaniceLee@lkkauto.com>

Sent:

Wednesday, 24 January, 2018 10:45 AM

To:

assignments

Subject:

FW: YOUR REF: XB2780Z (GA) [FMC.11852.18.LYM/WPT] DOA: 12.01.18

Jensons Girenay a

Attachments:

FMC11852-GAIC_20180124102401.pdf

Dear Catherine,

FYNA

Thank you.

Best Regards,

Janice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan, Rachel [mailto:Rachel.Tan@sg.gaig.com] Sent: Wednesday, January 24, 2018 10:37 AM

To: SUR <sur@lkkauto.com>

Subject: RE: YOUR REF: XB2780Z (GA) [FMC.11852.18.LYM/WPT] DOA: 12.01.18

Hi LKK

Attached letter FYI

Regards Rachel Tan

From: Tan, Rachel

Sent: Tuesday, January 23, 2018 6:55 PM

To: 'Legiste Law Corporation' <advocates@legiste.com.sg>

Cc: SUR < sur@lkkauto.com>

Subject: RE: YOUR REF: XB2780Z (GA) [FMC.11852.18.LYM/WPT] DOA: 12.01.18

Without Prejudice

Dear Gina

Noted on your contents of the letter dated 23 Jan 2018 that you do not agree with our proposed list of surveyors. We will be appointing LKK Auto consultants to conduct Pre-repair inspection on our behalf. Please provide us with the location of survey.

Thank you

Regards

Rachel Tan

Executive, Motor Claims, Great American Insurance Company

Tel: 6804 7846

From: Legiste Law Corporation [mailto:advocates@legiste.com.sg]

Sent: Tuesday, January 23, 2018 5:43 PM
To: Tan, Rachel < Rachel. Tan@sg.gaig.com >

Subject: YOUR REF: XB2780Z [FMC.11852.18.LYM/WPT]

Importance: High

Dear Mdm

Please see attached.

Regards Gina Pat (secretary) M/s Legiste Law Corporation

Tel: 6227 9909 Fax: 6227 2767

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

Legiste Law Corporation

ADVOCATES & SOLICITORS
NOTARIES PUBLIC
COMMISSIONERS FOR OATHS
INCORPORATED WITH LIMITED LIABILITY
Co. & GST Regn. No. 200305183Z

FOK MUN CHEONG TAN KIM KEE NG LAI LENG

24 Peck Seah Street #04 - 06, Nehsons Building Singapore 079314 Telephone +65-62279909 Facsimile +65-62272767 E-mail advocates@legiste.com.sg

Your Ref

XB2780Z

Email

Rachel.Tan@sg.gaig.com

Our Ref

FMC.11852.18.LYM/WPT

24th January 2018

URGENT

The Motor Claims Department
Great American Insurance Company
No. 3 Temasek Avenue
#16 – 01 Centennial Tower
Singapore 039190
Attn: Ms Rachel Tan

BY EMAIL ONLY

Dear Sirs

PRE-REPAIR SURVEY
ACCIDENT ON 12.01.18 INVOLVING SJN 7414B & XB 2780Z
ALONG KEPPEL ROAD

CLAIMANT :

LEE YUKE MOI (NRIC No. S0106720F)

ADDRESS

C/O NO. 5 TUAS AVENUE 11 SINGAPORE 639071

We refer to your email dated 23rd January 2018.

As you have rejected our client's nominee as the Single Joint Expert, our client will proceed to appoint her own surveyor to carry out the PRS in accordance with the NIMA Protocol. On your part, please instruct your loss adjustors/surveyors to contact our client's appointed workshop as follows to carry out their own PRS:

Name:

Westpoint Bus Pte Ltd

Address:

5 Tuas Avenue 11

Contact Person:

Singapore 639071

Contact Ferson

Ms Connie Lim

Contact No.:

6861 9731

Yours faithfully

Joseph Fok Mun Cheong Legiste Law Corporation

enc



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT CS3/GAI18001548/R1be2 GREAT AMERICAN INSURANCE COMPANY Ref: 23-04-2018 3 TEMASEK AVENUE #16-01 CENTENNIAL Date: TOWER SINGAPORE 039190 Code: GAI Policy Particulars :- (THIRD PARTY CLAIM) 1. SJN 7414B Veh. Inspected Insured Veh. XB 2780Z 0.00 Coverage (\$) Policy No. 0.00 Excess (\$) Claim No. 24/01/2018 **Assign Date** RACHEL TAN Assign From Vehicle Particulars & Condition 2. 0 VOLVO S80 C.C Make & Model Year of Reg. HIDDEN Engine No. GREY YV1AS565081073274 Colour Chassis No. IN ORDER Steering 153365 KM Odometer SPORTS RIM Modification IN ORDER Brakes FAIR General **Conditions of Tyres** 3. Balance Make Size 6 mm DUNLOP 225/50 R17 R/H Front Tyre 6 mm DUNLOP 225/50 R17 L/H Front Tyre DUNLOP 6 mm 225/50 R17 R/H Rear Tyre 6 mm DUNLOP 225/50 R17 L/H Rear Tyre **Description of Damages** 4. THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. **General Information** 5. 26/01/2018 (10:00 AM) Inspect Date / Time 12/01/2018 **Accident Date** 33 FABER WALK SINGAPORE 128967 Survey held at WESTPOINT TRANSIT PTE LTD Repairer Remarks 5a. A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$5,000 **Estimate Days of Repair** 5b. 4 Working Days ESTIMATED NORMAL PERIOD FOR REPAIR:

Report Ref No. CS3/GAI18001548/R1be2

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES: This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contact or tors, is accepted to any third party who may reply on the Report wholly or in part, Any third party act replying on this Report, in whole or in part, does so at his or her own risk.