

12/02/2002

ASS. REC. BY:

REF: C93/MSG17011808/Ur1b-1<sup>02</sup>

Special Instructions

SURVIVOR:

Mehmen

## ASSIGNMENT (Office)

From (Person):

Tirel Foo

of

mslh

Date/Time:

17-012018

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJP 23678

Insured:

FGL 1819L

at Workshop m/s

: Petrise Auto

Tel:

of

Bik 1 Kaki Bukit Ave 6 #02-34/36

Policy No:

msD/vms / 16-347082

Claim No:

MSC/V/17-000937

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 18062017

CA / REV / REP. / REV 24 HRS Wp

H.O.D. Endorsement:

Date/Time:

19062017 952am

Person Contacted:

Arme

Vehicle IN/OUT

Date/Time	Action/Instruction ( X ) Estimate	Do Not Finalize
	SJP 23678 X	
	FGL 1819L X	
	Dismantle Part : 20062017	
	After repair : 22062017	

240617 1259pm Email to Tirel Foo thru Mehmen

4/5 2800 4/5 (Red 2000f, 41%)

RECEIVED 10 2018

PRS  
SIRIVILLAR RICHARD


REF: MSLH

### ASSIGNMENT

From: \_\_\_\_\_ Date: 19062017  
 Estimated Cost: \_\_\_\_\_  
 OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MY  
 To Inspect Vehicle No: SJP 23678  
 at Workshop m/s Precise Auto  
 of Bik 1 Kuku Bukit Ave 6 #0234  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 4 days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SJP 23678 Yr Regn: 2009 16/03  
 Type: ☒ M.Cad / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: KIA PICANTO cc 1086

Colour: WHITE A/C: Insured / Std / NI / NA

Sp. Reading: 44804 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KNABA 24329T732397

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ Order / Jammed / Leaked / Burnt or

Brake: ☒ Order / Jammed / Leaked / Burnt or

Modi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size: F: 195/50/15

R: \_\_\_\_\_

☒ BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 15/06 08:45 D.O.I. 19/6 3.50pm

Survey held at Precise Auto

Des. of Damages: Fnt / Rear ☒ O/S / NIS / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

Estimate repair range \$2,000 - \$2,500

*[Signature]*  
10/8/2017

Date/Time. File Pass to?

☐

Prell. Report

1) 17062017

☐

Final Report

Date/Time. File Return to?

2) \_\_\_\_\_

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transportation

\_\_\_\_ S - RS \_\_\_\_ Si

\_\_\_\_ Photos

\_\_\_\_ Others

\_\_\_\_

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

PRS.

Lump Sum / I.B.I: (\$

120
50
10
180

# Survey Department Check List (Case Handler)

Reference No. : CS3/MSG17011308/UB-1  
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

**Admin ( Catherine )**: Case handler to make sure all information created by the assignment team are **ACCURATE**.

## (1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code	✓			
N	Assign From	✓			
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer				
C	Excess				

**Surveyor ( Marcus )**: Case handler to make sure the surveyor completed all required information.

## (1) Assignment Form

C	Vehicle No				
C	Regn Month/Year				
N	Vehicle Type				
N	Make & Model				
C	Engine Capacity. (C.C)				
N	Colour				
C	Odometer. (Sp.Reading)				
C	Chassis No				
N	General Condition				
N	Steering				
N	Brake				
N	Modification (Modi)				
C	Tyre Size				
N	Tyre Make				
C	Tyre Balance				
C	Date of Inspection				
N	Survey held				
N	Des.of Damages				

## (2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded				
---	--------------------------------------	--	--	--	--

## (3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

## (4) System - (Views/Merimen)

C	Resurvey photo Uploaded				
---	-------------------------	--	--	--	--

Check By:

Catherine 14/3/18  
Case Handler Date

\*C: Critical \*N: Non-Critical

21/05/20



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale De Experts En Automobile				
MSG INSURANCE (SINGAPORE) PTE LTD			Ref : CS3/MSG17011808/rb-1	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 25-01-2018	
			Code : MSG	
<b>1. Policy Particulars - THIRD PARTY CLAIM</b>				
Insured Veh.	FBL 1819L	Veh. Inspected	SJP 2367B	
Policy No.	MSD/VMS/16-347082	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From	MERIMEN (FIEVEL FOO)	Assign Date	19/01/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	Steering			
Brakes	Modification			
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Engine No.	HIDDEN	Accident Date	15/06/2017	Inspection Date
		25/01/2018		
Survey held at	PRECISE AUTO SERVICE NO.1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 Jun 2017		19 Jun 2017 08:59 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

#### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LIEW YAW MIN, ID: S8138717F		
Main Claimant:	EE GEOK SWEE, ID: S1384761D		
Vehicle Reg. No.:	SJP2367B	Date of Loss:	15/06/2017 08:00 - :59
Claim Type:	TP / MSC/V/17-000937	Policy/Cover Note No.:	MSD/VMS/16-347082-CA (TP, Fire & Theft) Coverage: 04/07/2016 - 03/07/2017
Vehicle Reg. No. (Insured):	FBL1819L	Policy No. (Claimant):	
		Excess:	
Repairer:	Precise Auto Services (HQ) NO.1 KAKI BUKIT AVE 6 #02-34/36, 417883 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Flevel Foo Wenyao - 6643 1316]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Richard Harjanto] ... [Final Rpt due 23/01/2018]		
Driver/Custodian (Insured):	LIEW YAW MIN (), NRIC: S8138717F		

#### ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

- MSIG\_SG (19/01/2018): Report Send Back Alerts - SJP2367B (TP)

#### ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	16/06/2017 15:39
Date Of Accident	15/06/2017 08:45
Exact Location Of Accident	ALONG SEMBAWANG AVE SLIP RD TO GAMBAS AVE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJP2367B
<b>Insured/Policyholder</b>	
Name Of Registered Owner	EE GEOK SWEE
NRIC No	S1384761D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-83336222
Alternative Phone No	OFFICE-83336222

### Vehicle Particulars

Manufacturer	KIA
Model	PICANTO
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	M490684
Cover Note Number	

### Driver's Particulars

Name of Driver	WONG WAI MUN
NRIC No	S6939893F
Date Of Birth	31/10/1969
Occupation	INDOOR
Date Of Driving Pass	22/10/1997
Driving Experience	19 YEARS AND 7 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-98502499
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 327 SEMBAWANG CRESCENT #04-38
Postcode	750327
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - -
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE- SAME DIRECTION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	SEMBANWANG NPC
Police Station Address	ROAD: 4 SEMBAWANG CRESCENT , POSTCODE: 757633 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO POLICE REPORT: T/20170615/2183.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBL1819L
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Name of Driver	LIEW YAW MIN
NRIC/Passport Number	S8138717F
Contact Number	96838145
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### Details of Witness

Name	
Phone Number	

Email Address

**DETAILS OF INJURED PERSON 1**

Name LIEW YAW MIN

Approximate Age

Injuries Sustain

Injured person in which vehicle? FBL1819L

Were seat belts worn?

Was injured conveyed to hospital by ambulance?

Address

Postcode



## Sketch Plan Pg. 1

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

#### Sketch Plan







**SINGAPORE  
POLICE FORCE**



T/20170615/2183

Police Station Of Origin:  
Sembawang N.P.C  
4 Sembawang Crescent SINGAPORE  
757633  
Tel No: 1800-5549999

1 of 3

Report No. T/20170615/2183

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 15/08/2017 21:49	Vide Report No.:	Station Diary No.: 98
--	------------------	--------------------------

**Informant's Particulars**

Name of Informant: WONG WAI MUN			Address: APT BLK 327 SEMBAWANG CRESCENT #04-38 SINGAPORE 750327		
ID Type / ID No.: NRIC NO / S6939893F			Contact No.: Home/Office: Mobile: 98502499		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Female	Age: 47	Date of Birth: 31/10/1969	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: CUSTOMER ACCOUNT SPECIALIST			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 15/06/2017 08:45	Type of Location: T-Junction
Location: Along Road 1 Traveling Toward Road 2 SEMBAWANG AVENUE GAMBAS AVENUE Along sembawang avenue slip road to gambas ave left turn				
Weather: Clear		Road Surface: Dry	Road Speed Limit: 50 Km/h	
Traffic Flow: Two Way		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBL1819L	Motorcycle				Slightly Damaged	0
SJP2367B	Car				Slightly Damaged	0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE  
POLICE FORCE**



T/20170615/2183

Police Station Of Origin:  
Sembawang N.P.C  
4 Sembawang Crescent SINGAPORE  
757633  
Tel No: 1800-5549999

2 of 3

Report No. T/20170615/2183

## CONTINUATION OF REPORT

<b>Rider</b>			
Name	Liew Yaw Min	ID No.	S8138717F
Related Vehicle	FBL1819L (Motorcycle)	Contact No.	96838142
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	15/06/2017	Date Discharge	15/06/2017
No. of Days granted Medical Leave	14	Degree of Injury	Slight
<b>Driver</b>			
Name	WONG WAI MUN	ID No.	S6939893F
Related Vehicle	SJP2367B (Car)	Contact No.	98502499
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On the 15/06/2017 at around 0845hrs, I was travelling along Sembawang Avenue towards Gambas Avenue while my vehicle was in the filter lane awaiting for a left turn. One motorcycle Bearing no. FBL1819L came up to the right side of my vehicle, he hit upon the right side of my vehicle and then wobbled and came to a stop in front of my vehicle. I moved my vehicle forward and came up to the motorcyclist to offer help, we exchanged particulars and he informed that he could have fractured his fingers but has no need for ambulance and will sought out medical treatment himself.

After the accident, My boyfriend called the motorcyclist at around 1510hrs and the motorcyclist informed that he has sought medical treatment and is issued with 2 weeks mc, I do not know which hospital or medical center. My car suffered the following damages.

- Driver front side door scratches and dents
- Driver front side mirror dropped off

The motorcycle suffered scratches on the left side of the body work. I currently do not know how much is the damages to my vehicle and how much the other party is going to claim towards my self.

I wish to inform that this is the first time that this has happened to me that is all.



**SINGAPORE  
POLICE FORCE**



T/20170615/2183

Police Station Of Origin:  
Sembawang N.P.C  
4 Sembawang Crescent SINGAPORE  
757633  
Tel No: 1800-5549999

3 of 3

Report No. T/20170615/2183

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: F / NG BOON WEE	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 15/06/2017 21:49
Officer In Charge Of Case: TP / AEIT / Sr Staff Sgt ANG YI TING, STEPHANIE Contact No.: 65476414	Classification Of Case:
Authentication Stamp NP188	

## CARLINK CONSULTANCY

60 Hillside Drive, Singapore 549009

Fax: 62874788 Tel: 62856178

## INVOICE

Ee Geok Swee  
C/o 1 Kaki Bukit Ave 6 #02-34/36  
Singapore 417883

Invoice No: CL 11888 TP  
Our Ref: CL 11888 SJP 2367 B  
Date: 27th July 2017

S/N	DESCRIPTION	QTY	UNIT PRICE (\$)	AMOUNT (\$)
1	Vehicle No: SJP 2367 B Charges for accident vehicle inspection and appraisal report, transportation, photographs and etc** (photographs - 59 copies)			\$519.00
Total:				\$519.00

We thank you for the opportunity to serve you and assure you of our best at all times



Automotive Engineer Assessor  
MIMI, MIRTE, LCGI, I ENG, LAE, CGLI FTC.

Note: Payment by cheque should be crossed and made payable to "CARLINK CONSULTANCY"

**CARLINK CONSULTANCY**


60 Hillside Drive  
Singapore 549009

Tel : 62856178

Fax : 62874788

**ACCIDENT VEHICLE INSPECTION / ASSESSMENT REPORT**

Our Ref: CL 11888 SJP 2367 B

<b>1 REFERENCE</b>			
Date of request	:	19th June 2017	
Requested by	:	Ee Geok Swee C/o 1 Kaki Bukit Ave 6, #02-34/36 Singapore 417883	
Type of claim	:	Third party	
Workshop	:	M/S Precise Auto Service 1 Kaki Bukit Ave 6, #02-34/36 Singapore 417883	
Date of survey	:	19th June 2017	
Accident date	:	15th June 2017	
<b>2 DETAILS OF VEHICLE</b>			
Registration No.	:	SJP 2367 B	
Make & Model	:	Kia Picanto 1.1 (A)	
Date of registration	:	16th March 2009	
Engine No.	:	G4HG9540870	
Chassis No.	:	KNABA24339T732397	
Speedometer reading	:	44804 Km	
Transmission	:	Automatic	
Colour	:	White	
<b>3 STATIC CHECK</b>			
Steering	:	see annex(es)	Paintwork : Good
Footbrake	:	see annex(es)	Modification : Nil
Handbrake	:	see annex(es)	General condition : Good
<b>4 TYRE CONDITION</b>			
		<u>Nearside/Make</u>	<u>Offside/Make</u> <u>Size</u>
Front tyre	:	6mm/Turanza	6mm/Turanza : 195/50 R15
Rear tyre	:	6mm/Turanza	6mm/Turanza : 195/50 R15
<b>5 POINT OF IMPACT</b>			
See Annex(es) and Motor Accident Reports			
<b>6 REMARK</b>			
This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis and we have not authorised any repair.			

## Annex A : Assesement / Adjustment on Spare Parts

SJP 2367 B

Item	Vehicle Parts Description	Condition	Qty	W/shop Est. (\$)	Disc (%)	Adjusted Cost (\$)	
List Items							
1	Front door assy RH 182	Buckled	20/bul	1	\$600.00	10%	\$540.00
2	Front door protector	Bent/cut	bul	1	\$58.00	10%	\$52.20
3	Front door protector clips	Necessary	neu	6	\$39.00	10%	\$35.10
4	Front door hinges	Distorted/jammed	bul	2	\$84.00	10%	\$75.60
5	Front door checker	Bent/cut	bul	1	\$38.00	10%	\$34.20
6	Front door weatherstripe	Deformed/leaked	neu	1	\$72.00	10%	\$64.80
7	Front door window regulator	Bent	bul	1	\$68.00	10%	\$61.20
8	Front door window regulator motor	Distorted/faulty	sun	1	\$230.00	10%	\$207.00
9	Front door window glass channel rubber	Deformed/cut	11	1	\$56.00	10%	\$50.40
10	Front door stopper	Necessary	11	1	\$12.00	10%	\$10.80
11	Front door window glass channel bracket	Bent	11	1	\$42.50	10%	\$38.25
12	Front door lock	Distorted/jammed	11	1	\$115.00	10%	\$103.50
13	Front door lock striker	Bent	11	1	\$28.00	10%	\$25.20
14	Front fender RH	Warped/dented	bul	1	\$186.00	10%	\$167.40
15	Front knuckle arm RH	Distorted	11	1	\$222.40	10%	\$200.16
16	Front lower RH	Distorted	11	1	\$214.00	10%	\$192.60
17	Front absorber	Bent/leaked	11	1	\$179.00	10%	\$161.10
18	Front absorber mounting	Distorted/slack	11	1	\$105.00	10%	\$94.50
19	Front wheel bearing kit	Distorted/cracking sound	neu	1	\$124.00	10%	\$111.60
20	Front knuckle hub	Distorted	11	1	\$184.00	10%	\$165.60
21	Front side mirror RH	Grazed/base cracked	bul	1	\$210.00	10%	\$189.00
S/Nett Items							
22	Front door sun visor	Necessary	neu	1	\$120.00		\$120.00
23	Front sport rim assy	Grazed/warped/chipped	bul	1	\$580.00		\$580.00
24	Tyre assy	Grazed/bulge	bul	1	\$210.00		\$210.00

Total for Spare Parts : \$3,776.90 \$3,490.21

1683



## Annex B : Adjustment on Labour and Spray Painting

SJP 2367 B

Item	Job Description	Workshop Est. (\$)	Adjusted Cost (\$)	
1	Towing	11 \$80.00	\$60.00	X
2	To tuff coat affected areas	\$120.00	\$80.00	✓
3	To remove & refix front RH door mechanism	\$180.00	\$80.00	60
4	To check/adjust computer wheel alignment (before/after)	\$240.00	\$200.00	100
5	To remove & refix front RH mechanism	\$280.00	\$250.00	60
6	To remove & refix front RH sport rim & contact wheel balancing	\$120.00	11 \$100.00	X
7	To respray affected areas	\$850.00	\$700.00	✓
8	To renew damaged parts, straighten/repair rear pillar and aligned all parts	\$750.00	\$700.00	520

**TOTAL FOR LABOUR & SPRAY PAINTING :** \$2,620.00 \$2,170.00

### Summary

	Workshop Est. (\$)	Adjusted Cost (\$)
TOTAL FOR SPARE PARTS :	\$3,776.90	\$3,490.21
TOTAL FOR LABOUR & SPRAY PAINTING :	\$2,620.00	\$2,170.00
<b>TOTAL REPAIR COSTS :</b>	<u><b>\$6,396.90</b></u>	<u><b>\$5,660.21</b></u>

## CARLINK CONSULTANCY

SJP 2367 B

### Annex C: Recommendation

We have inspected thoroughly the actual damages found on the vehicle and our assessment is appended in the Annex(es) attached. The condition and age of the vehicle was considered before we reached our recommendation as to whether the parts need replacement or repair.

M/S Precise Auto Service estimated repair cost is **S\$6,396.90** and we have adjusted it to **S\$5,660.21** on a part by part basis. However, taking into consideration the age of the vehicle and the availability of used/recondition components. We, therefore recommend a contract lump sum repair cost.

The repairer have agreed to undertake the repairs on a contract lump sum of **S\$4,800.00**, according to acceptable quality and standard. (Repairer discretion to repair parts, to replace with old parts, or to replace with OEM or genuine parts).

The entire repair of the damaged vehicle should be completed within a reasonable period of 7 working days.

We have advised the repairer that the inspection was conducted strictly on a WITHOUT PREJUDICE basis and we have not given any instruction and authorisation to proceed with the repair of the vehicle.

We are reverting the matter to you for your discretion and enclosed is our invoice for service rendered.

Yours faithfully,  
CARLINK CONSULTANCY

A circular stamp with the text "CARLINK CONSULTANCY" around the top edge and "PATRICK NG" in the center. A handwritten signature is written over the stamp.

Automotive Engineer Assessor  
MIMI, MIRTE, LCGI, I ENG, LAE, CGLI FTC.

## PRECISE AUTO SERVICE

NO 1 KAKI BUKIT AVE 6 #02-34/36 AUTOBAY SINGAPORE 417883

TEL : 6745 7367 FAX : 6841 3390

CO. REG. NO. : 35766600C GST REG. NO. : 35766600C

=====

Accident Date : 15-06-17

OUR REF : SJP 2367B/T/17

EE GEOK SWEE

Blk 327 Sembawang Crescent

#04-38

Singapore 750327

## TAX INVOICE

Invoice No. : TP1709-010

DATE : 03-09-17

FINAL BILL ON VEH. NO. : SJP 2367B

VEHICLE MODEL : KIA PICANTO

PART BY PART REPAIR

INCLUDING SUPPLY OF PARTS & LABOUR

PANEL BEATING & SPRAY PAINTING

4,800.00

SUB-TOTAL	:	<u>4,800.00</u>
ADD GST 7%	:	<u>336.00</u>
TOTAL AMOUNT SGD	:	<u><u>5,136.00</u></u>

This is a computer generated document and requires no signature.

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Jun 2017		19 Jun 2017 08:59 <a href="#">Edit Adj Rpt</a>	<b>S\$2,800.00</b> <a href="#">Edit Estimates</a>	<b>S\$2,800.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS			[Created by insurer]
Insured:	LIEW YAW MIN, ID: S8138717F		
Main Claimant:	EE GEOK SWEE, ID: S1384761D		
Vehicle Reg. No.:	SJP2367B	Date of Loss:	15/06/2017 08:00 - :59
Claim Type:	TP / MSC/V/17-000937	Policy/Cover Note No.:	MSD/VMS/16-347082-CA (TP, Fire & Theft) Coverage: 04/07/2016 - 03/07/2017
Vehicle Reg. No. (Insured):	FBL1819L	Policy No. (Claimant):	
		Excess:	
Repairer:	Precise Auto Services (HQ) NO.1 KAKI BUKIT AVE 6 #02-34/36, 417883 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wenyao - 6643 1316]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Richard Harjanto] ... [Final Rpt due 23/01/2018]		
Driver/Custodian (Insured):	LIEW YAW MIN (), NRIC: S8138717F		

ASSOCIATED MAIL RECEIVED		<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
<ul style="list-style-type: none"> <li>MSIG_SG (19/01/2018): Report Send Back Alerts - SJP2367B (TP)</li> </ul>			

ALL ASSOCIATED TASKS			<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>			
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									


































## Claim Documents

**\*SJP2367B (MSC/V/17-000937)**  
**[FBL1819L]**  
**TP**  
**EE GEOK SWEE**  
**Jun 15 2017 8:00AM**  
**[LIEW YAW MIN]**  
**Precise Auto Services**

[Upload Documents](#) | 
 [Upload Photos](#) | 
 [Compose New Letter](#)

[View](#) [View in Browser ▼](#)

Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	19/06/17 09:39	<b>Accident Statement</b> From: SC - Reg. No: FBL1819L, Claimant: LIEW YAW MIN	 Load HTM	
Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/06/17 12:38	General View	 Load JPG	<input checked="" type="checkbox"/>
2	24/06/17 12:38	General View	 Load JPG	<input checked="" type="checkbox"/>
3	24/06/17 12:38	General View	 Load JPG	<input checked="" type="checkbox"/>
4	24/06/17 12:38	General View	 Load JPG	<input checked="" type="checkbox"/>
5	24/06/17 12:38	General View	 Load JPG	<input checked="" type="checkbox"/>
6	24/06/17 12:38	General View	 Load JPG	<input checked="" type="checkbox"/>
7	24/06/17 12:38	General View	 Load JPG	<input checked="" type="checkbox"/>
8	24/06/17 12:38	General View	 Load JPG	<input checked="" type="checkbox"/>
9	24/06/17 12:38	General View	 Load JPG	<input checked="" type="checkbox"/>
10	24/06/17 12:38	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
11	24/06/17 12:38	General View	 Load JPG	<input checked="" type="checkbox"/>
12	24/06/17 12:38	General View	 Load JPG	<input checked="" type="checkbox"/>
13	24/06/17 12:38	General View	 Load JPG	<input checked="" type="checkbox"/>
14	24/06/17 12:38	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
15	24/06/17 12:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
16	24/06/17 12:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
17	24/06/17 12:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
18	24/06/17 12:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
19	24/06/17 12:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
20	24/06/17 12:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
21	24/06/17 12:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
22	24/06/17 12:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
23	24/06/17 12:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
24	24/06/17 12:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
25	24/06/17 12:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
26	24/06/17 12:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
27	24/06/17 12:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
28	24/06/17 12:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
29	24/06/17 12:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
30	24/06/17 12:39	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

31	24/06/17 12:39	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
32	24/06/17 12:39	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
33	24/06/17 12:40	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
34	24/06/17 12:40	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
35	24/06/17 12:40	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
36	24/06/17 12:40	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
37	24/06/17 12:40	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
38	24/06/17 12:40	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	16/06/17 17:25	PRI from Precise Auto Service		Load PDF	
2	19/06/17 09:08	Survey Disagree on SJE		Load PDF	
3	19/06/17 09:39	SJP2367B GIA, POLICE REPORT, DL & IC From: SC - Reg. No: FBL1819L, Claimant: LIEW YAW MIN		Load PDF	
4	26/09/17 12:56	Survey Report & Final Repair Bill		Load PDF	
5	26/09/17 12:56	Survey Photos		Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	14/02/18 15:32	Invoice		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

//

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.





# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/MSG17011808/URBE2-1  
**Date:** 14/02/2018

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: MSD/VMS/16-347082-CA  
**Claimant Vehicle No :** SJP2367B **Insured Vehicle No :** FBL1819L  
**Date of Loss:** 15/06/2017 **Nature of Claim:** TP **Claim No:** MSC/V/17-000937

### DESCRIPTION & IDENTIFICATION OF VEHICLE

**Reg No:** SJP2367B  
**Make & Model:** KIA PICANTO, 1.1 (A) **Engine No:** G4HG9540870  
**Reg. Date:** 16/03/2009 (Man. Year: 2009) **Chassis No:** KNABA24339T732397  
**Colour:** White **Odometer:** 44804 km  
**Engine Capacity:** 1086 cc  
**Market Value/New Car Price:** N/A  
**Sum Insured (\$\$):** Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

**General Condition:** Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes  
**Handbrake (Serviceable):** Yes **Engine Modification:** No **Pre-accident Condition:**

### CONDITION OF TYRES

**Front Tyre Size:** 195/50 R15 **Rear Tyre Size:** 195/50 R15  
**Front Left Side:** Bridgestone 6 mm **Rear Left Side:** Bridgestone 6 mm  
**Front Right Side:** Bridgestone 6 mm **Rear Right Side:** Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,776.90	2,021.90	1,755.00	46.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,620.00	1,520.00	1,100.00	41.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>6,396.90</b>	<b>3,541.90</b>	<b>2,855.00</b>	<b>44.63</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>2,800.00</b>		
<b>(\$\$)</b>	6,396.90	2,800.00	3,596.90	56.23
<b>+ GST 7.00/7.00% (\$\$)</b>	447.78	196.00	251.78	56.23
<b>Nett Amount (\$\$)</b>	<b>6,844.68</b>	<b>2,996.00</b>	<b>3,848.68</b>	<b>56.23</b>

### INSPECTION

**Date of Assignment:** 19/06/2017  
**Date Inspected:** 19/06/2017 **Inspected At:** Precise Auto Services (HQ)  
 NO.1 KAKI BUKIT AVE 6 #02-34/36  
 Singapore 417883  
**Estimated Period of Repair:** 4.0 days

**Adjuster:** Richard Harjanto

**Manager:** CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

*any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference**

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 14 Feb 2018)

**Parts:** 144      KIA PICANTO 1.1 (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SJP2367B)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR ASSY RH	Dented / Bent	600.00 F	*582.00 FL
2	1		*FRONT DOOR PROTECTOR	Bent	58.00 F	*58.00 FL
3	6		*FRONT DOOR PROTECTOR CLIPS	Necessary	39.00 F	*39.00 FL
4	2		*FRONT DOOR HINGES	Bent	84.00 F	*84.00 FL
5	1		*FRONT DOOR CHECKER	Bent	38.00 F	*38.00 FL
6	1		*FRONT DOOR WEATHERSTRIPE	Necessary	72.00 F	*72.00 FL
7	1		*FRONT DOOR WINDOW REGULATOR	Bent	68.00 F	*68.00 FL
8	1		*FRONT DOOR WINDOW REGULATOR MOTOR	Smashed	230.00 F	*230.00 FL
9	1		*FRONT DOOR WINDOW GLASS CHANNEL RUBBER	Not Necessary	56.00 F	*- FL
10	1		*FRONT DOOR STOPPER	Not Necessary	12.00 F	*- FL
11	1		*FRONT DOOR WINDOW GLASS CHANNEL BRACKET	Not Necessary	42.50 F	*- FL
12	1		*FRONT DOOR LOCK	Not Necessary	115.00 F	*- FL
13	1		*FRONT DOOR LOCK STRIKER	Not Necessary	28.00 F	*- FL
14	1		*FRONT FENDER RH	Dented	186.00 F	*186.00 FL
15	1		*FRONT KNUCKLE ARM RH	Not Necessary	222.40 F	*- FL
16	1		*FRONT LOWER RH	Not Necessary	214.00 F	*- FL
17	1		*FRONT ABSORBER	Not Necessary	179.00 F	*- FL
18	1		*FRONT ABSORBER MOUNTING	Not Necessary	105.00 F	*- FL
19	1		*FRONT WHEEL BEARING KIT	Necessary	124.00 F	*124.00 FL
20	1		*FRONT KNUCKLE HUB	Not Necessary	184.00 F	*- FL
21	1		*FRONT SIDE MIRROR RH	Broken	210.00 F	*210.00 FL
22	1		*FRONT DOOR SUN VISOR	Necessary	120.00 FS	*120.00 FS
23	1		*FRONT SPORT RIM ASSY	Dented	580.00 FS	*380.00 FS
24	1		*TYRE ASSY	Serviceable	210.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>3,776.90</b>	<b>2,191.00</b>
<b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b>	<b>0.00</b>	<b>169.10</b>
<b>Total Parts (\$\$)</b>	<b>3,776.90</b>	<b>2,021.90</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TOWING	New	80.00	0.00
2	TO TUFF COAT AFFECTED AREAS	New	120.00	80.00
3	TO REMOVE & REFIX FRONT RH DOOR MECHANISM	New	180.00	60.00
4	TO CHECK / ADJUST COMPUTER WHEEL ALIGNMENT (BEFORE/AFTER)	New	240.00	100.00
5	TO REMOVE & REFIX FRONT RH MECHANISM	New	280.00	60.00
6	TO REMOVE & REFIX FRONT RH SPORT RIM & CONTACT WHEEL BALANCING	New	120.00	0.00
7	TO RESPRAY AFFECTED AREAS	New	850.00	700.00
8	TO RENEW DAMAGED PARTS, STRAIGHTEN / REPAIR REAR PILLAR AND ALIGNED ALL PARTS	New	750.00	520.00
<b>Gross Labour Cost (\$)</b>			<b>2,620.00</b>	<b>1,520.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >