

(08/11/13) wef

ASS. REC. BY: Marius

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: CB6462P

at Workshop m/s profu 11 am

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

1/2021

Vehicle: IN / OUT

Veh No: CB6462P Yr Regn: 1 01

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or Car

Make: Toyota hace c.c. 2986

Colour: silver A/C: Insured / Std / NI / NA

Sp. Reading: 450425 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: LH1740006138

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185-214

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

westlake

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 24/1/18

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 29/1/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

n/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to? _____

☐ : Preli. Report

☐ : Final Report

Date/Time, File Return to? _____

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Survey Fee: _____

Transportation: _____

) S + RS, SI

) Photos

) Others

TOTAL

Report Format : _____

Lump Sum / I.B.I. (\$) _____

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8784F
Vehicle Details	
Vehicle No.:	CB6462P
Vehicle to be Exported:	No
Intended De-registration Date:	29 Jan 2018
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE COMM D
Primary Colour:	White
Secondary Colour:	Silver
Manufacturing Year:	2000
Engine No.:	5L5034420
Chassis No.:	LH1740006138
Maximum Power Output:	-
Open Market Value:	\$33,355.00
Original Registration Date:	09 Jan 2001
First Registration Date:	09 Jan 2001
Transfer Count:	5
Actual ARF Paid:	\$1,668.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Rebate Amount:	\$0.00
Total Rebate Amount:	\$0.00

The information contained herein is correct as at 29 Jan 2018

OK